


Grills (Group 1)

1969 GS Grill




G-69GS.....\$499.00 ea.

1969 GS Grill Emblem.

GE-679G.....\$31.00 ea.

1970 GS Grill. (Includes Mounting Studs)



G-70GS.....\$499.00

1970 GS Grill Emblem. "GS by Buick"


GE-70G.....\$49.50 ea.

1970 GSX Grill Emblem. "GSX by Buick"

GE-70X.....\$67.50 ea.



1971 GS Grill



G-71GS.....\$629.00

1971 GS Grill Emblem. "GS by Buick"


GE-71G.....\$39.50 ea.

1971 GSX Grill Emblem. "GSX by Buick"

GE-71X.....\$52.25 ea.



1972 Skylark & GS Grill



G-72GS.....in production, please inquire

GE-72G.....\$52.25 ea.

1972 GS Grill Emblem. "GS by Buick"

GE-72G.....\$52.25 ea.

GEP-72.....(Backing Plate.....\$9.50 ea.

1972 GSX Grill Emblem. "GSX by Buick"

GE-72X.....\$52.25 ea.

GEP-72.....(Backing Plate.....\$9.50 ea.



Cooling & Oiling (Group 1)

Grill Emblems (1.303)

1965 "Gran Sport" Grill Emblem.
GE-65GS.....\$42.50 ea.

Gran Sport

1966 "Gran Sport" Grill Emblem.
GE-66GS.....\$42.50 ea.


1968 "GS" Grill Emblem.
GE-68GS.....\$30.25 ea.



1967, 1969 "GS" Grill Emblem.
GE-679G.....\$30.25 ea.



1970 "GS By Buick"
Grill Emblem.
GE-70G.....\$39.50 ea.



1970-1972 Hood Release Handle.
Neoprene coated as original.
HH-702.....\$12.50 ea.


1971 "GS By Buick" Grill Emblem.
GE-71G.....\$39.50 ea.



1971-1972 "GSX By Buick" Grill Emblem.
GE-71X.....\$52.25 ea.



1970 "GSX By Buick" Grill Emblem.
GE-70X.....\$52.25 ea.



1971 "Skylark By Buick"
Grill Emblem.
GE-71S.....\$32.50 ea.



1972 "GS By Buick" Grill Emblem.
GE-72G.....\$39.50 ea.

1968-1972 Radiator Core Support Repair Kits

Core support Mounts and Hardware

Our 3 piece kit of heavy gauge metal, repairs rusted box & lower panel area

1968-1969 All. Repair for R.H.. side.
CSK-689R.....\$114.50 ea.
1968-1969 All. Repair for L.H.. side.
CSK-689L.....\$114.50 ea.


Our 3 piece kit of heavy gauge metal, repairs rusted box & lower panel area

1970-1972 All. Repair for R.H.. side.
CSK-702R.....\$114.50 ea.
1970-1972 All. Repair for L.H.. side.
CSK-702L.....\$114.50 ea.




1967-1972 Lower radiator support
mount with metal core.
3/4" ID. 2 1/2" OD. 1 1/8.
BM-644.....\$8.25 ea.

1967-1972 Upper radiator core support
mount.
BM-644A.....\$7.25 ea.




1967-1972 Core Support Hardware Kit.
CSK-644BK.....\$4.75 ea.

1967-1972 Core support mount kit.
Lower mounts, 2 upper mounts and
hardware.
CSK-644.....\$35.75



Cooling & Oiling (Group 1)



Fans

Radiator Fan

1961-1972 Stock, 4 Blade - Replacement.
 FB-416.....\$ 18.50 ea.

Clutch Fan Blades

1961-1972 18" Clutch Fan Blade - Replacement.
 FB-626C\$ 64.25 ea.
1964-1968 Clutch Fan Blade. 19" Replacement
 FB-648C\$ 43.50 ea.

Flex Fan Blades

1969-1972 Flex Fan Blade..
 FB-696F.....\$ 54.50 ea.
1968 Flex Fan Blade.
 FB-68F.....\$ 54.50 ea.
1964-1968 Flex Fan Blade.
 FB-648F.....\$ 57.25 ea.




Fan Spacer Kit



1969-1972 Fan Spacer Kit.
 FSK-696\$ 16.50 ea.



Fan Shrouds (1.277)




Fiberglass Reproductions

1965-1966 GS.
 FS-656\$ 133.75 ea.
1965-1967
 1965 300 engine with crossflow radiator;
 1966-1967 All 300 and 340 engines.
 FS-657\$133.75 ea.
1967 GS-400.
 FS-67\$ 133.75 ea.
1968-1969 GS 400.
 FS-689\$ 114.50 ea.
1970 GS and GSX 455.
 FS-70\$ 159.00 ea.
1971-1972 All 455 engines.
 FS-712.....\$ TOS ea

Fan Clutches (1.050)



1964z-1972
 1964-1967: 225, 300 and 340 engines;
 1968-1972: 350 engine.
 FC-642.....\$ 57.75 ea.
1965-1972
 1965-1969 400 engine;
 1969-1972 250 engine;
 1970-1972 455 engine.
 FC-626.....\$ 57.75 ea.
1968 250 engine.
 FC-68.....\$ 60.50 ea.



Fan Belts

Don't Rely On Old Belts!

The price of a new belt is a small fraction of the repair costs a broken belt can cause.

We Stock Hundreds of Different Fan Belts.
 When Ordering, Please Include:
 The Model, The Year, Engine Size, and if you have
 Power Steering? or Air Conditioning?

ALSO: WHICH BELT (Fan-Alt., Fan-AC Comp.,
 Steering Pump-Air Pump, etc.).

Cooling & Oiling (Group 1)


Thermostat (with Gasket) (1.246)

1961-1972 All except 1965-1966 GS.	
T-330.....(180°).....	\$9.25 ea.
T-330L.....(160°).....	\$9.25 ea.
T-330H.....(195°).....	\$9.25 ea.
1965-1966 GS	
T-536.....(180°).....	\$9.25 ea.
T-536L.....(160°).....	\$9.25 ea.
T-536H.....(195°).....	\$9.25 ea.


Thermostat By Pass Hoses

1962-1972	
1962-1967 V-6 engines;	
1964-1972 300, 340 and 350 engines.	
BP-625.....	\$7.25 ea.
1967-1972 400 and 455 engines.	
BP-676.....	\$7.25 ea.

Water Pumps (1.069)



1961-1963 198, 215 engine w/o ac;	
1962-1963 all V-6	
WP-613.....(exchange item).....	\$46.25 ea.
1961-1963 215 engine w/ ac	
WP-613A.....(exchange item).....	\$49.50 ea.
1964-1970 225, 300, 340 and 350 engines.	
WP-640.....	\$54.00 ea.
1965-1966 400 engine without A. C.	
WP-626.....(exchange item).....	\$78.25 ea.
1965-1966 400 engine with A.C.	
WP-626A.....(exchange item).....	\$67.50 ea.
1967-1970 400, 455 with A. C.	
WP-670.....	\$79.75 ea.
1968-1972 250 engine.	
WP-684.....	\$41.25 ea.
1971-1972 350 engine.	
WP-712S.....	\$46.25 ea.
1967-1972 400, 455 without A.C.	
WP-672.....	\$56.75 ea.
1971-1972 455 engines with A.C.	
WP-716.....	\$52.00 ea.




Water Pump Mounting Gaskets

1961-1972 198, 215, 225, 300, 340 and 350 engines.	
WPG-615.....	\$3.25 ea.
1965-1972 400 engines.	
WPG-626.....	\$3.25 ea.
1967-1972 400 and 455 engines.	
WPG-675.....	\$3.25 ea.

Water Outlets

1961-1972	
1961 thru 1972 all except 1965 & 1966 GS.400	
WO-615.....	\$16.50 ea.
1965-1966 400 engine.	
WO-626.....	\$19.50 ea.

Temperature Sending Units



1961-1965 All except 1965 GS - One (1) terminal.	
TSU-615.....	\$13.25 ea.
1965-1968 GS 400 - Two (2) terminals.	
TSU-608.....	\$13.25 ea.
1966-1972 300, 340, 350 and 455 engines with lights.	
One (1) terminal.	
TSU-662.....	\$10.75 ea.
1970-1972 All with gauges.	
TSU-702.....	\$21.50 ea.

Water Manifold Gasket Kit	
1961-1966 All 400,401. Includes 2 gaskets and "O" ring.	
WMK-536.....	\$8.50 ea.


Water Outlet Gasket

1961-1972 All.	
WOG-615.....	\$2.00 ea.

Crankcase Vent Hose (To Carb)

1972 All 350 & 455 with 4BBL Carb. (Formed Hose)	
VH-725.....	\$14.75 ea.


Cooling & Oiling (Group 1)



Radiators

1968 thru 1972 All with manual transmission. Concours correct
 R-682M.....\$695.00 ea.


Radiator Insulators

 **1962** all 2nd type; Lower
1963 All. Lower
 RI-623S\$14.50 ea.

1962 all 2nd type; Upper. 2 per car
1963-1964 All. Upper. 1 per car
1965 All with downflow radiator. 2 per car
 RI-625S.....\$15.00 ea.

1965 All with cross-flow radiator;
1966 All.
 RI-656\$26.00 pair

 **1965** GS;
1966 All.
 RI-656B.....\$26.00 pair

 **1968-1972** All with 3 core radiators.
 Set of 4. (1970 cars compare with RI-690 below)
 RI-682S.....\$40.50 set

1970 Some with 3 core radiator. 2 pair used per car.
 Compare with RI-682S
 RI-690\$20.00 pair.

4-Core Radiator Insulators



Correct replacement for 4-core radiators.. All years as required.
 RI-600\$15.00 pair

Radiator Caps

Take a good look at these Caps.They are identical to the originals. Correct in every detail, they feature the cap number, instructions and of course genuine "AC" identification stamped right into the zinc plated surface. Show quality, approved and licensed by Buick.



1961-1964 All. 15 lb.
 RC-15D.....\$29.50 ea.
1965-1968 All. 15 lb.
 RC-15F.....\$29.50 ea.
1969-1970 All w/o coolant recovery sys. 15 lb.
 RC-15H.....\$29.50 ea.
1970-1972 All with coolant recovery sys. 15 lb.
 RC-29.....(plate has scalloped edge).....\$39.50 ea.
1970-1972 All with coolant recovery sys. 15 lb.
 RC-29S.....(plate has smooth edge).....\$39.50 ea.

Replacement Radiator Caps



1961-1969 All. 15 lb.
 RC-579.....\$13.75 ea.
1970-1972 All.
 RC-706.....\$6.50 ea.


Radiator Overflow Hose

Correct "Ribbed" Hose sold in 3 1/2' length. All years as required.
 OH-600.....\$ 6.50 ea.

Cooling & Oiling (Group 1)


Radiator Hoses

We Can Supply Almost Any Model/Year Check NOS Section Also! **Please Inquire.**



1961 All V8, lower.	
RH-369	\$ 17.50 ea.
1962 V6 (Radiator 126 or 127), Lower.	
RH-509	\$ 17.50 ea.
1962 V8 (Radiator 121 or 143), Lower.	
RH-369	\$ 17.50 ea.
1962-1963 V6 , Upper.	
UH-623	\$ 17.50 ea.
1964-1965 Upper	
1964: V6;	
1965: V6 (Down Flow)	
RH-392	\$ 19.50 ea.
1965 8 cyl without AC (Down Flow), Upper.	
RH-439	\$ 18.25 ea.
1965 8 cyl with AC, Upper.	
RH-755	\$ 14.75 ea.
1965-1968 Lower	
1965: 8 cylinder (X-Flow);	
1966: 300, without AC, with AP;	
1967-1968 All 300, 340, 400.	
RH-742	\$ 19.50 ea.
1966-1967 Upper	
1966 -1967 All 340	
RH-485	\$ 19.50 ea.
1966-1967 Lower	
1966: Special, with AC;	
1967: 340 (Exc. SP), without AC;	
RH-512	\$ 16.50 ea.
1967 340 (Exc. SP), without AC, Upper.	
RH-533	\$ 17.50 ea.
1968-1970 Upper	
1968 All 350 & 400;	
1969-1970: 350 (Special and Skylark);	
1969: 400 (GS, Sportwagon);	
1970: 455 (GS).	
RH-980	\$ 18.25 ea.
1969-1972 All Skylark/GS, 350, 400 & 455, Lower.	
RH-597	\$ 16.25 ea.
1969-1972 Upper	
1969-1970 All GS-350;	
1971 All 455;	
1972: All GS-350.	
RH-715	\$ 20.25 ea.
1971-1972 Upper	
1971 All 350 ;	
1972 All exc. GS-350	
RH-869	\$16.00 ea.

Radiator Hose Support



1969-1970 All GS.	
HS-690.....	\$ 22.00 ea.

Radiator Overflow Reservoir

1970 thru 1972 models. Note that 1970 early models came with a clear top. Later 1970 models and all 1971-1972 models had Black tops. This is a fine reproduction with correct embossed letters and numbers, made a bit more sturdy than the original.

OR-702B.....	Black Top.....	\$149.00 ea.
OR-702C.....	Clear Top.....	\$149.00 ea.



Radiator Hose Clamps

ORIGINAL EQUIPMENT
" TOWER TOP " HOSE CLAMP

Authentic reproduction of "Tower Top" Hose clamps made by the Wittek Company for GM. They are correct for all 1961-1972 models.

RC-216..	2 1/16" Diameter fits most upper hoses.\$ 2.00 ea.
RC-214..	2 1/4" Diameter fits most lower hoses.\$ 2.00 ea.

Cooling & Oiling (Group 1)




Heater Hose

- 3/4" All Years.
HH-34\$ 1.00 ft.
- 3/4" All Years: 50 ft.
HH-3450\$ 39.00
- 5/8" All Years.
HH-58\$ 1.00 ft.
- 5/8" All Years: 50 ft.
HH-5850\$ 39.00

Breather Tubes

(Air Cleaner to Rocker Cover) (1.745)

Breather Tube




1968-1969 All 350 and 400 4BBL.
VT-689\$16.00 ea.

1970-1971 all V-8; 1972 all 455 engines
VT-704.....\$13.75 ea.

Crankcase Vent Hose (To Carb) (1.746)

1972 All 350 & 455 with 4BBL Carb. (Formed Hosed)
VH-725\$14.75 ea.

Tower Top Heater Hose Hose Clamps



"Tower Top"

Buick used "Tower Top" hose clamps on all cars from 1961-1972. We supply the identical clamps made by the Wittek Company. They are authentic and correct.


- 1 1/16" for 5/8" heater hose.
HC-580\$ 2.00 ea.
- 1" for use on thin walled 5/8" hose.
HC-580S.....\$ 2.00 ea.
- 1 1/4" for 3/4" heater hose.
HC-340\$ 2.00 ea.
- 1 3/16" for use on thin walled 3/4" hose
HC-340S.....\$ 2.00 ea.

Wire Hose Clamps



- For 9/16" OD diameter hose.
HC-916W\$ 0.85 ea.
- For 5/8" OD diameter hose.
HC-580W\$ 0.75 ea.
- For 3/4" OD diameter hose.
HC-340W\$ 0.75 ea.
- For 15/16" OD diameter hose.
HC-1516W\$ 0.75 ea.
- For 1"OD diameter hose.
HC-100W\$ 1.00 ea.

Cooling & Oiling (Group 1)



Oil Filters

1961-1972 All except 250 engines.
OF-590.....\$ 8.25 ea.

1968-1971 All 250 engines.
OF-681.....\$ 9.25 ea.

PF-24 Oil Filters

A brand new quality reproduction on the original red, white, and blue, "AC TYPE PF-24 oil filter with logo and proper coloring. A must for the concourse restorer.

OF-590AC.....\$21.50 ea.

PCV VALVES

1963-1967
1963 All;
1964-1967 V-6.



PCV-637\$ 6.50 ea.

1964-1972 All V8.
PCV-644\$ 4.50 ea.

PCV Valve Grommet.



1963-1972 all.
VG-634\$ 6.50 ea.

PCV Valve Hose Clamp. ALL on PCV Hose.

HC-660P\$ 1.50 ea.

Oil Pan

1969-1970 all 400, 430, 455 engines;
1971-1972 all 455 engines.

Not for factory exhaust crossover systems.

OP-676\$159.00 ea.

Oil Pan Drain Plug & Gasket Kit

1961-1972 Oil pan drain plug and gasket.

1/2" x 20" thread.

OP-595.....\$ 5.25 kit

GM Engine Lubricant (E.O.S.)

Genuine GM EOS provides excellent lubrication. Highly recommended. 16 oz.

EOS-300.....\$17.50 each




Oil Pick-up Tube and Screen

1967-1972 400 and 455 engines. (Increased oil pick-up over stock 1/2" tube. Gives 5-10 psi oil pressure increase. 1967-1970 engines require that pick-up passage drilled to 5/8". Acts as replacement for 1970 and later engines).

OPU-675\$82.00 ea.

1969-1972 350 engine.

OPU-695\$ 19.50 ea.



Oil Pumps (1.652)

1965-1966 400 engine.

OP-626\$ 107.00 ea.

1967-1972 400 and 455 engines.

OP-675\$ 107.00 ea.

OP-675H.....(High Volume).....\$ 91.25 ea.

1968-1981 350 engines.

OP-681PLEASE INQUIRE

Oil Pump Kits (1.652)

1961-1963 215 engine.

OPK-613\$38.00 kit

1964-1972

1964-1967 225, 300 engine;

1966-1967 340 engine;

1968-1972 350 engine.

OPK-642\$ 32.50 kit

OPK-642H.....(High Volume Kit).....\$ 39.50 kit

1965-1972 400 and 455 engines.

OPK-676\$ 31.25 kit

OPK-656H.....(High Volume Kit).....\$ 58.75 kit

Oil Pump Thrust Plate Repair Kit

This kit provides a NEW WEARING Surface for badly scored or worn cover housing. Kit contains all necessary screws, gaskets and instructions.


1961-1972 all 215, 225, 300, 340, 350, 455 engines

OPK-685\$ 20.50 ea.

Cooling & Oiling (Group 1)



OC-397A



OC-397 & OC-647



OC-684 & OC-694

Oil Filler Breather Caps

1961-1967 All exc. chrome jobs. Genuine "AC OIL" Exact.

OC-397.....\$ 24.50 ea.

1961-1967 All except chrome jobs - replacement.

OC-397A.....\$ 8.50 ea.

1965 & 1967 GS Models with chrome twist on "AC Oil"

OC-647.....\$ 34.00 ea.

1968-1972 All (twist on type) replacement.

OC-684.....\$ 4.50 ea.

1969-1972 All Stage 1 engines. Chrome. replacement.

OC-694.....\$ 9.50 ea.

Oil Pressure Switches (1.800)



1961-1966

1961 All;

1962-1963 All 8 Cylinder;

1964-1966 225, 300, and 340.

OPS-606.....\$ 9.25 ea.



1962-1972

1962-1963 All 6 Cylinder;

1967 All;

1968-1972 All with 1/4" Thread;

OPS-620.....\$ 7.50 ea.

1965-1966GS. 400 engine

OPS-606.....\$9.25 ea.

1968-1972

1968 1/8 Thread;

1969-1970 1/8 Thread;

1971-1972 1/8 Thread.

OPS-682.....\$ 9.50 ea.

1970-1972 All with Gauges.

OPS-702.....\$ inquire



Adjustable Oil Pressure Regulator

1961-1972 All. Regulate your oil pressure by adjusting tension on relief spring. Allows for safe and easy adjustment externally.

OPR-600\$38.00 ea.

Oil Gaskets

	1962-63 198 V-6	1961-63 215 V-8	1964-67 225 V-6	1964-72 300, 340, 350	1965-66 400	1967-72 400 455 engines
Oil Pan	OPG-623 \$ 10.50 ea.	OPG-613 \$ 10.50 ea.	OPG-647 \$ 10.50 ea.	OPG-645 \$ 10.50 ea.	OPG-576 \$ 11.00 ea.	OPG-676 \$ 14.00 ea.
Oil Pan Drain Plug	ODG-615 \$ 2.00 ea.	ODG-615 \$ 2.00 ea.	ODG-615 \$ 2.00 ea.	ODG-61 \$ 2.00 ea.	ODG-615 \$ 2.00 ea.	ODG-675 \$ 2.00 ea.
Rear Main Bearing Set	RMS-615 \$ 9.50 set	RMS-615 \$ 9.50 set	RMS-615 \$ 9.50 set	RMS-615 \$ 9.50 set	RMS-576* \$ 19.50 set	RMS-615 \$ 9.50 set

*RMS-576 is the new Rubber Lip Type for easy installation and leak-free seal.



Cars Inc., recognized leader in Buick
Parts & Service since 1973