


# Hood, Front Fenders (Group 8)



## Hood Insulation (8.021)

**1961-1963** All. 48" X 55" X 1" gray. trim to fit  
 HI-415 .....\$30.00 ea.

## Hood Insulation Kits (Die Cut)

**1961-1962** All. Pre-cut, ready to install  
 HI-612 .....\$29.50 ea.  
**1964-1967** All. 5 piece kit. Pre-cut, ready to install  
 HI-647 .....\$30.75 ea.  
**1968-1972** All. 5 piece kit. Pre-cut, ready to install  
 HI-682 .....\$30.75 ea.

## Spray Adhesive for application of Hood Insulation

SA-360.....(20 oz).....\$16.50 ea.



## Hood Bumpers

**1961-1972** Adjustable Front Hood  
 Rubber Bumper with stud. 8mm x 1 1/2"  
 HB-585 .....\$3.50 ea.  
 HS-585.....Stud Only.....\$2.00 ea.  
 Retaining nut for above.  
 BN-650 .....\$5.00 ea.  
**1961-1972** Front Hood Rubber Bumper Cap.  
 HB-595 .....\$2.00 ea.

**1961-1962** All. Hood to fender bumper. 4 per car.  
 HFB-612S.....\$4.75 ea.

**1963-1968** All. Hood to fender bumper.  
 HFB-610 .....\$2.50 ea.

**1969-1972** All. Hood to fender bumper.  
 HFB-611 .....\$2.50 ea.

**1963** All Special and Skylark. Hood to fender bumper.  
 HFB-63 .....\$3.25 ea.

**1968-1972** All. Hood to cowl bumper.  
 HB-682 .....\$2.00 ea.

## Hood Emblems

### 400


**1969** GS "400" Emblem Fits either side.  
 HE-400 .....\$35.00 ea.  
 HE-400P.....(Matched Pair).....\$65.00 pr.

### 350

**1969** GS "350" Emblem. Fits either side.  
 HE-350 .....\$35.00 ea.  
 HE-350P.....(Matched Pair).....\$65.00 pr.

## STAGE 1


**1969** GS "Stage 1" Hood Emblem. Fits either side.  
 HE-69S1 .....\$25.00 ea.  
 HE-69S1PP.....(Matched Pair) .....\$45.00 pr.



## Hood Release Handle (Rubber Coated as original)

**1970-1972** All  
 HH-702 .....\$15.00 ea.

## Front Fender Aprons



GS Fast with Class  
 FC-4 .....\$18.50 ea.

GSX , Beats you in stages  
 FC-5 .....\$18.50 ea.

# Front Fenders (Group 8)


## Front Fenders

We have a limited supply of NOS fenders. Please check Group 8.130 in NOS Section or call for latest availability.

## Front Fender Patch Panels


FP-689L	1968-1969 All - Left.....	\$TOS ea.
FP-689R	1968-1969 All - Right.....	\$TOS ea.
FP-702L	1970-1972 All - Left.....	\$55.00 ea.
FP-702R	1970-1972 All - Right.....	\$55.00 ea.

## Front Inner Fender Repair Panel



Replaces the usually rusted area on the Battery Side, Inner Fender. 1970 thru 1972 all.

BP-702.....	\$75.00 ea.
-------------	-------------



## Fender Splash Aprons

1964-1965 Front Inner Fender.

FA-645.....	\$28.50 set.
1966-1967 Front Inner Fender.	
FA-667.....	\$28.50 set.
1968-1972 Inner Fender. Includes Staples as original	
FA-682.....	\$20.25 set.

## Make You Own Fender Splash Aprons

Correct composition rubber material is excellent for duplication using your old aprons as a pattern.

MR-4243.....(42" x 43").....	\$56.00 ea.
MR-2143.....(21" x 43").....	\$28.00 ea.

## 1969 Skylark Front Fender Louvers

FO-69L.....(L.H. side).....	\$29.00 ea.
FO-69R.....(R.H. side).....	\$29.00 ea.

## Rocker Panel Mouldings (8.304)


1970-1972 All models as required. Available with red stripes. Sold in pairs. Hardware included.

RM-702R.....Red Stripes.....	\$199.75 pr.
------------------------------	--------------

## Rocker Panel Moulding Clips (8.304)

Round discs for retaining mouldings.

Use for any hanging moulding.



MC-99.....	\$1.50 ea.
MC-99S.....(set of 25).....	\$35.00 ea.

## Front Fender Nameplates

### 1965 Skylark Fender Emblems



FE-65B.....	\$57.50 set.
-------------	--------------



1968-1972 "GS" Fender monogram. Please note: Mounting studs may be slightly different from some earlier models.

FM-682G.....	\$23.00 ea..
--------------	--------------

## Buick Motor Division

1970-1972 "Buick Motor Division" Plate.

FM-702BMD.....	\$38.50 ea..
----------------	--------------



1970-1972 "455" Plate.

FM-455.....	\$19.25 ea..
-------------	--------------



1970-1972 "Stage 1" monogram. Please note: mounting studs are 5 1/4" apart exactly like originals.

FM-702.....	\$49.50 ea..
-------------	--------------

FM-704.....(replacement pins are 2" apart).....	\$32.50 ea..
---	--------------



1970-1972 "Stage 2" monogram.

FM-705.....	\$49.50 ea..
-------------	--------------

## 1963 Gas Door Guard (8.210)

Genuine Buick Accessory to protect paint and dress-up rear 1/4 panel.

DG-63.....	\$24.50 ea.
------------	-------------