

Grille Emblems • Mouldings (Group 1)



1937
Grille Emblem
GO37....\$68.00 ea.

1939
Vertical Grille Moulding. All Models.
GM39.....\$149.50 ea.



1940
GE40.....\$115.00 ea..



1941
Grille Emblem
GE41...\$149.75 ea.

1956
Grille Emblem
GE56...

Cooling • Oiling (Group 1)

Water Pumps (New!) Sold Outright



Years	Part No.	Price
1936-1940 Series 60-70-80-90; 1941-1949 All.....	WP369.....	\$149.00 ea.
1950-1952 All; 1953 Specials.....	WP503.....	\$145.00 ea.
1953-1955 All V-8 engines - New Water Pump Sold Outright.	WP535.....	\$145.00 ea
1956 All.....	WP56.....	\$145.00 ea.
1957 All.....	WP578.....	\$148.50 ea.
1958 All w/o AC	WP578.....	\$148.50 ea.
1958 All with AC Except 5 Bladed Fan.....	WP578.....	\$148.50 ea.
1959-1960 All.....	WP591.....	\$148.50 ea.

Water Pump Exchange or Rebuilding Services (1.069)

Water pumps are freshly re-built to assure long lasting performance. If in stock, they are sold on an exchange basis with a core charge, or send in your pump for fresh rebuild. Core charge will be refunded after your OEM rebuildable pump is returned. **1934-1949** ball bearing type pumps can also be rebuilt on a case by case basis. Allow about 2-4 weeks.



Years	Part No.	Core Charge	Price
1934-1939 Series 40; 1940 Series 40-50.....	WP340EI.....	\$100.00.....	\$118.50 ea.

Water Pump Covers (1.113)

"Backing Plates" includes gasket and bolts.

1934 thru **1940** all straight 8.

WPC340.....\$19.50 ea.

1941 thru **1953** all straight 8.

WPC413.....\$19.50 ea.

Water Pump Nipple

1934-1960

WPN341.....\$6.95 ea.



Water Pump Hardware Kits

You never have to worry about breaking another bolt. High strength stainless steel bolts will never rust.



1934-1939 Special; **1940** Special and Super.

WPH340.....\$4.25 kit

1950-1953 All Straight-8 engines.











WPH503.....\$4.25 kit

1953-1958 all V-8.

WPH538.....\$11.75 kit

Radiator Hoses

Our radiator hoses are pre-formed as the originals, (no flex type), to fit and look authentic. Some may come longer and need minor trimming.

	Year	(1.159)	Upper Hose Part No.	Lower Hose Part No.		
	1934-1938 Specials		UH360	LH360	\$11.50	\$18.50
UH 360	1936-1938 Series 60-70-90		UH360	LH360	\$11.50	\$18.50
	1936-1953 By-pass hose		BP363			\$ 4.00
LH 360	1939-1940 Specials and Supers..		UH393	LH393	\$12.75	\$18.50
	1939-1940 Series 60-70		UH393	LH393	\$12.75	\$18.50
	1939-1940 Series 80-90		UH360	LH360	\$11.50	\$18.50
	1941 Specials and Supers		UH413	LH41	\$13.50	\$18.50
LH 41	1941 All 320 engines		UH413	LH393	\$13.50	\$18.50
	1942-1947 Series 40-50 to frame #14717304		LH429	LH429	\$18.50	\$18.50
	1942-1947 Series 60-70-90		UH478	LH393	\$18.50	\$18.50
LH 429	1947 Series 40-50 after frame #14717304		UH478	LH429	\$18.50	\$18.50
	1948-1949 Special and Super.		UH478	LH429	\$18.50	\$18.50
UH 478	1948 Roadmaster before frame #14710654.....		UH478	LH393	\$18.50	\$18.50
	1948 Ser. 70 after #14710654.....		UH478	LH393	\$18.50	\$18.50
	1949-1952 Roadmaster.		UH428	LH393	\$18.50	\$18.50
UH 428	1950-1952 Series 40-50; 1953 Series 40.....		UH413	LH393	\$13.50	\$18.50
	1953 Super, Roadmaster and Skylark		UH428	LH536	\$18.50	\$18.50
UH 54	1954-1956 All.....		UH54	LH536	\$18.50	\$18.50
	1957 All.....		UH57	LH570	\$16.50	\$18.50
UH 57	1958 All.....		UH58	LH570	\$18.75	\$18.50
	1959 All.....		UH590	LH570	\$17.75	\$18.50
UH 58	1960 All.....		UH590		\$17.75	
						
UH 590						

Radiator Hose Clamps


These are the correct "Wittek Tower Top" hose clamps. They are correct for all 1941-1960 models.

2 1/16" Diameter fits most upper hose. This is a stock size.

HC216.....\$2.75 ea.

2" Diameter fits most upper hose. Smaller than stock.

HC200.....\$2.75 ea.



1956-1959 Bumper, radiator fan shroud as required.

HB429.....\$2.25 ea.

Cooling System Seal Tabs

Developed by GM for sealing and stabilization of your cooling system. Highly recommended by Buick engineers for all older cars. Pack of 6 non-toxic tabs.

CT300.....\$6.00 pack



Wire Hose Clamps



For 9/16" diameter hose.

HC916W.....\$ 1.00 ea.

HC916WP.....(5 Pack).....\$ 3.25 ea.

For 3/4" diameter hose.

HC340W.....\$ 0.75 ea.

HC340WP.....(5 Pack).....\$ 3.25 ea.

For 13/16" diameter hose.

HC1316W.....\$ 1.00 ea.

HC1316WP.....(5 Pack).....\$ 4.25 ea.

For 15/16" diameter hose.

HC1516W.....\$ 0.75 ea.

HC1516WP.....(5 Pack).....\$ 4.25 ea.

For 1" diameter hose.

HC100W.....\$ 1.00 ea.

HC100WP.....(5 Pack).....\$ 4.25 ea.

For 1-1/4" diameter hose.

HC114W.....\$ 1.00 ea.

HC114WP.....(5 Pack).....\$ 5.00 ea.

For 2" diameter hose.

HC200W.....\$ 2.75 ea.

HC200WP.....(5 Pack).....\$12.25 ea.

Buick Fan Belts, Power Steering,

AC Belts (1.416)



Please note that 1953-1960 belts are also offered as 100% authentically correct. They feature a flat un-cogged surface for a smooth and quiet ride, comes with the original GM numbers, stamped right into the belt.

		Cars	Part #	
1934-1939	*Specials.....		FB340.....	\$21.50 ea.
1936-1939	Series 60-80-90.....		FB369.....	\$32.00 ea.
1940	All Special & Super.....		FB40S.....	\$26.50 ea.
1940	Series 60-70-80-90.....		FB40B.....	\$28.50 ea.
1941-1949	Special & Super.....		FB419S.....	\$18.50 ea.
1941-1949	*Series 60-70-90.....		FB419B.....	\$36.50 ea.
1950	All Special & Super.....		FB340.....	\$21.50 ea.
1950	Roadmasters.....		FB50B.....	\$24.50 ea.
1951-1952	Roadmaster.....		FB512.....	\$13.50 ea.
1951-1952	Special & Super;			
	1953 Specials.....		FB513.....	\$15.00 ea.
1953	All V-8 Fan/Gen Belt		FB530.....	\$18.75 ea.
	Exact Reproduction.....		FB1343438.....	\$34.50 ea.
1953	All V-8 Power Steering Belt		FB530.....	\$18.75 ea.
	Exact Reproduction.....		FB1343438.....	\$34.50 ea.
1953	All V-8			
	Matched Pair Belt Set		FB53S.....	\$35.00 pr.
	Exact Reproduction.....		FB1343438S.....	\$65.00 pr.
1954-1957	All Fan/Gen Belt w/o AC ;			
1957	Fan/Gen Belt w/ AC Early ..		FB548.....	\$19.75 ea.
1954	Power Steering Belt		FB548.....	\$19.75 ea.
	Exact Reproduction.....		FB1163447.....	\$34.50 ea.
1954 & 1956	All Fan/Gen Belts .			
	Matched Pair.....		FB548S.....	\$37.50 pr.
	Exact Reproduction.....		FB1163447S.....	\$65.00 pr.
1955-1956	Power Steering Belt		FB556.....	\$21.50 ea.
1957	All Late Fan/Gen Belt w/ AC		FB578A	\$21.50 ea.
1957	All w/o AC and 1" type w/ AC			
	Power Steering Belt		FB578.....	\$21.50 ea.
	Exact Reproduction.....		FB1163447.....	\$34.50 ea.
1957	All Early. AC Belt		FB57E.....	\$21.50 ea.
1957	All Late. AC Belt		FB57E.....	\$21.50 ea.
1958	All Fan/Gen Belt w/ AC		FB578A	\$21.50 ea.
1958	All Fan/Gen Belt w/o AC		FB548.....	\$19.75 ea.
	Exact Reproduction.....		FB1180978.....	\$34.50 ea.
1958	All w/o AC or Air Ride			
	Power Steering Belt		FB578.....	\$21.50 ea.
1958	All AC Belts (uses 2 belts)		FB58S.....	\$43.50 pr.
1959-1960	All Fan/Gen Belt w/o AC		FB530.....	\$18.75 ea.
	Exact Reproduction.....		FB1188358.....	\$34.50 ea.
1959-1960	All Fan/Gen/AC Belts			
	364 eng. Uses 2 belts.....		FB590S.....	\$43.50 pr.
	Exact Reproduction.....		FB1180978S.....	\$65.00 pr.
1959-1960	All Fan/Gen/AC Belts			
	401 eng. Uses 2 belts.....		FB590S.....	\$43.50 pr.
1959-1960	All Power Steering Belt		FB591.....	\$21.50 ea.

* Not as wide as original

Water Outlets (1.153)



1954-1957 Thermo. Housing water outlet and gasket.
WO547.....\$24.50 ea.

1958-1960 Thermo. Housing water outlet and gasket.
WO581.....\$25.00 ea.

Temperature Sending Unit



1960 All.
TSU608.....\$13.25 ea.

Thermostats (1.246)

All thermostats include gaskets



1933-1953 All except 1953 V-8.
T330180°.....\$9.75 ea.
T330L160°.....\$9.75 ea.
T330H195°.....\$9.75 ea.
WOG330.....Gasket for Above.....\$2.25 ea.

1953-1960 All V-8 Engines.
T536180°.....\$9.75 ea.
T536L160°.....\$9.75 ea.
T536H195°.....\$9.75 ea.
WOG536.....Gasket for Above.....\$2.25 ea.



RC2

Radiator Caps



RC10

Take a good look at these caps. They are identical to the originals. Correct in every detail, they feature the cap number, instructions and of course genuine "AC" identification stamped right into the cadmium plated surface. Show quality, approved and licensed by Buick.

- 1934-1936 All**
- RC2\$39.50 ea.
- 1937-1939 All. Non-pressure. No detail.**
- RC10\$36.50 ea.
- 1940-1946 All;**
- 1947 up to frame 14717305 on Special and Super; up to frame 14710656 on Roadmaster. 7 lb.**
- RC13\$33.50 ea.
- 1947 after frame 14717305 on Special and Super; after frame 14710656 on Roadmaster; 4lb.**
- 1948 All**
- RC509\$33.50 ea.
- 1949 Roadmaster Early. 13lb. cap.**
- RC559\$33.50 ea.
- 1949 all Special and Super. Roadmaster Late;**
- 1950 thru 1956 All. 7 lb.**
- RC549\$33.50 ea.
- 1957-1960 All. 15 lb.**
- RC15D\$33.50 ea.

Replacement Radiator Caps



- 1937-1939 All. Non-pressure.**
- RC379\$10.50 ea.



- 1940-1947 All. 7 lb.**
- RC407\$10.50 ea.



- 1948-1949 All. 4 lb.**
- RC489\$10.50 ea.



- 1950-1956 All. 7 lb.**
- RC506\$10.50 ea.



- 1957-1960 All. 15 lb.**
- RC579\$16.50 ea.

Heater Hose



- HH58.....5/8"\$1.00 per foot
- HH5850.....5/8"\$39.00 per 50 feet
- HH34.....3/4"\$1.00 per foot
- HH3450.....3/4"\$39.00 per 50 feet

Heater Hose Clamps (1.066)



Buick used "Tower Top" Heater hose clamps on all cars from **1942-1960**. We supply a reproduction identical to the clamp made by the Wittek Company. They are authentic and correct. Measure your OD.

- 1942-1960 "Tower Top" Heater hose clamps. All GM.**
- HC340.....(for 3/4" hose with 1 1/4" OD).....\$2.75 ea.
- HC340S.....(for 3/4" hose with 1 3/16" OD)\$2.75 ea.
- HC580.....(for 5/8" hose with 1 1/16" OD).....\$2.75 ea.
- HC580S.....(for 5/8" hose with 1" OD)\$2.75 ea.



www.oldbuickparts.com
908-369-3666

Oil Pump Rebuilding Service

1936-1937 Specials.
OP367RS\$129.50 ea.

1938-1952
1938-1940: Series 60, 70, 80, 90;
1946-1952: Roadmaster.
OP382RS\$129.50 ea.

1938-1953
1938-1939: Special;
1940-1952: Special and Super;
1953: Special.
OP383RS\$129.50 ea.

1953 V-8 Oil pump.
OP53RS\$129.50 ea.

1954-1956 Oil pump.
OP546RS\$129.50 ea.

1957-1958 Oil pump rebuilt.
OP578RS.....Oil pump only.....\$299.00 ea.

1959-1960 With engine 401 engine oil pump.
OP591RS.....\$107.00 ea.

Oil Pump Kits (1.652)



1934-1939 Special and Super.
OPK349\$93.50 ea.

1936-1952 Century, Roadmaster w/ 320 eng, oil pump kit.
OPK362\$93.50 ea.

1940-1952 Special and Super; **1953** Special. Oil pump kit.
OPK403\$93.50 ea.

1953-1956 All V-8 engines. Oil pump kit.
OPK536\$71.50 ea.

1957-1958 Oil pump kit.
OPK578\$74.50 ea.

1959-1960 All. Oil pump kit.
OPK591\$69.50 ea.



GM Engine Lubricant (E.O.S.)

Genuine GM EOS provides excellent lubrication. Highly recommended. 16 oz.
EOS300.....\$20.00 ea.

Oil Filter Elements (1.836)

1939-1947 All. (Replaces AC-P112)
OF397\$17.50 ea.

1948 All except Roadmaster with hydraulic lifters. (Replaces AC-P115)
OF48\$15.50 ea.

1948-1953 (Replaces AC-P127)
1948: Roadmaster with hydraulic lifters;
1949-1952: All;
1953: Specials.
OF493.....\$15.00 ea.

1953-1958 All V-8. (Replaces AC-P122)
OF538.....\$11.50 ea.

1959-1960 All. (Replaces AC-PF24)
OF596.....\$9.75 ea.

Oil Pan Drain Plug and Gasket (1.453)

1929-1937 All. Self threading 11/16" oversize.
OP297\$4.00 set

1938-1958 All. Self threading 5/8" oversize.
OP388\$5.75 set

1934-1958 All engines. Oil pan drain plug gasket.
ODG348.....\$2.75 ea.

1959-1960 1/2", x 20 thread.
OP595.....\$5.50 set

Oil Pressure Switch

1960 All.
OPS606.....\$11.75 ea.

Oil Filter/Breather Caps (1.758)

1936-1960 All. Twist on type. Genuine "AC" reproduction with embossed letters. Show quality.
OC397.....Black.....\$26.50 ea.
OC647.....Chrome.....\$36.00 ea.

1939-1960 All. Twist on type. Aftermarket replacement.
OC397A\$9.75 ea.

1953-1955 V-8 All. Push in type. Aftermarket replacement.
OC535.....\$7.50 ea.

Thermostat Related Gaskets



1933-1953 All straight 8 engines. Water outlet.
WOG330\$2.25 ea.



1934-1940 All Special & Super. Thermostat housing.
BG2172\$2.75 ea.



1936-1940 All 60, 70, 80, 90 320 engines;
1941-1949 All engines. Thermostat housing.
BG2173\$3.00 ea.



1950-1953 All straight 8 engine. Thermostat housing/head.
BG3386\$2.75 ea.



1934-1953 All straight 8 engines. Therm. Hsg. bolt seals.
BG134.....(2 needed per car)\$1.00 ea.



1953-1960 All V-8 engines. Water outlet.
WOG536\$2.25 ea.

Water Pump & Manifold Gaskets



1934-1940 All Special and Super. Water pump backing plate.
WPG340\$4.95 ea.



1936-1940 Series 60, 70, 80, 90 engines w/ water pump backing plate;



1941-1953 All straight-8 eng. Water pump backing plate.
WPG413\$4.95 ea.



1934-1940 All Special and Super. Water pump to block.
BG2204\$2.75 ea.



1936-1940 All 60, 70, 80, 90 320 engines w/ pump to block;



1941-1949 All engines water pump to block;



1950-1953 All straight-8 engines. Water pump to elbow.
BG2140\$3.00 ea.



1950-1953 All straight-8 eng. Water pump elbow to block.
BG3015\$3.00 ea.



1953-1955 All V-8 engines. Water pump mounting gasket.
WPG535\$4.75 ea.



1953-1960 All V-8 engines. Water manifold seal kit. Contains two end gaskets and center "o" ring.
WMK536\$9.00 ea.



1956-1960 All V-8 engines. Water pump mounting gasket.
WPG561\$4.75 ea.



Oil Pan Gaskets

1934-1952 All Special and Super; **1953** Special.
OPG343\$16.00 ea.

1936-1952 All series 60, 70, 80, 90. 320 engines.
OPG362\$16.00 ea.

1953-1956 All V-8 engines.
OPG536\$14.50 ea.

1957-1960 All V-8 engines.
OPG576\$14.50 ea.

Misc. Oil Gaskets



1934-1958 All engines. Oil pan drain plug gasket.
ODG348.....\$2.75 ea.



1934-1952 Special and Super; **1953** Special. Oil pump cover.
BG3381.....\$4.50 ea.



1934-1952 Special and Super; **1953** Special. Oil pump/block.
BG3292.....\$4.50 ea.



1936-1952 Ser. 60, 70, 80, 90. 320 engines. Oil pump mtg.
BG3871.....\$4.50 ea.



1953-1956 All V-8 engines. Oil pump inlet triangular.
BG3484.....\$4.50 ea.



1953-1960 All V-8 engines. Oil pump body.
BG2380.....\$4.50 ea.



1953-1960 All V-8 engines. Oil filter housing to block.
BG3486.....(except 1957-1958)\$4.50 ea.
BG3595.....(1957-1958 only)\$4.50 ea.



1953-1960 All except 1959. Oil pump inlet.
BG2324.....(All except 1959).....\$4.50 ea.
BG1479.....(1959 only).....\$4.50 ea.



1957-1958 All engines. Oil pump body.
BG2469.....\$4.50 ea.