

# Grille Emblems • Mouldings (Group 1)



**1937**  
Grille Emblem  
GO37....\$68.00 ea.

**1939**  
Vertical Grille Moulding. All Models.  
GM39.....\$149.50 ea.



**1940**  
GE40.....\$115.00 ea..



**1941**  
Grille Emblem  
GE41...\$149.75 ea.

**1956**  
Grille Emblem  
GE56...

# Cooling • Oiling (Group 1)

## Water Pumps (New!) Sold Outright



Years	Part No.	Price
<b>1936-1940</b> Series 60-70-80-90; <b>1941-1949</b> All.....	WP369.....	\$149.00 ea.
<b>1950-1952</b> All; <b>1953</b> Specials.....	WP503.....	\$145.00 ea.
<b>1953-1955</b> All V-8 engines - New Water Pump Sold Outright.	WP535.....	\$145.00 ea
<b>1956</b> All.....	WP56.....	\$145.00 ea.
<b>1957</b> All.....	WP578.....	\$148.50 ea.
<b>1958</b> All w/o AC .....	WP578.....	\$148.50 ea.
<b>1958</b> All with AC Except 5 Bladed Fan.....	WP578.....	\$148.50 ea.
<b>1959-1960</b> All.....	WP591.....	\$148.50 ea.

## Water Pump Exchange or Rebuilding Services (1.069)

Water pumps are freshly re-built to assure long lasting performance. If in stock, they are sold on an exchange basis with a core charge, or send in your pump for fresh rebuild. Core charge will be refunded after your OEM rebuildable pump is returned. **1934-1949** ball bearing type pumps can also be rebuilt on a case by case basis. Allow about 2-4 weeks.



Years	Part No.	Core Charge	Price
<b>1934-1939</b> Series 40; <b>1940</b> Series 40-50.....	WP340EI.....	\$100.00.....	\$118.50 ea.

## Water Pump Covers (1.113)

"Backing Plates" includes gasket and bolts.

**1934** thru **1940** all straight 8.

WPC340.....\$19.50 ea.

**1941** thru **1953** all straight 8.

WPC413.....\$19.50 ea.

## Water Pump Nipple

**1934-1960**

WPN341.....\$6.95 ea.



## Water Pump Hardware Kits







You never have to worry about breaking another bolt. High strength stainless steel bolts will never rust.

<b>1934-1939</b> Special; <b>1940</b> Special and Super.	
WPH340.....	\$4.25 kit
<b>1950-1953</b> All Straight-8 engines.	
WPH503.....	\$4.25 kit
<b>1953-1958</b> all V-8.	
WPH538.....	\$11.75 kit



## Radiator Hoses

Our radiator hoses are pre-formed as the originals, (no flex type), to fit and look authentic. Some may come longer and need minor trimming.

	Year	(1.159)	Upper Hose Part No.	Lower Hose Part No.		
	1934-1938 Specials .....		UH360	LH360	\$11.50	\$18.50
UH 360	1936-1938 Series 60-70-90 .....		UH360	LH360	\$11.50	\$18.50
	1936-1953 By-pass hose .....		BP363			\$ 4.00
LH 360	1939-1940 Specials and Supers..		UH393	LH393	\$12.75	\$18.50
	1939-1940 Series 60-70 .....		UH393	LH393	\$12.75	\$18.50
	1939-1940 Series 80-90 .....		UH360	LH360	\$11.50	\$18.50
	1941 Specials and Supers .....		UH413	LH41	\$13.50	\$18.50
LH 41	1941 All 320 engines .....		UH413	LH393	\$13.50	\$18.50
	1942-1947 Series 40-50 to frame #14717304 .....		LH429	LH429	\$18.50	\$18.50
	1942-1947 Series 60-70-90 .....		UH478	LH393	\$18.50	\$18.50
LH 429	1947 Series 40-50 after frame #14717304 .....		UH478	LH429	\$18.50	\$18.50
	1948-1949 Special and Super. ....		UH478	LH429	\$18.50	\$18.50
UH 478	1948 Roadmaster before frame #14710654.....		UH478	LH393	\$18.50	\$18.50
	1948 Ser. 70 after #14710654.....		UH478	LH393	\$18.50	\$18.50
	1949-1952 Roadmaster. ....		UH428	LH393	\$18.50	\$18.50
UH 428	1950-1952 Series 40-50; 1953 Series 40.....		UH413	LH393	\$13.50	\$18.50
	1953 Super, Roadmaster and Skylark .....		UH428	LH536	\$18.50	\$18.50
UH 54	1954-1956 All.....		UH54	LH536	\$18.50	\$18.50
	1957 All.....		UH57	LH570	\$16.50	\$18.50
UH 57	1958 All.....		UH58	LH570	\$18.75	\$18.50
	1959 All.....		UH590	LH570	\$17.75	\$18.50
UH 58	1960 All.....		UH590		\$17.75	
						
UH 590						

## Radiator Hose Clamps


These are the correct "Wittek Tower Top" hose clamps. They are correct for all 1941-1960 models.

2 1/16" Diameter fits most upper hose. This is a stock size.

HC216.....\$2.75 ea.

2" Diameter fits most upper hose. Smaller than stock.

HC200.....\$2.75 ea.



1956-1959 Bumper, radiator fan shroud as required.

HB429.....\$2.25 ea.

## Cooling System Seal Tabs

Developed by GM for sealing and stabilization of your cooling system. Highly recommended by Buick engineers for all older cars. Pack of 6 non-toxic tabs.

CT300.....\$6.00 pack



## Wire Hose Clamps



**For 9/16" diameter hose.**

HC916W.....\$ 1.00 ea.

HC916WP.....(5 Pack).....\$ 3.25 ea.

**For 3/4" diameter hose.**

HC340W.....\$ 0.75 ea.

HC340WP.....(5 Pack).....\$ 3.25 ea.

**For 13/16" diameter hose.**

HC1316W.....\$ 1.00 ea.

HC1316WP.....(5 Pack).....\$ 4.25 ea.

**For 15/16" diameter hose.**

HC1516W.....\$ 0.75 ea.

HC1516WP.....(5 Pack).....\$ 4.25 ea.

**For 1" diameter hose.**

HC100W.....\$ 1.00 ea.

HC100WP.....(5 Pack).....\$ 4.25 ea.

**For 1-1/4" diameter hose.**

HC114W.....\$ 1.00 ea.

HC114WP.....(5 Pack).....\$ 5.00 ea.

**For 2" diameter hose.**

HC200W.....\$ 2.75 ea.

HC200WP.....(5 Pack).....\$12.25 ea.

## Buick Fan Belts, Power Steering,

### AC Belts (1.416)



Please note that 1953-1960 belts are also offered as 100% authentically correct. They feature a flat un-cogged surface for a smooth and quiet ride, comes with the original GM numbers, stamped right into the belt.

		Cars	Part #	
1934-1939	*Specials.....		FB340.....	\$21.50 ea.
1936-1939	Series 60-80-90.....		FB369.....	\$32.00 ea.
1940	All Special & Super.....		FB40S.....	\$26.50 ea.
1940	Series 60-70-80-90.....		FB40B.....	\$28.50 ea.
1941-1949	Special & Super.....		FB419S.....	\$18.50 ea.
1941-1949	*Series 60-70-90.....		FB419B.....	\$36.50 ea.
1950	All Special & Super.....		FB340.....	\$21.50 ea.
1950	Roadmasters.....		FB50B.....	\$24.50 ea.
1951-1952	Roadmaster.....		FB512.....	\$13.50 ea.
1951-1952	Special & Super;			
	1953 Specials.....		FB513.....	\$15.00 ea.
1953	All V-8 <b>Fan/Gen Belt</b> .....		FB530.....	\$18.75 ea.
	Exact Reproduction.....		FB1343438.....	\$34.50 ea.
1953	All V-8 <b>Power Steering Belt</b> .....		FB530.....	\$18.75 ea.
	Exact Reproduction.....		FB1343438.....	\$34.50 ea.
1953	All V-8			
	<b>Matched Pair Belt Set</b> .....		FB53S.....	\$35.00 pr.
	Exact Reproduction.....		FB1343438S.....	\$65.00 pr.
1954-1957	All <b>Fan/Gen Belt w/o AC</b> ;			
1957	<b>Fan/Gen Belt w/ AC Early</b> ..		FB548.....	\$19.75 ea.
1954	<b>Power Steering Belt</b> .....		FB548.....	\$19.75 ea.
	Exact Reproduction.....		FB1163447.....	\$34.50 ea.
1954 & 1956	All <b>Fan/Gen Belts</b> .			
	Matched Pair.....		FB548S.....	\$37.50 pr.
	Exact Reproduction.....		FB1163447S.....	\$65.00 pr.
1955-1956	<b>Power Steering Belt</b> .....		FB556.....	\$21.50 ea.
1957	All Late <b>Fan/Gen Belt w/ AC</b> .....		FB578A .....	\$21.50 ea.
1957	All w/o AC and 1" type w/ AC			
	<b>Power Steering Belt</b> .....		FB578.....	\$21.50 ea.
	Exact Reproduction.....		FB1163447.....	\$34.50 ea.
1957	All Early. <b>AC Belt</b> .....		FB57E.....	\$21.50 ea.
1957	All Late. <b>AC Belt</b> .....		FB57E.....	\$21.50 ea.
1958	All <b>Fan/Gen Belt w/ AC</b> ....		FB578A .....	\$21.50 ea.
1958	All <b>Fan/Gen Belt w/o AC</b> ..		FB548.....	\$19.75 ea.
	Exact Reproduction.....		FB1180978.....	\$34.50 ea.
1958	All w/o AC or Air Ride			
	<b>Power Steering Belt</b> .....		FB578.....	\$21.50 ea.
1958	All <b>AC Belts (uses 2 belts)</b> .....		FB58S.....	\$43.50 pr.
1959-1960	All <b>Fan/Gen Belt w/o AC</b> ... ..		FB530.....	\$18.75 ea.
	Exact Reproduction.....		FB1188358.....	\$34.50 ea.
1959-1960	All <b>Fan/Gen/AC Belts</b>			
	364 eng. Uses 2 belts.....		FB590S.....	\$43.50 pr.
	Exact Reproduction.....		FB1180978S.....	\$65.00 pr.
1959-1960	All <b>Fan/Gen/AC Belts</b>			
	401 eng. Uses 2 belts.....		FB590S.....	\$43.50 pr.
1959-1960	All <b>Power Steering Belt</b> ....		FB591.....	\$21.50 ea.

\* Not as wide as original

## Water Outlets (1.153)



1954-1957 Thermo. Housing water outlet and gasket.

WO547.....\$24.50 ea.

1958-1960 Thermo. Housing water outlet and gasket.

WO581.....\$25.00 ea.

## Temperature Sending Unit



1960 All.

TSU608.....\$13.25 ea.

## Thermostats (1.246)

All thermostats include gaskets



1933-1953 All except 1953 V-8.

T330 .....180°.....\$9.75 ea.

T330L .....160°.....\$9.75 ea.

T330H .....195°.....\$9.75 ea.

WOG330.....Gasket for Above.....\$2.25 ea.

1953-1960 All V-8 Engines.

T536 .....180°.....\$9.75 ea.

T536L .....160°.....\$9.75 ea.

T536H .....195°.....\$9.75 ea.

WOG536.....Gasket for Above.....\$2.25 ea.



RC2

### Radiator Caps



RC10

Take a good look at these caps. They are identical to the originals. Correct in every detail, they feature the cap number, instructions and of course genuine "AC" identification stamped right into the cadmium plated surface. Show quality, approved and licensed by Buick.

- 1934-1936 All**
- RC2 .....\$39.50 ea.
- 1937-1939 All. Non-pressure. No detail.**
- RC10 .....\$36.50 ea.
- 1940-1946 All;**
- 1947 up to frame 14717305 on Special and Super; up to frame 14710656 on Roadmaster. 7 lb.**
- RC13 .....\$33.50 ea.
- 1947 after frame 14717305 on Special and Super; after frame 14710656 on Roadmaster; 4lb.**
- 1948 All**
- RC509 .....\$33.50 ea.
- 1949 Roadmaster Early. 13lb. cap.**
- RC559 .....\$33.50 ea.
- 1949 all Special and Super. Roadmaster Late;**
- 1950 thru 1956 All. 7 lb.**
- RC549 .....\$33.50 ea.
- 1957-1960 All. 15 lb.**
- RC15D .....\$33.50 ea.

### Replacement Radiator Caps



- 1937-1939 All. Non-pressure.**
- RC379 .....\$10.50 ea.



- 1940-1947 All. 7 lb.**
- RC407 .....\$10.50 ea.



- 1948-1949 All. 4 lb.**
- RC489 .....\$10.50 ea.



- 1950-1956 All. 7 lb.**
- RC506 .....\$10.50 ea.



- 1957-1960 All. 15 lb.**
- RC579 .....\$16.50 ea.

### Heater Hose



- HH58.....5/8" .....\$1.00 per foot
- HH5850.....5/8" .....\$39.00 per 50 feet
- HH34.....3/4" .....\$1.00 per foot
- HH3450.....3/4" .....\$39.00 per 50 feet

### Heater Hose Clamps (1.066)



Buick used "Tower Top" Heater hose clamps on all cars from **1942-1960**. We supply a reproduction identical to the clamp made by the Wittek Company. They are authentic and correct. Measure your OD.

- 1942-1960 "Tower Top" Heater hose clamps. All GM.**
- HC340.....(for 3/4" hose with 1 1/4" OD).....\$2.75 ea.
- HC340S.....(for 3/4" hose with 1 3/16" OD) .....\$2.75 ea.
- HC580.....(for 5/8" hose with 1 1/16" OD).....\$2.75 ea.
- HC580S.....(for 5/8" hose with 1" OD) .....\$2.75 ea.



[www.oldbuickparts.com](http://www.oldbuickparts.com)  
**908-369-3666**

## Oil Pump Rebuilding Service

**1936-1937** Specials.  
OP367RS .....\$129.50 ea.

**1938-1952**  
1938-1940: Series 60, 70, 80, 90;  
1946-1952: Roadmaster.  
OP382RS .....\$129.50 ea.

**1938-1953**  
1938-1939: Special;  
1940-1952: Special and Super;  
1953: Special.  
OP383RS .....\$129.50 ea.

**1953** V-8 Oil pump.  
OP53RS .....\$129.50 ea.

**1954-1956** Oil pump.  
OP546RS .....\$129.50 ea.

**1957-1958** Oil pump rebuilt.  
OP578RS.....Oil pump only.....\$299.00 ea.

**1959-1960** With engine 401 engine oil pump.  
OP591RS.....\$107.00 ea.

## Oil Pump Kits (1.652)



**1934-1939** Special and Super.  
OPK349 .....\$93.50 ea.

**1936-1952** Century, Roadmaster w/ 320 eng, oil pump kit.  
OPK362 .....\$93.50 ea.

**1940-1952** Special and Super; **1953** Special. Oil pump kit.  
OPK403 .....\$93.50 ea.

**1953-1956** All V-8 engines. Oil pump kit.  
OPK536 .....\$71.50 ea.

**1957-1958** Oil pump kit.  
OPK578 .....\$74.50 ea.

**1959-1960** All. Oil pump kit.  
OPK591 .....\$69.50 ea.



## GM Engine Lubricant (E.O.S.)

Genuine GM EOS provides excellent lubrication. Highly recommended. 16 oz.  
EOS300.....\$20.00 ea.

## Oil Filter Elements (1.836)

**1939-1947** All. (Replaces AC-P112)  
OF397 .....\$17.50 ea.

**1948** All except Roadmaster with hydraulic lifters. (Replaces AC-P115)  
OF48 .....\$15.50 ea.

**1948-1953** (Replaces AC-P127)  
1948: Roadmaster with hydraulic lifters;  
1949-1952: All;  
1953: Specials.  
OF493.....\$14.75 ea.

**1953-1958** All V-8. (Replaces AC-P122)  
OF538.....\$11.50 ea.

**1959-1960** All. (Replaces AC-PF24)  
OF596.....\$9.75 ea.

## Oil Pan Drain Plug and Gasket (1.453)

**1929-1937** All. Self treading 11/16" oversize.  
OP297 .....\$4.00 set

**1938-1958** All. Self threading 5/8" oversize.  
OP388 .....\$5.75 set

**1934-1958** All engines. Oil pan drain plug gasket.  
ODG348.....\$2.75 ea.

**1959-1960** 1/2", x 20 thread.  
OP595.....\$5.50 set

## Oil Pressure Switch

**1960** All.  
OPS606.....\$11.75 ea.

## Oil Filter/Breather Caps (1.758)

**1936-1960** All. Twist on type. Genuine "AC" reproduction with embossed letters. Show quality.  
OC397.....Black.....\$26.50 ea.  
OC647.....Chrome.....\$36.00 ea.

**1939-1960** All. Twist on type. Aftermarket replacement.  
OC397A .....\$9.75 ea.

**1953-1955** V-8 All. Push in type. Aftermarket replacement.  
OC535.....\$7.50 ea.

### Thermostat Related Gaskets



**1933-1953** All straight 8 engines. Water outlet.  
WOG330 .....\$2.25 ea.



**1934-1940** All Special & Super. Thermostat housing.  
BG2172 .....\$2.75 ea.



**1936-1940** All 60, 70, 80, 90 320 engines;  
**1941-1949** All engines. Thermostat housing.  
BG2173 .....\$3.00 ea.



**1950-1953** All straight 8 engine. Thermostat housing/head.  
BG3386 .....\$2.75 ea.



**1934-1953** All straight 8 engines. Therm. Hsg. bolt seals.  
BG134.....(2 needed per car) .....\$1.00 ea.



**1953-1960** All V-8 engines. Water outlet.  
WOG536 .....\$2.25 ea.

### Water Pump & Manifold Gaskets



**1934-1940** All Special and Super. Water pump backing plate.  
WPG340 .....\$4.95 ea.



**1936-1940** Series 60, 70, 80, 90 engines w/ water pump backing plate;



**1941-1953** All straight-8 eng. Water pump backing plate.  
WPG413 .....\$4.95 ea.



**1934-1940** All Special and Super. Water pump to block.  
BG2204 .....\$2.75 ea.



**1936-1940** All 60, 70, 80, 90 320 engines w/ pump to block;



**1941-1949** All engines water pump to block;



**1950-1953** All straight-8 engines. Water pump to elbow.  
BG2140 .....\$3.00 ea.



**1950-1953** All straight-8 eng. Water pump elbow to block.  
BG3015 .....\$3.00 ea.



**1953-1955** All V-8 engines. Water pump mounting gasket.  
WPG535 .....\$4.75 ea.



**1953-1960** All V-8 engines. Water manifold seal kit. Contains two end gaskets and center "o" ring.  
WMK536 .....\$9.00 ea.



**1956-1960** All V-8 engines. Water pump mounting gasket.  
WPG561 .....\$4.75 ea.



### Oil Pan Gaskets

**1934-1952** All Special and Super; **1953** Special.  
OPG343 .....\$16.00 ea.

**1936-1952** All series 60, 70, 80, 90. 320 engines.  
OPG362 .....\$16.00 ea.

**1953-1956** All V-8 engines.  
OPG536 .....\$14.50 ea.

**1957-1960** All V-8 engines.  
OPG576 .....\$14.50 ea.

### Misc. Oil Gaskets



**1934-1958** All engines. Oil pan drain plug gasket.  
ODG348.....\$2.75 ea.



**1934-1952** Special and Super; **1953** Special. Oil pump cover.  
BG3381.....\$4.50 ea.



**1934-1952** Special and Super; **1953** Special. Oil pump/block.  
BG3292.....\$4.50 ea.



**1936-1952** Ser. 60, 70, 80, 90. 320 engines. Oil pump mtg.  
BG3871.....\$4.50 ea.



**1953-1956** All V-8 engines. Oil pump inlet triangular.  
BG3484.....\$4.50 ea.



**1953-1960** All V-8 engines. Oil pump body.  
BG2380.....\$4.50 ea.



**1953-1960** All V-8 engines. Oil filter housing to block.  
BG3486.....(except 1957-1958) .....\$4.50 ea.  
BG3595.....(1957-1958 only) .....\$4.50 ea.



**1953-1960** All except 1959. Oil pump inlet.  
BG2324.....(All except 1959).....\$4.50 ea.  
BG1479.....(1959 only).....\$4.50 ea.



**1957-1958** All engines. Oil pump body.  
BG2469.....\$4.50 ea.