


1933-1936 Transmission support pad. Lower.
1933-1935 All;
1936 Series 40. Sold outright!
 TM336\$12.75 ea.



1934-1936 Series 40. Transmission support pa. Upper. Sold outright!
 TM346\$15.75 ea.



1936-1937 Pad set, transmission support. Use your original channel, plate and cap. One set (2 pad per set) per car. Series 60, 80 and 90. Sold outright!
 TM367\$108.75 set



1937 Series 40. Pad, transmission support. Two per car. Sold outright!
 TM37\$29.75 pr.

1938-1939 Insulator blocks, transmission support, upper and lower. These blocks are not vulcanized to steel, but are installed in shells at time of assembly like the original.



1938: Series 60, 80, and 90;
1939: Series 80 and 90. Sold outright!
 TI389.....\$71.75 pr.

1940-1947 Transmission Mount.
 TM407.....\$74.00 ea.



1948-1958 All Dynaflow except 1953 Super, Roadmaster, Skylark. Sold outright!
 TM488.....\$32.00 ea.



1948-1956 All Standard; 1953 Super, Roadmaster and Skylark. Sold outright!
 TM486S.....\$55.00 ea.



1948-1956 All. (Thrust Pad). outright!
 Includes Nuts & Washers
 TP486.....\$48.50 ea.





1957-1959 All. Ex. flight pitch. (Thrust pad).
 TP579.....\$59.00 ea. outright



Transmission Mount Rebuilding

We now offer you complete revulcanization of your transmission mounts. Fresh, new rubber will insure safe and smooth running. If we have your needed mount ready to ship we will charge you an additional core deposit of \$50.00 per item. This charge is fully refundable upon receiving your rebuildable cores. We prefer you send your mounts for rebuilding. Please allow at least 2-3 weeks for this process. See NOS section, group 4.085 for outright sales.


1958-1959 All flight pitch transmissions.
 TM589FRS.....\$211.25 pr.



1959-1960 All with automatic transmission.
 TM590RS.....\$135.25 ea.



Shift Rod Insulators

1938 Special, with standard transmission.
 Pad, transmission mounting upper and lower.
 TM38RS.....\$127.50 set



1941-1954 (4.019)

1941-1948 All;
1949-1953 Series 40-50;
1954 Series 40-50-60. All standard trans. (3 per car) Shift Lever Insulator.
 SLI400.....\$4.25 ea.



1938-1940 Special with semi-auto trans.
 TM380RS.....\$165.75 set

Shift Boots



1934-1938 Shift Boot

1934-1935 Series 40-60;
1936-1938 Series 40.
 SB348.....(Black).....\$17.00 ea.
 SB348N.....(Brown).....\$38.75 ea.

Transmission (Group 4)

Automatic Transmission Kits (4.005)

Model	Year	Master Overhaul Kit	Banner Kit	Paper, Rubber, Rings & Seals	External Seal-up Kit	Torque Ball Seal Kit
Buick Dynaflow	1948-1952	TOK484 \$259.00 ea	TKB484 \$223.00 ea	TRK484 \$199.50 ea	TSK484 \$95.00 ea	TBK482 \$89.50 ea
Buick Dynaflow	1953-1956	TOK484 \$259.00 ea	TKB484 \$223.00 ea	TRK484 \$199.50 ea	TSK484 \$95.00 ea	TBK535 \$89.50 ea
Buick Dynaflow	1955	TOK550 \$279.50 ea	TKB550 \$242.50 ea	TRK550 \$219.00 ea	TSK550 \$79.50 ea	TBK535 \$89.50 ea
Buick Dynaflow	1956	TOK550 \$279.50 ea	TKB550 \$242.50 ea	TRK550 \$219.00 ea	TSK550 \$79.50 ea	TBK56 \$89.50 ea
Buick Dynaflow	1957-1958	TOK550 \$279.50 ea	TKB550 \$242.50 ea	TRK550 \$219.00 ea	TSK550 \$79.50 ea	TBK578 \$89.50 ea
Buick Dynaflow	1959-1960	TOK550 \$279.50 ea	TKB550 \$242.50 ea	TRK550 \$219.00 ea	TSK550 \$79.50 ea	TBK590 \$89.50 ea
Buick Flightpitch	1958-1959	N/A N/A	N/A N/A	TRK589 \$445.00 ea	TSK589 \$134.50 ea	TBK538 \$89.50 ea

Master Overhaul Kit: Gaskets, Friction (lined) Clutches, Lip Seals, Steel Clutches, "O" Rings, Front Pump Seal, Metal Sealing Rings and Torque Ball Seals.


Paper, Rubber, Rings & Seals: All gaskets, Lipseals, O-Rings, Sealing Rings, Front Pump Seal and Ext. Hsg. Seal.

Banner Kit: Same as Master Kit, but w/o Steel Clutches.

External Seal-up Kit: Stops any external Leaks. Contains Front Pump Seal, Extension Housing Seal, Selector Lever Seal and External Gaskets (including Pan Gasket and Converter Gasket or O-Ring).

Torque Ball Kit: Torque Ball Retainer with seal, rear transmission seal, gasket and seal.

Clutch Pressure Plate Assembly 1939-55 Buick



1939-1955 Buick Series 40 (Special)


1939-1953 Buick Series 50 (Super)


New Clutch, Pressure Plate, Throwout Bearing, Pilot Bearing And Alignment Tool


No Core Charge Required


CPA395.....\$285.00 ea.

Standard Transmission Gasket Kits


 **1934-1938 Special.**
TGK348.....\$15.00 ea.

1936-1939 Century, Roadmaster, Limited.
TGK379.....\$22.25 ea. 

 **1939-1948** Series 60, 70, 80, 90.
1953-1960 All.
Includes: Extension Housing Gasket, Case To
Clutch Housing Gasket, Case Cover Gasket.
TGK390.....\$16.00 ea.

1939-1955 Special and Super.
TGK395.....\$15.00 ea. 


Dynaflow Transmission Pan Gaskets


 **1948-1960 All.**
TPG483\$10.00 ea.


1958-1960 All. Flight pitch.
TPG589.....\$19.00 ea. 

Transmission Seals


 **1939-1954 All standard trans.** Front main drive
seal. (4.354)
TS394\$11.75 ea.

1939-1960 All selector seal on side of case.
SS390.....\$21.75 ea. 

 **1940-1952:**
1940-1942 Series 60 and 70;
1946-1952 All. Rear. (serves as propeller shaft
seal also).
TS482.....\$15.25 ea.

1951-1960 All. converter pump seal. "O' Ring".
PS513.....\$10.75 ea. 

 **1948-1960 Dynaflow front pump seal.** Exc. 3T.
TS483F.....\$14.00 ea.

1953-1958 All. Rear.
(serves as propeller shaft seal also).
TS538.....\$11.50 ea. 


1959-1960 All. Rear.
(serves as propeller shaft seal also).
TS590.....\$11.50 ea.


Transmission Bands


1948-1960 All. Rebuilding service only.
TB483.....\$75.75 ea.


Speedometer Cables & Casings


Our speedometer cable assemblies are made exactly as original. They feature rust proof and leak proof galvanized armor casings so they function and look authentic. Lengths are matched for your car-not just an oversized "fits all" cable.

1937-1940 Series 40, 60;
1938 Series 80, 90;
1940 Series 50, 70;
1941 Series 40, 50;
1942-1949 All ;
1950 Series 40, 50;
1951-1952 Series 50;
1951-1963 Series 40;
1954-1955 Series 40, 60, 100;
1954-1958 All Standard Trans.
SC378\$29.50 ea. 

1937 Series 80, 90 ;
1938 Series 40 w/ auto trans.
1939-1940 Series 80, 90;
1941 Series 60, 70, 90;
1951-1953 Series 50, 70;
1959-1960 All.
SC370\$32.50 ea. 

 **1954-1955** Series 50, 70, AT;
1956 All AT;
1957-1958 All AT.
SC378B.....\$30.50 ea.

1936-1960 All. Speedometer cable repair kit.
SRK360.....\$16.00 ea. 

 **All Years.**
Speedometer cable lubricant.
SCL300\$5.00 ea.

See Group 5 for Torque Ball Sealing Kits.

Brakes (Group 4)

We prefer you send **your** master cylinder for resleeving. This process takes about two weeks. Units are cleaned, honed or sleeved as necessary. They are returned with a fresh repair kit ready for assembly. Please note, we can re-sleeve any master cylinder, but, we can only supply kits as listed in the "Repair Kit" section. Please keep your filler cap, end caps, internal parts and push rod. We can also send you a master cylinder on an exchange basis. If we have your needed part ready to ship we will charge you an additional core deposit of \$100.00 refundable upon receiving your original equipment and rebuildable core. Previously sleeved units are \$25 additional.

Master Cylinder Resleeving Regular Brakes (4.650)

1936 Special.	
MC36RS.....	\$132.50 ea.
1936 Century, Roadmaster, Limited.	
MC36BRS	\$137.50 ea.
1937-1938 Special.	
MC378SRS	\$137.50 ea.
1937-1938 Century.	
MC378CRS.....	\$137.50 ea.
1937 thru 1940 Roadmaster and Limited.	
MC370RS.....	\$137.50 ea.
1939-1949	
1939-1940: Except Limited;	
1941-1949 All.	
MC399RS.....	\$137.50 ea.
**Also see MC399 and MC503 below, a brand new unit	
1950-1953	
1950-1952 All;	
1953 Special.	
MC503RS.....	\$137.50 ea.
1953 Super, Roadmaster with dynaflo.	
MC53RS.....	\$137.50 ea.
1954-55 All.	
MC545RS.....	\$147.50 ea.
1956 All regular brakes.	
MC56RS.....	\$194.50 ea.
1957 Regular brakes.	
MC57RS.....	\$137.50 ea.
1958 Regular brakes.	
MC58RS.....	\$137.50 ea.
1959 Regular brakes.	
MC59RS.....	\$137.50 ea.
1960 Regular brakes.	
MC60RS.....	\$137.50 ea.

1939-1953 New Master Cylinders

Fully assembled, ready to install

1939-1940: Except Limited;	
1941-1949 all.	
MC399.....	\$148.50 ea.
1950-1952 All;	
1953 Special	
MC503.....	\$164.00 ea.



Master Cylinder Cap for Above	
MCC393.....	\$12.00 ea.

Master Cylinders Repair Kits (4.649)



1936 Special, Series 40. 1"	
MK36S.....	\$29.50 ea.
1936 Series 60, 80, 90. 1 1/8"	
MK36	\$32.50 ea.
1937-1940 Series 80, 90. 1 1/8" diameter	
MK370	\$32.50 ea.
1937-1955	
1937-1940: All except 80 and 90;	
1941-1955: All regular brakes.	
MK375.....(1" Diameter).....	\$23.50 ea.
1956 All with standard brakes	
MK56	\$59.50 ea.
1957 All with standard brakes	
MK57	\$23.50 ea.
1958-1960 All with regular brakes.	
MK596	\$26.25 ea.
1960 All with power brakes.	
MK602	\$22.25 ea.

Power Brake Master Cylinder Rebuilding Kits and Parts (4.649)



1955-1959 Moraine power brake overhaul kit.	
PBK559.....	\$98.50 ea.

1953-1960 Moraine power brake leather piston seal.	
BL530.....	33.50 ea.



Master Cylinders Power Brakes Power Brake Unit Rebuilding Service

1954-1960 All Delco Moraine and Bendix Treadlevac.	
MC530.....	\$325.00 ea.
1953-1954 All Kelsey Hayes. Note. It is our understanding that the 1953 kelsey hayes units were recalled by Buick and replaced with 1954 units. They can be identified by a 6 1/2" piston chamber as opposed to 4" on 1954 units. We cannot rebuild the early 1953 models (cast #37002).	
MC534K	\$548.50 ea.

Moraine Brake Shafts (Pistons)



1955 All.	
BS55.....	\$97.50 ea.
1956 All.	
BS56.....	\$97.50 ea.
1957-1959 All.	
BS579.....	\$97.50 ea.

Wheel Cylinders (4.665)**FRONT:****1937-1942:**

1937-1939 Special and Century;

1940-1941 All except 80 and 90;

1942 All except series 90.

FWC372R.....R.H. Side\$39.00 ea.

FWC372L.....L.H. Side\$39.00 ea.

1942-1957 All.

FWC427R.....R.H. Side\$39.00 ea.

FWC427L.....L.H. Side\$39.00 ea.

1958-1960 All

FWC580R.....R.H. Side\$48.50 ea.

FWC580L.....L.H. Side\$48.50 ea.

REAR:**1938-1942:**

1938-1939 Special and Century;

1940 Special, Super, Century, Roadmaster;

1941 All;

1942 Series 90.

RWC380.....Fits Either Side\$39.50 ea.

1942-1949 All.

RWC429R.....R.H. Side\$35.00 ea.

RWC429L.....L.H. Side\$35.00 ea.

1950-1960 All.

RWC500R.....R.H. Side\$35.00 ea.

RWC500L.....L.H. Side\$35.00 ea.

**Wheel Cylinder Repair Kits** (4.667)**Front**

1936 Series 40, front. 1 1/16"

FK36\$8.50 ea.

1936-1940

1936: Series 60, 80, and 90;

1937-1940: Series 80 and 90. Front. 1 1/4"

FK360.....\$11.00 ea.

1937-1941 All, except 80-90, front. 1 3/32"

FK371.....\$10.50 ea.

1942-1960 All. Front. 1 1/8"

FK426.....\$10.25 ea.

Rear

1936 Series 60-80-90;

1937-1940 Series 80 and 90, rear. 1 3/16"

RK360\$11.25 ea.

1936-1960 All Except above listed.

RK370\$9.50 ea.

**Wheel Cylinder
Re-Sleeving Service**

1936-1941 We re-sleeve your cylinders with brass.

WCS361\$89.50 ea.

Brake Overhaul Kits

Our complete kits include the following:

- 4 Wheel cylinder kits
- * • 1 Master cylinder kit. Standard brakes only
- 4 Brake shoe sets
- 3 Hydraulic brake hoses
- 2 Brake spring hardware kits

* Not available for 1956

1936 Special.

BOK36S\$189.50 ea.

1937-38 Special with 1-3/4" shoes.

BOK378.....\$189.50 ea.

1937-38 Century and Roadmaster with 2" shoes.

BOK378B\$189.50 ea.

1939 All except 80 - 90 and Convertibles;

1940 Series 50, 70;

1941 All except convertibles.

BOK391.....\$189.50 ea.

1940 Special.

BOK40S\$189.50 ea.

1941-1949 Roadmaster.

BOK419.....\$189.50 ea.

1942-1949 Special and Super.

BOK429.....\$209.50 ea.

1950-51 Special and Super.

BOK501.....\$189.50 ea.

1950-51 Century and Roadmaster. All w/o power brakes.

BOK501B\$189.50 ea.

1952 Super.

BOK52.....\$189.50 ea.

1952-55 Special.

BOK525.....\$189.50 ea.

1952 Roadmaster Early;

1953-1956 all Roadmaster.

BOK526R.....\$189.50 ea.

1953-55 Super, Century;

1954 Skylark.

BOK535.....\$189.50 ea.

1956 Special, Super, Century.

BOK56.....\$239.50 ea.

1957 Special, Super, Century.

BOK57.....\$189.50 ea.

1958 All.

BOK58.....\$189.50 ea.

1959 All.

BOK59.....\$189.50 ea.

1960 All.

BOK60.....\$189.50 ea.

**Silicone Brake Fluid**

One Gallon Size

SF360.....\$63.00 gal.

Brakes (Group 4)

Brake Shoes (5.017)

Years	Part No.	Width	Price
FRONT (set is enough for 2 wheels)			
1936-1951	1936-1951 Special and Super.....	BS29.....1 3/4"	\$69.50 set
1937-1938	1937-1938 Century, Roadmaster w/ 2" shoes.....	BS340.....2"	\$59.50 set
1940-1957	1940-51 Ser. 60-70; 1952-57 Sr 40,50,60,100.....	BS197....2 1/4"	\$49.50 set
1952-1957	52 sr. 70 late; 53-57 all Roadmaster.	BS64.....2 1/2"	\$64.50 set (rebuilding service)
1958-1960	1952 Roadmaster early; 1958-1960 all.....	BS65.....2 1/2"	\$58.00 set
REAR (set is enough for 2 wheels)			
1936-1955	1936-1955 Series 40; 1940-1952 Series 50.....	BS29.....1 3/4"	\$69.50 set
1940-1960	1940-1952 Series 60-70; 1953-1955 Series- 50-60-70-100; 1956-1960 All.....	BS197....2 1/4"	\$49.50 set



Brake Hoses (4.680)

Years	Part No.	Price
FRONT		
1936-1940	1936 All; 1937-1940 Series 80-90 Front.....	FH360.....\$18.00 ea.
1937-1938	1937-1938 Series 40-60 Front.....	FH378.....\$19.00 ea.
1939-1949	1939 Series 40-60; 1940 Series All exc. 80, 90. 1941-1949 All. Front.....	FH399.....\$17.00 ea.
	New Modern Stainless Steel Braided	FH399SS...\$29.50 ea.
1950-1956	1950-1956 All. Front.....	FH506.....\$18.00 ea.
1957-1960	1957-1960 All. Front.....	FH575.....\$18.50 ea.



Brake Drums (5.809)

Brand New! Cast Iron replacements.
(When replacing aluminum front
drums - purchase in pairs.)

REAR		
1936-1941	1936 46C, 66C, 80C; 1937 80C; 1938-1939 All convertibles; 1941-1949 All convertibles.....	RH369C...\$26.50 ea.
	1936 Exc. convert.; 1937 All exc. 80C; 1938-1939 All exc.convert; 1941 All. Except convertibles. Rear.....	RH361.....\$18.00 ea.
	New Modern Stainless Steel Braided	RH361SS..\$34.00 ea.
	1936 Models 46C, 66C, 80C; 1937 80C; 1938-1939 All convertibles; 1941-1949 Models 51C, 56C, 71C, 76C.....	RH369C....\$26.50 ea.
1940-1949	1940 Series 80-90; 1940 Series 40-60 except convertibles; 1941-1949 All.Except convertibles.Rear.....	RH409.....\$18.50 ea.
1950-1955	All. Rear.....	RH505.....\$17.50 ea.
1956-1958	All. Rear.....	RH568.....\$24.50 ea.
1959-1960	All. Rear.....	RH590.....\$24.50 ea.

Front 1 3/4"
1936-1951 Super;
1936-1951 Special.
BD365..... \$114.50 ea.

Rear 1 3/4"
1936-1952 Super exc. wagons;
1936-1955 Special
BD365..... \$114.50 ea.

Front 2 1/4"
1942-1951 Roadmaster;
1942-1957 Century;
1952-1957 Super exc. wagons;
1952-1957 Special;
BD420.....\$114.50 ea.

Rear 2 1/4"
1942-1957 Century and Roadmaster;
1953-1957 Super;
1956-1957 Special;
1958-1960 All.
BD420.....\$114.50 ea.

Years	Part No.	Price
Brake Spring Kits (5.023) Kits are per one axle		
1936-1955	1936-1951 All Front or Rear, exc. 89,90; 1952-1955 Special, Rear.....	BSK365.....\$22.50 ea.
1952-1960	1952-1957 All Roadmaster, Front; 1956-1960 All Front.....	BSK520F.....\$22.50 ea.
1952-1960	1952-1957 All exc. Roadmaster, Front; 1952-1955 Roadmaster, Rear; 1952-1955 Super, Century, Skylark, Rear; 1956-1960 All Rear.....	BSK520.....\$22.50 ea.
1936-1960	All. Brake Adjusting Screw. Fits front & rear.....	BAS362.....\$10.75 ea.



BAS362

Brake Hose Clip



1936-1960 All.
BC360\$1.25 ea.

Brake Pedal Pads (4.630)




1932-1940 Pad, brake and clutch pedals full slip-over type as original.

1936: Series 60, 80 and 90;

1937-1940: Series 80 and 90.

PC320.....(Black).....\$58.00 pr.

PC320N.....(Brown).....\$59.00 pr.



1936-1955

1936: Series 40;

1937-1939: Series 40-60;

1940-1947: All except 80-90;

1948-1952: All Park brake pedal;

1953: Early models, park brake pedal;

1948-1955: Standard transmission. Three per car.


PC345.....(Black).....\$8.50 ea.

PC345N.....(Brown).....\$8.50 ea.



1948-1952 All Brake pedal pads with dynaflow transmission. (Black).

PC482\$15.00 ea.



1953-1954 Park brake pedal pad.

1953: All. Late models;

1954: All.

PC534\$26.00 ea.



1953-1955 Brake pedal pad. All with dynaflow and regular brakes.

PC535R\$23.25 ea.



Stop on a Dime!
With Brake Parts From Cars, Inc.

Brake Pedal Pads



1953-1955 All with power brakes.

PC535P.....("Power Brake").....\$18.50 ea.

PC535.....(no letters on pad).....\$22.25 ea.



1955-1958 Park Brake pedal pad.

PC558.....(Black).....\$10.50 ea.

PC558U.....(Blue).....\$13.50 ea.

PC558G.....(Green).....\$13.50 ea.



1956 All with power brakes.

PC56.....\$19.50 ea.



1956 All with regular brakes.

PC56R\$24.50 ea.



1956-1958 All with manual trans. Clutch and brake pedal.

PC568S.....(Black).....\$37.75 pr.



1957-1958 Power brake pedal cover.


PC578B.....(Black).....\$23.25 ea.

PC578PY.....(Gray).....\$28.25 ea.



1957-1958 All with regular brakes and auto trans.

PC578S.....(Black).....\$27.50 ea.



1953-1954 Vacuum pump mount.

PM534\$4.75 ea.

Stop Light Switches (2.447)



1936-1940 All.

SLS360\$17.50 ea.



1941-1955 All.

SLS415\$9.75 ea.



1956-1960 All.

SLS563\$9.75 ea.



1936-1980 Brake adjuster hole plug.

(4 per car).


BC340\$1.00 ea.



1936-1958 All, brake and clutch pedal return grommets.(9.775) (2 per car)

PG365.....\$7.75 ea.

Brake Cables (Group 4)




1934-1960

We can now reproduce any cable listed from **1934 thru 1960**. Cables are made using correct conduit, cable and hardware. Please note, some cables (*) require that we have your old unit for parts as some hardware items are not available. Some are available with a core charge. (4.779)


Year & Model	Front	Cost	Rear	Cost
1934-1935 (40)	R1266724 (2)	\$93.50 ea.	R1267082 (2)	\$86.50 ea.
1934-1935 (50)	R1282837 (2)	\$93.50 ea.	R1284204 (2)	\$86.50 ea.
1934-1935 (60)	R1282594 (2)	\$93.50 ea.	R1284205 (2)	\$86.50 ea.
1934-1935 (90)	R1282538 (2)	\$93.50 ea.	R1284205 (2)	\$86.50 ea.
1936 (40)	R1293175 (1)	\$93.50 ea.	R1289833 (2)	\$86.50 ea.
1936 (60)	R1294332 (1)	\$93.50 ea.	R1294331 (2)	\$86.50 ea.
1936 (80)	R1293288 (1)	\$93.50 ea.	R1290372 (2)	\$86.50 ea.
1936 (90)	R1293288 (1)	\$93.50 ea.	R1290319 (2)	\$86.50 ea.
1937 (40, 60)	R1298782 (1)	\$93.50 ea.	R1299321 (2)	\$86.50 ea.
1937 (80)	R1298783 (1)	\$93.50 ea.	R1299322 (2)	\$86.50 ea.
1937 (90)	R1298783 (1)	\$93.50 ea.	R1299323 (2)	\$86.50 ea.
1938 (40, 60)	R1304324 (1)	\$93.50 ea.	R1304326 (1)	\$87.50 ea.
1938 (80)	R1305200 (1)	\$93.50 ea.	R1305229 (1)	\$86.50 ea.
1938 (90)	R1305201 (1)	\$93.50 ea.	R1305229 (1)	\$86.50 ea.
1939 (40, 60)	R1308610 (1)	\$93.50 ea.	R1308315 (1)	\$86.50 ea.
1939 (80)	R1309111 (1)	\$93.50 ea.	R1309114 (1)	\$86.50 ea.
1939 (90)	R1309112 (1)	\$93.50 ea.	R1310348 (1)	\$86.50 ea.
1940 (40, 50, 60, 70)	R1315857 (1)	\$93.50 ea.	R1315855 (1)	\$86.50 ea.
1940 (80)	R1314860 (1)	\$93.50 ea.	R1310348 (1)	\$86.50 ea.
1940 (90)	R1314861 (1)	\$93.50 ea.	R1310348 (1)	\$86.50 ea.
1941 (44,44C,46S,47)	R1321478 (1)	\$93.50 ea.	R1316875 (1)	\$86.50 ea.
1941 (41, 41SE, 46, 46S, 46SSE, 49, 50, 60, 70)	R1315857 (1)	\$93.50 ea.	R1316815 (1)	\$86.50 ea.
1941 (90)	R1319737 (1)	\$93.50 ea.	R1310348 (1)	\$86.50 ea.
1942 (44, 44C, 47, 48, 48S)	R1325350 (1)	\$93.50 ea.	R1316875 (1)	\$86.50 ea.

Year & Model	Front	Cost	Rear	Cost
1942 (41, 41SE, 46, 46s, 46SSE, 49);				
1942 all Century;				
1946-1949 (Specials)	R1339588 (1)	\$92.50 ea.	R1316875 (1)	\$86.50 ea.
1942-1948 (50, 70)	R1323639 (1)	\$92.50 ea.	R1322613 (1)	\$86.50 ea.
1949 (50, 70)	R1339589 (1)	\$92.50 ea.	R1316875 (1)	\$86.50 ea.
1950 all except models 52 and 72;				
1951-1953 all Super, Roadmaster and Skylark, except models				
(52,72,72R)	R1338927 (1)	\$97.50 ea.	R1316875 (1)	\$86.50 ea.
1951-1953 (Specials)	R1338927 (1)	\$97.50 ea.	R1342444 (1)	\$86.50 ea.
1950-1953 (52, 72, 72R)	R1339434 (1)	\$95.50 ea.	R1316875 (1)	\$86.50 ea.
1954-1956 Special, Century,				
Skylark	R1166151 (1)	\$92.50 ea.	R1163029 (1)	\$86.50 ea.
1954-1956 Super and Rdmst. ..	R1173411 (1)	\$92.50 ea.	R1162575 (1)	\$86.50 ea.
1957-1958 Special -				
standard trans.	R1178540 (1)	\$92.50 ea.	R1174857 (1)	\$86.50 ea.
1957-1958 Special and				
Century A.T.	R1175039 (1)	\$95.50 ea.	R1174857 (1)	\$86.50 ea.
1957-1958 Super, Limited,				
Roadmaster	R1175040 (1)	\$92.50ea.	R1174857 (1)	\$86.50 ea.
1959 LeSabre, Invicta	R1187115 (1)	\$92.50 ea.	R1187358 (1)	\$86.50 ea.
1959 Electra	R1187116 (1)	\$92.50 ea.	R1187358 (1)	\$86.50 ea.
1960 LeSabre and Invicta	R1193879 (1)	\$92.50 ea.	R1193782 (1)	\$86.50 ea.
1960 Electra	R1193880 (1)	\$92.50 ea.	R1193782 (1)	\$86.50 ea.

* Old cable needed or \$25 core charge



1934-1935 Boot or collar for hand brake lever.
HB345.....\$58.50 ea.



1934-1948 Brake cable anti-rub cover.
CB348.....\$4.75 ea.



1938-1958 All. Parking brake cable rubber buffer.
CB388.....\$7.75 ea.



1959-1960 All. Parking brake cable rubber buffer.
CB590.....\$6.75 ea.

1940-1959 Parking Brake Return Spring.
BRS409.....\$15.00 ea.



www.oldbuickparts.com

908-369-3666