


Fan Shrouds (1.277)

1962-1964 All 401 and 425 engines.
FS635.....\$149.50 ea.

1967-1968 All 430 engines with a.c.
FS670.....\$169.50 ea.



Radiator Caps

Take a good look at these Caps.They are identical to the originals. Correct in every detail, they feature the cap number, instructions and of course genuine "AC" identification stamped right into the cadmium plated surface. Show quality, approved and licensed by Buick.




1961-1964 All. 15 lb.
RC15D.....\$32.50 ea.
1965-1968 All. 15 lb.
RC15F.....\$32.50 ea.
1969-1970 All w/o coolant recovery system. 15 lb.
RC15H.....\$32.50 ea.

Replacement Radiator Caps


1961-1969 All. 15 lb.
RC579.....\$16.50 ea.
1970-1976 All.
RC706.....\$9.75 ea.

Radiator Insulators


1961-1964 Radiator mounting rubber insulator. All as required.
RI614.....\$8.75 ea.



1965-1966 All. Radiator support bracket insulator. Fully Molded.
RI656.....\$32.00 pr.



1970 Some with 3 core radiator. 2 pair used per car. Compare with RI682S.
RI690.....\$35.50 pr.



Fan Belts

Cars Part#

1961-1962 All
Exact Reproduction* FB1163447 \$34.50
1963 Wildcat with 425 engine w/o AC
Exact Reproduction* FB1188358 \$34.50
1961-1975 All other non-listed belts. (state all information).
FB400.....\$17.50 ea.
**Exact reproduction belts are 100 % authentically correct and include original part number.*

Radiator Hoses

1961 Lower radiator hose. Formed.
LH61L.....\$18.50 ea.
1962-1966 401 and 425 engines. Lower radiator hose. Formed.
LH429.....\$18.50 ea.
1962-1965 All with out air conditioning formed upper radiator hose.
UH625.....\$21.75 ea.
1967-1970 Upper
1967: 430 engine;
1968-1970: All.
RH980.....\$22.25 ea.



Radiator Hose Clamps

These are the correct "Tower Top" hose clamps made by the Wittek Company for GM. They are correct for all 1961-1975 models.



RC134....1 3/4"\$ 2.75 ea.
RC200....2"\$ 2.75 ea.
RC216....2 1/16" Diameter fits most upper hoses\$ 2.75 ea.
RC214....2 1/4" Diameter fits most lower hoses.....\$ 2.75 ea.
RC250....2 1/2"\$ 2.75 ea.
RC2516..2 5/16"\$ 2.75 ea.
RC400....4"\$ 4.00 ea.

Fan Clutches

1962-1976 401-425-430-455 engines, thermal fan clutch.
FC626.....\$65.50 ea.
1964-1972 300, 340 and 350 engines.
FC642.....\$54.50 ea.



Cooling • Oiling (Group 1)

Water Outlets (1.153)



1961 All. Includes gasket.
WO581\$25.00 ea.



1962-1966 401 and 425 engines.
Engine block water outlet. Includes gasket.
WO626\$22.25 ea.



1964-1974
1964-1966: 300 and 340 engines;
1967-1974: All V-8 water outlet. Includes gasket.
WO615\$24.50 ea.

Water Outlet Gasket



1961-1975 All (except 364, 400, 401, 425).
WOG615.....\$2.25 ea.



1961-1966 All 364, 400, 401, 425.
WOG536.....\$2.25 ea.

By-Pass Hoses



1964-1975 300,340 and 350 engines.
Thermo by-pass hose.
BP625.....\$9.75 ea.




1967-1975 400-430-455 engines.
Thermostat by-pass hose.
BP676.....\$9.75 ea.

Breather Tubes (1.762)

(Air Cleaner to Rocker Cover)

Breather Tube



1968-1969 All 350, 400, 430 engine except 1968 2bbl.
VT689\$19.50 ea.



1970-1971 all V-8; **1972** all 455 engines.
VT704\$16.50 ea.



Crankcase Vent Hose (To Carb) (1.726)



1971-1975 All 350 and 455 engines with 4BBL carb. (Formed Hose).
VH725\$20.25 ea.

Thermostats (1.246)



1961-1966 364, 400, 401, 425 engines.
Thermostat with gasket.
T536.....(180 degree).....\$9.75 ea.
T536L.....(160 degree).....\$9.75 ea.
T536H.....(195 degree).....\$9.75 ea.
1967-1980 Thermostat with gasket.
T330\$9.75 ea.

Temperature Sending Units



1961-1968 400, 401, 425, and 430 engines. (two terminals).
TSU608.....(Dash Light Type).....\$19.75 ea.
1966-1972
1966-1970: 340-350;
1969-1972: All V-8 (1 terminal in intake manifold).
TSU662.....(Dash Light Type)\$12.50 ea.
1969-1974 430 and 455 engines. (In cylinder head).
TSU694.....(Dash Light Type)\$16.50 ea.

Wire Hose Clamps



For 9/16" diameter hose.
HC916W\$ 1.00 ea.
HC916WP.....(5 Pack)\$ 3.25 ea.
For 5/8" diameter hose.
HC580W\$ 0.75 ea.
For 3/4" diameter hose.
HC340W\$ 0.75 ea.
HC340WP.....(5 Pack)\$ 3.25 ea.
For 13/16" diameter hose.
HC1316W\$ 1.00 ea.
HC1316WP.....(5 Pack)\$ 4.25 ea.
For 15/16" diameter hose.
HC1516W\$ 0.75 ea.
HC1516WP.....(5 Pack)\$ 4.25 ea.
For 1" diameter hose.
HC100W\$ 1.05 ea.
HC100WP.....(5 Pack)\$ 4.25 ea.
For 1-1/4" diameter hose.
HC114W\$ 1.00 ea.
HC114WP.....(5 Pack)\$ 5.00 ea.
For 2" diameter hose.
HC200W\$ 2.75 ea.
HC200WP.....(5 Pack)\$12.25 ea.



Water Pumps

- 1961** All with air conditioning.
WP61RS.....(Rebuilding Service).....\$99.50 ea.
- 1961** All without air conditioning.
WP591.....\$179.50 ea.
- 1962-1966** 401-425 engines with air conditioning. This pump will also fit non - AC cars.
WP626A.....\$79.50 ea.
- 1965-1970** All 300, 340, 350 engines.
WP640.....\$54.50 ea.
- 1967-1970** 400, 430 and 455 engines with air conditioning.
WP670.....\$80.25 ea.
- 1967-1976** 400, 430 and 455 engines without air conditioning.
WP672.....\$57.25 ea.
- 1971-1972** LeSabre with 350 engine.
WP712S\$47.50 ea.
- 1971-1976**
 - 1971-1972:** All 455 engines with air conditioning;
 - 1973-1976:** All 455 engines.
- WP716.....\$56.75 ea.
- 1973-1981** All with 350 engine.
WP731.....\$58.25 ea.

Water Pump Mounting Gaskets



- 1961** All.
WPG561\$4.75 ea.
- 1961-1981** All
225,231,300,340,350,350B,350X engines.
WPG615.....\$3.50 ea.
- 1962-1966** All 400, 401 and 425 engines.
WPG626.....\$3.75 ea.
- 1967-1975** All 400 and 455 engines.
WPG675.....\$3.25 ea.

Water Manifold Gasket Kit



- 1961-1966** All. Includes 2 gaskets and "O" ring.
WMK536\$9.00 ea.

Adjustable Oil Pressure Regulator



Regulate your oil pressure by adjusting tension on relief spring. Allows for safe and easy adjustment externally. 1964 thru 1975 all 225, 300, 340, 350, 430, 455 engines
OPR600.....\$38.00 ea.

Heater Hose



- 1961-1975** 5/8" Black heater hose.
HH58\$1.00 per foot
HH5850.....(50 foot roll).....\$39.00 roll
- 1961-1975** 3/4" Black heater hose.
HH34\$1.00 per foot
HH3450.....(50 foot roll).....\$39.00 roll

"Tower Top" Heater Hose Clamps

Buick used "Tower Top" hose clamps on all cars from 1961-1975. We supply the identical clamps made by the Wittek Company. They are authentic and correct.



- 1 1/16" for 5/8" heater hose.
HC580.....\$2.00 ea.
- 1" for use on thin walled 5/8" hose.
HC580S\$2.00 ea.
- 1 1/4" for 3/4" heater hose.
HC340.....\$2.00 ea.
- 1 3/16" for use on thin walled 3/4" hose.
HC340S\$2.00 ea.



Cars Inc., recognized leader in Buick Parts and Service since 1973

Cooling • Oiling (Group 1)

Oil Filters



1961-1966 All. (Also fits thru 1980 where there is room for taller filter). PF-7 type.
OF596.....\$9.75 ea.

1967-1980 All exc. V-6 and 260 engines. PF-24 type.
OF670.....\$9.75 ea.

PF-24 Oil Filters



A brand new quality reproduction on the original 1967-1975 red, white, and blue, "AC" TYPE PF-24 oil filter with logo and proper coloring. A must for the concours restorer.
OF590AC.....\$22.25 ea.

Oil Pans

1967-1970 All 430, 455 engines. Center sump.
OP670.....\$165.00 ea.



1969-1976 All 400, 430, 455 engines. Not for cross-over apps.
OP676.....\$165.00 ea.




Oil Pan Drain Plug Gasket



1961-1975 Oil pan drain plug and gasket. 1/2"-20 thread.
OP595.....\$5.50 ea.

Oil Pumps (1.652)



1961 All. Rebuilding Service.
OP591RS\$107.00 ea.
1962-1966 401-425 engines, oil pump.
OP626\$112.00 ea.

Oil Pump Kits



1961 All. Oil pump kit.
OPK591\$69.50 ea.
1962-1966 400, 401, 425 engines, oil pump kit.
OPK626\$47.50 ea.
1964-1987 1964-81 300,340,350; 77-81 231-a; 86-87 3.87; 84-85 231-9; 78-85 231-3; 83 231-8; 78-79 231-2; 78 231-g; 75-77 231-c Oil pump Kit .
OPK642.....\$33.75 kit
OPK642H.....(High volume kit).....\$45.50 ea.
1967-1976 400-430-455 oil pump kit.
OPK676\$32.25 ea.
OPK656H.....(High volume kit).....\$59.25 ea.

Oil Pick-up Tube and Screen



1964-1968 all 225,300,340,350 engines. Has 5/8" tube. Requires passage drilled to 5/8".
OPU647\$24.50 ea.

1965-1966 GS 400,401,425 engine. Stock size.
OPU626.....\$155.00 ea.

1967-1976 400,455 w/ rear sump. (Increased oil pick-up over stock 1/2" tube. Gives 5-10 psi oil pressure increase. 1967-1970 engines require that pick-up passage drilled to 5/8". Acts as replacement for 1970 Stage 1 and all 1971-1976 455 engines).
OPU676R.....\$69.75 ea.



1967-1976 400,430,455 w. center sump. 5/8" Tube. Requires passage drilled to 5/8"
OPU676C\$74.50 ea.



1969-1981 350 engine. Stock size.
OPU695.....\$20.00 ea.



1969-1981 all 350. Has 5/8" tube requiring windage tray to be removed or trimmed.
OPU691.....\$29.75 ea.

Oil Pump Thrust Plate Repair Kit



This kit provides a NEW WEARING surface for badly scored or worn cover housing. Kit contains all necessary screws, gaskets and instructions.

1961-1972 all 215, 225, 300, 340, 350, 455 engines.
OPK685.....\$21.00 ea.

Distributor Gear Oiler



1967-1976 all 400, 430 & 455. This modification increases the life of the distributor gear and cam gear - a must since the cam gear is not replaceable. Provides constant supply of oil spray to both gears. Modification requires small hole to be drilled and tapped on the inside of timing chain cover. Oil pressure is not affected. Requires 1/8" pipe tap and 2-1/64 drill bit no supplied in kit. Instructions included.
GO676.....\$16.50 ea.

Oil Filler Caps

1961-1967 All except chrome jobs.
Genuine "AC OIL" Embossed Repro.
OC397.....\$26.50 ea.



1964-1967

1964-1966: GS with 2-4 carbs;
1967: with engine dress up kit.
"AC OIL" Chrome twist on cap.
OC647.....\$31.00 ea.

1968-1975 All (Twist on type).
OC684.....\$4.75 ea.



PCV Valves

1963-1967 All V-6.
PCV637.....\$6.75 ea.

1963-1977 All V-8.
PCV635.....\$6.75 ea.



GM Engine Lubricant (E.O.S.)

Genuine GM EOS provides excellent lubrication.
Highly recommended. 16 oz.
EOS300.....\$20.00 ea.



Oil Pressure Switch



1961-1966 401-425 engine, oil pressure switch.
OPS606.....\$11.75 ea.
1965-1975
1965-1966: 300-340;
1967-1975: All, oil pressure switch.
OPS620.....\$13.75 ea.

Fax Us Your Order
Save Time!
When sending us a long order
it is easier to just fax it.
908-369-7595

Oil Gaskets

	1961-1966 364, 400, 401 and 425 Engines	1964-1981 300, 340 and 350 Engines	1967-1976 400, 430 and 455 Engines
Oil Pan Gasket	OPG576.....\$14.50	OPG645.....\$10.75	OPG676.....\$19.00
Oil Pan Drain Plug Gasket	ODG615.....\$2.25	ODG615.....\$2.25	ODG675.....\$2.25
Rear Main Bearing Seal Set	RMS576..Rubber Lip type.....\$19.50 RMS346.....Rope type.....\$15.50	RMS615.....\$18.75	RMS615.....\$18.75



OPG576



RMS615



ORDER BY PHONE!
908-369-6666