


Carburetor Rebuilding and Restoration Service (3.725)



Each carburetor is totally disassembled and cleaned in a hot tank solution. Then, each component is correctly plated, painted and colored to duplicate it's original factory finish. The carburetor is reassembled using all proper gaskets, pumps, needles and seats, etc. and new correct screws. Finally, all bench adjustments are made to factory specs. This includes correct shimming of the start switch. The result, the best rebuilt and restored carburetor available in the Hobby. **NOTE:** *This is not an area to skimp on your restoration. Demand the best!*

- 1961-1980** All 2bbl Carburetors w/ Bakelite switch.
CRS390.....\$329.00 ea.
- 1961-1980** 4bbl. Carburetor rebuilding service.
CRS520.....\$389.00 ea.
- 1964-1966** All Carter 2 X 4 sets..
CRS636D.....\$692.00 ea.

Carburetor Kits Carter Carburetors

- 1961-1967** 4BBL. Numbers: 3088, 89, 3297, 3578, 79,3633, 35, 65, 3826, 27, 3921, 22, 23, 4053, 54, 55, 56, 59, 60, 61, 4179, 80, 81, 4331, 32, 44, 4453. (Carter AFB 4BBL). 2 kits needed for 2 x 4 carbs.
CKC617.....\$49.50 ea.
- 1961-1967** All with Carter AFB 4bbl. Stainless steel plate between carb. and intake manifold.
BP576.....\$15.50 ea.

Rochester Carburetors

- 1961-1962** All GC 4BBL. Numbers: 7013044, 7015040, 7019040, 7020040, 7020041.
CKR592.....\$41.50 ea.
- 1961-1965** With 300 and 364 engines. 2GC 2BBL. Numbers: 7019042, 090, 093, 7020146, 147, 7023046, 047, 142, 7024046, 047, 7025046, 047.
CKR615.....\$39.50 ea.
- 1962-1963** With 401 engines. 2GC 2BBL. Numbers: 7020046, 047, 048, 049, 7023041, 042, 043, 145, 146.
CKR623.....\$39.50 ea.
- 1963-1966** With 401 engines. 4GC 4BBL. Numbers: 7023040, 7023143, 7024040, 7025040, 7025140, 7026040.
CKR636.....\$39.50 ea.

- 1964** 300 engines. 4GC 4BBL. Numbers: 7024044, 7024045.
CKR64.....\$35.00 ea.
- 1964-1965** All Rochester 1bbl.
CKR645.....\$44.75 ea.
- 1966-1967**
 - 1966:** All 400, 401, 425;
 - 1967:** Early with 400 and 430 engines. 4MV 4BBL. Numbers: 7025240, 242, 7027146, 147, 148, 149, 7027240, 241, 7036240, 242.
CKR667.....\$39.50 ea.
 - 1966-1969** With 300, 340 and 350 engines. 2GC, GV 2BBL. Numbers: 7026046, 047, 146, 147, 7027044, 045, 046, 049, 7028140, 7028141, 7029140, 141, 7036046, 048, 146, 248, 7037034, 7037044, 17054649.
CKR669.....\$33.50 ea.
 - 1967** Late; With 400, 430 and 455 engines.MVBBL. Numbers: 7027244, 246, 248, 7041304, 305, 306, 307, 308, 309.
 - 1968-1970** Numbers: 7028240, 242, 243, 246, 247, 248, 7029240, 241, 242, 243, 7029246, 7040240, 7040243.
CKR670.....\$35.00 ea.
 - 1968-1974** With 350 and 455 engines. 4MV 4BBL. Numbers: 7028244, 245, 7029244, 245, 7040244, 245, 7041245, 7041544, 7042244, 245, 944, 7043244, 245, 246, 7044244, 246, 544, 7044546, 17054900, 901, 902.
CKR684.....\$29.00 ea.
 - 1970-1973** With 455 high performance engine. 4MV 4BBL. Numbers: 7040246, 247, 7041242, 243, 540, 7042240, 242, 243, 940, 7042942, 7043240, 242, 243, 7044240, 241, 252, 540.
CKR702.....\$27.50 ea.
 - 1970-1974** 350, 455 engines with 2bbl. Numbers: 7040142, 143, 148, 444, 446, 7041142, 143, 442, 7042142, 7042143, 842, 7043142, 143, 144, 7044141, 142, 144, 442, 7044444, 17054651, 17055003, 17057350, 351.
CKR704.....\$26.50 ea.
 - 1975** With 400 engine. 4MC 4BBL. Number: 7045254.
CKR75.....\$26.50 ea.
 - 1975-1976** 455 engine. 4MC, MV 4BBL. Numbers: 7045240, 541, 548, 17056240, 540.
CKR756.....\$26.50 ea.

Stromberg Carburetors

- 1959-1961** LeSabre with Dynaflo transmission. WW type, 2BBL. Numbers: 7-112A, 7-113A and 7-114A.
CKS591.....\$59.50 ea.
- 1961** LeSabre with WW 2BBL. Number: 7-114.
CKS61.....\$49.50 ea.



Remember!

Check to see that the carburetor number matches that of the part you are ordering.

Fuel • Exhaust (Group 3)

Air Filter Elements

1961-1962 All with 4 BBL carburetor.
AF582.....\$15.50 ea.

1961-1967

1961-1962: 2 BBL;
1963-1964: All;
1965-1967: 300-340.

AF607\$15.00 ea.

1964-1966 All V-8 with 2 X 4BBL carburetors.

AF646\$28.75 ea.

1965-1967

1965-1966: 401-425 engines;
1967: 430 except dual inlet. For 4bbl carbs.

AF657\$15.25 ea.

1968-1975

1968: All 4 BBL;
1970-1975: 455 engines.

AF680\$12.25 ea.

1968 All with 350 engine 2 BBL carburetors.

AF625\$11.25 ea.

1969-1975 350, 400 and 430 engines with 4 BBL except GS.

AF698\$11.75 ea.



Air Cleaner Wing Nuts

1961-1970 Air cleaner wing nut (1/4"-20 thread).

WN530.....\$1.75 ea.

1971-1980 Air cleaner wing nut (3/8"-16 thread).

WN710.....\$.75 ea.




Exhaust Manifold Heat Pipe

(Air Cleaner to Exhaust Manifold)

1970-1974 All.

HP704.....Silver.....\$14.50 ea.

HP704B.....Black.....\$17.25 ea.



Crankcase Ventilation Filter

On Side Of Air Cleaner

1968-1972 All.

CVF682.....\$4.75 ea.



Carburetor Stud

Made of stainless steel.

1968-1975 All. 350, 400, 430, 455, 4BBL.

CS685.....\$6.00 ea.



Carburetor Bowl Floats

1960-1967 Carter AFB 4BBL. Brass.(2 needed per car)

CF577C.....\$34.50 ea.

1961-1965 Rochester 2 GC. Brass.

1961-1965 300, 364 engines;

1962-1963 401 engine.

CF615R.....\$24.50 ea.

1966-1967 Rochester 4BBL

1966 All.

1967 Early.

CF667R.....\$19.50 ea.


1967-1974 Rochester 4BBL

1967 Late.

1968-1974 All.

CF674R.....\$19.50 ea.

Air Cleaner to Rocker Cover Hoses (formed as original) (1.745)



1968-1969 All 350, 400 and 430 engines except 1968 2bbl.

VT689\$18.50 ea.

1970-1974 All.

VT704\$17.50 ea.

Intake Manifold Plugs

This plug is often rusted out and sometimes missing. Leakage around this plug causes poor carburetion.



1961-1966: All 364, 400, 401, 425 engines with 4-bbl. carburetor.

MP596.....\$12.75 ea.

Choke Stove Pipe Replacement Kit

1961-1967

All as required.

CSK530.....\$18.25 kit



Choke Stove Pipe Insulator



This modern aramid fiber sleeve greatly resembles the original. It is heat resistant up to 1100°F. White in color. Also, excellent for wrapping vapor locked fuel lines. Sold by the foot. All years.

PI300.....\$5.25 ft.

Carburetor Mounting Gaskets

1961 All Stromberg 2BBL Carbs.

CMG551\$4.75 ea.

1961-1964 All Carter and Rochester 2BBL Carbs.

CMG554\$4.50 ea.

1961-1965 All 4BBL;

1966 4BBL w/square bore;

1967 300, 340 4bbl.

CMG576.....\$4.75 ea.

1966 425 Engine;

1967 All 400, 430, 455 with Rochester.

CMG667.....\$6.50 ea.

1969-1975 All 400, 430, 455 with Rochester 4BBL.

CMG695.....\$4.75 ea.



Carburetor to Air Cleaner Gaskets

1966-1975 All 400, 430, 455 with Rochester 4BBL.

BG5152\$3.75 ea.

Choke Pull Offs




1968-1974 350, 400, 430 and 455 engines with 4BBL Rochester. Front.
CPO684.....\$16.00 ea.

1968-1971


1968-1970: 350, 400, 430 and 455 engines.
1971: 350 engines.
For Rochester 4BBL. Rear.
CPO681.....TOS
1971 455 engines. Rochester 4BBL. Rear.
CPO71\$24.75 ea.

Gas Filters

1960-1962 Gas filter element.
Cars without air conditioning.
GF572.....\$7.50 ea. 



1960-1962 Gas filter assembly.
Cars without air conditioning.
GF572A.....\$29.50 ea.


1960-1962 Gas filter element.
Cars with air conditioning.
GF602.....\$9.50 ea. 




1963-1966 Gas filter.
All cars without air conditioning.
GF636\$10.75 ea.



1963-1966 All V-8 gas filter for cars with air conditioning.
GF636A.....\$12.50 ea.

1967 All;
1968-1974 All 350 2bbl;
1975 All 350 and 400 engines.
GF675.....\$3.50 ea. 

1968-1974 All except 350 2bbl engines;
1975 All 455 engines.
GF682.....\$3.50 ea. 



All years replacement. Clear in-line gas filter.
Great for near gas tank or frame installation.
Important for insuring clean fuel to fuel pump.
GF100.....\$4.50 ea.

In Line Gas Filters



GF140.....For 1/4" ID Hose.....\$9.25 ea.


GF516.....For 5/16" IDHose.....\$9.25 ea. 



GF516C..For 5/16" ID Hose(clear).\$6.50 ea.

GF380.....For 3/8" ID Hose.....\$9.25 ea. 

PCV Valves

1963-1967 V6.
PCV637.....\$6.75 ea.
1963-1972 All. V8.
PCV635.....\$4.75 ea. 

PVC Valve Clamp


All Years For PCV hose.
HC100W.....\$1.10 ea.

PVC Valve Grommet




All Years
VG634.....\$7.75 ea.

Dash Pots

1961-1971 All. Dash pot.
DP611.....\$23.50 ea. 

Rod Clips

1961-1966 Carburetor throttle rod clip. 1/4" rod diameter.
RC460.....\$0.75 ea. 

Ported Vacuum Switches (2.410)




1968-1976 350, 400, 430 and 455 engines. (except PVS72 listed below). Located on front of intake manifold: 3 port.
PVS684.....\$49.50 ea.



Intake Manifold Gasket Sets

1960-1966 All 364, 400, 401, 425 engines.
IMG576\$11.75 ea.
1964 All 300 engines.
IMG64\$19.50 ea.
1964-1967 All 225 V-6 engines.
IMG647\$14.25 ea.
1965-1967 All 300 engines.
IMG657\$16.50 ea.
1966-1967 All 340 engines.
IMG667\$16.50 ea.
1967-1971 All 400, 430, 455 engines.
IMG671\$47.50 ea.
1968-1980 All 350 engines.
IMG685\$39.50 ea.
1972-1976 All 455 engines.
IMG726\$39.50 ea.

Carter Baffle Plate

1961-1967 All with Carter AFB 4bbl. Stainless steel plate between carb. and intake manifold. This plate is essential for protection against disintegration of aluminum base of carb. It is also necessary for proper idle and smooth running. Recommended is gasket, baffle plate, gasket.
BP576.....\$16.25 ea. 

Fuel and Exhaust (Group 3)

Fuel Pumps (3.900)



1961-1965 All. 364, 401, 425 engines. Rebuilding service or sold on an exchange with \$50.00 core charge.
 FP595RS\$89.25 ea.

1961-1965 All 364, 401 and 425 engines. Replacement fuel pump. No exchange necessary, sold outright.
 FP575\$39.75 ea.

1964-1965 All 300 engines.
 FP635\$44.00 ea.

1966 All 340 engines w/o a.c
 FP66S\$39.50 ea.

1966 401 and 425 engines without air conditioning.
 FP66.....Replacement.....\$44.50 ea.
 FP66R.....Rebuild service.....\$59.50 ea.

1966 All. 401 and 425 engines with air conditioning.
 FP66A.....Replacement.....\$69.50 ea.
 FP66AR.....Rebuild service.....\$59.50 ea.

1967 300 and 340 without air conditioning.
 FP67\$49.50 ea.

1967 300 and 340 with air conditioning.
 FP67A.....\$39.00 ea.

1968-1971 All 350 engines with air conditioning
 FP682A.....\$38.50 ea.

1967-1975 All 400, 430, 455 engines.
 FP674\$44.25 ea.

1968-1975 All 350 without A.C.
 FP685\$38.50 ea.

1975-1976 All 455 engines.
 FP756\$51.00 ea.

Fuel Pump Rebuilding Kits

1961-1965 All 364, 401, 425 engines. Rebuilding kit.
 FPK575\$59.50 ea.

Fuel Pump Cam Eccentric

1964-1975 225, 300, 340 and 350 engines.
 FPC615.....\$87.50 ea.



Electric Fuel Pump

1961-1972 All. 12V Universal replacement pump.
 FP12\$68.50 ea.

Fuel Lines Fuel Pump to Carburetor

CARS#	YEARS	APPLICATION	PRICE
FL350	1968-1972:	All 350-4 ~~~~~	\$26.50
FL455	1968-1972:	400, All 455-4 ~~~~~	\$26.50
FL455S	1968-1972:	STAGE 1 455 ~~~~~	\$26.50
FL70	1970:	All 4 Bbl. carburetors~~~	\$26.50

Fuel Pump Block-off Plates

1961-1972 All as required.
 CP300.....\$10.75
 ea.



Fuel Pump Hardware Kits

1961-1966 all 364, 400, 401, 425 engines. Correct bolts/washers.
 FPH406.....\$2.25 ea.



Pinch Clamps

For fuel lines, vacuum lines and PCV hoses

CARS#	YEARS	PRICE
PC380	All	3/8" OD hose\$ 1.00
PC716	All	7/16" OD hose.....\$ 1.00
PC150	All	1/2" OD hose.....\$ 1.00
PC916	All	9/16" OD hose.....\$ 1.00
PC580	All	5/8" OD hose.....\$ 1.00
PC1116	All	1 1/16" OD hose.....\$ 1.25
PC100	All	1" OD hose.....\$ 1.25

Fuel Line Clip Kits

1967-1969 Electra, Wildcat, Invicta. 3/8" with return line. 12 piece kit.
 FLC679R\$15.00 ea.
1967-1969 Electra, Wildcat, Invicta. 3/8" without return line. 4 piece kit.
 FLC679\$6.00 ea.
1970 Electra, Wildcat, Invicta. 3/8" with return line. 9 piece kit.
 FLC70BR\$15.00 ea.
1970 Electra, Wildcat, Invicta. 3/8" without return line. 8 piece kit.
 FLC70B.....\$10.00 ea.
1971-1976 Electra, Wildcat, Invicta. 3/8" with return line. 16 piece kit.
 FLC716R\$28.00 ea.
1971-1976 Electra, Wildcat, Invicta. 3/8" without return line. 16 piece kit.
 FLC716\$18.00 ea.
1971-1976 Electra, Wildcat, Invicta. 3/8" with return line. 27 piece kit.
 FLC776R\$32.00 ea.
1971-1976 Electra, Wildcat, Invicta. 3/8" without return line. 20 piece kit.
 FLC776\$25.00 ea.



Exhaust Manifold Gaskets



1957-1966 All. 364, 400, 401, 425 engines.
EMG576\$11.75 pr.
FG576.....(Flange gasket)\$8.75 pr.



1964-1967 All 300 and 340 engines.
EMG647\$13.00 pr.



1967-1976 All 400, 430 and 455 engines.
EMG676\$15.00 pr.

1968-1981 All 350 engines.
EMG681\$16.50 pr

Exhaust Manifold French Locks



1961-1966 All 364, 400, 401, 425 engines. Stainless steel. As required.
FL576\$3.50 ea.



1962-1966 All 400, 401, 425 engines;
1966 All 300, 340 Engines. Stainless steel. As required.
FL626\$1.75 ea.

Brass Nuts. Tall. All years as required.
3/8-16. Used on manifolds, pipes, exhaust, trim etc. Solid brass.
N6P.....\$3.75 pr.



Gas Tank Parts



1961-1964 Gas tank fuel gauge gasket.
GG355\$3.75 ea.



1961-1975 All. Gas tank strap cushions.
SC350.....\$12.75 pr.


1965-1966 All. Gas tank fuel gauge gasket.
GG642\$5.00 ea.

1967-1981 All. Gas tank fuel gauge gasket
GG671\$6.75 ea.

Gas Tank Bolt Kit



1961-1967 All as needed. Two 3/8-16 x 3" Bolts and two (2) lock nuts. Brightly zinc plated.
GB610\$5.50 kit



1967-1975 Gas door. (License plate) bumper.
GDB635.....\$5.00 pr.

Gas Caps



1961-1964 Gas cap. (vented).
GC575\$9.00 ea.



1965-1970 All except wagons. Gas tank cap. (non-vented).
GC640\$7.50 ea.



1971-1974 All .
GC714\$9.75 ea.



1982-1984 All Electra.
1982-1985 All LeSabre and Wagon;
GC827\$12.75 ea.

1982-1984 All Electra.
1982-1985 All LeSabre and Wagon. GM locking type with key.
GC827L\$33.50 ea

Gas Tank Sealer/Liner

Alcohol resistant. Quart can.
TS1.....\$30.00 ea.



Gas Tank Etch

Removes light rust and will prep for sealer/liner. 16oz.
TE1\$16.00 ea.



Lead Additive

All Buick engines needing leaded gas.
LA1.....\$13.50 ea.

