

Chrome Mag Wheels Coming Soon!



Chrome Wheel Center Caps & Emblems



1966-1970 Chrome mag wheel caps.
WC660.....\$39.50 ea.



1966-1970 LeSabre, Wildcat and Electra wire and mag wheel plastic center emblems. (Tri-shield).
WP660T\$18.00 ea.



1966-1970 Wildcat wire and mag plastic. (Wildcat).
WP660W.....\$18.00 ea.



1966-1970 Mag wheel chrome cap retainer. For wheels with 2 1/8" hole.
WCR650\$7.00 ea.

1966-1970 Mag wheel chrome cap retainer. For wheels with 2" hole.
WCR650S\$7.00 ea.

Wheel Nuts

1961-1995 Wheel nuts (1/2-20. Standard).
1963-1975: All as required;
1976-1995: LeSabre and Electra all as required.
WN610.....\$1.75 ea.



Solid Stainless Steel Wheel Nuts




1963-1981 We have reproduced these hard-to-find nuts to look identical to the originals. Of course they are far superior to the originals as they will never rust and feature the durability and strength of stainless steel.

1963-1981 1/2"-20 Solid stainless steel.
1963-1975: All;
1976-1981: LeSabre and Electra.
WN635.....\$6.25 ea.
WN635S.....(Set of 20).....\$96.00 set

1969-1981 7/16"-20 Solid Stainless Steel.
1969-1975: Apollo, Century, Regal, Skyhawk;
1976-1979: All except LeSabre and Electra;
1980-1981: All
WN695.....\$6.25 ea.
WN695S.....(Set of 20).....\$96.00 set.


Chrome Wheel Nuts Replacement Stainless Steel Capped



1963-1981 Wheel nuts (1/2-20. Chrome capped).
1963-1975: All;
1976-1981: LeSabre and Electra.
WN641.....\$3.00 ea.



1973-1981 7/16-20 wheel nuts.
1973-1975: Apollo, Century, Regal and Skylark;
1976-1979: Except LeSabre and Electra;
1980-1981: All.
WN691.....\$3.25 ea.
WN691S.....(Set of 20).....\$44.25 ea.



1971-1976 14" Chrome wheel cap with Tri-shield emblem.
WC712.....\$39.50 ea.



1971-1987 Buick LeSabre, Centurion, Electra with chrome wheels with 2" holes. Wheel cap with Tri-Shield for 15" wheels.
WC715.....\$43.00 ea.

1971-1987 Buick LeSabre, Centurion, Electra with chrome wheels with 2-1/8" holes. Wheel cap with Tri-Shield for 15" wheels.
WC715B\$43.00 ea.



1977-1987 All Chrome Wheels with 3" cap. Tri-shield plastic emblem on black background.
WC777\$39.50 ea.

Driveshaft Center Bearing Support New Manufacture



1961-1964 All. Driveshaft center bearing support. Almost always oil soaked and in need of replacements and often the cause of vibration. This is an entirely new part made as per original. No Exchange is necessary. Complete with bearing retainer clips. Order DSB611 bearing separately.

BS619\$92.75 ea.



1965-1968 LeSabre, Wildcat, Electra. Driveshaft center bearing support. Order DSB611 bearing separately.

BS658.....\$64.00 ea.

1961-1971 Driveshaft Center Bearing

1961-1971 All. Driveshaft center bearing.

DSB611\$37.00 ea.


Driveshaft Universal Joints



1961-1975 All. Driveshaft U-joint. Fits front, center and rear as arranged. Saginaw type: 1 1/8" O.D. cap. UJ574.....\$20.00 ea.



1961-1963 All. Driveshaft U-joint. All except rear. Spicer type. 1 1/16 od cap. (type2). UJ573.....\$20.00 ea.



Type 2

1961-1963 All. Driveshaft U-joint, rear. Spicer type. 1 1/16 O.D. cap (type2). UJ613R.....\$22.25 ea.

Constant Velocity Repair Kits



1961-1965 All.

CVK615.....\$59.00 ea.



1966-1967 Wildcat (center);
1966-1968 LeSabre & Electra (center).
Driveshaft constant velocity repair kit.
Does not include ball.

CVK668\$59.00 ea.

1971-1973 LeSabre and Centurion driveshaft constant velocity repair kits. Rear with out ball.


CVK713\$22.25 ea.


1971-1976 LeSabre, Centurion and Electra driveshaft constant velocity repair kits. Includes ball.

CVK716\$39.50 ea.

Visit us at our
Worldwide
Headquarters

We're located in a small
village amongst the vast
farmland in western New
Jersey





Rear Axle Control Arm Bushings



1965-1970 One pair per arm.
 1965-1970: All upper;
 1966-1970: All lower.

RAB652\$29.50 pr.
 RAB6525.....Set of 8 (4 pair).....\$106.50 set

1971-1988 All upper. Two per car.

RAB716U\$29.25 pr.

1971-1988 All lower. Two per car.

RAB716L\$29.50 pr.

1961-1970 Rear axle radius rod bushing.
 Two per car.

RRB600\$49.50 set

1961-1964 Track bar bushing. Buna rubber with metal sleeve.

1961-1962: All convertibles and wagons;
1963-1964: All wagons.



RRB604.....\$47.75 pr.

Rear Axle Parts



1961-1962 Rear axle pinion bearing (front). (5.447)

PBF562.....\$34.00 ea.

1961-1962 Rear axle pinion bearing (rear). (5.484)

PBR562\$90.25 ea.



1961-1962 Rear axle pinion seal (front).

(5.445)
 PS562\$32.50 ea.



1963-1964 all;
1965 thru 1970 all except LeSabre. Rear axle pinion seal.

PS630\$20.00 ea.

Rear Axle Carrier Gaskets



1961-1965

1961-1964: All;

1965: Wildcat and Electra.

RCG560.....\$9.00 ea.

Rear Axle Cover Gasket

1964-1970 LeSabre - 10 Bolt.

RAG640.....\$8.75 ea.

1966-1970 All.

RAG660.....\$8.75 ea.

1971-1975

1971-1972: All with 455 engine;

1973-1975: Electra.

RAG715.....\$8.50 ea.

Rear Axle Posi Traction Tag



All models.

PT635\$5.75 ea.

Rear Axle Posi-Traction Additive

All years as required. For Posi Rears.
 Reduces chatter and noise. Genuine GM.

AL300\$11.75 ea.

Rear Axle Bumpers (5.395)

1971-1975 All LeSabre, Centurion, Electra, except wagons.

AB715.....\$19.00 pr.

Rear Axle Backing Plate Gasket (5.819)

1961-1970: All. Wildcat, Electra, Except Wagons.
1968-1970: LeSabre.

Rear axle housing to backing plate and between rear wheel bearing. Gasket-shim.

AG562\$4.50 ea.



Rear Axle (Group 5)

Rear Wheel Bearings (5.855)



1961-1962 All.
RWB562\$74.50 ea.

1963-1967
1963-1964: All;
1965-1967: Wildcat and Electra.
RWB637\$47.50 ea.

1965 LeSabre.
RWB645\$147.50 ea.



1966-1967
1966: LeSabre;
1967: LeSabre 1st type - 2 7/8" diameter.
RWB667\$103.50 ea.

1967-1970
1967: LeSabre 2nd type 3 1/16" diameter;
1968-1970: LeSabre.
RWB670\$44.50 ea.

1968-1970 Wildcat and Electra, except wagons.
RWB680\$54.50 ea.



1971-1973 LeSabre and Centurion.
RWB696\$40.75 ea.

Brake Drums (5.809)

Cast Iron replacements.

(When replacing aluminum front drums - purchase in pairs.)



Front

1961-1964 LeSabre, Wildcat, Invicta and Electra.
BD614F\$112.50 ea.

1965-1970 LeSabre.
BD650\$109.00 ea.

1966-1967 Wildcat and Electra.
BD667\$112.50 ea.

1968-1970 Wildcat, Electra and Est. Wagon
BD680\$113.50 ea.

Rear

1961-1964 LeSabre, Wildcat, Invicta and Electra.
BD614\$109.00 ea.

1965-1970 LeSabre.
BD650R\$109.00 ea.

Rear Axle Oil Seals (5.822)

1961-1962 All.
OS612\$11.50 ea.



1963-1970
1963-1967: All except LeSabre;
1968 thru 1970 All except LeSabre and Wagon.
OS630\$11.00 ea.

1963-1965 LeSabre.
OS648\$11.50 ea.



1966 All LeSabre;
1967 LeSabre w/ 2 7/8" bearing.
OS668\$14.50 ea.

1967 LeSabre with 3 1/16th wheel bearing;
1968 thru 1970 all LeSabre.
OS670\$11.50 ea.

1971-1979
1971-1974: LeSabre, Centurion with 2 9/16" OD seal;
1975-1979: All Century, Regal. LeSabre, Electra w/ 2 9/16".
OS719\$8.50 ea.

1971-1976 LeSabre, Centurion, Electra, Riviera w/ 2 7/8".
OS716\$11.50 ea.

1971-1977 For "B" and "O" axles
1971-1975: Estate Wagon;
1971-1976: Electra with 8.5 ring gear;
1976: Estate wagon with 9.375 gear;
1971-1979: LeSabre, Centurion 8.5 & 9.375 gear.
OS709\$9.50 ea.



www.oldbuickparts.com
908-369-3666