


(Group 8) Hood • Front Fenders

Hood Insulation

Below listed Insulators are pre-cut, ready to install. Should you not see your car and or model listed, please send us you old items to make new patterns. You will receive a discounted new insulator. See spray adhesive below for application.



1961 LeSabre, Invicta, Electra.	
HI61	\$38.50 ea.
1962 All.	
HI62	\$37.50 ea.
1963 All.	
HI63	\$37.50 ea.
1964 LeSabre, Wildcat, Electra.	
HI64	\$37.50 ea.
1965 All.	
HI65	\$37.50 ea.
1966 All.	
HI66	\$37.50 ea.
1967 All.	
HI67	\$37.50 ea.
1968 LeSabre and Wildcat.	
HI68	\$37.50 ea.
1968 Electra.	
HI68E	\$37.50 ea.
1969-1970 LeSabre, Wildcat, Electra.	
HI690	\$37.50 ea.
1971-1972 All.	
HI712	\$37.50 ea.
1973-1974 All.	
HI734	\$49.50 ea.
1975 LeSabre and Centurion.	
HI75A	\$37.50 ea.
1975 Electra.	
HI75	\$37.50 ea.
1977-1980 Electra.	
HI770E	\$37.50 ea.
1982-1983 LeSabre and Electra.	
HI823	\$37.50 ea.

For years and models not listed above generic hood insulation pad. Gray fiberglass. Easy to trim and apply. 48" x 55" x 1".

HI415	\$36.50 ea.
1978-1990 All as required.	
HIR783	\$.75 ea.
HIR78359.....(Pack of 9)	\$8.00 ea.




Spray Adhesive for application of hood Insulation

SA360.....(20 oz).....\$18.00 ea.

1961-1976 All.
Front hood rubber bumper. Fits over metal pedestal. (8.204)
HB595.....\$2.50 ea.



 Retaining nut for above. All as required.
BN650.....\$5.50 ea.

1973-1975 Adjustable front hood bumper with rubber cap (8.024) and stainless steel stud.

1973-1974 All.;
1975 All LeSabre, Centurion, Electra, Apollo.
HA585.....\$5.75 ea.
HS585...Stud only. Stainless Steel....\$4.75 ea.



BUICK

1964-1965 All. "BUICK" hood letters. Die cast chrome.
HL645

1966, 1968, 1969, 1970 All. "BUICK" hood letters. die cast chrome.
HL660

1967 All. "BUICK" hood letters.
HL67

1966 Wildcat stand up hood ornament.
HO66W.....\$51.00 ea.



Hood to Fender Bumpers



1963 All. Hood to fender bumper. (8.037)
HFB635



1961-1968 all as required. Hood to fender bumper. Compare to your original. (8.037)
HFB610



1969-1970 Hood to fender bumper. (8.037)
HFB611



1971-1976 Hood to fender bumper. (8.037)
1971-1974 Rear. 2 per car.;
1975-1976 Front. 4 per car.
HFB715.....\$3.00 ea.



1976 Hood to fender bumper. All LeSabre Centurion and Electra.
HFB76.....\$4.00 ea.

Hood • Front Fenders (Group 8)



1970-1974 "Stage 1" monogram. Please note: Mounting studs may be slightly different from some earlier models.
 FM704.....\$41.50 ea.



1973-1974 Centurion "455" front fender plate. Maybe others.
 FM455CT.....\$25.25 ea.

1969 All. "WILDCAT" Front fender script. Fits either side.
 FM69W.....\$40.75 ea.

1970 "WILDCAT" Monogram. Fits either side.
 FM70W.....\$25.25 ea.

Fender Splash Aprons



1961 All LeSabre, Electra, Invicta.
 FA61\$16.00 set
1963-1964 All LeSabre, Wildcat, Electra.
 FA634\$54.50 set
1967 All LeSabre, Wildcat, Electra.
 FA67\$21.50 set
1970 All LeSabre, Wildcat, Electra.
 FA70\$17.50 set
1971-1973 All. Includes all factory holes required.
 FA713\$17.50 set
1971-1973 All. Includes all factory holes required.

Fender Apron Clip



1963-1966 All as required for aprons in engine compartment.
 FSC636\$2.25 ea.
 FSC636S.....(set of 15).....\$33.50 set

Make Your Own Fender Splash Aprons

Correct composition rubber material is excellent for duplication using your old aprons as a pattern.

MR4812.....(48" x 12").....\$40.75 ea.
 MR4824.....(48" x 24").....\$81.50 ea.
 MR4836.....(48" x 36").....\$122.25 ea.
 MR4848.....(48" x 48").....\$163.00 ea.
 MR4860.....(48" x 60").....\$203.75 ea.

Cowl Lace Retainers (12.801)



1961-1964 All.
 LR615.....\$2.25 ea.



1971-1978 Hood lace and cowl lace plastic retainer.
 LR685.....\$1.00 ea.

Cars Inc. World Leader in



Parts & Service