

(Group 9) **Cowl • Body to Frame Mounting Pads**

**Hood to Cowl Seals** (9.127)



**1965 thru 1967** LeSabre, Wildcat, Electra.  
CS657 .....\$30.75 ea.

**1971-1978** LeSabre, Centurion, Electra. 72".  
Includes fasteners.  
CS718 .....\$38.25 ea.

**1973-1974** Apollo.  
CS734A .....\$14.75 ea.



**1961-1964** Grommet for speedometer cable or trunk release cable through.  
FWG614 .....\$5.50 ea.



**1961-1964** Grommet for antenna lead on firewall through sheet metal.  
FG599 .....\$9.00 ea.



**1968-1971** All. Cowl vent screen "H" retainers. 5 per car.  
CSR682 .....\$4.00 ea.  
CSR682S.....(set of 5) .....\$17.00 set.




**1961-1964** Pad, body mounting. 1-7/8" O.D. x 11/16" with 1-1/8" diameter collar, washer and 7/8" O.D. sleeve. Number used varies.  
**1961-1964:** All.  
BM584.....\$8.75 ea.



**1961-1965** Insulator, body hold down bolt. 2" O.D. x 7/8" I.D. Number used as required. Some models.  
BM595.....\$6.50 ea.



**1963-1965** Pad, body mounting. Original type with metal core and spool liner. Number needed varies with application.  
**1963-1964:** All;  
**1965:** LeSabre and Wildcat.  
BM635.....\$6.75 ea.



**1967-1974** Lower radiator support mount with metal core. 3/4" ID 2 1/2" OD 1 1/8"  
BM644.....\$8.75 ea.



**1967-1974** Core support mount kit. Lower mounts, 2 upper mounts and hardware.  
CSK644.....\$38.00 kit

**1973-1977 Body Mount Kit**


**1973-1977** all Century and Regal. 24 piece kit includes rubber bushings with metal sleeves and shell inserts just like factory. Even the factory numbers are embossed into them.  
BMK737 .....\$236.50 kit

**Don't See Your Body Mounts Listed?**

If you send your old mounts and bolts, we will try and make a complete kit for you at a discounted price!

# Body to Frame Mounting Pads (Group 9)

## Body Mount Bolts



7/16-14 x 2". grade 5.  
 B1.....\$.75 ea.  
 B1B.....(Box of 25).....\$12.75 ea.

7/16-14 x 2 1/2". grade 5.  
 B2.....\$1.00 ea.  
 B2B.....(Box of 25).....\$15.00 ea.

**Don't see your body mounts listed?  
 If you send your old mounts and bolts,  
 we will try and make a complete kit for  
 you at a discounted price!  
 Universal body mounts.**

These body mounts are made from original GM molds. They were used in many Buick applications, however, parts books will not identify them by number. Many can be cut, doubled-up, or shaved to fit your needs.



Diameter - 1 11/16"  
 Thickness - 11/16"  
 Hole Size - 15/16"  
 BM2.....\$6.50 ea.



Diameter - 1 15/16"  
 Thickness - 3/4"  
 Hole Size - 1"  
 BM3.....\$8.75 ea.



Diameter - 2 5/8"  
 Thickness - 1 "  
 Hole Size - 7/8"  
 Includes metal insert.  
 BM4.....\$8.75 ea.



Diameter - 2"  
 Thickness - 1/2 "  
 Hole Size - 1/2"  
 BM5.....\$8.75 ea.



Diameter - 2 1/2"  
 Thickness - 3/4 "  
 Hole Size - 9/16"  
 Includes metal insert.  
 BM6.....\$8.75 ea.



Diameter - 2 1/2"  
 Thickness - 13/16 "  
 Hole Size - none. Solid rubber.  
 Insert diameter - 1 5/16"  
 BM7.....\$8.75 ea.



Diameter - 1 5/8"  
 Thickness - 7/16"  
 Hole Size - 3/4"  
 BM9.....\$8.75 ea.



Diameter - 2 1/16"  
 Thickness - 13/16 "  
 Hole Size - none. Solid rubber.  
 Insert diameter - 1 5/16"  
 BM11.....\$8.75 ea.




Diameter - 2"  
 Thickness - 13/16"  
 Hole Size - 7/8"  
 BM12.....\$8.75 ea.




Diameter - 2 "  
 Thickness - 7/8 "  
 Hole Size - 9/16"  
 Includes metal insert.  
 BM13.....\$8.75 ea.



Diameter - 1 3/4"  
 Thickness - 1 11/16"  
 Hole Size - 7/8"  
 BM15.....\$8.75 ea.





**Air Conditioning Parts  
Compressor with Clutch  
Remanufactured by Delco**

1962 thru 1977 all 6cyl type as pictured. Delco reman.  
AC627.....\$349.00 ea.



**1961-1975 A.C. clutch bearing.** All 6 cyl.  
compressors. (9.181)  
ACB585.....\$41.00 ea.

**1963-1965** Hot gas muffler insulator  
(sponge rubber).

MI635.....\$13.50 ea.  
MIS635..(2 Straps for above).\$13.50 ea.



**1965-1973** A.C. evaporator thermo  
expansion valve. (POA)

EV653.....\$41.00 ea.



**1965-1970 Heater Valve.**

**1965** All;  
**1966** All with A.C.;  
**1969-1970:** All manual A.C.

HV652.....\$29.50 ea.



**Heater Valve Insulator**

**1969-1974** All with air conditioning.  
VI694.....\$17.00 ea.

**1965-1976** A.C. Blower relay.

**1965-1967:** Manual;  
**1968-1970:** All except manual;  
**1972:** LeSabre and Electra;  
**1973-1976:** All except manual.

ACR656.....\$22.25 ea.



**1971-1977** A.C. Compressor thermal  
limiter switch.

TL717.....\$11.75 ea.

**1985-1989** A.C. Compressor relay.

**1985-1989** LeSabre and Electra w/ 307;  
**1982-1985** Skylark 2.5R;  
**1982-1987** Century;  
**1985-1986** Skyhawk;  
**1985-1988** Skylark and Somerset.

CR840.....\$11.75 ea.



**Heater Blower Motor**

**1963-1983** Electra.  
HBM646.....\$39.75 ea.



**A/C Vacuum Valve (9 Port)**

**1982-1983** Electra.  
**1982-1999** LeSabre.  
ACV820.....\$34.50 ea.

**Heater Cores** (9.779)

**1963-1968** All without A.C.  
HC638.....\$129.50 ea.  
**1963-1968** All with A.C.  
HC638A .....\$129.50 ea.  
**1969-1970** All without A.C.  
HC690.....\$97.00 ea.  
**1969-1970** All with A.C.  
HC638A .....\$129.50 ea  
**1971 thru 1976** LeSabre, Centurion,  
Electra.  
HC644.....\$90.25 ea.



**A.C. Refrigerant for R-12 and 134-a**




5 oz. standard can. Includes red dye for leak  
detection. A drop-in replacement for CFC-12  
and HFC-134a. No system evacuation  
needed. Up to 30% more efficient than CFC-  
12 and far more efficient than HFC-134a.  
ACR360.....\$10.00 ea.

**Firewall Insulators**



**1961-1962** Electra 225.  
FI612.....\$207.50 ea.  
**1963-1964** Electra.  
FI634.....\$237.50 ea.



**Firewall Insulator Retainer**

1961 thru 1990 all as required.  
IR500.....\$1.75 ea.

# Heating • Antennas • Dash Parts (Group 9)



## 1982-1989 Power Antenna Assembly (9.645)

This is a new reproduction antenna, using your old antenna cable connection, antenna nut and antenna tip. A very nice replacement, complete with bracket.

- 1982-1984** Electra;
- 1982-1989** LeSabre;
- 1983-1985** Skylark.
- PA829.....\$165.00 ea.

## Power Antenna Mast and Tube (9.645)



- 1982-1984** Electra;
- 1982-1989** LeSabre;
- 1983-1985** Skylark.
- AM829.....\$139.50 ea.

Power antenna tip for items above. Screws onto top of the mast and aids in pulling the antenna down when radio is turned-off.

AT829.....\$4.25 ea.

Power antenna repair cable for items above. If your power antenna does not go up or down and just hums, it is probably a broken internal cable. This is also the top most solid section of the antenna.

AC829.....\$30.00 ea.



All years as required. For view of traffic lights hidden by roof. A reproduction of a Genuine Buick accessory.

LF300.....\$39.75 ea.



**1961-1964** Chrome plated antenna retaining nut. AN544.....\$15.00 ea.

**1961-1963** Antenna grommet. (9.622) AG403.....\$3.75 ea.

**1967-1968** Antenna grommet. For rear mounted power antennas. AG678.....\$14.25 ea.



## Fixed Antenna Mast (9.645)

- 1982-1994:**
- 1982-1991** Regal;
- 1983-1988** Century and Skyhawk;
- 1984** Electra;
- 1984-1990** LeSabre and LeSabre Wagon;
- 1985-1991** Somerset Regal;
- 1992-1993** Skylark;
- 1994** Century, LeSabre, Regal, Roadmaster, Skylark.
- AM824.....(Chrome).....\$27.50 ea.



## Antenna Lead



**1970-1972** Antenna lead in for windshield antennas. AL708.....\$20.00 ea.

## 1961-1962 Cigar Lighter Fuse (9.712)



**1953-1962** All Casco lighters. CF532.....\$13.00 ea.