

(Group 9) **Cowl • Body to Frame Mounting Pads**

Hood to Cowl Seals (9.127)



1965 thru 1967 LeSabre, Wildcat, Electra.
CS657\$30.75 ea.

1971-1978 LeSabre, Centurion, Electra. 72".
Includes fasteners.
CS718\$38.25 ea.

1973-1974 Apollo.
CS734A\$14.75 ea.



1961-1964 Grommet for speedometer cable or trunk release cable through.
FWG614\$5.50 ea.



1961-1964 Grommet for antenna lead on firewall through sheet metal.
FG599\$9.00 ea.



1968-1971 All. Cowl vent screen "H" retainers. 5 per car.
CSR682\$4.00 ea.
CSR682S.....(set of 5)\$17.00 set.




1961-1964 Pad, body mounting. 1-7/8" O.D. x 11/16" with 1-1/8" diameter collar, washer and 7/8" O.D. sleeve. Number used varies.
1961-1964: All.
BM584.....\$8.75 ea.



1961-1965 Insulator, body hold down bolt. 2" O.D. x 7/8" I.D. Number used as required. Some models.
BM595.....\$6.50 ea.



1963-1965 Pad, body mounting. Original type with metal core and spool liner. Number needed varies with application.
1963-1964: All;
1965: LeSabre and Wildcat.
BM635.....\$6.75 ea.



1967-1974 Lower radiator support mount with metal core. 3/4" ID 2 1/2" OD 1 1/8"
BM644.....\$9.75 ea.



1967-1974 Core support mount kit. Lower mounts, 2 upper mounts and hardware.
CSK644.....\$39.75 kit

1973-1977 Body Mount Kit


1973-1977 all Century and Regal. 24 piece kit includes rubber bushings with metal sleeves and shell inserts just like factory. Even the factory numbers are embossed into them.
BMK737\$236.50 kit

Don't See Your Body Mounts Listed?

If you send your old mounts and bolts, we will try and make a complete kit for you at a discounted price!

Body to Frame Mounting Pads (Group 9)

Body Mount Bolts



7/16-14 x 2". grade 5.
 B1.....\$.75 ea.
 B1B.....(Box of 25).....\$12.75 ea.

7/16-14 x 2 1/2". grade 5.
 B2.....\$1.00 ea.
 B2B.....(Box of 25).....\$15.00 ea.

**Don't see your body mounts listed?
 If you send your old mounts and bolts,
 we will try and make a complete kit for
 you at a discounted price!
 Universal body mounts.**

These body mounts are made from original GM molds. They were used in many Buick applications, however, parts books will not identify them by number. Many can be cut, doubled-up, or shaved to fit your needs.



Diameter - 1 11/16"
 Thickness - 11/16"
 Hole Size - 15/16"
 BM2.....\$6.50 ea.



Diameter - 1 15/16"
 Thickness - 3/4"
 Hole Size - 1"
 BM3.....\$8.75 ea.



Diameter - 2 5/8"
 Thickness - 1 "
 Hole Size - 7/8"
 Includes metal insert.
 BM4.....\$8.75 ea.



Diameter - 2"
 Thickness - 1/2 "
 Hole Size - 1/2"
 BM5.....\$8.75 ea.



Diameter - 2 1/2"
 Thickness - 3/4 "
 Hole Size - 9/16"
 Includes metal insert.
 BM6.....\$8.75 ea.



Diameter - 2 1/2"
 Thickness - 13/16 "
 Hole Size - none. Solid rubber.
 Insert diameter - 1 5/16"
 BM7.....\$8.75 ea.



Diameter - 1 5/8"
 Thickness - 7/16"
 Hole Size - 3/4"
 BM9.....\$8.75 ea.



Diameter - 2 1/16"
 Thickness - 13/16 "
 Hole Size - none. Solid rubber.
 Insert diameter - 1 5/16"
 BM11.....\$8.75 ea.




Diameter - 2"
 Thickness - 13/16"
 Hole Size - 7/8"
 BM12.....\$8.75 ea.




Diameter - 2 "
 Thickness - 7/8 "
 Hole Size - 9/16"
 Includes metal insert.
 BM13.....\$8.75 ea.



Diameter - 1 3/4"
 Thickness - 1 11/16"
 Hole Size - 7/8"
 BM15.....\$8.75 ea.





**Air Conditioning Parts
Compressor with Clutch
Remanufactured by Delco**

1962 thru 1977 all 6cyl type as pictured. Delco reman.
AC627.....\$349.00 ea.



1961-1975 A.C. clutch bearing. All 6 cyl.
compressors. (9.181)
ACB585.....\$41.00 ea.

1963-1965 Hot gas muffler insulator
(sponge rubber).

MI635.....\$13.50 ea.
MIS635..(2 Straps for above).\$13.50 ea.



1965-1973 A.C. evaporator thermo
expansion valve. (POA)

EV653.....\$41.00 ea.



1965-1970 Heater Valve.

1965 All;
1966 All with A.C.;
1969-1970: All manual A.C.

HV652.....\$29.50 ea.



Heater Valve Insulator

1969-1974 All with air conditioning.
VI694.....\$17.00 ea.

1965-1976 A.C. Blower relay.

1965-1967: Manual;
1968-1970: All except manual;
1972: LeSabre and Electra;
1973-1976: All except manual.

ACR656.....\$22.25 ea.



1971-1977 A.C. Compressor thermal
limiter switch.

TL717.....\$11.75 ea.

1985-1989 A.C. Compressor relay.

1985-1989 LeSabre and Electra w/ 307;
1982-1985 Skylark 2.5R;
1982-1987 Century;
1985-1986 Skyhawk;
1985-1988 Skylark and Somerset.

CR840.....\$11.75 ea.



Heater Blower Motor

1963-1983 Electra.
HBM646.....\$39.75 ea.



A/C Vacuum Valve (9 Port)

1982-1983 Electra.
1982-1999 LeSabre.
ACV820.....\$34.50 ea.

Heater Cores (9.779)

1963-1968 All without A.C.
HC638.....\$129.50 ea.
1963-1968 All with A.C.
HC638A\$129.50 ea.
1969-1970 All without A.C.
HC690.....\$97.00 ea.
1969-1970 All with A.C.
HC638A\$129.50 ea
1971 thru 1976 LeSabre, Centurion,
Electra.
HC644.....\$90.25 ea.



A.C. Refrigerant for R-12 and 134-a




5 oz. standard can. Includes red dye for leak
detection. A drop-in replacement for CFC-12
and HFC-134a. No system evacuation
needed. Up to 30% more efficient than CFC-
12 and far more efficient than HFC-134a.
ACR360.....\$10.00 ea.

Firewall Insulators



1961-1962 Electra 225.
FI612.....\$222.00 ea.
1963-1964 Electra.
FI634.....\$237.50 ea.



Firewall Insulator Retainer

1961 thru 1990 all as required.
IR500.....\$1.75 ea.

Heating • Antennas • Dash Parts (Group 9)



1982-1989 Power Antenna Assembly (9.645)

This is a new reproduction antenna, using your old antenna cable connection, antenna nut and antenna tip. A very nice replacement, complete with bracket.

- 1982-1984** Electra;
- 1982-1989** LeSabre;
- 1983-1985** Skylark.

PA829.....\$165.00 ea.

Power Antenna Mast and Tube (9.645)



- 1982-1984** Electra;
- 1982-1989** LeSabre;
- 1983-1985** Skylark.

AM829.....\$139.50 ea.

Power antenna tip for items above. Screws onto top of the mast and aids in pulling the antenna down when radio is turned-off.

AT829.....\$4.25 ea.

Power antenna repair cable for items above. If your power antenna does not go up or down and just hums, it is probably a broken internal cable. This is also the top most solid section of the antenna.

AC829.....\$30.00 ea.



All years as required. For view of traffic lights hidden by roof. A reproduction of a Genuine Buick accessory.

LF300.....\$39.75 ea.



1961-1964 Chrome plated antenna retaining nut. AN544.....\$15.00 ea.

1961-1963 Antenna grommet. (9.622) AG403.....\$3.75 ea.

1967-1968 Antenna grommet. For rear mounted power antennas. AG678.....\$14.25 ea.



Fixed Antenna Mast (9.645)

- 1982-1994:**
- 1982-1991** Regal;
- 1983-1988** Century and Skyhawk;
- 1984** Electra;
- 1984-1990** LeSabre and LeSabre Wagon;
- 1985-1991** Somerset Regal;
- 1992-1993** Skylark;
- 1994** Century, LeSabre, Regal, Roadmaster, Skylark.

AM824.....(Chrome).....\$27.50 ea.



Antenna Lead



1970-1972 Antenna lead in for windshield antennas. AL708.....\$20.00 ea.

1961-1962 Cigar Lighter Fuse (9.712)



1953-1962 All Casco lighters. CF532.....\$13.00 ea.