

# Floor Pans • Rockers • Body Mouldings (Group 12)



FP614FFL



FP614RFL

## Floor Pans and Rocker Panels

1961-1964 All models. .(12.980)

Floor Pans

FP614FFL.....(FRONT LEFT) .....	\$69.50 ea.
FP614FFR.....(FRONT RIGHT) .....	\$69.50 ea.
FP614RFL..... (REAR LEFT) .....	\$69.50 ea.
FP614RFR..... (REAR RIGHT) .....	\$69.50 ea.

Rocker Panels for all 2-door models. .(12.934)

RP614L.....(LEFT OUTER PANEL) .....	\$112.50 ea.
RP614R..... (RIGHT OUTER PANEL) .....	\$112.50 ea.
RP614IL..... (LEFT INNER PANEL) .....	\$89.50 ea.
RP614IR..... (RIGHT INNER PANEL) .....	\$89.50 ea.

Body mount braces behind rear wheels. .(12.934)

BMB614L.....(LEFT).....	\$99.50 ea.
BMB614R..... (RIGHT).....	\$99.50 ea.

Trunk Panels above body mount braces. .(12.981)

TP614L..... (LEFT).....	\$99.50 ea.
TP614R..... (RIGHT).....	\$99.50 ea.

Center body brace (curved, under rear floor plan)

CBB614L..... (LEFT INNER PANEL) .....	\$89.50 ea.
CBB614R..... (RIGHT INNER PANEL) .....	\$89.50 ea.

1964-1970 All models.

Rocker panels for all 2-door models. .(12.934)

RP640L.....(LEFT OUTER PANEL) .....	\$34.50 ea.
RP640R..... (RIGHT OUTER PANEL) .....	\$34.50 ea.

Rocker Panels for all 4-door models. .(12.934)

RP6404L.....(LEFT OUTER PANEL) .....	\$79.50 ea.
RP6404R..... (RIGHT OUTER PANEL) .....	\$79.50 ea.

## Trunk Paint

**Correct Speckles in Paint  
Finishes Trunk Correctly  
Spray Can Allows Easy Access  
to Hard to Reach Spaces**



TP642.....(Black and aqua).....	\$14.00 ea.
TP642G.....(White and gray).....	\$14.00 ea.



## Body Plugs

BP120 .1/2" Hole Diameter .....	\$1.75 ea.
BP580 .5/8" Hole Diameter .....	\$1.75 ea.
BP340 .3/4" Hole Diameter .....	\$2.25 ea.
BP780 .7/8" Hole Diameter .....	\$2.25 ea.
BP100 1" Hole Diameter.....	\$1.75 ea.
BP114 1 1/4" Hole Diameter .....	\$1.75 ea.
BP112 1 1/2" Hole Diameter .....	\$2.25 ea.
BP118 1 1/8" Hole Diameter .....	\$2.50 ea.



## Fender Skirt Seals

1967-1968 All Wildcat and Electra with factory skirts.

FS678.....	\$43.00 set
------------	-------------

## Plastic Side Moulding Clip



1963-1972 For 3/8" wide retention.

As required.

MC600.....	\$1.00 ea.
------------	------------

## WILDCAT

1967 All. "WILDCAT" rear 1/4 panel letters. Either side.

QM67W .....	\$51.00 set
-------------	-------------

1967 All. "WILDCAT" trunk letters.

TL67W .....	\$51.00 set
-------------	-------------

1969 All. "WILDCAT" trunk script.

DM69W .....	\$40.75 set
-------------	-------------

## BUICK

1970 Lesabre trunk emblem. "BUICK".

DM71 .....	\$37.50 ea.
------------	-------------

1966 Wildcat monogram. Used on rear 1/4 and trunk lid.

QM66GS.....	\$34.50 ea.
-------------	-------------



1975 Skylark 1/4" monogram "Skylark"

QM75S.....	\$39.50 ea.
------------	-------------

1975 Skylark "S/R" emblem.

QM75SR.....	\$15.50 ea.
-------------	-------------





## Trunk Weatherstripping

**1961-1976** Trunk weatherstrip .(12.269)  
TW54217 .....\$28.25 ea.

**1976-1985:** Trunk weatherstrip. Pinchweld type.  
**1976-1984** Century and Electra;  
**1976-1985** LeSabre;  
**1976-1979** Skyhawk;  
**1979 Skylark** 2-dr. Hatchback;  
**1980-1985** All Skylark.  
TW761 .....\$33.00 ea.





**1986-1991:** Trunk weatherstrip.  
**1981-1987** Regal;  
**1986-1991** Skyhawk.  
TW811 .....\$159.50 ea.

**1973-1974** Apollo Hatchback weatherstrip.  
HW734A .....\$49.00 ea.


**1973-1977** All Century wagon tail gate weatherstrip.  
TGW737 .....\$59.50 ea.

## Trunk Parts


**1961-1976** Trunk bumper. Rubber "cap" type.  
TB415.....\$1.75 ea. 



**1961-1976** Trunk bumper.  
Rubber "plug in" type.  
TB495 .....\$2.75 ea.



**1961-1964** All Wagons. Bumper and tailgate  
latch striker.  
TB598.....\$3.75 ea.



**1961-1967** All Wagons.  
Bumper upper and lower.  
TB617.....\$5.75 ea.

## Trunk Bumper



**1977-1985** LeSabre, Electra;  
**1977-1981** Century.  
TB777.....\$2.50 ea.

**1961-1981** Spare tire hold down bolt, 5/16"-18 x 9 1/2".  
STB611.....\$11.75 ea.



**1961-1972** Spare tire hold down wing nut.  
TN615 .....\$18.00 ea.


## Trunk Lock and Keys Replacements

**1973-1975** All with lock on lid.  
TL609.....\$16.50 set



**1961-1975** Lock on body.  
**1961:** All;  
**1965-1975:** All.  
TL609B .....\$19.75 set

**1971** Electra Glove box lock and trunk lock  
sets with 2 matching original keys.  
LS712.....\$59.75 set



## Trunk Lock Gaskets

**1961-1975** All as required. As pictured.  
KLG540 .....\$1.25 ea.

**1963-1965** Tri-shield lock gasket. As required.  
TLG65.....\$4.75 ea.



## Trunk Mat

**1973-1977** Century and Regal. Green/Gray felt.  
TM737 .....\$41.00 ea.

## 1961 thru 1975 Accessory Trunk Mats

Heavy as original with Buick tri-shield logo. Available in  
black or saddle. Either comes with white center logo.  
TM615.....(Black with White Logo).....\$139.00 ea.  
TM615S.....(Saddle with White Logo).....\$139.00 ea.



We have a limited quantity of saddle mats that we are  
selling as "Blems". Due to their weight, the center emblem  
has pressed itself onto the one stored below leaving it's  
impression, otherwise very presentable.

TM615S2.....\$79.50 ea.