

Floorpans and Rocker Panels (12.000)

1963-1965 ALL

Front Toeboard (12.980)

- FP635TL.....(LEFT SIDE)\$74.50 ea.
- FP635TR.....(RIGHT SIDE)\$74.50 ea.

Floor Pan (12.980)

- FP635FFL.....(FRONT LEFT)\$87.50 ea.
- FP635FFR.....(FRONT RIGHT)\$87.50 ea.
- FP635RFL.....(REAR LEFT)\$87.50 ea.
- FP635RFR.....(REAR RIGHT)\$87.50 ea.

Under Seats (12.980)

- FP635FSL.....(FRONT LEFT)\$74.50 ea.
- FP635FSR.....(FRONT RIGHT)\$74.50 ea.
- FP635RSL.....(REAR LEFT)\$111.50 ea.
- FP635RSR.....(REAR RIGHT)\$111.50 ea.

Rocker Panels (12.934)

- RP635RL.....(LEFT OUTER PANEL)\$34.50 ea.
- RP635RR.....(RIGHT OUTER PANEL)\$34.50 ea.
- RP635IL.....(LEFT INNER PANEL)\$39.50 ea.
- RP635IR.....(RIGHT INNER PANEL)\$39.50 ea.

1971-1973 ALL

Front Toeboard (12.980)

- FP713TL.....(LEFT)\$97.50 ea.
- FP713TR.....(RIGHT)\$97.50 ea.

Floor Pan (12.980)

- FP713FFL.....(FRONT LEFT)\$74.50 ea.
- FP713FFR.....(FRONT RIGHT)\$74.50 ea.
- FP713RFL.....(REAR LEFT)\$74.50 ea.
- FP713RFR.....(REAR RIGHT)\$74.50 ea.


Under Seats (12.980)

- FP713FSL.....(FRONT LEFT)\$74.50 ea.
- FP713FSR.....(FRONT RIGHT)\$74.50 ea.
- FP713RSL.....(REAR LEFT)\$137.50 ea.
- FP713RSR.....(REAR RIGHT)\$137.50 ea.

Body Plugs



- BP1201/2" Hole Diameter\$1.75 ea.
- BP5805/8" Hole Diameter\$1.75 ea.
- BP3403/4" Hole Diameter\$2.25 ea.
- BP7807/8" Hole Diameter\$2.25 ea.
- BP1001" Hole Diameter\$1.75 ea.
- BP1141 1/4" Hole Diameter\$1.75 ea.
- BP1121 1/2" Hole Diameter\$2.25 ea.



1963-1965 Riviera rocker panel rubber hole plug.
RP635\$4.75 ea.



Trunk Floor Pan

1963-1965 All.

Trunk pan (12.980)

TP635\$239.00 ea.

1963-1965 Door Panel Retainers

We have reproduced the correct bolts and nuts that retain the unique removable door panels on your Riviera. These visible hardware items are needed for correct installation and show appearance.



Hex nut with dome. 8 needed per door.
N1\$3.75 ea.
N1S.....(Set of 8 for 1 door)\$25.75 set



Hex nut. 7 needed per door.
N2\$1.25 ea.

T-screw. 14 needed per door.

S9.....\$3.75 ea.



Complete kit for both doors. 58 pieces. A \$171.50 value.

DPK635\$129.50 ea.



www.oldbuickparts.com

908-369-3666

Rear 1/4 Panel • Roof (Group 12)

1963-1964 Rear 1/4 Ornaments



After years of R&D these ornaments or "Horseshoes" are finally completed. They are quality made to be better than Buick produced. The fit and finish are beautiful, chrome plated to perfection and ready to install. Clips are included in the kit. During production in late 1963 or early 1964 Buick changed the pin location of these ornaments. It is believed that the forward end of the ornament was lifting possibly from car wash brushes. The forward pin was located nearer to the end for better support. Our answer was to make pins in both locations. You merely twist the 2 pins not needed with pliers, then dress with a file or dremel tool to level the remaining stud.

1963-1964 All. Set of all 4 pieces for entire car.
RO634.....\$247.00 set


Panel Ornament Clips



1963-1964 Rear 1/4 panel ornament clips for retaining chrome "Horseshoe" ornaments.
MC2\$2.25 ea.
MC2S.....(Set of 36).....\$51.00 ea.



Convertible Tops please inquire!



Convertible Top Pumps

1982-1985 Convertible top motor pump.
TP645\$175.00 ea.

Plastic Side Moulding Clip

1963-1972 For 3/8" wide retention. Fits all **1963-1965** Fenders, doors and quarter panel side mouldings.



MC600\$1.00 ea.
1963-1965 All. Front fender and rear 1/4 panel moldings. Wire molding clip. Possibly fits other models.
MC5\$0.50 ea.

Side Molding Clip Kit



1963-1965 Contains all necessary and correct plastic clips, wire clips, nuts, etc. To attach all side molding to both sides of car. **36 pieces included.**
CK635R.....\$27.75 kit

Roof Panel Emblems

1982-1985 All. Fits either side.
RE825R.....\$40.75 ea.



Sunroof Weatherstripping

1978 thru 1985 all with electric sliding sunroof.
SW787\$149.50 ea.

Vinyl Roofs - Landau Tops

We can supply vinyl roofs and Landau tops for any Riviera from 1963 thru 1993. Please state year and color. See our website for colors.


VR633R.....Black or White\$199.00 ea.
VR633RC.....Colors\$229.00 ea.



1963-1975 Trunk weatherstrip.
TW54217\$28.25 ea.




1976-1983 Trunk Weatherstrip. Pinchweld type
TW761\$33.00 ea.



1963-1976 Trunk bumper. Rubber "cap" type.
TB415\$1.75 ea.



1963-1976 Trunk bumper.
Rubber "plug in" type.
TB495\$2.75 ea.



1966-1968 Trunk latch bumper.
TB598\$3.75 ea.



1963-1981 Spare tire hold down bolt.
5/16"-18 x 9 1/2"
STB611\$11.75 ea.



1963-1972 Spare tire hold down wing nut.
TN615\$18.00 ea.



1982-1985 All. Tire/jack retaining nut.
TN820\$12.75 ea.



1963-1980 As required. Trunk lock gasket.
KLG540\$1.25 ea.



1963-1965 Riviera. Trunk lock gasket.
TLG65\$4.75 ea.



1963-1968 Trunk floor pan plug. 3/4" hole.
BP598\$2.25 ea.



1963-1975 As required. Body plug. 1 1/2" hole.
BP355\$3.25 ea.



Trunk Release Button

1979-1985 All as required.
TRB829\$21.50 ea.

Trunk Lock and Keys



1963-1964 All with lock on body. Not for locks in emblems.
TL609B\$19.75 set



1966-1968 1966, 1967, 1968. All with lock on lid.
TL609\$16.50 set



1971-1972
TL712\$33.50 set

Trunk Emblems



1965 "Riviera" deck lid monogram. 6 flat spade studs.
DM65R\$36.00 ea.



1965-1967; 1970 "Riviera" deck lid monogram. 4 Round studs.
DM657R\$33.50 ea.



1965 "Gran Sport" trunk script. 2nd type. 5 3/4" long. Located on rear panel.
DM65GS2\$39.50 ea.



1971-1972 "Riviera by Buick" deck lid monogram.
DM712R\$35.50 ea.



1973 "Riviera Buick" deck lid monogram.
DM73R\$35.00 ea.

Trunk Supports

(gas charged)



1979 thru 1983 All. Fits either side.
TS793R\$22.25 ea.

Hog Rings

For attaching seat covers to frame
HR360Bag of 100\$8.75 ea.



Hog Ring Pliers

For attaching hog rings to seat covers.
HRP360\$30.25 ea.

