

Firewall Insulator Retainer.
1963-1990 All as required.
 IR500.....\$1.75 ea.



Firewall Insulator

1963-1965 Riviera. Contour molded as original from strong ABS material. Pre-cut holes. Insulation and rubber draft seals are included as required. Modification may be required for air conditioning. Show quality!
 FI635R.....\$167.50 ea.



Body Mounting (9.023)

1963-1964 Pad, body mounting. 1-7/8" O.D. x 11/16" with 1-1/8" diameter collar, washer and 7/8" O.D. sleeve. Number used varies.
1963-1964 All .
 BM584\$8.75 ea.



1963-1965 Insulator, body hold down bolt. 2" O.D. x 7/8" I.D. Number used as required. Some Models.
 BM595\$6.50 ea.



1967-1974 Body mount with metal core. 3/4" ID. 2 1/2" OD. 1 1/8".
 BM644\$9.75 ea.




1963-1965 All. Pad, body mounting. Original type with metal core and spool liner. 10 per car. 2" OD. 3/4" sleeve ID 5/8" high.
 BM635\$6.75 ea.



1967-1974 Core support mount kit. Lower mounts, 2 upper mounts and hardware.
 CSK644\$39.75 ea.

Body to Frame Mounting Pads (Group 9)

Body Mount Bolts



7/16-14 x 2". grade 5
 B1.....\$.75 ea.
 B1B.....(Box of 25).....\$12.75 ea.

7/16-14 x 2 1/2". grade 5
 B2.....\$1.00 ea.
 B2B.....(Box of 25).....\$15.00 ea.

**Don't see your Body Mounts listed?
 If you send your old mounts and bolts,
 we will try and make a complete kit for
 you at a discounted price!**

Universal Body Mounts

These Body mounts are made from original GM molds. They were used in many Buick applications, however, parts books will not identify them by number. Many can be cut, doubled-up, or shaved to fit your needs.



Diameter - 1 11/16"
 Thickness - 11/16"
 Hole Size - 15/16"
 BM2.....\$6.50 ea.



Diameter - 1 15/16"
 Thickness - 3/4"
 Hole Size - 1"
 BM3..... \$8.75 ea.



Diameter - 2 5/8"
 Thickness - 1 "
 Hole Size - 7/8"
 Includes metal insert.
 BM4..... \$8.75 ea.



Diameter - 2"
 Thickness - 1/2 "
 Hole Size - 1/2"
 BM5..... \$8.75 ea.



**1961-1964 Grommet for antenna lead
 on firewall through sheet metal.**
 FG599.....\$8.00 ea.



Diameter - 2 1/2"
 Thickness - 3/4 "
 Hole Size - 9/16"
 Includes metal insert.
 BM6..... \$8.75 ea.



Diameter - 2 1/2"
 Thickness - 13/16 "
 Hole Size - none. Solid rubber.
 Insert diameter - 1 5/16"
 BM7..... \$8.75 ea.



Diameter - 1 5/8"
 Thickness - 7/16"
 Hole Size - 3/4"
 BM9..... \$8.75 ea.



Diameter - 2 1/16"
 Thickness - 13/16 "
 Hole Size - none. Solid rubber.
 Insert diameter - 1 5/16"
 BM11..... \$8.75 ea.




Diameter - 2"
 Thickness - 13/16"
 Hole Size - 7/8"
 BM12.....\$8.75 ea.



Diameter - 2 "
 Thickness - 7/8 "
 Hole Size - 9/16"
 Includes metal insert.
 BM13..... \$8.75 ea.



Diameter - 1 3/4"
 Thickness - 1 11/16"
 Hole Size - 7/8"
 BM15..... \$8.75 ea.





Remanufactured Compressor with Clutch

1963 thru 1977 all 6cyl type as pictured. Delco remanuf.
AC627 (Single Pulley)\$286.25 ea.
AC627D (Double Pulley)\$391.00 ea.

A.C. Refrigerant for R-12 and 134-a



6 oz. standard can. Includes red dye for leak detection. A drop-in replacement for CFC-12 and HFC-134a. No system evacuation needed. Up to 30% more efficient than CFC-12 and far more efficient than HFC-134a.
ACR360\$10.00 ea.



1966-1976 A.C. Blower relay.
1966-1967: All manual;
1968: All;
1969-1970: All auto climate control;
1972: All;
1973-1976: All auto climate control.
ACR656\$22.25 ea.



1963-1965 A.C. evaporator thermo expansion valve replacement.
EV635.....\$41.00 ea.



1971-1972 A.C. evaporator thermo expansion valve. (POA).
EV653.....\$29.50 ea.



1963-1965 Hot gas muffler insulator (sponge rubber).
MI635.....\$13.50 ea.



MIS635.....Straps for Above.....\$13.50



1963-1974 A.C. compressor clutch bearing.
ACB585\$41.00 ea.



1971-1977 A.C. compressor thermal limiter Switch.
TL717\$11.75 ea.



1984-1985 A.C. Compressor relay.
1984-1985 All V-6;
1985 All with 307 engine.
CR840\$11.75 ea.



1979-1985 AC condenser insulator. 4 per car needed.
RI770\$7.25 ea.



Heater Cores (9.779)

1963-1965 All with A.C. heater core.
HC638\$129.50 ea.
1966-1968 All with A.C.
HC668\$124.50 ea.
1969-1970 All with A.C.
HC690R.....\$124.50 ea.
1971-1978
1971-1976: All;
1977-1978: All without A.C.
HC644\$90.25 ea.
1979-1985 All.
HC795R.....\$50.50 ea.



Heater Blower Motor

1963-1976 Riviera.
HBM646.....\$39.75 ea.



Heater Control Valve

1965-1970
1965-1966: All;
1969-1970: All manual A.C.
HV652.....\$29.50 ea.



A/C Vacuum Valve (9 Port)

1979-1985 Riviera.
ACV820\$39.50 ea.



Heater Valve Insulator

1969-1974 All with air conditioning.
VI694\$17.00 ea.



1979-1985 Power Antenna Assembly (9.645)

This is a new reproduction antenna, using your old antenna cable connection, antenna nut and antenna tip. A very nice replacement, complete with bracket.
1979-1985 All.
PA829.....\$165.00 ea.
AC829...(Replacement cable for above)...\$30.00
AT829...(Replacement tip for above).....\$4.25



Power Antenna Mast and Tube

1979-1985 All
AM829\$139.50 ea.



Power Antenna Retaining Nut

1979-1985 All.
AN827C (Chrome).....\$7.25 ea.
AN827 (Black)\$8.00 ea.



Antenna Lead

1970-1972 Antenna lead for windshield antennas.
AL708\$20.00 ea.