

G67GS

1967 Special and GS Grille

(Includes Mounting Studs)

G67GS\$527.00 ea.

1967 GS Grille Emblem.

GE679G\$32.50 ea.

1968 GS Grille

G68Gs.....\$499.00 ea.



G69GS

1969 GS Grille

G69GS\$499.00 ea.

1969 GS Grille Emblem.

GEG79G\$32.50 ea.



G70GS

1970 GS Grille

(Includes Mounting Studs)

G70GS\$494.00 ea.

1970 GS Grille Emblem. "GS by Buick".

GE70G\$39.00 ea.

1970 GSX Grille Emblem. "GSX by Buick".

GE70X.....\$49.50 ea.



GE70G



GE70X



GM70

1970 Grille Surround Molding Set - 3 pieces.

GM70.....\$159.00 set.

1971 GS Grille


G71GS\$625.00 ea.

1971 GS Grille Emblem. "GS by Buick".

GE71G\$38.50 ea.

1971 GSX Grille Emblem. "GSX by Buick".

GE71X.....\$49.50 ea.



G71GS

1972 Skylark and GS Grille

G72GS.....\$499.00 ea.

1972 GS Grille Emblem. "GS by Buick".

GE72G\$43.50 ea.

GEP72.....(Backing Plate).....\$9.75 ea.

1972 GSX Grille Emblem. "GS by Buick".

GE72X.....\$65.00 ea.

GEP72.....(Backing Plate).....\$9.75 ea.



GE72G



GEP72

Grilles • Cooling • Oiling (Group 1)

Grille Emblems (1.303)

1965 "Gran Sport" Grille Emblem.
GE65GS.....\$37.50 ea.



1966 "Gran Sport" Grille Emblem.
GE66GS.....\$43.75 ea.



1968 "GS" Grille Emblem.
GE68GS.....\$25.00 ea.



1967, 1969 "GS" Grille Emblem.
GE679G.....\$32.50 ea.



1970 "GS By Buick" Grille Emblem.
GE70G.....\$39.00 ea.



1970 "GSX By Buick" Grille Emblem.
GE70X.....\$49.50 ea.



1971 "Skylark By Buick" Grille Emblem.
GE71S.....\$43.75 ea.



1971 "GS By Buick" Grille Emblem.
GE71G.....\$38.50 ea.



1971 "GSX By Buick" Grille Emblem.
GE71X.....\$77.75 ea.



1972 "GS By Buick" Grille Emblem.
GE72G.....\$43.50 ea.



1970-1972 Hood Release Handle.
HH702.....\$19.50 ea.



1968-1972 Radiator Core Supports, Repair Kits Core Support Mounts and Hardware

Our 3 piece kit of heavy gauge metal, repairs rusted box and lower panel area.

1968-1969 All. Repair for R.H. side.
CSK689R.....\$139.00 ea.

1968-1969 All. Repair for L.H. side.
CSK689L.....\$139.00 ea.

Our 3 piece kit of heavy gauge metal, repairs rusted box and lower panel area.

1970-1972 All. Repair for R.H. side.
CSK702R.....\$139.00 ea.

1970-1972 All. Repair for L.H. side.
CSK702L.....\$139.00 ea.



1968-1972 Lower radiator support mount with metal core.
3/4" ID. 2 1/2" OD. 1 1/8.
BM644.....\$8.75 ea.

1968-1972 Upper radiator core support mount.
BM644A.....\$7.50 ea.

1964-1967 Core support hardware kit.
CSK647BK.....\$5.00 ea.
1968-1972 Core support hardware kit.
CSK644BK.....\$5.00 ea.

1964-1967 Core support mount kit. Lower mounts, 2 upper mounts and hardware.
CSK647.....\$38.00

1968-1972 Core support mount kit. Lower mounts, 2 upper mounts and hardware.
CSK644.....\$38.00



1970-1972 Complete Core Support
CS702.....\$395.00 ea.



Fans

Clutch Fan Blades

- 1961-1972** 18" Clutch fan blade. Replacement
 FB626C\$67.50 ea.
1964-1968 Clutch fan blade. 19" Replacement
 FB648C\$90.25 ea.

Fan Spacer Kit

- 1969-1972** Fan spacer kit.
 FSK696\$17.00 ea.

Fan Clutches (1.050)




- 1964-1972**
1964-1967 225, 300 and 340 engines;
1968-1972 350 engine.
 FC642\$54.50 ea.
1965-1972
1965-1969 400 engine;
1969-1972 250 engine;
1970-1972 455 engine.
 FC626\$64.50 ea.

Fan Shrouds (1.277)

Fiberglass Reproductions



- 1965-1967**
1965 300 engine with crossflow radiator;
1966-1967 All 300 and 340 engines.
 FS657.....\$157.50 ea.
1965-1966 GS 400
 FS656.....\$157.50 ea.
1967 Skylark, GS 400
 FS67.....\$157.50 ea.
1968-1969 GS 400
 FS689.....\$154.50 ea.
1970 GS and GSX 455.
 FS70 (ABS Reproduction).....\$157.50 ea.



Fan Belts

Don't Rely On Old Belts!

The price of a new belt is a small fraction of the repair costs a broken belt can cause.

We Stock Hundreds of Different Fan Belts.
 When Ordering, Please Include:
 The Model, The Year, Engine Size, and if you have
 Power Steering? or Air Conditioning?

- Fanbelt - All**
 FB400.....\$19.75 ea.

ALSO: WHICH BELT (Fan-Alt., Fan-AC Comp.,
 Steering Pump-Air Pump, etc.).

Cooling • Oiling (Group 1)

Thermostat (with Gasket) (1.246)



1961-1972 All except 1965-1966 GS.

T330.....	(180°)	\$9.75 ea.
T330L.....	(160°)	\$9.75 ea.
T330H.....	(195°)	\$9.75 ea.
1965-1966 GS		
T536.....	(180°)	\$9.75 ea.
T536L.....	(160°)	\$9.75 ea.
T536H.....	(195°)	\$9.75 ea.

Thermostat By Pass Hoses



1962-1972
1962-1967 V-6 engines;
1964-1972 300, 340 and 350 engines.

BP625.....	\$9.75 ea.
1967-1972 400 and 455 engines.	
BP676.....	\$9.75 ea.

Water Pump Mounting Gaskets



1961-1972 198, 215, 225, 300, 340 and 350 engines.

WPG615	\$3.75 ea.
1965-1972 400 engines.	
WPG626	\$3.50 ea.
1967-1972 400 and 455 engines.	
WPG675	\$3.25 ea.

Temperature Sending Units



1961-1965 All except 1965 GS - One (1) terminal.

TSU615.....	\$13.75 ea.
1965-1968 GS 400 - Two (2) terminals.	
TSU608.....	\$19.75 ea.
1966-1972 300, 340, 350 and 455 engines with lights.	
One (1) terminal.	
TSU662.....	\$12.50 ea.
1970-1972 All with gauges.	
TSU702.....	\$19.50 ea.

Water Pumps (1.069)



1961-1963 198, 215 engine w/o ac;
1962-1963 all V-6.

WP613.....	(exchange item)	\$64.50 ea.
1962-1963 all V-6.		
WP613A.....	(exchange item)	\$64.50 ea.
1964-1970 225, 300, 340 and 350 engines.		
WP640.....		\$54.50 ea.
1965-1966 400 engine with A.C. This pump will also fit non - A.C. cars.		
WP626A.....		\$79.50 ea.
1967-1970 400, 455 with A. C.		
WP670.....		\$80.25 ea.
1971-1972 350 engine.		
WP712S.....		\$47.50 ea.
1967-1972 400, 455 without A.C.		
WP672.....		\$57.25 ea.
1971-1972 455 engines with A.C.		
WP716.....		\$56.75 ea.

Water Outlets



1961-1972
 1961 thru 1972 all except 1965 and 1966 GS.400.

WO615.....	\$24.50 ea.
1965-1966 400 engine.	
WO626.....	\$22.25 ea.



Water Manifold Gasket Kit



1961-1966 All 400, 401. Includes 2 gaskets and "O" ring.

WMK536.....	\$9.00 ea.
-------------	------------

Water Outlet Gasket

1961-1972 All.


WOG615.....	\$2.25 ea.
-------------	------------

Crankcase Vent Hose (To Carb)



1972 All 350 and 455 with 4BBL Carb. (Formed hose).

VH725	\$20.25 ea.
-------------	-------------



Radiators

- 1968-1972** Skylark and GS with manual transmission. 4 core. Concours correct.
 R682M\$729.00 ea.
- 1968-1972** Skylark and GS with automatic transmission. 4 core. Concours correct.
 R682A\$729.00 ea.

Radiator Insulators

- 1962** all 2nd type; Lower.
- 1963** All. Lower.
 RI623S\$16.00 ea.

- 1962** all 2nd type; Upper. 2 per car.
- 1963-1964** All. Upper. 1 per car.
- 1965** All with downflow radiator. 2 per car.
- RI625S.....\$17.50 ea.

- 1965** All with cross-flow radiator;
- 1966** All.
- RI656.....\$30.00 pr.

- 1965** GS;
- 1966** All.
- RI656B\$30.75 pr.

- 1968-1972** All with 3 core radiators.
- Set of 4. (1970 cars compare with RI690 below).
 RI682S.....\$64.25 set

- 1970** Some with 3 core radiator. 2 pair used per car. Compare with RI682S.
- RI690.....\$35.50 pr.

4-Core Radiator Insulators



Correct replacement for 4-core radiators. All years as required.
 RI600\$15.50 pr.

Radiator Caps



Take a good look at these caps. They are identical to the originals. Correct in every detail, they feature the cap number, instructions and of course genuine "AC" identification stamped right into the zinc plated surface. Show quality, approved and licensed by Buick.

- 1961-1964** All. 15 lb.
 RC15D\$32.50 ea.
- 1965-1968** All. 15 lb.
 RC15F\$32.50 ea.
- 1969-1970** All w/o coolant recovery sys. 15 lb.
 RC15H\$32.50 ea.
- 1970-1972** All with coolant recovery sys. 15 lb.
 RC29(plate has scalloped edge).....\$29.75 ea.
- 1970-1972** All with coolant recovery sys. 15 lb.
 RC29S(plate has smooth edge).....\$29.75 ea.
- 1961-1969** All. 15 lb.
 RC579.....\$16.50 ea.
- 1970-1972** All.
 RC706.....\$9.75 ea.

Radiator Overflow Hose



Correct "Ribbed" Hose sold in 3 1/2' length. All years as required.
 OH600\$13.50 ea.











Cars Inc., recognized leader in Buick Parts and Service since 1973

Cooling (Group 1)

Radiator Hoses

We Can Supply Almost Any Model/Year Check, NOS Section Also! **Please Inquire.**

	1961 All V8, Lower. RH369.....\$19.50 ea.
	1962 V6 (Radiator 126 or 127), Lower. RH509.....\$19.50 ea.
	1962 V8 (Radiator 121 or 143), Lower. RH369.....\$19.50 ea.
	1962-1963 V6, Upper. UH623.....\$22.50 ea.
	1964-1965 Upper. 1964: V6; 1965: V6 (Down Flow) RH392.....\$19.50 ea.
	1965 All V8 (Down Flow), Lower. RH396.....\$23.50 ea.
	1965 8 cyl without AC (Down Flow), Upper. RH439.....\$17.75 ea.
	1965 All Cross Flow, Upper. RH510.....\$17.50 ea.
	1965 8 cyl with AC (Down Flow) Upper. RH755.....\$22.25 ea.
	1965-1968 Lower. 1965: 8 cylinder (X-Flow); 1966: 300, without AC, with AP; 1967-1968 All 300, 340, 400. RH742.....\$22.50 ea.
	1966-1967 Upper. 1966 -1967 All 340 RH485..... \$23.50 ea.
	1966-1967 Lower. 1966: Special, with AC; 1967: 340 (Exc. SP), without AC; RH512.....\$22.50 ea.
	1967 340 (Exc. SP), without AC, Upper. RH533.....\$22.25 ea.
	1968-1970 Upper. 1968 All 350 and 400; 1969-1970: 350 (Special and Skylark); 1969: 400 (GS, Sportwagon); 1970: 455 (GS). RH980.....\$22.25 ea.
	1969-1972 All Skylark/GS, 350, 400 and 455, Lower. RH597.....\$24.50 ea.
	1969-1972 Upper. 1969-1970 All GS350; 1971 All 455; 1972: All GS-350. RH715.....\$22.50 ea.
	1971-1972 Upper. 1971 All 350; 1972 All exc. GS350. RH869.....\$22.50 ea.

Radiator Hose Support



1969-1970 All GS.
HS690.....\$ 27.50 ea.

Radiator Overflow Reservoir



1970 through 1972 models. Note that 1970 early models came with a clear top. Later 1970 models and all 1971-1972 models had Black tops. This is a fine reproduction with correct embossed letters and numbers, made a bit more sturdy than the original.

OR702B.....Black Top.....\$149.00 ea.
OR702C.....Clear Top.....NLA

Radiator Hose Clamps

**ORIGINAL EQUIPMENT
" TOWER TOP " HOSE CLAMP**



Authentic reproduction of "Tower Top" Hose clamps made by the Wittek Company for GM. They are correct for all 1961-1972 models.

RC134....1 3/4"\$ 2.75 ea.
RC200....2"\$ 2.75 ea.
RC216....2 1/16" Diameter fits most upper hoses ..	\$ 2.75 ea.
RC214....2 1/4" Diameter fits most lower hoses ..	\$ 2.75 ea.
RC250....2 1/2"\$ 2.75 ea.
RC2516..2 5/16"\$ 2.75 ea.
RC400....4"\$ 4.00 ea.




Heater Hose

3/4" All years. HH34	\$1.00 ft.
3/4" All years: 50 ft. HH3450	\$39.00
5/8" All years. HH58	\$1.00 ft.
5/8" All years: 50 ft. HH5850	\$39.00

Breather Tubes (Air Cleaner to Rocker Cover) (1.745)

Breather Tube



1968-1969 All 350 and 400 4BBL. VT689	\$19.50 ea.
---	-------------



1970-1971 all V-8; 1972 all 455 engines VT704	\$16.50 ea.
--	-------------



Crankcase Vent Hose (To Carb) (1.746)

1972 All 350 and 455 with 4BBL Carb. (Formed Hosed). VH725	\$20.25 ea.
---	-------------



Tower Top Heater Hose Clamps



"Tower Top"

Buick used "Tower Top" hose clamps on all cars from 1961-1972. We supply the identical clamps made by the Wittek Company. They are authentic and correct.

1 1/16" for 5/8" heater hose. HC580	\$2.75 ea.
1" for use on thin walled 5/8" hose. HC580S	\$2.75 ea.
1 1/4" for 3/4" heater hose. HC340	\$2.75 ea.
1 3/16" for use on thin walled 3/4" hose. HC340S	\$2.75 ea.

Wire Hose Clamps



For 9/16" diameter hose.	
HC916W	\$ 1.00 ea.
HC916WP	(5 Pack) \$ 3.25 ea.
For 5/8" diameter hose.	
HC580W	\$ 0.75 ea.
For 3/4" diameter hose.	
HC340W	\$ 0.75 ea.
HC340WP	(5 Pack) \$ 3.25 ea.
For 13/16" diameter hose.	
HC1316W	\$ 1.00 ea.
HC1316WP	(5 Pack) \$ 4.25 ea.
For 15/16" diameter hose.	
HC1516W	\$ 0.75 ea.
HC1516WP	(5 Pack) \$ 4.25 ea.
For 1" diameter hose.	
HC100W	TOS
HC100WP	(5 Pack) \$ 4.25 ea.
For 1-1/4" diameter hose.	
HC114W	\$ 1.00 ea.
HC114WP	(5 Pack) \$ 5.00 ea.
For 2" diameter hose.	
HC200W	\$ 2.75 ea.
HC200WP	(5 Pack) \$12.25 ea.

**Fax Us
Your Order
Save Time!**

When sending us a long order
it is easier to just fax it.

908-369-7595

Cooling • Oiling (Group 1)

Oil Filters



1961-1966 All. (Also fits thru 1980 where there is room for taller filter). PF-7 type.
OF596\$9.75 ea.

1967-1980 All exc. V-6 and 260 engines.
PF-24 type.
OF670\$9.75 ea.

PF-24 Oil Filters



A brand new quality reproduction on the original 1967-1975 red, white, and blue, AC TYPE PF-24 oil filter with logo and proper coloring. A must for the concours restorer.
OF590AC\$22.25 ea.

Oil Pan



1969-1970 all 400, 430, 455 engines;
1971-1976 all 455 engines.

Not for factory exhaust crossover systems. Powder coated.
OP676\$165.00 ea.

Oil Pan Drain Plug and Gasket Kit

1961-1976 Oil pan drain plug and gasket. 1/2" x 20" thread.
OP595\$5.50 kit

Oil Pick-up Tube and Screen



1964-1968 all 225, 300, 340, 350 engines. Has 5/8" tube. Requires passage drilled to 5/8".
OPU647\$24.50 ea.

1965-1966 GS 400, 401, 425 engine. Stock size.
OPU626\$155.00 ea.

1967-1976 400,455 w/ rear sump. (Increased oil pick-up over stock 1/2" tube. Gives 5-10 psi oil pressure increase. 1967-1970 engines require that pick-up passage drilled to 5/8". Acts as replacement for 1970 Stage 1 and all 1971-1976 455 engines).
OPU676R\$69.75 ea.

1967-1976 400, 430, 455 w. center sump. 5/8" tube. Requires passage to be drilled to 5/8".
OPU676C\$74.50 ea.

1969-1981 350 engine. Stock size.
OPU695\$20.00 ea.

1969-1981 all 350. Has 5/8" tube requiring windage tray to be removed or trimmed.
OPU691\$29.75 ea.



Oil Pumps (1.652)

1965-1966 400 engines.
OP626\$112.00 ea.

Oil Pump Kits (1.652)

1961-1963 215 engine.
OPK613\$39.00 kit

1964-1981 All 225, 300, 340, 350 engines.
OPK642\$33.75 kit
OPK642H.....(High Volume Kit)\$45.50 kit


1965-1966 All 400, 401 engines.
OPK626\$47.50 kit



1967-1976 All 400, 430, 455 engines.
OPK676\$32.25 kit
OPK676H....(High Volume Kit).....\$59.25 kit

Oil Pump Thrust Plate Repair Kit

This kit provides a NEW WEARING Surface for badly scored or worn cover housing. Kit contains all necessary screws, gaskets and instructions.



1961-1981 all 215, 225, 300, 340, 350, 455 engines.
OPK685\$21.00 ea.

Distributor Gear Oiler



1967-1976 all 400, 430 and 455. This modification increases the life of the distributor gear and cam gear - a must since the cam gear is not replaceable. Provides constant supply of oil spray to both gears. Modification requires small hole to be drilled and tapped on the inside of timing chain cover. Oil pressure is not affected. Requires 1/8" pipe tap and 2-1/64 drill bit no supplied in kit. Instructions included.
GO676\$16.50 ea.

Oil Pump Covers

1964-1981 All 225, 300, 340, 350, 430, 455 engines.
1967-1969 400 engines.
OPC646\$79.50 ea.



1974-2009 All 3.8 (231), 4.1 (252) Metric.
OPC749\$79.50 ea.



OC397A



OC397 and OC647



OC684 and OC694

Oil Filler Breather Caps

- 1961-1967** All exc. chrome jobs. Genuine "AC OIL" exact.
 OC397\$26.50 ea.
1961-1967 All except chrome jobs - replacement.
 OC397A\$9.75 ea.
1965 and 1967 GS models with chrome twist on "AC Oil"
 OC647\$31.00 ea.
1968-1972 All (twist on type) replacement.
 OC684\$4.75 ea.
1969-1972 All stage 1 engines. Chrome. Replacement.
 OC694\$9.75 ea.



Oil Pressure Switches (1.800)

- 1961-1966**
1961 All;
1962-1963 All 8 Cylinder;
1964-1966 225, 300, and 340.



- OPS606.....\$11.75 ea.
1962-1972
1962-1963 All 6 Cylinder;
1967 All;
1968-1972 All with 1/4" Thread;
 OPS-620\$13.75 ea.
1965-1966GS. 400 engine
 OPS606\$11.75 ea.
1968-1972
1968 1/8 Thread;
1969-1970 1/8 Thread;
1971-1972 1/8 Thread.
 OPS682\$9.75 ea.
1970-1972 All with gauges
 OPS702.....\$ inquire

PCV Valves



- 1963-1967**
1963 All;
1964-1967 V-6.
 PCV637\$ 6.75 ea.

- 1964-1972** All V8.
 PCV644\$6.75 ea.

PCV Valve Grommet.

- 1963-1972** All.
 VG634.....\$7.75 ea.



PCV Valve hose clamp. All on PCV hose.

- HC660PTOS

Adjustable Oil Pressure Regulator



- 1961-1972** All. Regulate your oil pressure by adjusting tension on relief spring. Allows for safe and easy adjustment externally.
 OPR600\$38.00 ea.

GM Engine Lubricant (E.O.S.)

Genuine GM EOS provides excellent lubrication. Highly recommended. 16 oz.



- EOS300.....\$20.00 ea.

Oil Gaskets

	1962-63 198 V-6	1961-63 215 V-8	1964-67 225 V-6	1964-72 300, 340, 350	1965-66 400	1967-72 400, 455 engines
Oil Pan	OPG623 \$ 10.75 ea.	OPG613 \$ 12.75 ea.	OPG647 \$ 10.75 ea.	OPG645 \$ 10.75 ea.	OPG576 \$ 14.50 ea.	OPG676 \$ 19.00 ea.
Oil Pan Drain Plug	ODG615 \$ 2.25 ea.	ODG-615 \$ 2.25 ea.	ODG615 \$ 2.25 ea.	ODG615 \$ 2.25 ea.	ODG615 \$ 2.25 ea.	ODG675 \$ 2.25 ea.
Rear Main Bearing Set	RMS615 \$ 18.75 set	RMS615 \$ 18.75 set	RMS615 \$ 18.75 set	RMS615 \$ 18.75 set	RMS576* \$ 19.50 set	RMS615 \$ 18.75 set

*RMS576 is the new rubber lip type for easy installation and leak-free seal.