

G67GS

### 1967 Special and GS Grille

(Includes Mounting Studs)

G67GS .....\$527.00 ea.

**1967 GS Grille Emblem.**

GE679G .....\$32.50 ea.

**1968 GS Grille**

G68Gs.....\$499.00 ea.



G69GS

### 1969 GS Grille

G69GS .....\$499.00 ea.

**1969 GS Grille Emblem.**

GEG79G .....\$32.50 ea.



G70GS

### 1970 GS Grille

(Includes Mounting Studs)

G70GS .....\$494.00 ea.

**1970 GS Grille Emblem. "GS by Buick".**

GE70G .....\$39.00 ea.

**1970 GSX Grille Emblem. "GSX by Buick".**

GE70X.....\$77.75 ea.



GE70G



GE70X



GM70

**1970 Grille Surround Molding Set - 3 pieces.**

GM70.....\$159.00 set.

### 1971 GS Grille


G71GS .....\$625.00 ea.

**1971 GS Grille Emblem. "GS by Buick".**

GE71G .....\$38.50 ea.

**1971 GSX Grille Emblem. "GSX by Buick".**

GE71X.....\$77.75 ea.



G71GS

### 1972 Skylark and GS Grille

G72GS.....\$499.00 ea.

**1972 GS Grille Emblem. "GS by Buick".**

GE72G .....\$43.50 ea.

GEP72.....(Backing Plate).....\$9.75 ea.

**1972 GSX Grille Emblem. "GS by Buick".**

GE72X.....\$65.00 ea.

GEP72.....(Backing Plate).....\$9.75 ea.



GE72G



GEP72

# Grilles • Cooling • Oiling (Group 1)

## Grille Emblems (1.303)

**1965 "Gran Sport" Grille Emblem.**  
GE65GS.....\$37.50 ea.



**1966 "Gran Sport" Grille Emblem.**  
GE66GS.....\$43.75 ea.



**1968 "GS" Grille Emblem.**  
GE68GS.....\$25.00 ea.



**1967, 1969 "GS" Grille Emblem.**  
GE679G.....\$32.50 ea.



**1970 "GS By Buick" Grille Emblem.**  
GE70G.....\$39.00 ea.



**1970 "GSX By Buick" Grille Emblem.**  
GE70X.....\$77.75 ea.



**1971 "Skylark By Buick" Grille Emblem.**  
GE71S.....\$43.75 ea.



**1971 "GS By Buick" Grille Emblem.**  
GE71G.....\$38.50 ea.



**1971-1972 "GSX By Buick" Grille Emblem.**  
GE71X.....\$77.75 ea.



**1972 "GS By Buick" Grille Emblem.**  
GE72G.....\$43.50 ea.



**1970-1972 Hood Release Handle.**  
HH702.....\$19.50 ea.



## 1968-1972 Radiator Core Supports, Repair Kits Core Support Mounts and Hardware

**Our 3 piece kit of heavy gauge metal, repairs rusted box and lower panel area.**

**1968-1969 All. Repair for R.H. side.**  
CSK689R.....\$139.00 ea.

**1968-1969 All. Repair for L.H. side.**  
CSK689L.....\$139.00 ea.

**Our 3 piece kit of heavy gauge metal, repairs rusted box and lower panel area.**

**1970-1972 All. Repair for R.H. side.**  
CSK702R.....\$139.00 ea.

**1970-1972 All. Repair for L.H. side.**  
CSK702L.....\$139.00 ea.



**1968-1972 Lower radiator support mount with metal core.**  
3/4" ID. 2 1/2" OD. 1 1/8.  
BM644.....\$8.75 ea.

**1968-1972 Upper radiator core support mount.**  
BM644A.....\$7.50 ea.

**1964-1967 Core support hardware kit.**  
CSK647BK.....\$5.00 ea.

**1968-1972 Core support hardware kit.**  
CSK644BK.....\$5.00 ea.

**1964-1967 Core support mount kit. Lower mounts, 2 upper mounts and hardware.**  
CSK647.....\$38.00



**1970-1972 Complete Core Support**  
CS702.....\$395.00 ea.

**1968-1972 Core support mount kit. Lower mounts, 2 upper mounts and hardware.**  
CSK644.....\$38.00





## Fans

### Clutch Fan Blades

- 1961-1972** 18" Clutch fan blade. Replacement  
 FB626C .....\$67.50 ea.  
**1964-1968** Clutch fan blade. 19" Replacement  
 FB648C .....\$90.25 ea.

### Fan Spacer Kit

- 1969-1972** Fan spacer kit.  
 FSK696 .....\$17.00 ea.

### Fan Clutches (1.050)




- 1964-1972**  
**1964-1967** 225, 300 and 340 engines;  
**1968-1972** 350 engine.  
 FC642 .....\$54.50 ea.  
**1965-1972**  
**1965-1969** 400 engine;  
**1969-1972** 250 engine;  
**1970-1972** 455 engine.  
 FC626 .....\$64.50 ea.

## Fan Shrouds (1.277)

Fiberglass Reproductions



- 1965-1967**  
**1965** 300 engine with crossflow radiator;  
**1966-1967** All 300 and 340 engines.  
 FS657.....\$157.50 ea.  
**1965-1966** GS 400  
 FS656.....\$157.50 ea.  
**1967** Skylark, GS 400  
 FS67.....\$157.50 ea.  
**1968-1969** GS 400  
 FS689.....\$154.50 ea.  
**1970** GS and GSX 455.  
 FS70 (ABS Reproduction).....\$157.50 ea.



## Fan Belts

### Don't Rely On Old Belts!

The price of a new belt is a small fraction of the repair costs a broken belt can cause.

We Stock Hundreds of Different Fan Belts.  
 When Ordering, Please Include:  
 The Model, The Year, Engine Size, and if you have  
 Power Steering? or Air Conditioning?

- Fanbelt - All**  
 FB400.....\$19.75 ea.

ALSO: WHICH BELT ( Fan-Alt., Fan-AC Comp.,  
 Steering Pump-Air Pump, etc. ).

# Cooling • Oiling (Group 1)

## Thermostat ( with Gasket ) (1.246)



**1961-1972** All except 1965-1966 GS.

T330.....(180°)	\$9.75 ea.
T330L.....(160°)	\$9.75 ea.
T330H.....(195°)	\$9.75 ea.
<b>1965-1966 GS</b>	
T536.....(180°)	\$9.75 ea.
T536L.....(160°)	\$9.75 ea.
T536H.....(195°)	\$9.75 ea.

## Thermostat By Pass Hoses



**1962-1972**  
**1962-1967** V-6 engines;  
**1964-1972** 300, 340 and 350 engines.

BP625.....	\$9.75 ea.
<b>1967-1972</b> 400 and 455 engines.	
BP676.....	\$9.75 ea.

## Water Pump Mounting Gaskets



**1961-1972** 198, 215, 225, 300, 340 and 350 engines.

WPG615 .....	\$3.75 ea.
<b>1965-1972</b> 400 engines.	
WPG626 .....	\$3.50 ea.
<b>1967-1972</b> 400 and 455 engines.	
WPG675 .....	\$3.25 ea.

## Temperature Sending Units



**1961-1965** All except 1965 GS - One (1) terminal.

TSU615.....	\$13.75 ea.
<b>1965-1968</b> GS 400 - Two (2) terminals.	
TSU608.....	\$19.75 ea.
<b>1966-1972</b> 300, 340, 350 and 455 engines with lights.	
One (1) terminal.	
TSU662.....	\$12.50 ea.
<b>1970-1972</b> All with gauges.	
TSU702.....	\$19.50 ea.

## Water Pumps (1.069)



**1961-1963** 198, 215 engine w/o ac;  
**1962-1963** all V-6.

WP613.....(exchange item)	\$64.50 ea.
<b>1962-1963</b> all V-6.	
WP613A.....(exchange item)	\$64.50 ea.
<b>1964-1970</b> 225, 300, 340 and 350 engines.	
WP640 .....	\$54.50 ea.
<b>1965-1966</b> 400 engine with A.C. This pump will also fit non - A.C. cars.	
WP626A.....	\$79.50 ea.
<b>1967-1970</b> 400, 455 with A. C.	
WP670 .....	\$80.25 ea.
<b>1971-1972</b> 350 engine.	
WP712S.....	\$47.50 ea.
<b>1967-1972</b> 400, 455 without A.C.	
WP672 .....	\$57.25 ea.
<b>1971-1972</b> 455 engines with A.C.	
WP716 .....	\$56.75 ea.

## Water Outlets



**1961-1972**  
 1961 thru 1972 all except 1965 and 1966 GS.400.

WO615 .....	\$24.50 ea.
<b>1965-1966</b> 400 engine.	
WO626.....	\$22.25 ea.



## Water Manifold Gasket Kit



**1961-1966** All 400, 401. Includes 2 gaskets and "O" ring.

WMK536.....	\$9.00 ea.
-------------	------------

## Water Outlet Gasket

**1961-1972** All.


WOG615.....	\$2.25 ea.
-------------	------------



## Crankcase Vent Hose (To Carb)

**1972** All 350 and 455 with 4BBL Carb. (Formed hose).


VH725 .....	\$20.25 ea.
-------------	-------------





### Radiators


- 1968-1972** Skylark and GS with manual transmission. 4 core. Concours correct.  
 R682M .....\$729.00 ea.
- 1968-1972** Skylark and GS with automatic transmission. 4 core. Concours correct.  
 R682A .....\$729.00 ea.


### Radiator Insulators


- 1962** all 2nd type; Lower.   
**1963** All. Lower. RI623S .....\$16.00 ea.

- 1962** all 2nd type; Upper. 2 per car.  
**1963-1964** All. Upper. 1 per car.  
**1965** All with downflow radiator. 2 per car.  
 RI625S.....\$17.50 ea.
- 

- 1965** All with cross-flow radiator;  
**1966** All.  
 RI656.....\$30.00 pr.
- 

- 1965** GS;  
**1966** All.  
 RI656B .....\$30.75 pr.
- 

- 1968-1972** All with 3 core radiators. Set of 4. (1970 cars compare with RI690 below).  
 RI682S.....\$64.25 set
- 

- 1970** Some with 3 core radiator. 2 pair used per car. Compare with RI682S.  
 RI690.....\$35.50 pr.
- 

### 4-Core Radiator Insulators



Correct replacement for 4-core radiators. All years as required.  
 RI600 .....\$15.50 pr.

### Radiator Caps



Take a good look at these caps. They are identical to the originals. Correct in every detail, they feature the cap number, instructions and of course genuine "AC" identification stamped right into the zinc plated surface. Show quality, approved and licensed by Buick.

- 1961-1964** All. 15 lb.  
 RC15D .....\$32.50 ea.
- 1965-1968** All. 15 lb.  
 RC15F .....\$32.50 ea.
- 1969-1970** All w/o coolant recovery sys. 15 lb.  
 RC15H .....\$32.50 ea.
- 1970-1972** All with coolant recovery sys. 15 lb.  
 RC29 .....(plate has scalloped edge).....\$29.75 ea.
- 1970-1972** All with coolant recovery sys. 15 lb.  
 RC29S .....(plate has smooth edge).....\$29.75 ea.
- 1961-1969** All. 15 lb.  
 RC579.....\$16.50 ea.
- 1970-1972** All.  
 RC706.....\$9.75 ea.

### Radiator Overflow Hose



Correct "Ribbed" Hose sold in 3 1/2' length. All years as required.  
 OH600 .....\$13.50 ea.












Cars Inc., recognized leader in Buick Parts and Service since 1973

# Cooling (Group 1)

## Radiator Hoses

We Can Supply Almost Any Model/Year Check, NOS Section Also! **Please Inquire.**

	<b>1961</b> All V8, Lower. RH369.....\$19.50 ea.
	<b>1962</b> V6 ( Radiator 126 or 127 ), Lower. RH509.....\$19.50 ea.
	<b>1962</b> V8 ( Radiator 121 or 143 ), Lower. RH369.....\$19.50 ea.
	<b>1962-1963</b> V6, Upper. UH623.....\$22.50 ea.
	<b>1964-1965</b> Upper. <b>1964:</b> V6; <b>1965:</b> V6 ( Down Flow ) RH392.....\$19.50 ea.
	<b>1965</b> 8 cyl without AC ( Down Flow ), Upper. RH439.....\$17.75 ea.
	<b>1965</b> 8 cyl with AC, Upper. RH755.....\$22.25 ea.
	<b>1965-1968</b> Lower. <b>1965:</b> 8 cylinder ( X-Flow ); <b>1966:</b> 300, without AC, with AP; <b>1967-1968</b> All 300, 340, 400. RH742.....\$22.50 ea.
	<b>1966-1967</b> Upper. <b>1966 -1967</b> All 340 RH485.....\$23.50 ea.
	<b>1966-1967</b> Lower. <b>1966:</b> Special, with AC; <b>1967:</b> 340 ( Exc. SP ), without AC; RH512.....\$22.50 ea.
	<b>1967</b> 340 ( Exc. SP ), without AC, Upper. RH533.....\$22.25 ea.
	<b>1968-1970</b> Upper. <b>1968</b> All 350 and 400; <b>1969-1970:</b> 350 ( Special and Skylark); <b>1969:</b> 400 ( GS, Sportwagon ); <b>1970:</b> 455 ( GS ). RH980.....\$22.25 ea.
	<b>1969-1972</b> All Skylark/GS, 350, 400 and 455, Lower. RH597.....\$24.50 ea.
	<b>1969-1972</b> Upper. <b>1969-1970</b> All GS350; <b>1971</b> All 455; <b>1972:</b> All GS-350. RH715.....\$22.50 ea.
	<b>1971-1972</b> Upper. <b>1971</b> All 350; <b>1972</b> All exc. GS350. RH869.....\$22.50 ea.

## Radiator Hose Support



**1969-1970** All GS.  
HS690.....\$ 24.75 ea.

## Radiator Overflow Reservoir



1970 through 1972 models. Note that 1970 early models came with a clear top. Later 1970 models and all 1971-1972 models had Black tops. This is a fine reproduction with correct embossed letters and numbers, made a bit more sturdy than the original.

OR702B.....Black Top.....\$149.00 ea.  
OR702C.....Clear Top.....\$149.00 ea.

## Radiator Hose Clamps

**ORIGINAL EQUIPMENT  
" TOWER TOP " HOSE CLAMP**



*Authentic reproduction of "Tower Top" Hose clamps made by the Wittek Company for GM. They are correct for all 1961-1972 models.*

RC134....1 3/4"	.....\$ 2.75 ea.
RC200....2"	.....\$ 2.75 ea.
RC216....2 1/16" Diameter fits most upper hoses ..	\$ 2.75 ea.
RC214....2 1/4" Diameter fits most lower hoses ..	\$ 2.75 ea.
RC250....2 1/2"	.....\$ 2.75 ea.
RC2516..2 5/16"	.....\$ 2.75 ea.
RC400....4"	.....\$ 4.00 ea.




## Heater Hose

3/4" All years. HH34 .....	\$1.00 ft.
3/4" All years: 50 ft. HH3450 .....	\$39.00
5/8" All years. HH58 .....	\$1.00 ft.
5/8" All years: 50 ft. HH5850 .....	\$39.00

## Breather Tubes (Air Cleaner to Rocker Cover) (1.745)

### Breather Tube



<b>1968-1969</b> All 350 and 400 4BBL. VT689 .....	\$19.50 ea.
---	-------------



<b>1970-1971</b> all V-8; <b>1972</b> all 455 engines VT704 .....	\$16.50 ea.
--	-------------



## Crankcase Vent Hose (To Carb) (1.746)

<b>1972</b> All 350 and 455 with 4BBL Carb. ( Formed Hosed ). VH725 .....	\$20.25 ea.
---	-------------



## Tower Top Heater Hose Clamps



"Tower Top"

Buick used "Tower Top" hose clamps on all cars from 1961-1972. We supply the identical clamps made by the Wittek Company. They are authentic and correct.

1 1/16" for 5/8" heater hose. HC580 .....	\$2.75 ea.
1" for use on thin walled 5/8" hose. HC580S .....	\$2.75 ea.
1 1/4" for 3/4" heater hose. HC340 .....	\$2.75 ea.
1 3/16" for use on thin walled 3/4" hose. HC340S .....	\$2.75 ea.

## Wire Hose Clamps



<b>For 9/16" diameter hose.</b>	
HC916W .....	\$ 1.00 ea.
HC916WP .....	(5 Pack) ..... \$ 3.25 ea.
<b>For 5/8" diameter hose.</b>	
HC580W .....	\$ 0.75 ea.
<b>For 3/4" diameter hose.</b>	
HC340W .....	\$ 0.75 ea.
HC340WP .....	(5 Pack) ..... \$ 3.25 ea.
<b>For 13/16" diameter hose.</b>	
HC1316W .....	\$ 1.00 ea.
HC1316WP .....	(5 Pack) ..... \$ 4.25 ea.
<b>For 15/16" diameter hose.</b>	
HC1516W .....	\$ 0.75 ea.
HC1516WP .....	(5 Pack) ..... \$ 4.25 ea.
<b>For 1" diameter hose.</b>	
HC100W .....	TOS
HC100WP .....	(5 Pack) ..... \$ 4.25 ea.
<b>For 1-1/4" diameter hose.</b>	
HC114W .....	\$ 1.00 ea.
HC114WP .....	(5 Pack) ..... \$ 5.00 ea.
<b>For 2" diameter hose.</b>	
HC200W .....	\$ 2.75 ea.
HC200WP .....	(5 Pack) ..... \$12.25 ea.

**Fax Us  
Your Order  
Save Time!**

When sending us a long order  
it is easier to just fax it.

**908-369-7595**

# Cooling • Oiling (Group 1)

## Oil Filters



**1961-1966** All. (Also fits thru 1980 where there is room for taller filter). PF-7 type.  
OF596 .....\$9.75 ea.

**1967-1980** All exc. V-6 and 260 engines.  
PF-24 type.  
OF670 .....\$9.75 ea.

## PF-24 Oil Filters



A brand new quality reproduction on the original 1967-1975 red, white, and blue, AC TYPE PF-24 oil filter with logo and proper coloring. A must for the concours restorer.  
OF590AC .....\$22.25 ea.

## Oil Pan



**1969-1970** all 400, 430, 455 engines;  
**1971-1976** all 455 engines.  
Not for factory exhaust crossover systems. Powder coated.  
OP676 .....\$165.00 ea.

## Oil Pan Drain Plug and Gasket Kit

**1961-1976** Oil pan drain plug and gasket. 1/2" x 20" thread.  
OP595 .....\$5.50 kit

## Oil Pick-up Tube and Screen



**1964-1968** all 225, 300, 340, 350 engines. Has 5/8" tube. Requires passage drilled to 5/8".  
OPU647 .....\$24.50 ea.

**1965-1966** GS 400, 401, 425 engine. Stock size.  
OPU626 .....\$155.00 ea.

**1967-1976** 400,455 w/ rear sump. (Increased oil pick-up over stock 1/2" tube. Gives 5-10 psi oil pressure increase. 1967-1970 engines require that pick-up passage drilled to 5/8". Acts as replacement for 1970 Stage 1 and all 1971-1976 455 engines).  
OPU676R .....\$69.75 ea.

**1967-1976** 400, 430, 455 w. center sump. 5/8" tube. Requires passage to be drilled to 5/8".  
OPU676C .....\$74.50 ea.

**1969-1981** 350 engine. Stock size.  
OPU695 .....\$20.00 ea.

**1969-1981** all 350. Has 5/8" tube requiring windage tray to be removed or trimmed.  
OPU691 .....\$29.75 ea.



## Oil Pumps (1.652)

**1965-1966** 400 engines.  
OP626 .....\$107.00 ea.

## Oil Pump Kits (1.652)

**1961-1963** 215 engine.  
OPK613 .....\$39.00 kit

**1964-1981** All 225, 300, 340, 350 engines.  
OPK642 .....\$33.75 kit  
OPK642H.....(High Volume Kit) .....\$45.50 kit


**1965-1966** All 400, 401 engines.  
OPK626 .....\$47.50 kit



**1967-1976** All 400, 430, 455 engines.  
OPK676 .....\$32.25 kit  
OPK656H....(High Volume Kit).....\$59.25 kit

## Oil Pump Thrust Plate Repair Kit

This kit provides a NEW WEARING Surface for badly scored or worn cover housing. Kit contains all necessary screws, gaskets and instructions.



**1961-1981** all 215, 225, 300, 340, 350, 455 engines.  
OPK685 .....\$21.00 ea.

## Distributor Gear Oiler



**1967-1976** all 400, 430 and 455. This modification increases the life of the distributor gear and cam gear - a must since the cam gear is not replaceable. Provides constant supply of oil spray to both gears. Modification requires small hole to be drilled and tapped on the inside of timing chain cover. Oil pressure is not affected. Requires 1/8" pipe tap and 2-1/64 drill bit no supplied in kit. Instructions included.  
GO676 .....\$16.50 ea.



www.oldbuickparts.com

908-369-3666





OC397A



OC397 and OC647



OC684 and OC694

### Oil Filler Breather Caps

- 1961-1967** All exc. chrome jobs. Genuine "AC OIL" exact.  
 OC397 .....\$26.50 ea.  
**1961-1967** All except chrome jobs - replacement.  
 OC397A .....\$9.75 ea.  
**1965 and 1967** GS models with chrome twist on "AC Oil"  
 OC647 .....\$31.00 ea.  
**1968-1972** All (twist on type) replacement.  
 OC684 .....\$4.75 ea.  
**1969-1972** All stage 1 engines. Chrome. Replacement.  
 OC694 .....\$9.75 ea.



### Oil Pressure Switches (1.800)

- 1961-1966**  
**1961** All;  
**1962-1963** All 8 Cylinder;  
**1964-1966** 225, 300, and 340.



- OPS606.....\$11.75 ea.  
**1962-1972**  
**1962-1963** All 6 Cylinder;  
**1967** All;  
**1968-1972** All with 1/4" Thread;  
 OPS-620 .....\$13.75 ea.  
**1965-1966**GS. 400 engine  
 OPS606 .....\$11.75 ea.  
**1968-1972**  
**1968** 1/8 Thread;  
**1969-1970** 1/8 Thread;  
**1971-1972** 1/8 Thread.  
 OPS682 .....\$9.75 ea.  
**1970-1972** All with gauges  
 OPS702.....\$ inquire

### PCV Valves



- 1963-1967**  
**1963** All;  
**1964-1967** V-6.  
 PCV637 .....\$ 6.75 ea.

- 1964-1972** All V8.  
 PCV644 .....\$6.75 ea.

PCV Valve Grommet.

- 1963-1972** All.  
 VG634.....\$7.75 ea.



PCV Valve hose clamp. All on PCV hose.

- HC660P .....TOS

### Adjustable Oil Pressure Regulator



- 1961-1972** All. Regulate your oil pressure by adjusting tension on relief spring. Allows for safe and easy adjustment externally.  
 OPR600 .....\$38.00 ea.

### GM Engine Lubricant (E.O.S.)

Genuine GM EOS provides excellent lubrication. Highly recommended. 16 oz.



- EOS300.....\$20.00 ea.

### Oil Gaskets

	1962-63 198 V-6	1961-63 215 V-8	1964-67 225 V-6	1964-72 300, 340, 350	1965-66 400	1967-72 400, 455 engines
<b>Oil Pan</b>	OPG623 \$ 10.75 ea.	OPG613 \$ 12.75 ea.	OPG647 \$ 10.75 ea.	OPG645 \$ 10.75 ea.	OPG576 \$ 14.50 ea.	OPG676 \$ 19.00 ea.
<b>Oil Pan Drain Plug</b>	ODG615 \$ 2.25 ea.	ODG-615 \$ 2.25 ea.	ODG615 \$ 2.25 ea.	ODG615 \$ 2.25 ea.	ODG615 \$ 2.25 ea.	ODG675 \$ 2.25 ea.
<b>Rear Main Bearing Set</b>	RMS615 \$ 18.75 set	RMS615 \$ 18.75 set	RMS615 \$ 18.75 set	RMS615 \$ 18.75 set	RMS576* \$ 19.50 set	RMS615 \$ 18.75 set

\*RMS576 is the new rubber lip type for easy installation and leak-free seal.