

Heater • Air Conditioning • Firewall • Radio • Antenna (Group 9)

Firewall/Cowl Seals and Parts



1964-1967 All. Hood to cowl rubber seal.
CS647.....\$17.00 ea.



1964-1967 All. cowl grill side seals.
Necessary to keep water out of interior
of car. Don't overlook these. (12.800)
CS647S.....\$9.50 pr.



1968-1972 All. Hood to cowl rubber
sealing strip.
CS682.....\$14.25 ea.



1968-1972 All. Cowl vent screen. Die cut,
dipped and powder coated.
CS682A.....\$30.25 ea.



1968-1972 All. cowl vent screen "H"
Retainers. 5 per car.
CSR682.....\$4.00 ea.
CSR682S.....(set of 5).....\$17.00 set.


1968-1972 Hood lace and cowl lace.

Plastic retainer.

LR685\$ 1.00 ea.



Firewall Insulator Pads



1964-1967 Firewall insulation pad (15.280).

FP647\$39.50 ea.

1968-1972 Firewall insulation pad. For cars w/o a.c.

FP682\$29.50 ea.

1968-1972 Firewall insulation pad. For cars with a.c.

FP682AC\$38.50 ea.

Firewall insulator retainers.

1968 thru 1972 all as required.

IR500.....\$1.75 ea.



1961-1967 firewall grommet for heater
blower wire. Cars w/o a.c.
FWG577\$6.75 ea.



1968-1972 Center firewall grommet. 3 holes
for ac cars.
FWG682A.....\$12.00 ea.

Dash Rallye Pack Gauges

New reproduction includes fuel, temp and oil gauges. This
quality made item fits all 1970 -1972 models. Comes with flat
or convex lens and instructions. Fully tested and calibrated.

RP702.....(Convex Lens).....\$236.50 ea.

RP702F.....(Flat Lens).....\$236.50 ea.



Dash Tachometers (9.750)

T702F.....(Flat Lens).....\$196.50 ea.

T702C.....(Convex Lens).....\$196.50 ea.



Hood Tachometers

T702H...(Lit numbers and pointer)....\$228.50 ea.

WH702T..(wiring harness for above)..\$33.50 ea.

Dash Instrument Lenses

1970 all late;

1971-1972 All. Flat lens.

IL702.....\$18.00 ea.

Antenna Chrome Bases (9.618)

1961-1963 all. Chrome "nut". (9.618)

AN544.....\$15.00 ea.

AG403.....(grommet for above).....\$3.75 ea.



1964-1965 all with manual antenna.

AB645.....\$18.75 ea.

Antenna Lead

1970-1972 Antenna lead in for windshield antennas.

AL708\$20.00 ea.

Radio Bezels



1968-1972 All. Chrome plated so it is correct as is for 1970-
1972 models. 1968-1969 were painted silver so you can
paint or leave as is. Does not come with woodgrain.

RP682\$68.50 ea.



1970-1972 All. Plastic Dash Bezel.

DB702.....\$367.50 ea.



Heater Blower Motor


1964-1972 All.
HBM646.....\$39.75 ea.



Heater Control Valve

1965-1972 Heater control valve.
1965 All;
1966 All with A.C.;
1969-1972 All A.C.
HV652\$41.00 ea.

Heater Control Valve Insulator



1969-1974 All with A.C.
V1694.....\$17.00 ea.

Heater Control Valve Repair

1961-1963 Ranco type. 9.795
HV420.....\$153.50 ea.



Heater Cores

1964-1967 all w/o A.C.
HC644.....\$90.25 ea.
1964-1967 All with A.C.
HC647A\$96.00 ea.
1968 thru 1972 all w/o A.C.
HC682.....\$54.00 ea.
1968-1972 all with A.C.
HC682A\$48.50 ea.

Compressor with Clutch Remanufactured by Delco

1964-1977 All 6cyl type as pictured.
Delco remanuf.
AC627 Single pulley.....\$349.00 ea.
AC627D Dual pulley.....\$391.00 ea.



A.C. Evaporator Thermo Expansion Valve

1965-1972 A.C. evaporator thermo expansion valve. (POA)
EV653.....\$29.50 ea.



A.C. Refrigerant for R-12 and 134-a



6 oz. standard can. Includes red dye for leak detection. A drop-in replacement for CFC-12 and HFC-134a. No system evacuation needed. Up to 30% more efficient than CFC-12 and far more efficient than HFC-134a.

ACR360.....\$10.00 ea.



1971-1977 A.C. Compressor thermal limiter switch.
TL717.....\$11.75 ea.

Air Conditioning Blower Relay

1969-1972 All.
ACR656.....\$22.25 ea.



908-369-3666