

Heater, Air Conditioning, Firewall, Radio and Antenna (Group 9)


Firewall/Cowl Seals & Parts

1964-1967 All. Hood to Cowl Rubber Seal
CS-647\$16.50 ea.



1964-1967 All. Cowl Grill Side Seals. Necessary to keep water out of interior of car. Don't overlook these. (12.800)

CS-647S.....\$7.75 pr.



1968-1972 All. Hood to Cowl Rubber Sealing Strip.
CS-682\$12.75 ea.

1968-1972 All. Cowl Vent Screen. Die cut, dipped & powder coated.
CS-682A\$29.50 ea.

1968-1972 All. Cowl Vent Screen "H" Retainers. 5 per car.
CSR-682\$3.75 ea.
CSR-682S.....(set of 5)\$16.50 set.



1968-1972 Hood Lace & Cowl Lace. Plastic retainer.
LR-685\$ 1.00 ea.

Firewall Insulators

1964-1967 Firewall Insulation Pad (15.280)
FP-647.....\$84.50 ea.

1968-1972 Firewall Insulation Pad. For cars w/o a.c.
FP-682.....\$59.50 ea.

1968-1972 Firewall Insulation Pad. For cars with a.c.
FP-682AC\$59.50 ea.

Firewall Insulator Retainers.

1968 thru 1972 all as required.
IR-500.....\$1.50 ea.



1961-1967 firewall grommet for heater blower wire. Cars w/o a.c.
FWG-577\$4.50 ea.



1968-1972 Center Firewall Grommet. 3 holes for ac cars.



FG-682A\$12.00 ea.

Dash Rallye Pack Gauges

New Reproduction includes Fuel, Temp and Oil gauges. This quality made item fits all 1970-1972 models. Comes with flat or convex lens and instructions. Fully tested and calibrated.

RP-702.....(Convex Lens).....\$239.00 ea.

RP-702F.....(Flat Lens).....\$239.00 ea.

Dash Tachometers (9.750)

T-702F.....(Flat Lens).....\$165.00 ea.

T-702C.....(Convex Lens).....\$165.00 ea.

1970-1972 Dash Instrument Lenses

1970 all late;

1971-1972 All. Flat lense

IL-702\$19.50 ea.

Antenna Masts (9.647)

1964-1965 All

AM-645.....\$49.00 ea.

1966-1967 All.

AM-667.....\$46.75 ea.

1968-1969 All 3 section type.

AM-689.....\$46.75 ea.



Antenna Chrome Bases (9.618)

1961-1963 all. Chrome "nut". (9.618)

AN-544\$14.75 ea.

AG-403.....(grommet for above).....\$4.75 ea.

1964-1965 all with manual antenna.

AB-645\$18.25 ea.

1966-1967 all with manual antenna.

AB-667\$21.50 ea.

Antenna Lead

1970-1972 Antenna lead in for Windshield antennas


AL-708\$19.50 ea.

Heater, Air Conditioning, (Group 9)

Heater Blower Motor

1964-1972 All.

HBM-646.....\$35.75 ea.




Heater Control Valve Repair

1961 thru 1963. Ranco Type. 9.795

HV-420.....\$125.00 ea.


A.C. Refrigerant for R-12 and 134-a



5 oz. standard can. Includes red dye for leak detection.

ACR-360.....\$8.99 ea.

Heater Cores



1964-1967 all w/o A.C.

HC-644.....\$69.75 ea.

1964-1967 All with A.C.

HC-647A.....\$80.50 ea.

1968 thru 1972 all w/o A.C.

HC-682.....\$69.75 ea.

1968 thru 1972 all with A.C.

HC-682A.....\$69.75 ea.

1971-1977 A.C. Compressor Thermal Limiter Switch

TL-717\$11.50 ea.

Compressor with clutch. Remanufactured by Delco

1964 thru 1977 all 6cyl type as pictured. Delco remanuf.



AC-627 Single Pulley.....\$269.00 ea.


AC-627D Dual Pulley.....\$269.00 ea.

1968-1972 A.C. evaporator core

EC-682.....\$189.50 ea.

1965-1972 A.C. evaporator thermo expansion valve. (POA)

EV-653.....\$54.50 ea.



1965-1972 Heater Valve.



1965 All;

1966 All with A.C.;

1969-1972 All A.C.

HV-652\$29.25 ea.

AC Compressor Bracket (9.171)

1965-1966 All nail head eng. with aluminum valve covers

CB-566.....\$37.50 ea.