

### Carburetor Rebuilding and Restoration Service (3.725)


Each carburetor is totally disassembled and cleaned in a hot tank solution. Then, each component is correctly plated, painted and colored to duplicate it's original factory finish. The carburetor is reassembled using all proper gaskets, pumps, needles and seats, etc. and new correct screws. Finally, all bench adjustments are made to factory specs. This includes correct shimming of the start switch. The result, the best rebuilt and restored carburetor available in the Hobby Allow about 4 weeks.

**NOTE:** *This is not an area to skimp on your restoration. Demand the best!*

- 1932-1938** Marvel Carburetors.  
CRS328M.....\$425.00 ea.
- 1935-1936** Stromberg Carburetors.  
CRS356.....\$390.00 ea.
- 1937-1938** Stromberg Carburetors.  
CRS378.....without choke.....\$325.00 ea.  
CRS378C.....with choke.....\$345.00 ea.
- 1939-1948** All with Diaphragm type starter switch.  
CRS398.....\$355.00 ea.
- 1939-1960** All 2bbl Carburetors w/ Bakelite switch.  
CRS390.....\$329.00 ea.
- 1952-1960** 4bbl. Carburetor rebuilding service.  
CRS520.....\$389.00 ea.

Others by inspection and quotation

### Carter Carburetor Rebuilding Kits



- 1936-1940** All models. WDO 2 BBL.  
Numbers: 419, 440, 448, 474.  
CKC360.....\$42.75 ea.
- 1941-1942** All 40-90. WCD 2BBL.  
Numbers: 487, 549, 551.  
CKC412.....\$42.75 ea.
- 1941-1942** Dual Carbs. WCD 2 BBL.  
Numbers: 528, 529, 533, 534, 543, 544. For both kits.  
CKC412D.....\$58.50 ea.
- 1946-1949** Models 40-50-70. WCD 2 BBL. Numbers: 608, 609, 663, 664.  
CKC469.....\$41.50 ea.
- 1950-1955**  
**1950-1951:** Roadmaster. WCD 2 BBL. Numbers: 725, 726, 882, 883, 2017, 2081, 2179.  
**1950-1955:** Models 40-50. WCD 2 BBL. Numbers: 725, 726, 882, 883, 2017, 2081.  
CKC505.....\$41.50 ea.  
CKC505A.....(#2179 only).....\$41.50 ea.
- 1952-1953** Roadmaster. WCFB 4 BBL.  
Numbers 894, 996, 2053, 2083.  
CKC523.....\$44.75 ea.
- 1954-1956** Super and Skylark WCFB 4 BBL.  
Numbers: 2082, 2197, 2347, 2358.  
CKC546.....\$42.75 ea.
- 1955-1960** Special and LeSabre. WGD 2 BBL.  
Numbers: 2292, 2378, 2400, 2536, 2529, 2548, 2674, 2675, 2682, 2837, 2838, 2845, 2979, 2980.  
CKC550.....\$42.75 ea.
- 1957-1960** All AFB 4 BBL.  
Numbers: 2507, 2800, 2840, 2877, 2981, 2982.  
CKC570.....\$42.75 ea.



CKC546



## Remember!

**Check to see that the carburetor number matches that of the part you are ordering. Any letters after the main number are also included in our kits.**

**Carter** numbers after 1937 are stamped on the bottom of the throttle body.

**Stromberg** numbers from 1939 are stamped on the top bowl cover.

# Fuel • Carburetion • Exhaust (Group 3)

## Rochester Carburetor Kits

- 1955** All models. 4 GC 4 BBL.  
Numbers: 7006200, 7009100.  
CKR55.....\$41.50 ea.
- 1956** All models. 4 GC 4 BBL.  
Numbers: 7009200.  
CKR56.....\$41.50 ea.
- 1957-1958** All models. 4 GC 4 BBL.  
Numbers: 7010070, 7011570, 7011600.  
CKR578.....\$41.50 ea.
- 1958 Late** All models. 4 GC 4 BBL.  
Numbers: 7013100.  
CKR58.....\$41.50 ea.
- 1959-1960** All 4 GC 4 BBL. Numbers: 7013044, 7015040, 7019040, 7020040, 7020041.  
CKR592.....\$41.50 ea.

## Stromberg Carburetor Kits

- 1934-1936** Model 40. EE-1, 2 BBL.  
Numbers: 7-1, 7-2, 7-4, 7-5, 7-7, 7-9.  
CKS346.....\$57.50 ea.
- 1936** 60-80-90. EE-22,2 BBL.  
Numbers: 7-6, 7-8, 7-10.  
CKS36.....\$44.50 ea.
- 1937-1949** 40-50. AA 2 BBL.  
Numbers: 7-12, 7-17, 7-19, 7-24, 7-31, 7-32, 7-66, 7-69, 7-74, 7-75, 7-79, 7-81, 7-82,  
CKS379.....\$49.50 ea.
- 1937-1955**  
1937-1951: 60-70-80-90. AA 2 BBL.  
Numbers: 7-13, 7-15, 7-18, 7-20, 7-22, 7-23, 7-33, 7-34, 7-36.  
1953-1955: Special and Super. AA 2 BBL.  
Numbers: 7-57, 7-70, 7-77, 7-80, 7-89, 7-91, 7-95, 7-96, 7-102, 380150.  
CKS375.....\$49.50 ea.
- 1941-1942** All with Dual Carbs. AA 2 BBL.  
Numbers: 7-39, 41, 42, 43, 44, 45, 46, 47, 55, 59 and 60. Contains parts for both carbs.  
CKS412D.....\$64.50 ea.
- 1950-1953**  
**1950-1952:** Special and Super. AA 2 BBL.  
Numbers: 7-88, 7-90.  
**1953:** Special. AA 2 BBL. Numbers: 7-88, 7-90.  
CKS503.....\$47.50 ea.
- 1952-1954** Roadmaster and Skylark. 4A 4 BBL.  
Numbers: 7-92, 7-94, 7-98.  
CKS524.....\$54.50 ea.
- 1955-1956** Special. WW 2 BBL.  
Numbers: 7-103, 7-104, 7-105.  
CKS556.....\$57.50 ea.
- 1957** Special with Dynaflo. WW 2 BBL.  
Numbers: 7-106.  
CKS57.....\$57.50 ea.
- 1958-1960** Special and LeSabre. WW 2 BBL.  
Numbers: 7-109, 7-112, 7-113.  
CKS580.....\$59.50 ea.

## Carburetor Bowl Floats










- 1934-1936** Stromberg EE1. Brass.  
CF346S.....\$39.50 ea.
- 1936-1940** Carter WDO. Brass.  
CF360C.....\$37.50 ea.
- 1937-1953** Stromberg AA 2BBL. Brass.  
CF373S.....\$48.00 ea.
- 1941-1955** Carter WCD. Brass.  
CF415C.....\$47.50 ea.
- 1955-1956** Rochester 4GC. Brass. (2 needed per car)  
CF556R.....\$42.75 ea.
- 1955-1961** Stromberg WW. Plastic.  
CF551S.....\$37.50 ea.
- 1957-1960** Carter AFB 4BBL. Brass.(2 needed per car)  
CF577C.....\$34.50 ea.

## Fuel Bowl Gaskets



- 1936-1940** Special & Super. Fuel bowl gasket.  
BG2002.....\$2.25 ea.
- 1941-1953** All straight. Fuel bowl gasket.  
BG2088.....\$2.25 ea.

## Carburetor to Intake Manifold Gaskets

- 1935-1939** Special;  
**1940-1949** Special and Super.  
Use 2 on dual carb set-ups.
-  CMG359  
 CI3
- CMG359.....\$3.75 ea.  
CI3.....(Thick Insulator).....\$14.75 ea.
- 1936-1949** All 320 engines;  
**1950-1952** Special and Super;  
**1953** Special;  
**1954-1955** All 2bbl carbs.
-  CMG395  
 CI4
- CMG395.....\$3.75 ea.  
CI4.....(Thick Insulator).....\$14.25 ea.
- 1953** Roadmaster;  
**1954** Century, Roadmaster, Skylark;  
**1955-1956** Century, Super, Roadmaster  
For 4bbl carbs.
-  CMG536.....\$4.25 ea.
-  **1955** Late Carter and Rochester 2bbl;  
**1956-1960** All carter and Rochester 2bbl.  
CMG554.....\$4.50 ea.
-  **1957-1960** All 4bbl.  
CMG576.....\$4.75 ea.

### Carter Baffle Plates



Stainless steel plate between carb. and intake manifold. This plate is essential for protection against disintegration of aluminum base of carb. It is also necessary for proper idle and smooth running.



**1954-1956** All with 4bbl. carbs.  
BP546 .....\$15.25 ea.  
**1957-1960** All with Carter AFB 4bbl.  
BP576 .....\$16.25 ea.

### Linkage Rod Clips



**1946-1960** Carburetor throttle rod clip. 1/4" rod diameter.  
RC460.....\$0.75 ea.

### Linkage Rod Bushing



Carburetor throttle rod bushing and grommet. 1/4" rod diameter.  
RB460.....\$6.00 ea.

### Carburetor Dash Pots



**1954-1956** All. (3.440)  
DP546.....\$18.25 ea.  
**1957-1960** All.  
DP573 .....\$18.25 ea.

### Choke Stove Pipe Replacement Kits (3.545)




**1935-1953 all Straight-8 engines.**  
All as required. Includes PI300.  
CSK350.....\$15.50 kit  
**1935-1960 all V-8 engines.**  
All as required. Includes PI300.  
CSK530.....\$18.25 kit


### Choke Stove Pipe Insulator



This modern aramid fiber sleeve greatly resembles the original. It is heat resistant up to 650°F. Also, excellent for wrapping vapor locked fuel lines. Sold by the foot. All years.  
PI300 .....\$5.25 ft.

### Accelerator Return Springs (3.459)

**1939-1947** All except dual carburetor set-up.   
AS397.....( stainless steel ).....\$7.50 ea.

**1948-1956** Accelerator return spring.  
**1948-1952:** All;  
**1953:** Specials;  
**1955-1956** All.   
AS483.....( stainless steel ).....\$7.00 ea.


### Gas Filters



**1957-1960** Gas filter replacement element.  
GF572.....\$7.50 ea.

**1957-1960** AC replacement. Gas filter assembly with element.  
GF572A.....\$29.50 ea.



**All years** replacement. Clear in-line gas filter. Great for near gas tank or frame installation. Important for insuring clean fuel to fuel pump.   
GF100.....\$4.50 ea.

### In Line Gas Filters



GF140.....For 1/4" ID Hose.....\$9.25 ea.

GF516.....For 5/16" IDHose.....\$9.25 ea.



GF516C..For 5/16" ID Hose(clear)..\$6.50 ea.

GF380.....For 3/8" ID Hose.....\$9.25 ea.




### Carburetor to Air Cleaner Gaskets



**1953-1960** All 2bbl carbs.  
ACG535 .....\$3.50 ea.  
**1952-1956** All Carter and Stromberg 4bbl;  
**1957-1960** All 4bbl Carburetors.  
ACG526 .....\$3.50 ea.

### Air Filters (3.416)

**1958-1960**  
**1958:** All;  
**1959-1960:** with 4 bbl. carb., air filter.   
AF582.....\$15.50 ea.  
**1959** All with 2 bbl. carburetor, air filter.  
AF59.....\$14.50 ea.  
**1960** All with 2 bbl. carburetor, air filter.  
AF607 .....\$15.00 ea.

### Air Cleaner Wing Nut (3.920)

**1953-1960** Replacement air cleaner wing nut.  
WN530 .....\$1.75 ea.

## Intake Manifold Gaskets

1936-1953

1936-1953: Straight-8

(See Exhaust Manifold Gaskets);



1953-1956: All V-8.

IMG536 .....\$13.25 pr.

1957-1960

IMG576 .....\$11.75 pr.

## Intake Manifold Pilots

1934-1953

1934-1939: Specials;

1940-1952: Special and Super;

1953: Special.



MP253 .....\$2.50 ea.

1931-1952

1931-1935: Series 60;

1936-1939: Series 60, 80, 90;

1940-1952: Series 60, 70, 80, 90 (For 320 Engines).

MP312 .....\$2.50 ea.

## Intake Manifold/Carburetor Studs

1935-1949:

1935-1942 Special;

1937 Series 60, 80, 90;

1941-1942 All with dual carbs. front carb;

1942-1949 All with single carb.

S13 .....\$3.75 ea.

## Intake Manifold Plugs

This plug is often rusted out and sometimes missing.

Leakage around this plug causes poor carburetion.

1957-1960

1957-1958: All;

1959-1960: LeSabre with 2bbl carburetor.

MP579 .....\$11.50 ea.



1959-1960: All with 4-bbl. carburetor.

MP596 .....\$12.75 ea.



1955-1956: All manifold plug gasket.

BG3780 .....\$4.75 ea.

## Exhaust Manifold French Locks

The best restoration can be ruined by rust spreading from original unsightly locks to your engine block and manifolds. We made these from lifetime rust-free **stainless steel**.

1953-1956 All V-8.


FL536 .....\$2.75 ea.



1957-1960 All.

FL576 .....\$3.50 ea.

## V-8 Exhaust Manifold Gaskets



1953-1955 All V-8.

EMG536.....(To Engine block).....\$13.50 set

FG535.....( 3 pc. Flange set ).....\$11.75 set

1956 All

EMG536.....(To Engine block).....\$13.50 set

FG56.....( 4 pc. Flange set ).....\$12.50 set

1957-1960 All.

EMG576.....\$11.75 set

FG576.....( Flange gasket ).....\$8.75 set

Brass Nuts. Tall. 3/8-16. All years as required. For manifolds, pipes, trim etc.  
N6P.....\$3.75 pr.



## Cast Iron Paint

Extremely high temp. Excellent for manifolds and exhaust systems. Will not burn off.



EP3.....\$32.00 pt.

EP3S...(16 oz spray can).....\$19.50 ea.

## 1934 to 1953 248 & 263 Engines



### Exhaust Manifold (3.601)

**1939-1953**

**1939-1952:** All Special and Super;

**1953:** Special. Exhaust manifold.

EM393 .....\$710.00 ea.



### Exhaust Manifold Gaskets (3.270)

**1934-1953** Special and Super ( Straight eight ).  
Intake - exhaust manifold gaskets.

MG363.....(Composite material).....\$16.00 set

MG363C.....(Copper shielded material).....\$39.50 set

FG363.....( Flange gasket exc. dual carb).....\$4.50 ea.

BG4516.....( Flange 1941-1942 dual carb).....\$4.00 ea.

**1934-1953** Manifold to engine block threaded studs. Nine per car. Not a generic STUD. 100% correct.

MS363 .....\$2.75 ea.



**1934-1953** Manifold washer stamped steel as original 7 needed per car.

MW363.....\$4.50 ea.

MW363R.....Round-1 needed .....\$2.50 ea.



N14.....(nuts for above).....\$.75 ea.

MW363S.....Complete set of 8 w/ nuts .....\$39.50 ea.

### Valve Body



**1939-1953** All Straight 8. Valve body.

No Butterfly. (3.645)

**1939-1952** Special and Super;

**1953:** Special. For 248 and 263 engines.

VB393 .....\$525.00 ea.

VB393B.... (With Butterfly) .....\$595.00 ea.

### Valve Body Parts



**1934-1953** Special and Super valve body to exhaust, manifold ring.(3.657)

VBR343.....\$7.75 ea.

Brass Nuts. Tall. 3/8-16. All years as required. For manifolds, pipes, trim etc.

N6P.....\$3.75 pr.



### Valve Body Bolt Kits

Our Valve Body bolts washers & nuts are correct in every way. Bolts are grade 8 and zinc plated for strength and durability. Nuts are brass as original for authentic look and easy disassembly . NOTE: Always tighten manifolds in step sequence between hot and cold intervals then assemble manifolds gradually.

#### Valve Body to Intake Manifold

**1937-1951** All;

**1952** Super;

**1952-1953** Special.

VBB373I.....\$6.50 kit



#### Value Body to Exhaust Manifold

**1939-1952** All;

**1953** Special.

VBB393E .....\$11.50 kit



### Valve Body Gaskets (3.657)



**1934-1953** Special and Super, valve body to exhaust manifold gasket. Triangular.

VBG343 .....\$4.50 ea.



**1937-1953** Valve body to intake manifold gasket. All except dual carburetor set-ups.

VBI373.....\$6.00 ea.

### Valve Body Assembly Kits

Contains all necessary bolts, washers, studs, nuts, gaskets and ring for complete assembly.



**1937-1952** All. Special & Super exc. dual carb. jobs;

**1953** Special.

VBK373.....\$29.50 kit

**1936-1956** All. Exhaust manifold valve body return spring. (3.678)  
Correctly colored as original.

MS366.....\$3.50 ea.



**1940-1956** All. Exhaust manifold valve body thermostatic coil.

MT406 .....\$9.75 ea.

**1936-1953** Exhaust manifold valve body stud. (3.275)

MS363.....( 2 per car ).....\$2.75 ea.

## 1934 to 1952 320 Straight 8 Engines



(3.601)



### Exhaust Manifold Gaskets (3.270)

**1936-1952** Century, Roadmaster, Limited. Intake - Exhaust manifold gaskets.

- MG362.....16.50 set
- MG362C.....(Copper shielded material).....\$39.50 set
- FG360.(1936-1940 flange gasket. 2 needed ).....\$3.75 ea.
- FG412.(1941-1942 flange gasket. 2 needed ).....\$4.75 ea.
- FG462.....(1946-1952 flange gasket ).....\$4.00 ea.

**1936-1952** Series 60, 70, 80 and 90. Rear manifold section.  
MR362 .....\$395.00 ea.

**1937-1938** Series 60-80-90. Center section. (Can be altered for use on 1936).

MC378 .....\$395.00 ea.

**1939-1951** Series 60-70-80-90. Center section.

MC391 .....\$450.00 ea.

**1934-1953** Manifold to engine block threaded studs. Nine per car. Not a generic STUD. 100% correct.

MS363 .....\$2.75 ea.



**1934-1953** Manifold washer stamped steel as original 7 needed per car.

MW363.....\$4.50 ea.

MW363R.....Round-1 needed .....\$2.50 ea.



N14.....(nuts for above).....\$.75 ea.

MW363S.....Complete set of 8 w/ nuts .....\$39.50 ea.

### Exhaust Manifold Valve Body (3.645)

**1937-1951** Series 60-70-80-90.

VB371.....\$525.00 ea.



### Valve Body Parts



**1936-1952** Roadmaster and Limited valve body to exhaust manifold ring. (3.657)

VBR361.....\$7.75 ea.

**1936-1951** Century, Roadmaster, Limited. Valve body to exhaust manifold gasket. Triangular. (3.657)

VBG361 .....\$4.50 ea.



**1937-1953** Valve body to intake manifold gasket. All except dual carb. set-ups.

VBI373.....\$6.00 ea.

Brass Nuts. Tall. 3/8-16. All years as required. For manifolds, pipes, trim etc.

N6P.....\$3.75 pr.



### Manifold Parts

**1936-1956** All. Exhaust manifold valve

body return spring. (3.678) Correctly colored as original.

MSS366.....\$3.50 ea.



**1940-1956** All. Exhaust manifold valve body thermostatic coil.

MT406 .....\$9.75 ea.

## VALVE BODY

### Valve Body Bolt Kits

Our Valve Body bolts washers & nuts are correct in every way. Bolts are grade 8 and zinc plated for strength and durability. Nuts are brass as original for authentic look and easy disassembly . NOTE: Always tighten manifolds in step sequence between hot and cold intervals then assemble manifolds gradually.

#### Valve Body to Intake Manifold

**1937-1951** All;

VBB373I.....\$6.50 kit



#### Value Body to Exhaust Manifold

**1939-1952** All;

VBB393E .....\$11.50 kit



### Valve Body Assembly Kits

Contains all necessary bolts, washers, studs, nuts, gaskets and ring for complete assembly.

**1937-1951** Series 60, 70, 80, 90.

VBK371 .....\$29.50 kit



**Carburetor Mounting Insulators** (3.726)



**1935-1939** Special;  
**1940-1949** Special and Super  
 (use 2 on dual carb. set-ups.)  
 CI3.....Insulator .....\$14.25 ea.  
 CMG359.....Gasket.....\$3.75 ea.



**1939-1949** all 320 engines exc. dual carb  
 set-ups;  
**1950-1952** Special and Super;  
**1953** Special; **1954-1955** all 2bbl.  
 CI4.....Insulator\$14.25 ea.  
 CMG395.....Gasket...\$3.75 ea.

**Accelerator Return Springs** (3.459)

**1939-1947** All except dual carburetor set-up.  
 AS397.....( stainless steel ).....\$7.50 ea.



**1948-1956** Accelerator return spring.  
**1948-1952:** All;  
**1953:** Specials;  
**1955-1956** All.  
 AS483.....( stainless steel ).....\$7.00 ea.



**Gas Filters**



**1957-1960** Gas filter replacement element.  
 GF572 .....\$7.50 ea.



**1957-1960** AC replacement. Gas filter  
 assembly with element.  
 GF572A.....\$29.50 ea.

**In Line Gas Filters**



GF140.....For 1/4" ID Hose.....\$9.25 ea.

GF516.....For 5/16" IDHose.....\$9.25 ea.



GF516C..For 5/16" ID Hose(clear).\$6.50 ea.

GF380.....For 3/8" ID Hose.....\$9.25 ea.



**Air Cleaner Wing Nut** (3.920)

**1953-1960** Replacement air cleaner wing nut.  
 WN530 .....\$1.75 ea.

**Carter Baffle Plates**



Stainless steel plate between carb. and  
 intake manifold. This plate is essential for  
 protection against disintegration of aluminum  
 base of carb. It is also necessary for proper  
 idle and smooth running.



**1954-1956** All with 4bbl. carbs.  
 BP546 .....\$15.25 ea.  
**1957-1960** All with Carter AFB 4bbl.  
 BP576 .....\$16.25 ea.

**Linkage Rod Clips**



**1946-1960** Carburetor throttle rod clip.  
 1/4" rod diameter.  
 RC460.....\$0.75 ea.

**Linkage Rod Bushing**



Carburetor throttle rod bushing and  
 grommet. 1/4" rod diameter.  
 RB460.....\$6.00 ea.

**Carburetor Dash Pots**



**1954-1956** All. (3.440)  
 DP546.....\$23.50 ea.

**1957-1960** All.  
 DP573 .....\$18.25 ea.

**Air Filters** (3.410)



**1958-1960**  
**1958:** All;  
**1959-1960:** with 4 bbl. carb., air filter.  
 AF582.....\$15.50 ea.  
**1959** All with 2 bbl. carburetor, air filter.  
 AF59.....\$14.50 ea.  
**1960** All with 2 bbl. carburetor, air filter.  
 AF607.....\$15.00 ea.

**Gas Tanks**



**COMING SOON - Sign up now!**

**1954-1955** Special Century Skylark.  
GT545S.....

**1954-1955** Super and Roadmaster.  
GT545B.....

**1957** All.  
GT57.....

**1958** Special and Century.  
GT58S.....

**1958** Super, Roadmaster Limited.  
GT58B.....

**Gas Tank Sending Units 1939-1958**

**1939-1958** Complete quality re-productions. Our units are tested and calibrated before shipment. Gasket, float and strainer sock are included.



**1939 thru 1956** All. Complete with correct brass fittings.  
SU396.....\$72.50 ea.

**1957** All.  
SU57.....\$72.50 ea.



**1958** All. Includes strainer sock.  
SU58.....\$72.50 ea.

**1946-1958** Brass gas tank float.  
TF468.....\$8.50 ea.



**Gas Tank Gasket and Parts**



**1935-1960** Gas tank fuel gauge gasket.  
GG355.....\$3.75 ea.

**1935-1960** Fuel gauge screws & washers kit. (5)  
GGS355.....\$4.50 kit.



**1935-1960** All. Gas tank strap cushions.  
SC350.....\$12.75 pr.

**Gas Tank Cleaner/Degreaser**

Cleans and degreases. 1 Qt.  
TC1.....\$12.25 ea.



**Gas Tank Etch**

Removes light rust and will prep for sealer/liner. 16oz.  
TE1.....\$16.00 ea.



**Gas Tank Sealer/Liner**

Alcohol resistant. Quart can.  
TS1.....\$30.00 ea.



[www.oldbuickparts.com](http://www.oldbuickparts.com)

**908-369-3666**



### Lead Additive



All Buick engines needing leaded gas.  
LA1.....\$13.50 ea.



GC366A



GC346L



GC366R

### Gas Caps

**1932-1956** All. Cadmium as original. Aftermarket.  
GC366.....\$8.00 ea.

**1930-1956** All. Stainless steel. AC accessory type.  
GC366R.....\$9.25 ea.

**1932-1956** All. Authentic reproduction. Cadmium.  
GC366A.....\$19.75 ea.

**1934-1956** All. GM logo locking gas cap.  
GC346L.....\$54.00 ea.

**1957-1960** Gas cap.  
GC575.....\$9.00 ea.

### Gas Filler Grommets



**1933-1935** Gas filler grommet.  
**1933:** All Series 50 and 60 except Victoria Coupe;  
**1934-1935** All Models 66C, 66S, 67, 68.  
GF335.....\$46.75 ea.



**1933-1935** Gas filler grommet.  
**1933:** All Model 58, 68, 86, 90, 90L, 91;  
**1934-1935** All Models 61, 68C.  
GF335B.....\$43.75 ea.



**1936-1937** Gas filler grommet.  
**1936:** All;  
**1937:** Series 80-90.  
GF367.....\$17.50 ea.



**1937** Gas filler grommet. Special and Century.  
GF37.....\$17.50 ea.



**1937-1938** Rubber cover, automatic choke cable at carburetor.  
CC378.....\$32.50 ea.

# Fuel • Carburetion • Exhaust (Group 3)

## Gas Pedals (3.451)



**1931-1935** Full slip-over type. Sold outright.

**1931-1932** Series 60, 80, 90;

**1933** All;

**1934-1935** Series 50, 60, 90,

GP315.....(Black).....\$49.75 ea.

GP315N.....(Brown).....\$49.00 ea.

**1934-1935** Series 40. Send in your old core to have fresh rubber vulcanized. 3 week service.

GP345.....\$95.25 ea.

**1936-1937** Pad, accelerator pedal. Slip-over type with heavy retainer lip to fit over original pedal after stripping old rubber off.

**1936:** Series 80 and 90;

**1937:** All.

GP367.....\$39.25 ea.



**1938-1940** Pad, accelerator pedal. Rubber flanges all around as original to over pedal carcass.

**1938:** All;

**1939-1940:** All Series 80 and 90.

GP380.....\$39.25 ea.

### 1939-1942

**1939:** Special & Century;

**1940:** Series 40, 50, 60 and 70;

**1941-1942:** Most Models;

GP390B.....(Black).....\$44.50 ea.

GP390N.....(Brown).....\$46.50 ea.

**1940-1942** Pad, accelerator pedal.

Slip over type old carcass, perfect copy.

**1940:** Series 50 and 70;

**1941-1942:** All.

**1946-1948:** Series 50, 70;

**1948-1949:** All.

GP402.....\$35.00 ea.



**1946-1954** Made with steel core as original. ( Black ).

GP464.....\$24.50 ea.



**1948-1958 All;** Accelerator pedal bellows. Fits behind gas pedal. Often missing.

AB488.....\$7.25 ea.



**1955-1956** ( Black ).

GP556.....\$32.50 ea.

**1955-1956** ( Blue ).

GP556U.....\$34.50 ea.



**1957-1958** Gas pedal with steel core (Black).

GP578.....\$34.50 ea.

**1957-1958** Gas pedal with steel core ( Blue ).

GP578U.....\$36.50 ea.

## Universal Exhaust Hangers (3.616)



Fits 1 1/2" - 2" O.D. Twists or bends to any position. Absorbs road vibrations.

EH1.....\$5.75 ea.


Use with any 1 1/8" - 3" size muffler clamp. Rotates 360°. Absorbs road vibrations.

EH2.....\$6.50 ea.



Universal hanger.

EH3.....\$4.00 ea.



## Authentic Hangers/Supports

**1937-1952 All; 1953 Special; 1954** Special, Century, Skylark. Muffler, exhaust pipe and tail pipe clamp.

MC374.....\$15.00 ea.

**1939** Special and Century tail pipe hangers.

TPH39F.....(Front).....\$29.50 ea.

TPH39R.....(Rear Over Axle).....\$24.50 ea.

MS39R.....(Rear Muffler Support).....\$38.50 ea.

**1940** Super and Roadmaster; **1941** All. Muffler support.

MS401.....(Fits Front or Rear).....\$42.50 ea.

**1941** All; **1942-1949** Special; **1950** All. Tail pipe hangers.

TPH410F.....(Front).....\$24.50 ea.

TPH418R.....(Rear Over Axle).....\$24.50 ea.

## Exhaust Deflectors

**1936-1955** Original accessory. Stainless steel, complete with hardware.

ED365.....\$33.50 ea.

**1954-1955** All: Tubular type. Chrome plated steel.

ED545.....\$19.50 ea.



## 1957 Exhaust Deflector

**1957** All Models: Stamped steel. Looks identical to original. Correct for judging.

ED57.....\$74.50 ea.



### Fuel Pumps



**1930-1953** All 6 volt. Universal replacement electric fuel pump.

FP6 .....\$79.50 ea.

**1953-1960** All V-8. Universal replacement electric fuel pump.


FP12 .....\$68.50 ea.

**1957-1960** Replacement fuel pump. Sold outright no exchange necessary.

FP575 .....\$39.75 ea.



### Fuel Pump Rebuilding



Send in your fuel pump for the best quality rebuilding service available. Pumps are completely disassembled, refurbished and guaranteed. Allow about 3-5 weeks. If in stock, some are sold on an exchange basis - with core charge refundable after your old OEM is deemed rebuildable.

**We buy old Pumps...Please inquire.**

**1934-1935** Series 40.

FP345RS.....(Rebuilding Service) .....\$99.50 ea.

FP345EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1936-1937** Specials; ( State filtered or non-filtered type ).

**1938:** Specials ( early production ).

FP368RS.....(Rebuilding Service) .....\$99.50 ea.

FP368EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1938-1939**

**1938:** Specials ( late production );

**1939:** Specials. Inverted type.

FP389RS.....(Rebuilding Service) .....\$99.50 ea.

FP389EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1936-1939** Series 60-80-90.

FP369RS.....(Rebuilding Service) .....\$99.50 ea.

FP369EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1940-1951** Special and Super.

FP401RS.....(Rebuilding Service) .....\$99.50 ea.

FP401EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1940-1951** Series 60-70-80-90.

FP401LRS.....(Rebuilding Service) .....\$99.50 ea.

FP401LEI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1952-1953**

**1952:** Special and Super;

**1953:** Special.

FP523RS.....(Rebuilding Service) .....\$99.50 ea.

FP523EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1952** Roadmaster.

FP52RS.....(Rebuilding Service) .....\$99.50 ea.

FP52EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1953-1955**

**1953-1954:** All;

**1955:** Early. (Top mounts with 6 screws).

FP535RS.....(Rebuilding Service) .....\$99.50 ea.

FP535EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1955-1956**

**1955:** Late;

**1956:** All. (Top mounts with 1 screw).

FP556RS.....(Rebuilding Service) .....\$99.50 ea.

FP556EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1957-1958** All.

FP578RS.....(Rebuilding Service) .....\$89.25 ea.

FP578EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

**1959-1960** All.

FP595RS.....(Rebuilding Service) .....\$89.25 ea.

FP595EI....(Exchange w/ \$100 core charge)....\$125.00 ea.

### Fuel Pump Gaskets



**1934-1935** series 40, 50 fuel pump mounting gasket.

BG2085.....\$2.50 ea.

**1936-1960** All fuel pump mounting gasket.

BG2306.....\$2.50 ea.

### Fuel Pump Rebuilding Kits (3.925)

**1935-1938** Specials with single action (pump #421).

FPK358 .....\$49.00 ea.

**1936-1938** Series 60-80-90. Double action (pump #422).

FPK368 .....\$86.50 ea.

**1938-1939** Specials. For single action pumps (#518).

FPK389 .....\$54.00 ea.

**1940-1951** All double action pumps. (#519, 529, 530, 843).

FPK381 .....\$85.00 ea.

**1939** Series 60-80-90. Double action pump (#518).

FPK39 .....\$85.00 ea.

**1952-1953**

**1952:** All; **1953:** Specials.

FPK523 .....\$87.00 ea.

**1953-1955** All V-8 engine, double action pump.

FPK535.....(Top mounts with 6 screws).....\$86.00 ea.

**1955-1956** All.

FPK556.....(Top mounts with 1 screw) .....\$86.00 ea.

**1957-1958** All.

FPK578 .....\$59.50 ea.

**1959-1960** All.

FPK575 .....\$59.50 ea.

### Cover Plate Assembly



Used for cars with electric fuel pumps.

CP300.....\$10.75 ea.

### Fuel Pump Hardware Kits

**1940-1960** all engines. Correct bolts/washers.

FPH406.....\$2.75 ea.

### Gas Lines (3.158)

**1940-1953** Gas line to pump hose.

**1940-1952:** All;

**1953:** Specials.

GL403.....\$17.50 ea.

**1953-1956** All V-8, gas line to fuel pump hose.

GL536.....\$19.50 ea.

