


Stabilizer Repair Kits (7.240)



- 1937-1953** All Front;
1940-1941: All Rear.
SK373\$17.00 pr.
- 1954-1956** All Front.
SK373\$17.00 pr.
- 1957-1960** All Front.
SK373\$17.00 pr.



- 1937-1960** All. Stabilizer link bushing.
(8 needed per car).
SB376\$1.25 ea.



- 1934-1935** All. Stabilizer link bushing.
SB316\$8.50 ea.

Stabilizer Bar to Frame Bushings



- 1937** Front stabilizer bar bushing. Two per car.
Series 40 and 60.
SB37\$52.75 pr.

- 1937-1938** Bushing, stabilizer bracket.
1937: Series 80 and 90 only;
1938: Series 40 and 60 only.
SB378\$38.25 pr.



- 1941-1947** Front stabilizer bar bushing.
Two per car. Series 40, 50, 60 and 70.
SB417\$39.75 pr.



- 1948-1958** All. Front stabilizer bar bushing.
Two per car.
SB488\$11.50 pr.

- 1959-1960** All.
SB593\$15.25 pr.

Coil Springs



- 1935-1960** Front coil springs. (7.412)
CS350F\$195.00 pr.

- 1935-1960** Rear coil springs. (7.503)
CS350R\$185.00 pr.

- 1938-1960** Pad, front coil spring
insulator, upper. Two per car.
5 1/8" O.D. (7.420)
1938: All models;
1939-1941: Series 80 and 90;
1954-1960: All. (7.420)
SI381\$15.25 pr.



- 1939-1953** Insulators,
front coil spring. Fabric
reinforced rubber as original. One pair
required per car. (7.420)
1939-1940: Exc. Limited;
1941-53: All.
SI395\$10.00 pr.



- 1938-1958** Insulators, rear coil spring
clamp bolt (upper end). Two per car. Fabric
reinforced rubber as original. All models. 7.545
SI389\$21.25 pr.



- 1938-1960** Insulators, rear coil springs,
upper. Fabric reinforced rubber. One pair
per car.
SI380\$23.50 pr.

Spring Insulator Pad



- 1936-1937** Series 60, 80, 90.
Pad, rear spring insulator for 2 1/4" wide springs. 4 per car.
SI367\$29.75 ea.

Frame • Springs • Shocks (Group 7)



All Years: Satin Black paint: This is the correct enamel for frame and engine compartment, and is authentic for all years;

EP2\$24.50 qt.
 EP2S.....(12 oz. spray can)\$14.00 ea.

All Years: Universal gloss black: (Excellent for chassis, and general sse).

EP1.....\$19.50 qt.



"Miracle Paint" Tough stuff!

Hirsch brand, works very well as tested by our personnel. Bonds to rust, will not crack chip or peel. Impervious to gasoline, thinner, salt. Can be applied by brush or spray.

MP300B.....Black (quart)\$35.00 ea.
 MP300S.....Silver (quart)\$35.00 ea.
 MP300C.....Clear (quart)\$35.00 ea.
 MP300BG.....Black (gallon)\$101.00 ea.
 MP300SG.....Silver (gallon)\$101.00 ea.
 MP300CG.....Clear (gallon)\$101.00 ea.

Tubing and Wiring Clip

FC1.....\$2.50 ea.



License Plate Frame



1940-1956 Front or rear. Genuine GM repro
 LF406\$36.00 ea.



1920-1960 License plate bolt kit.
 Two bolts and two nuts per kit.
 LB300.....\$2.50 kit

Rear Bumper Fillers (Gravel Deflectors)



1937-1938 All Special and Century.
 BF378R\$95.00 ea.

1939 All Special and Century.
 BF39R\$210.00 pr.

1940 All Special and Century.
 BF40R\$220.00 ea.



www.oldbuickparts.com
908-369-3666



Send in your lever shocks for the best quality rebuilding service available. Shocks are disassembled and refurbished as necessary to guarantee correct performance. Allow only about 3 days. If in stock, they are sold on an exchange basis with core charge - refundable after receipt of your old rebuildable core. Add "EI" for exchange, "RS" for rebuilding service.

Lever Type Shocks	Front		Rebuild Price Each	Rear		Rebuild Price Each
	Right	Left		Right	Left	
1935 Ser. 40.....	S1932B	1932A	\$149.00	1431C.....	1431D	\$144.50
1936 Ser. 40.....	S1932B	1932A	\$149.00	1439E.....	1439F	\$144.50
1937 Ser. 40-60.....	S1947A	1947B	\$149.00	1713A.....	1713B	\$144.50
1938 Ser. 40-60.....	S1947A	1947B	\$149.00	*1754C.....	*1754D	\$144.50
1938 Ser. 80-90.....	S1933B	1933A	\$172.25	See Tube Section..		
1939 Ser. 40-60.....	S1948A	1948A	\$144.50	2103A, E.....	2103B, F	\$144.50
1939-40 Ser. 80-90.....	S1933B,D	1933A,C	\$163.25	1751R.....	1751S	\$144.50
1940 Ser. 40-50-60-70..	S1948A	1948A	\$144.50	2105A.....	2105B	\$144.50
1941 Ser. 40-50-60-70..	S1948AX	1948AX	\$144.50	2105C.....	2105D	\$144.50
1941-42 Ser. 90.....	S1948A	1948A	\$144.50	1757A.....	1758B	\$144.50
1942 Ser. 40-50-60-70..	S1948A	1948A	\$144.50	2105C.....	2105D	\$144.50
1946-53 Ser. 40-50-70.....	S1948A	1948A	\$144.50	2105C.....	2105D	\$144.50
1954-55 Ser. 40-50-60-70-100 (tube section)				2105X.....	2105Y	\$144.50

*1754C,D are knee action, see tube section for tube type

TUBE SHOCKS



Tube Shocks are state of the art Gas shocks, developed specifically for your Buick. We can also supply shocks in:

CS540.....COIL BOOSTER.....\$136.00 pr.
AS540.....AIR SHOCKS.....\$149.00 pr.

1938 All rear, tube type.....RS38 \$109.00 pr.
1954-55 All.....FS107 \$79.50 pr.....(see lever section)
1956 All.....FS107 \$79.50 pr.....RS94 \$79.50 pr.
1957 All.....FS132G \$93.50 pr.....RS94 \$79.50 pr.
1958 All.....FS155 \$89.50 pr.....RS94 \$79.50 pr.
1959-60 All.....FS144G \$103.50 pr.....RS145G \$89.50 pr.

Front Rear




Rear Shock Links

1937 Special and Century.
SL37.....\$58.00 pr.
N11S2.....Locknut kit for above.....\$1.75 kit
1939-1940
 1939 All;
 1940 Series 80 and 90.
SL390.....\$51.00 pr.
N11S2.....Locknut kit for above.....\$1.75 kit
1940 Special, Super, Century, Roadmaster
SL40.....\$53.00 pr.
N11S2.....Locknut kit for above.....\$1.75 kit
1941-1953 All except 1951-1953 Special;
1954-1955 Super and Roadmaster.
SL413.....\$42.50 pr.
N10S4.....Locknut kit for above.....\$3.75 kit
1951-1955
 1951-1953 Special;
 1954-1955 Special, Century, Skylark.
SL515.....\$42.50 pr.
N10S4.....Locknut kit for above.....\$3.75 kit

1934-1935 Rear shocks and brackets mounting kit. 18 piece hardened steel hardware kit.
SBK568R\$17.00 ea.

1931-1936 Shock absorber link bushing.




1931-1933 series 60, 80, 90.

1934-1935 series 50, 60, 90.

1936 All.

SB316\$8.50 ea.



1934-1935 Shock absorber link bushing. Some models as req. 1 5/16" OD, 7/16" ID.

SB345\$7.25 ea.



1934-1935 Shock absorber arm bushing. Series 40. 3/8" ID, 7/8" OD, 13/16" long.

SB345S\$4.25 ea.

1938 All Rear. Shock absorber bushing. Eight required per car.

SB38\$2.25 ea.

1955-1960 Grommet/bushing, shock absorber mounting 5/8" hole, 1-3/16" O.D., 3/4" thick. Double cone style. Rear.

SB556\$2.50 ea.

Bumpers (Group 7)



(7.799)

1953 Front Bumper "Special" Plastic Emblem.
BE53L.....\$98.50 ea.



(7.799)

1953 Front Bumper "Roadmaster" Plastic Emblem.
BE53R.....\$98.50 ea.



1953 Front Bumper "Super" Plastic Emblem.
BE53S.....\$98.50 ea.

1946-1949 Bumper Emblems



1946-1949 All. "Special".
BE468L.....\$39.00 ea.

1946-1948 "Super".
BE468.....\$39.00 ea.



1949 All. "Super".
BE49S.....\$43.00 ea.


1949 All. "Roadmaster".
BE49R.....\$43.00 ea.




ORDER BY PHONE!

Call 908-369-3666


Bumper Details



1940-1949 Anti-rattle, front or rear bumper gravel shield.
1940: Series 50, 70, Rear, 3 per car;
1941-1948: All, front, 2 or 4 per car;
1949: Series 40 front two or four per car.
HB379.....\$7.50 ea.




1941-1948 Anti-squeak, gravel shield-to-rear bumper, bulb type seal. 12 foot strip. Some models.
GS418.....\$41.75 ea.



1941-1953 Bumper, rear car bumper gravel deflector (anti-rattle), rubber. Five or more used per car.
1941: All (except style 49);
1942-1953: All.
DB413.....\$3.50 ea.



1936-1960 All cars. License plate mounting bolts. (two bolts - 2 nuts).
LB300.....\$2.50 set



1950-1953 All. Bumper, license plate.
LB505.....\$7.50 pr.

1946-1960 Gasket set, rear license lamp assembly. One rubber ring and one cork rubber gasket comprise set.



1946-1947: Series 50 and 70;
1950-1953: All series;
1958: Roadmaster;
1959: Station Wagons.

LG462.....\$6.75 set



1951-1952 Super and Roadmaster. Bumper, front gravel deflector as required.
HB429.....\$3.50 ea.



1955-1960 All front license plate rubber bumper. (two per car).
LB552.....\$2.75 pr.




1957 All. Gas lid rubber bumper.
GB57.....\$7.75 pr.




1957 "Fuel" door. Beautiful reproduction.
GD57.....\$79.00 ea.



1957 All. Grill to front bumper Insulators.
GI57.....\$39.75 pr.



1959-1960 All except wagons. Fuel filler door bumper.
GB590.....\$18.00 pr



- 1933-1935 Most models.**
 BGR335.....(Most models without luggage rack)\$119.50 pr.
 BGR335L.....(Most models with luggage rack)\$95.25 pr.
- 1934-1935 Series 40.**
 BGR345\$69.75 pr.
- 1936 All. Front bumper grommets.**
 BGF36\$37.50 pr.
- 1937-1938 Series 40-60. Front bumper grommets.**
 BGF378\$42.50 pr.
- 1939-1941 All except 80-90. Front bumper grommets.**
 BGF391\$40.00 pr.
- 1939-1941 Front Bumper. 1939-1940: Series 80, 90; 1941: Series 90.**
 BGF391B\$54.25 pr.
- 1936 All round type. Rear bumper grommets.**
 BGR36\$28.00 pr.
- 1936-1937 Rear bumper grommets. Series 80 and 90.**
 BGR367\$80.25 pr.
- 1937-1940 Series 40-60, except 1938. Rear bumper grommets.**
 BGR379\$39.50 pr.
- 1938 Series 40-60. Rear bumper grommets.**
 BGR38\$68.50 pr.
- 1938-1940 Rear bumper grommets. Excellent copy. Series 80 and 90.**
 BGR380\$96.50 pr.
- 1940 All except Series 80-90. Rear bumper grommets.**
 BGR40\$38.50 pr.
- 1942-1946 Series 50-70. Rear bumper grommets.**
 BGR426\$66.25 pr.
- 1951-1952 All. Seal, bumper arm. One pair per car. (7.829)**
 BGF512\$46.75 pr.



Bumper Bolts (7.859)

- 1937-1938 All front and rear.**
 BB378.....\$7.25 ea.
- 1939-1941**
1939-1940: Front and rear;
1941: Rear only.
 BB391\$2.75 ea.
- 1942-1949**
1942-1948: All;
1949: Special.
 BB429\$7.75 ea.
- 1949 Series 50-70 rear only.**
 BB490\$2.75 ea.
- 1949-1953**
1949: Series 50-70 front and rear;
1950-1953: Front;
1951-1953 Super & Roadmaster, Skylark rear.
 BB493\$7.50 ea.
- 1954-1960 All. (1/2-13 x 1 1/4).**
 BB490\$2.75 ea.



Rear Bumper Fillers (7.834)

- 1954-1955 All Special, Century, Skylark.**
 BF545.....\$35.00 pr.
- 1956 40-60. Rear bumper to body rubber seal.**
 BF56\$24.50 ea.
- 1956 50-70. Rear bumper to body rubber seal.**
 BF56B\$24.50 ea.
- 1954**
 BF54B\$35.00 ea.
- 1959**
 BF59\$3.00 pr.
- 1960 All, except wagons.**
 BF60\$26.00 pr.

Retaining Clips for Above Fillers

- MC12\$0.50 ea.

Make Your Own Fillers

- Correct composition rubber material is excellent for duplication using your old aprons as a pattern.
- MR4812.....(48" x 12").....\$40.75 ea.
 MR4824.....(48" x 24").....\$81.50 ea.
 MR4836.....(48" x 36").....\$122.25 ea.
 MR4848.....(48" x 48").....\$163.00 ea.