

Hood Ornaments (Group 8)

1937, 1938, 1940 and 1955 Hood Ornaments

These quality reproductions are in detail, highly polished and triple chrome plated for long lasting beauty. They have already enhanced many trophy winning **BUICKS**. We have a few "seconds" please ask.



HO37.....(1937)....\$139.50



HO558



HOB55



HO40....(1940)....\$90.00



HO38.....(1938)....\$149.50

HO558.....**1955** All Chrome....\$69.50 ea.
HO558G....**1955** All Gold.....
Hood Ornament Base - COMING SOON!
HOB55.....\$79.50 ea.
HUB55G.....Gold.....

Hood Letters

Hood letters are die cast and heavy chrome plated as the originals. Mounting pins are in correct locations for easy fit. *(We recommend silicone rubber for attaching letters) or, check page 59 for mounting clips.*



1939 Hood letters.
HL39.....\$51.25 set



1940 Hood letters.
HL40.....\$39.50 set



1941 Hood letters.
HL41.....\$38.50 set



1954 Hood letters.
HL54.....\$52.75 set
HL54G.....Gold.....



1955 Hood letters.
HL55.....\$52.75 set



1956 Hood letters.
HL56.....\$52.75 set
MC210..clip kit for above (10).\$17.50



1957 Hood letters. Includes "ARROWS".
HL57.....\$52.75 set



1958 Hood letters.
HL58.....\$52.75 set



1948-1949 Hood plastic emblem.
1948 All;
1949 Special.
HE489\$85.00 ea.



1949 Hood plastic emblem.
Super and Roadmaster.
HE49.....\$85.00 ea.



1950 Hood plastic emblem.
HE50.....\$85.00 ea.



1951-1952 Hood plastic emblem.
HE512.....\$85.00 ea.



1953 Hood plastic emblem.
HE53.....\$85.00 ea.

Hood Emblems (8.005)

1939 Hood emblem (Cloisonne).
HE39.....TOS

(Group 8) **Hood Bumpers**



1935-1940 Fisher Body I.D. Plate (oval metal).
FP320.....\$9.00 ea.




1936-1937 All. Pads, rear hood corners.
Original style with metal core and metal
fastening tabs.
HP367R\$48.00 pr.



1937-1949 Pad, hood rest. Metal core with tab.
All models.
1937-1938: Six per car;
1939-1949: Up to 12 per car.
HB379\$8.75 ea.



1939-1940 All. Hood bumper.
Vulcanized to metal (6 per car).
HB390\$7.00 ea.




1938-1958 Bumper, hood rest, cap type for
adjustable screw, 7/8" O.D., 3/8" thick. Some
models as required.
TB415.....\$1.75 ea.



1941 All. Pad, hood side center rest.
HB41A.....\$39.00 pr.



1941 All. Bumper for bracket, radiator upper
panel to grill. One per car. Rubber only. Use
original steel bracket.
HB41B.....\$5.50 ea.




1941 All models. Bumper, hood front. Two
required per car. Slips over metal bracket as
shown.
HB41C.....\$5.50 ea.



1941 All models. Bumper, hood side pilot. Set
of four. Steel washer vulcanized in rubber.
HB41D.....\$54.25 ea.



1941 All. Bumper, hood to cowl, for 1/4" hole.
HB426\$2.75 ea.




1942-1949 All models. Bumper, hood,
fastened to cowl at rear of hood. 1-11/16"
diameter. Two per car.
HFB429\$3.75 ea.



1942-1959 Bumper, hood two uses. Hood to
radiator shell at side panel, six per car. Hood
to fender and hood rail as required. 1956-1959
All on radiator shroud.
1942-1959: All;
HB429\$3.50 ea.



1948 Bumper, hood front in grille. 3/4"
diameter X 5/16" thick, self-retaining for 1/4"
hole, two per car. Series 50 and 70.
HB48\$2.75 ea.



1948-1953 Many models. Hood to fender
bumper.
HFB483.....\$3.75 ea.



1949 Series 50-70. Also fits other years. Hood
to fender bumper.
HFB49R.....\$4.50 ea.



1949 Super, Roadmaster. Seal plate, hood
fastener control, cable through firewall.
Rubber with steel core.
FWG49.....\$48.00 ea.




1949 Super, Roadmaster. Hood to fender
bumper.
HFB49B\$3.50 ea.




1949-1953 Bumper, rubber, hood ledge corner
at shroud. Two per car. Some as required.
HB493.....\$10.75 ea.



1949-1955
1949 Super, Roadmaster;
1950-1955 All. Hood to radiator grill frame
bumper.
GB495.....\$3.00 ea.



1950-1952 Bumper, hood side to fender ledge.
Metal core molded in as original.
1950: All models;
1951-1952: All Super, Roadmaster
HFB502.....\$8.25 ea.



1953-1954 Bumper, hood to fender. Uses four
per car for most models.
HFB534.....\$5.00 ea.



1953-1955 Most models. Bumper, fan shroud.
SB535\$2.50 ea.



1955-1958 Bumper, hood side, self-retaining
type. Six per car.
HFB558.....\$5.50 ea.




1958 Bumper, hood side on fender ledge.
HFB58.....\$11.25 ea.




1959-1960 All. Front hood rubber bumper.
HB595.....\$2.50 ea.



1958-1960 Many models. Bumper and stud,
adjustable type, hood front. Cadmium plated
bolt 8 mm x 1-1/4", rubber bumper 1-1/8" in
diameter, 5/8" thick.
HB585.....\$4.00 ea.
HS585.....Stud Only.....\$2.50 ea.




1959-1960 Bumper, hood to fender ledge. All
models as required.
HFB591R\$5.00 ea.



1959-1960 All full size models. Bumper hood
to fender ledge.
HFB591\$7.50 ea.

Hood • Running Boards (Group 8)

Hood Insulation 1941-1960 (8.021)



1953 Super & Roadmaster.
HI53\$37.50 ea.

Below listed insulators are pre-cut, ready to install. Should you not see your car and or model listed, please send us your old items to make new patterns. You will receive a discounted new insulator. See spray adhesive below for application. Our hood pads are in stock, ready to ship.

1954 All.
HI54\$37.50 ea.
1955-1956 All.
HI556\$37.50 ea.
1957 All.
HI57\$37.50 ea.
1958 All.
HI58\$37.50 ea.
1959 All
HI59\$37.50 ea.
1960 All
HI60\$37.50 ea.

For years and models not listed above

Generic hood insulation pad. Gray fiberglass. Easy to trim and apply. 48" x 55" x 1"

HI415.....\$39.50 ea.

Spray adhesive for application of hood Insulation


SA360.....(20 oz).....\$18.00 ea.

Hood Insulation Retainers (Sombreros)


1954-1956 All
HIR546.....\$11.50 ea.




Hood Corner Pads



1934-1935 All. Pads, hood corners, front.
HP345F.....\$48.00 pr.



1934-1935 Series 40. Pads, hood corners, rear.
HP345R\$66.75 pr.



1934-1935 Series 50, 60, 90. Pads, hood corners, rear.
HP345RB.....\$66.75 pr.



1936-1937 All. Pads, hood corners, front.
Original type with metal carcass and retaining tab.
HP367.....Front\$48.00 pr.
HP367R.....Rear\$48.00 pr.

1946-1960 Accessory Jack Cases (8.820)



A genuine Buick accessory, part # 981521, 981161. These cases were made from excess materials left over from the upholstery shops at GM. They came in assorted colors and trim.
JC460BT.....(Black with Tan Trim).....\$34.75 ea.
JC460BR.....(Black with Red Trim).....\$34.75 ea.
JC460BY.....(Black with Gray Trim).....\$34.75 ea.
JC460B.....(Black with White Trim).....\$34.75 ea.

Fender Splash Aprons



1960 All models. Fender apron set. Includes All factory holes required for installation.
FA60\$113.25 ea.

Make You Own Fender Splash Aprons

Correct composition rubber material is excellent for duplication using your old aprons as a pattern.
MR4812.....(48" x 12").....\$40.75 ea.
MR4824.....(48" x 24").....\$81.50 ea.
MR4836.....(48" x 36").....\$122.25 ea.
MR4848.....(48" x 48").....\$163.00 ea.

1942-1948 Hood Handle Frame



This item is often split or broken to a degree that the opening mechanism will not function. Die cast chrome. Triple plated. Fits either side. Does not include handle.

HF428\$85.00 ea.



Winged speed nut. For fastening 1/8" hood letters and other ornaments. Pack of 25.

MC38\$1.25 ea.



Tool necessary for removing and installing MC38 clips without damaging studs or paint.

CT555\$29.25 ea.

Hood Cables and Springs



1949 Hood release cables. Super and Roadmaster.
HC49\$37.00 pr.



1949 Super and Roadmaster, hood cable return spring. (Stainless steel).
AS397\$8.00 ea.




1950-1952 Hood cable return spring (Stainless steel).
CS502\$7.00 ea.



1950-1952 Hood release cable.
1950: All;
1951-1952: Super and Roadmaster.
HC502\$37.00 pr.



1951-1952 Special. Hood release cable.
HC512\$37.00 pr.



1950-1952 Hood cable spring protective sleeve.
SL502\$7.75 pr.




1949-1952 Hood cable pull handle. "HOOD"
HH492\$54.00 ea.



1950-1952 Air Intake tube end seals. (2 per car).
AS502\$19.25 pr.

(9.784)



Your Buick is mighty "Choosy" about the company it keeps.....Treat it to the Best! Use only Cars Quality Original and Reproduction Parts.

Fenders (Group 8)

Portholes

Throughout the years, one of **BUICK'S** most distinguishable trademarks has been the "Porthole" or "venti-port". We are proud to preserve this tradition in offering the following examples. Each is made identical to the original. (8.147)

PH49	1949 ALL Models.....	\$33.50 ea.
PH512	1951-1952 Specials and Supers;	
	PHL512 Left hand set.....	\$35.50 ea.
	PHR512 Right hand set.....	\$35.50 ea.
PH512R	1951-1952 Roadmasters.....	\$35.50 ea.

1952 Roadmaster Porthole Inserts

Replacement insert for worn or missing parts. Stainless.

PI512R.....	\$9.75 ea.
PH53	1953 All Models..(includings mounting bracket)...\$39.50 ea.
PH54	1954 All Models.....\$35.50 ea.
PH55	1955 All Models.....\$49.50 ea.
PH56	1956 All Models.....\$39.50 ea.
PH60L	1960 All Models.....(L.H. Side).....\$35.50 ea.
PH60R	1960 All Models.....(R.H. Side).....\$35.50 ea.



PH-53



PH-512R



PH-56

1948-1952 Scripts. The detail and workmanship on these three scripts is magnificent. The chrome plating is beautiful. Our scripts come complete with correct "speed nuts" for mounting on fenders.

SS480	1948-1950 Series 50.....(Super)	\$30.00 ea.
RS480	1948-1950 Series 70.....(Roadmaster).....	\$38.50 ea.
DS482	1948-1952 All Dyna. Trans.(Dynaflow).....	\$30.00 ea.



1955-1956 Rear Fender and Rear Door Scripts

SS55.....	1955 All "Special".....	\$53.00 ea.
SS56.....	1956 All "Special".....	\$53.00 ea.
CS56.....	1956 All "Century".....	\$53.00 ea.
SS56U.....	1956 All "Super".....	\$53.00 ea.

Fender Hardware

We had these pieces fabricated to be as close to the original as possible. All are finished with correct plating. These apply to All 1936-1960 Models.



1936-1960 Fender bolt. Zinc plated 5/16-18 thread, 25 pack. Correct head.	
FB1.....(1").....	\$8.00 pk.
FB12.....(1/2").....	\$8.00 pk.
FB34.....(3/4").....	\$8.00 pk.



1936-1960 Fender washer. Zinc 25 pack. 5/16 ID, 7/8 OD. Correct reproduction	
FW78	\$7.00 pk.

1936-1960 Fender star washer. 5/16 ID, 7/8 OD. 25 pack.	
FS78	\$.00 ea.



1936-1953 Rear. Fender cage nuts. (Also other uses).	
CN363	\$2.65 ea.

1959 Front Fender Monograms



FM59E.....	"Electra".....	\$33.50 ea.
FM59225.....	"225".....	\$19.00 ea.
FM59I.....	"Invicta".....	\$33.50 ea.

Curb Feelers for All Years



CF300.....	\$13.00 pr.
------------	-------------

1958 Front Fender Ornaments



Beautiful cast chrome, two per car.	
HO558.....	\$69.50 ea.

(Group 8) **Rear Fender • Running Boards**

1935-1960 Rear fender inner seal.
(between deflector and fender-36" length)
AS502.....\$16.50 ea.



(9.784)

**1959 and 1960
Rear Fender Fin Clips**



1959 All. For peak molding on rear fender.
MC79\$2.50 ea.



1960 All. For peak molding on rear fender.
MC80\$2.50 ea.

**1955-1956 Rear Fender
and Rear Door Scripts**



SS55.....**1955 "Special"**.....\$53.00 ea.
SS56.....**1956 "Special"**.....\$53.00 ea.
SS56U.....**1956 "Super"**.....\$53.00 ea.
CS56.....**1956 "Century"**.....\$53.00 ea.


**1958 Buick Limited
Rear Fender Louvers**



Rear Fender
Louver Moldings


1958 Limited rear fender louvers. Beautiful die cast reproduction. Chrome plated. Complete with hardware.
L58.....\$9.50 ea.
L58S.....(set of 30).....\$247.00 set

1958 Rocker Panel Clips (8.309)



1958 All Roadmaster and Limited. 20 per car.
MC6.....\$2.50 ea.

1960 All. 18 per car.
MC81.....\$2.50 ea.



Running Board Matting (8.299)

1934-1935 Running board matting, exact copy using parallel ribbed pattern. Extruded width 8 1/4", so butting is required. Give required dimensions. Series 40.



RB345.....\$318.25 set



1936 Specials. Made in one piece with steel backs and bend over tabs.
RB36.....\$499.50 pr.

1941 All. 5" wide x 41" long.
RB41.....\$189.50 pr.



1937-1938 Running board matting. Special original design, molded in solid aluminum molds, right and left. Size includes stock for apron riser and outer radius. Some splicing necessary. Subject to batching so order early. Series 40.
RB378.....\$694.25 set

1939 Running board matting, original pattern with material to come down over ends and sides. Super workmanship, made in solid aluminum molds, each in one piece; no splicing required. Series 40.
RB39.....\$689.50 set

1938-1949 All. Gas door return spring.
GDS389.....\$9.75 pr.

