

BUICK PARTS: GROUP NUMBERS

Engine • Clutch • Decals.....	Group 0
Cooling • Oiling • Grills	Group 1
Electrical • Lamps	Group 2
Fuel • Carburetion • Exhaust.....	Group 3
Transmission • Brakes	Group 4
Wheels • Propeller Shaft • Rear Axle	Group 5
Front Suspension • Steering	Group 6
Frame • Springs • Shocks • Bumpers	Group 7
Hood • Front Fenders • Running Boards.....	Group 8
Heater • Air Conditioner • Firewall • Radio • Antenna	Group 9
Glass • Doors • Cowl • Weatherstrip • Wiper • Dash.....	Group 10
Rear 1/4 Glass • Seats • Door Sills • Dome Lenses	Group 11
Rocker Panels • Rear Sheet Metal • Deck Lid.....	Group 12
Convertible Tops and Parts	Group 13
Door Panels • Misc. Interior • Headlinings	Group 14
Carpet • Floor Mats • Trunk Linings	Group 15
Literature.....	Group 16

-ATTENTION-

This catalog pertains to **1961 and Up**
LeSabre, Invicta, Wildcat, Electra 225, Centurion,
Century and Apollo **ONLY**

We also have catalogues and stock Buick parts for:


- **1930's and Up** All models
- **1961 and Up** Special, Skylark, Sportwagon and Gran Sport
 - **1963 and Up** Riviera
- **1973 and Up** Regal, Grand National, T-Type and GNX

Please inquire about separate catalogs for the above Buicks

www.oldbuickparts.com

All rights reserved. No part of this publication may be reproduced without prior written permission from CARS, Inc. Illustrations in this catalog are representations only and may not exactly depict any particular part or part number. Prices subject to change without notice.

Typical Buick V-8 Engine



Motor Mounts (.027)

1961-1965

1961-1963: All;
1964: LeSabre wagons;
1964-1965: Wildcat and Electra.



MM615\$57.50 pr.

1965-1967 With 300, 340 engine.

MM657\$24.00 pr.

1967-1976 With 430-455 engine, all with four hole flange.

MM676\$52.25 pr.

1968-1980 With 350 engine, motor mount.

MM685\$47.25 pr.

Motor Mount Shield


1967-1976 All 400, 430, 455 engines.
Right side heat shield. Mounts behind motor mount against engine block. Keeps heat off the rubber mount.



HS676.....\$29.50 pr.


Motor Mount Rebuilding Service

We can rebuild any mount. Please inquire.



1964 LeSabre 225 V-6 and 300 V-8. There are two types. This is not the interlocking type.


MM64\$204.00 pr.



1966 Electra and Wildcat. (Rebuild).

MM66RS.....\$144.50 pr.

MM66EI.(Exchange w/ \$75 core).\$215.00



1969 Wildcat and Electra first type.

There are two types. This is not the interlocking type.

MM670\$185.50 pr.

Crankshaft Main Bearing Sets

1961 With 364 engine. Main bearing set.

MBS571\$126.50 set

1961-1966 All 401-425 engines. Main bearing set.

MBS596\$129.75 set

1964-1967 With 300 V-8 engines.

MBS647\$104.00 set

1966-1976 All 340-350 engines. Main bearing set.

MBS666\$84.00 set

1967-1969 All 400-430 engines. Main bearing set.

MBS679\$97.50 set

1970-1976 All 455 engines. Main bearing set.

MBS706\$99.50 set

Connecting Rods

1961-1966 400, 401 and 425 engines.

CR596.....\$43.25 ea.



1967-1972 400, 430 and 455 engines.

CR672.....\$59.25 ea.

Connecting Rods Bearings



1961-1976 400-401-425-430-455 engines.

RBS576\$89.50 set

1964-1974 All 300, 340 and 350 engines.

CRB612.....\$9.00 ea

Camshafts



1961-1966 364, 401-425 engines.

CS576.....\$154.50 ea.

1964-1967 LeSabre 300 and 340 engine.

CS649.....\$154.00 ea.

1967-1976 400, 430 and 455 engines, except stage one.

CS676.....\$167.25 ea.

1968-1975 All 350 engines.

CS680.....\$132.00 ea.

All Years. All Engines. Cam break-in Lube.

CL300\$6.75 ea.

Camshaft Regrinding Service

1960-1961 All engines.

CS576R.....\$296.50 ea.

Camshaft Bearings Sets



1961-1966 401 and 425 engines.

CBS576\$38.50 set

1967-1976 All V-8, engines.

CBS676\$54.00 set

Engine Parts (Group 0)

Pistons (Others Custom made, please inquire)

- 1961-1966** All 400, 401 engines. Piston and pin.
 P401S.....(Set of 8)\$287.00 set
- 1963-1966** All 425 engines. Piston and pin.
 P425\$54.50 ea.
 P425S.....(Set of 8)\$375.00 set
- 1970-1976** All 455 engines. Piston and pin.
 P706\$57.25 ea.
 P706S.....(Set of 8)\$449.50 set

Piston Ring Sets (.643)

- 1961** LeSabre with 364 engine.
 PRS364C.....(cast iron).....\$68.50 set
 PRS364M.....(moly)\$129.50 set
- 1961-1966** 401 engine.
 PRS401C.....(cast iron).....\$94.50 set
 PRS401M.....(moly).\$125.00 set
- 1963-1966** 425 engine. Cast iron.
 PRS425C.....\$78.25 set
- 1967-1969** 430 engine. Cast iron.
 PRS430C.....\$138.00 set
- 1968-1981** 350 engine.
 PRS687C.....(cast iron).....\$129.00 set
 PRS350M.....(moly)\$64.50 set
- 1970-1976** 455 engine.
 PRS455C.....(cast iron).....\$64.50 set
 PRS455M.....(moly)\$95.00 set



Valves - Intake

- 1961** LeSabre 364 engine intake valve.
 IV578.....\$15.75 ea.
- 1961-1966** 401-425 intake valve.
 IV596.....\$14.25 ea.
- 1964** 300 engine.
 IV64.....\$18.25 ea.
- 1965-1967** 300-340 intake valve.
 IV657.....TOS ea.
- 1967-1976** 400-430-455 intake valve.
 (exc. GS stage 1)
 IV676\$11.50 ea.
- 1968-1980** 350 engine intake valve.
 IV680\$10.00 ea.

Valves - Exhaust



- 1961** LeSabre 364 engines.
 EV578.....\$16.25 ea.
- 1961-1966** 401-425 exhaust valve.
 EV596.....\$16.50 ea.
- 1964** 300 engines.
 EV64.....\$18.25 ea.
- 1965-1967** 300-340 engines.
 EV657\$18.25 ea.
- 1967-1974** 400-430-455 engines. (Except GS stage 1).
 EV674\$14.75 ea.
- 1968-1973** 350 engines.
 EV683\$18.25 ea.
- 1975-1976** 455 engines.
 EV756\$16.00 ea.

Valve Guides



- 1961-1965** All 364, 401 and 425 valve guide. (int./exh.).
 VG733\$4.00 ea.
- 1965-1966** 300-340 engine. Valve guide. (intake).
 VG5607\$3.00 ea.
- 1965-1967** 300, 340 engine. Valve guide. (exhaust).
 VG7460\$2.25 ea.
- 1966** All with 401 engine. Valve guide. (intake).
 VG937\$3.00 ea.
- 1966** All with 425 engine. Valve guide. (intake).
 VG733\$4.00 ea.
- 1967-1976** 400, 430 and 455 engine. Valve guide. (intake).
 VG6113\$2.75 ea.
- 1967-1976** 400, 430 and 455 engine. Valve guide. (exhaust).
 VG6114\$2.75 ea.
- 1968-1980** 350 engine, valve guide. (intake).
 VG6108\$3.00 ea.
- 1968-1980** 350 engine, valve guide. (exhaust).
 VG6113\$2.75 ea.

Valve Springs



1961-1966 All. (inner).
 VS536.....\$5.00 ea.
 VS536S.....Set of 16.....58.00 set

1961-1966 All. (outer).
 VS596.....\$4.75 ea.
 VS596S.....Set of 16.....\$52.25 set

1964 300 engine.
 VS614.....\$5.00 ea.
 VS614S.....Set of 16.....\$58.00 set

1965-1967 300 and 340 engine.
 VS657.....\$5.00 ea.
 VS657S.....Set of 16.....\$58.00 set

1967-1972 400, 430 and 455 engines. (exc. high performance)
 VS672.....\$4.50 ea.
 VS672S.....Set of 16.....\$53.25 set

1968-1974 350 engine intake and exhaust. (exc. 1971 exhaust).
 VS684.....\$3.25 ea.
 VS684S.....Set of 16.....\$44.00 set

1971 350 engine. (exhaust).
 VS71E.....\$4.75 ea.

1971-1974 455 high performance engine.
 VS714.....\$4.75 ea.

1973-1974 All with 455 engine.
 VS734.....\$4.75 ea.

Valve Stem Seals



1961-1966 364, 400, 401 and 425 engines.
 VSS536.....\$3.00 ea.

1964-1967 300 and 340 engines.
 VSS612.....\$2.75 ea.

1967-1974 300, 400, 430 and 455 engines.
 VSS674.....\$2.75 ea.

Valve Spring Caps

1967-1975 400, 430 and 455 engines.
 VC675.....\$2.50 ea.
 VC675S.....Set of 16.....\$37.50 set

Valve Spring Retainers (.310)

1961-1966 All 364, 400, 401, 425 engines;
1967-1975 all V-8 engines. 32 pairs needed per car.
 VR365.....\$3.00 pr.
 VR365S.....Set of 32.....\$42.50 set

Valve Seat Inserts

1961-1966 364, 400, 401 and 425 engines. (intake).
 VSI592.....\$4.75 ea.

1961-1966 364, 400, 401 and 425 engines. (exhaust).
 VSI590.....\$4.75 ea.

1964 300 engine. (intake).
 VSI648.....\$8.00 ea.

1964 300 engine. (exhaust).
 VSI614.....\$4.00 ea.

1965-1967 300 and 340 engines. (intake).
 VSI657.....\$5.75 ea.

1965-1967 300 and 340 engines. (exhaust).
 VSI557.....\$4.50 ea.

1967-1969 400 and 430 engines. (exhaust).
 VSI648.....\$8.00 ea.

1967-74 400, 430 and 455 engines. Exc. high performance (intake).
 VSI674.....\$8.00 ea.

1968-1970 350 engines. (exhaust).
 VSI590.....\$4.75 ea.

1968-1972 350 engines. (intake).
 VSI592.....\$4.75 ea.

1970-1974 455 engine. Except high performance. (exhaust).
 VSI704.....\$5.00 ea.

Hydraulic Valve Lifters



1961-1967
1961-1966: All;
1967: 300 and 340 engines.

VL567.....\$9.50 ea.
 VL567S.....(Set of 16).....\$139.50 set

1967-1969 400-430 engines.
 VL679.....\$7.00 ea.
 VL679S.....(Set of 16).....\$102.50 set

1968-1969 350 engine with hollow push rods.
 VL679.....\$7.00 set
 VL679S.....(Set of 16).....\$102.50 set

1970-1981 All 350 and 455 engines.
 VL680.....\$4.75 set
 VL680S.....(Set of 16).....\$69.50 set

Engine Parts (Group 0)

Rocker Arm Assembly (Sold Outright)

1968-1981 350 engine.	
RAA680	\$265.00 pr.
1970-1971 455 engine.	
RAA702	\$179.50 pr.

Rocker Arm Assembly Rebuilding

1961-1966 All 364, 401, 425 engines.	
RAA596	\$296.50 pr.
1964-1967 All 300, 340 engines.	
RAA617	\$204.75 pr.
1967-1976 All 400, 430, 455 engines.	
RAA676	\$262.25 pr.

Rocker Arm Shafts

1961-1966 364, 400, 401 and 425 engines.	
RS536	\$48.50 ea.
RAS536P.....Pair.....	\$89.50 pr.
1964-1967 300 and 340 engines.	
RS617	\$65.00 ea.
1967-1969 400-430 engines.	
RS679	\$55.00 ea.
1968-1969 350 engine.	
RS689S	\$44.75 ea.
1970-1976 455 engine.	
RS705	\$55.50 ea.
1970 -1981 All with 350 engines.	
RS700	\$39.50 ea.

Rocker Arm Retainers

1970-1972 All. Rocker arm retainers. For use with aluminum rocker arms. 16 per car. Nylon.

RR702.....	\$1.75 ea.
------------	------------



Harmonic Balancers

1967 thru 1976 all 400, 430, 455 engines. Sold outright.	
HB676	\$269.50 ea.

Rocker Arms and Sets

1961-1966 All 364, 401, 425 engines. Reproduced in steel. Set includes 16 rocker arms.	
RAS536.....	\$208.50 set
1961-1966 All 364, 400, 401, 425 engines. Fits LH 4 Rear and RH 4 Front. Reproduced in steel.	
RA596A.....	\$16.00 ea.
1961-1966 All 364, 400, 401, 425 engines. Fits RH 4 Rear and LH 4 Front. Reproduced in steel.	
RA596B.....	\$16.00 ea.
1968-1969 350, 400, and 430 engines. (intake 1458, exhaust 2367). Arm.	
RA689A.....	\$17.00 ea.
1968-1969 350, 400, and 430 engines. (intake 2367, exhaust 1458). Arm.	
RA689B.....	\$17.00 ea.
1968-1969 350, 400, and 430 engines. Complete set of 16.	
RA689S.....	\$259.00 ea.
1970-1976 All 455 engine. Intake, 1, 4, 5, 8, exhaust . 2, 3, 6, 7.	
RA705A.....	\$8.50 ea.
1970-1976 All 455 engine. Intake, 2, 3, 6, 7 exhaust . 1,4,5,8.	
RA705B.....	\$8.50 ea.
RA705S	\$105.25 ea.



Harmonic Balancer Rebuilding Service (.659)

Balancers are completely disassembled shot peened and inspected. Threaded holes are repaired and new seal saver is installed.(non-rope seal apps.) New silicone rubber is injected, then vulcanized for proper bonding. Please remove any bolted pulleys before sending. For those not listed, please inquire.




1961 All 364 engines. Riveted. 75% of weight removed from ring. Externally balanced.	
HB364RS.....	\$154.00 ea.
1959-1966 All 400, 401 engines. Riveted Type	
HB401RS.....	\$155.50 ea.
1963-1966 All 425 engines. Riveted hub seal dia. 2.00 inches, 1.440 id.	
HB425RS.....	\$154.00 ea.
1964-1967 All 225 V-6 engines.	
HB225RS.....	\$88.25 ea.
1964-1981 All 300, 340, 350 engines. .750 wide ring externally balanced hub and ring.	
HB350RS.....	\$88.25 ea.
1967-1976 400, 430, 455 engine. 1.100 wide ring. Externally balanced.	
HB455RS.....	\$111.50 ea.

Valve Rocker Cover Parts



-  **1960-1966** Valve rocker cover grommet. Four per car.
VCG572\$3.50 ea.
-  **1963-1966** Valve cover vent, rubber grommet. (1" hole).
VG634\$7.75 ea.
-  **1964-1967** Solid rocker cover plug.
CP647\$11.75 ea.
-  **1967-1974** Intake manifold vent grommet.
VG634\$7.75 ea.
-  **1970-1974** All V-8, left hand valve cover grommet.
VG704\$4.25 ea.

1964-1967


- 1964-1966:** GS with 2-4 carbs;
- 1967:** with engine dress up kit.
- "AC OIL" **Chrome** twist on cap.
- OC647\$31.00 ea.






Breather Tubes (1.762) (Air Cleaner to Rocker Cover)

-  **1968-1969** All 350, 400, 430 engine except 1968 2bbl.
VT689.....\$18.50 ea.
-  **1970-1971** all V-8; **1972** all 455 engines.
VT704.....\$16.50 ea.


Crankcase Vent Hose (To Carb) (1.726)

-  **1971-1975** All 350 and 455 engines with 4BBL carb. (Formed hose).
VH725\$20.25 ea.

Wire Retainer

-  **1961-1966:** All;
1966: 300, 340, 400 engine ign. wire retainer on rocker covers. Two per car.
WR596.....\$4.00 ea.
-  **1967-1972** All. Front "4", ign. wire retainer. Two per car.
WR683.....\$4.00 ea.
-  **1967-1972** All. Rear "3" ign. wire retainer.
WR673.....\$4.00 ea.

Chrome Valve Cover Set

- 1970-1976** Buick 455 Engines 
- 1967-1969** Buick 455 Engines - (Will Fit But Look Different)
- A beautiful chrome valve cover set.
- VC555C.....\$149.50 pr.

Aluminum Valve Covers

-  **1953 thru 1966** all 264, 322, 364, 400, 40, 425 engines. Grooved with "BUICK" as original. Nice reproduction! Matte finish.
AVC536.....\$199.00 pr.
-  **1953 thru 1966** all 264,322,364,400,401,425 engines. Grooved with "BUICK" as original. Nice reproduction! Bright finish. Includes PCV grommet and gaskets.
AVC536B\$199.00 pr.
-  **1953-1966** all with aluminum valve covers. Spark plug wire retainer stanchion. Chrome plated.
WRS636.....\$37.50 pr.

Powder coated so not to flake, peel or chip. Tall valve covers allow use of adjustable roller rockers, large valves, springs and retainers. Thick aluminum construction allows for even gasket compression and proper sealing. Will not bend, dent or distort. Results in reduced engine noise and heat.

- AVC350.....(350 Engines).....\$179.50 pr.
- AVC455...(1967-1976 400,430,455 Engines)...\$179.50 pr.

-  **1967-1976** Valve cover retaining nut and plate.
RCS686\$3.75 ea.
-  **1967-1976** Valve cover retaining nut and plate. Chrome plated.
RCS686C\$5.50 ea.
-  **1967-1976** Valve cover retainer with tall stud.
RCS686T\$5.50 ea.
-  **1967-1976** Valve cover retainer with tall stud. Chrome plated
RCS686TC\$5.75 ea.

Engine Parts (Group 0)

Push Rods

1961 All 364 engines.

PR573.....\$7.25 ea.

PR573S.....(Set of 16).....\$74.25 set

1961-1966 All 400, 401, 425 engines.

1965-1967 all 225, 300 engines.

PR597.....\$5.75 ea.

PR597S.....(Set of 16).....\$78.00 set

PR657S.....(Set of 12).....\$59.50 set

1964 All 225, 300 engines.

PR64.....\$3.75 ea.

PR64S6.....(Set of 12).....\$40.25 set

PR64S8.....(Set of 16).....\$52.00 set

1966-1969 All 340, 400, 430 engines.

PR669.....\$3.75 ea.

PR669S.....(Set of 16).....\$58.00 set

1968-1969 All 350 engines.

PR689.....\$4.25 ea.

PR689S.....(Set of 16).....\$58.00 set

1970-1981 All 350 engines.

PR701.....\$4.25 ea.

PR701S.....(Set of 16).....\$58.00 set


1970-1976 All 455 engines.

PR706.....\$4.25 ea.

PR706S.....(Set of 16).....\$58.00 set

Freeze Plug Kits

Kits contain necessary plugs for block, cam, oil holes. "B" kits contain brass water jacket plugs



1961-1966 All 364, 400, 401, 425 engines. Steel.

FPK536\$18.50 ea.

1964-1980 All 225, 300, 340 and 350 engines. Steel.

FPK640\$10.50 ea.



1964-1980 All 225, 300, 340 and 350 engines. Brass.

FPK640B\$11.50 ea.


1967-1976 All 400, 430 and 455 engines. Steel.

FPK670\$10.00 ea.



1967-1976 All 400, 430 and 455 engines. Brass.

FPK670B\$15.50 ea.



Harmonic Balancer Bolt

1967-1976 All 400, 430, 455 engines.
HBB676\$7.50 ea.

Timing Chain Covers

1961-1966 All 364, 401 and 425 engine. .
TC576.....\$ 299.00 ea.



1967-1976 All 400, 430 and 455 engine. Includes front seal.
TC676.....\$ 479.00 ea.

Timing Chain Sets With Iron Cam Gear



1961-1966 All 364, 401, 425 engines.
TS576\$108.50 ea.
TC536.....Chain Only.....\$34.50 ea.
1966-1972 All with 340, 350 engines.
TS610\$23.00 ea.
1967 430 engines. (early production cars w/ 2.20" pilot diameter on camshaft sprocket).
TS67E.....\$68.75 ea.
1967-1976
1967: Late prod. w/ 2.26 pilot diameter on cam sprocket;
1968-1976: 430 and 455 engines.
TS676\$56.25 ea.

Clutch Pilot Bearing



1961-1975 Standard transmission.
Clutch pilot bearing.
PB570.....\$8.25 ea



www.oldbuickparts.com
908-369-3666

Oil Slinger (.615)

1961-1975 All. 300, 340 and 350 engines.
OS615\$11.75 ea.
1967-1974 Intake manifold ventilation rubber grommet.
VG634\$7.75 ea.

Flywheels

1964-1975 All 300, 340 and 350 engines with auto. transmission
FW645.....\$39.50 ea.



1967-1976 All. 400, 430 and 455 engines with auto transmission.
FW676\$99.00 ea.

Timing Cover Seals



Our modern steel housed, silicon seals replace the OEM "rope" seal and steel retainer. A spring insert keeps pressure against balancer for improved sealing. Application may be greater than listed.

1961-1966 All 364,400, 401, 425 engines.
TCS536L\$11.75 ea.

1961-1967 All 215, 300, 340 engines.
TCS617\$11.75 ea.

1968-1975 All 350 engines.
TCS640\$11.75 ea.

1967-1976 All 400, 430 and 455 engines.
TCS650\$17.00 ea.

Rear Main Seals

Replaces OEM "rope" seal.



1957-1960 All. V-8 engines. Rubber lip type seal.
RMS576.....\$19.50 ea.

1964-1975 All 300, 340 and 350 engines.
RMS640.....\$18.00 ea.

1967-1976 All 430 and 455 engines.
RMS650.....\$25.25 ea.

Oil Pump Covers

1964-1981 All 225, 300, 340, 350, 430, 455 engines.
1967-1969 400 engines.
OPC646\$79.50 ea.



1974-2009 All 3.8 (231), 4.1 (252) Metric.
OPC749\$79.50 ea.

Engine Gaskets (Group 0)

Valve Cover Gaskets



1961-1966 364, 400, 401, and 425 engines.
VCG536\$16.50 pr.

1962-1967 198 and 225 V-6 engines.
VCG627\$12.50 pr.

1964-1967 300 and 340 engines.
VCG617\$15.00 pr.

1967-1972 400, 430 and 455 engines.
VCG676\$17.75 pr.

1968-1976 350 engines.
VCG686\$11.25 pr.

Push Rod Cover Gasket

1961-1966 364, 401 and 425 engines.
PRG576.....\$9.75 ea.

Timing Cover Gasket Sets

1961-1966 364, 401, 425 engines.
TCS536.....\$19.50 set

1964-1976 All 300, 340, 350 engines.
TCS646\$25.25 ea.

1967-1976 400, 430 and 455 engines.
TCS676\$25.25 set



Full Engine Overhaul Gasket Sets

1961-1966 364, 400, 401 and 425 engines.
FGS576.....\$129.50 set

1964-1967 300 and 340 engines.
FGS647B\$92.25 set

1967-1976 400, 430 and 455 engines. *
FGS676.....\$81.25 set

1968-1976 350 engines. *
FGS686.....\$84.25 set

* Intake manifold gasket not included, please see Group 3.

Cylinder Head Rebuilding Gasket Sets

1961-1966 364, 400, 401 and 425 engines.
HGS576\$79.95 set

1964-1967 300 and 340 engines.
HGS647B\$69.75 set

1967-1976 400, 430 and 455 engines. *
HGS676\$51.00 set

1968-1976 350 engines. *
HGS686\$41.50 set

* Intake manifold gasket not included, please see Group 1.

Cylinder Head Gaskets

1961-1966 364, 400, 401 and 425 engines.
HG576\$67.50 pr.


1964-1967 300 and 340 engines.
HG647B\$58.00 pr.

1967-1976 400, 430 and 455 engines.
HG676\$40.75 pr.

1968-1976 350 engines.
HG686\$36.75 pr.

Exact Original Colors to Authenticate your Engine. Our Enamels are the Finest available. Very High Temperature. Can be easily Brushed or Sprayed to obtain a Rich Deep Gloss. Sold in Quart or Spray Cans.

*** Note: Spray cans can not be shipped by Air.**



High Heat - High Gloss

1961-1967	Buick Green.....EP536	\$27.50 ea.	EP536S.....\$14.00 ea.
1961-1964	Buick Silver.....EP614	\$27.50 ea.	EP614S.....\$14.00 ea.
1965-1974	Buick Red.....EP644	\$27.50 ea.	EP644S.....\$14.00 ea.
1975-1982	Buick Lt. Blue.....EP770	n/a	EP752S.....\$14.00 ea.
1983	Black.....EP1.....	\$24.50 ea.	EP1S.....\$14.00 ea.

Spray Gun for Engine Enamels



Self-propelled unit enables you to spray up to 16 oz. of paint. Great for use on engine enamels listed above that are not available in spray cans.

SG220.....\$12.50 ea.

Refill cannister for above.

SGR220.....\$9.50 ea.



Cast Iron Paint

Extremely High Temperature - 1800 degrees. Excellent for manifolds and exhaust systems. **Will not burn OFF.**

EP3.....(pint).....\$32.00 ea.

EP3S.....(spray can).....\$19.50 ea.

Engine Compartment and Chassis Paint

Our satin black enamel contains the correct blend of dulling agents to give that "Authentic New Look". Use it on inner fender wells, under hood, radiator supports brackets, fan, air cleaner, etc. It is also correct for chassis.

All Years and Models

EP2.....\$24.50 ea.

EP2S.....\$14.00 ea.



12 oz.
Spray Can

Air Cleaner Identification (Group 0)

1964-1966 Air Cleaner I.D. Plate


Not just a "decal", but a high quality silk screened impression on a die cut reflective aluminum disc. Add the final touch to your highly detailed engine compartment. Will not fade or wrinkle. Easy to apply. Absolutely show quality. Approved and licensed by Buick.



1964-1966 401 Engines "Buick Wildcat 445". 10" Diameter.
D92A.....\$37.50 ea.



1964-1966 425 Engines "Buick Wildcat 465". 10" Diameter.
D99A.....\$37.50 ea.



1965-1966 401 Engines "Buick Wildcat 445". 14" Diameter.
D114A.....\$37.50 ea.



1964-1966 425 Engines "Buick Wildcat 465". 14" Diameter.
D94A.....\$37.50 ea.

(Group 0) Air Cleaner Identification



D126



D181



D98

- | | | | |
|-------|---|-------|--|
| D85 | 1960-1963 401 engine "Wildcat 445" Yellow two piece set.\$12.25 | D57 | 1967-1969 "430-4" Red & white crescent.....\$4.75 |
| D45 | 1961-1963 401 Engine Air Cleaner instructions. On side.\$5.00 | D58 | 1967-1969 "400-4" Red & white crescent.....\$4.75 |
| D349 | 1961 All Air Cleaner Instruction A63C Filter\$5.00 | *D58N | 1967-1969 "400-4" Red & white crescent.....\$12.75 |
| D350 | 1962-1963 "Wildcat 410" Snorkle decal\$6.25 | D56 | 1968-1974 "Keep Your GM Car All GM" #6424826.....\$5.00 |
| D180 | 1962-1963 Wildcat with 401, "445 Wildcat" 10" diameter silver.\$12.75 | *D56N | 1968-1974 "Keep Your GM Car All GM" #6424826.....\$8.25 |
| D352 | 1964-1965 300 Engine A96C Air Filter Instruc.\$5.50 | D47 | 1968-1974 "350-2" Red & white crescent.....\$5.00 |
| D243 | 1964-1966 300 Engine Air Filter Instrut. #6421191.....\$5.00 | D48 | 1968-1974 "350-4" Red & white crescent. 8"\$5.00 |
| D94 | 1964 & 1966 425 engine "Buick Wildcat 465". Red 14" diameter.\$12.50 | *D48N | 1968-1974 "350-4" Red & white crescent. 8"\$12.75 |
| *D94A | Same application as above. Authentic Reproduction Show Quality Silk Screened Metal Plate.....\$37.50 | D49 | 1968-1974 "350-4" Red & white crescent. 11"\$6.00 |
| D159 | 1964-1965 LeSabre with 300 2BBL - "Wildcat 310". 8" diameter.\$14.25 | D50 | 1970-1971 "350-4 Hi-compression" crescent.\$6.00 |
| D109 | 1964-1965 LeSabre with 300 4 BBL "Buick Wildcat 355". 8" diameter.\$12.75 | *D50N | 1970-1971 "350-4 Hi-compression" crescent.\$12.75 |
| D96 | 1965 401 Eng. Air cleaner instruct. #6420861.....\$6.25 | D54 | 1970-1975 "455-4" Red & white crescent.....\$5.00 |
| D99 | 1964-1966 425 engine "Buick Wildcat 465". Red 10" diameter.\$12.50 | D51 | 1970-1975 "GS-455" Red & white crescent.....\$5.00 |
| *D99A | Same application as above. Authentic Reproduction Show Quality Silk Screened Metal Plate.....\$37.50 | D51E | 1970-1975 "GS-455" Red & white crescent.....\$8.50 |
| D92 | 1964-1966 401 engine "Buick Wildcat 445". Red 10" diameter.....\$12.50 | D52 | 1970-1973 "Stage 1" Red & white crescent.....\$6.00 |
| *D92A | Same Application as above. Authentic Reproduction Show Quality Silk Screened Metal Plate.....\$37.50 | D52E | 1970-1973 "Stage 1" Embossed as original.\$6.00 |
| D126 | 1964-1966 425 engine, 2 X 4BBL (chrome air cleaner) "Super Wildcat".....\$8.00 | D53 | 1970-1973 "Stage 2" Red & white crescent.....\$6.00 |
| D141 | 1966 LeSabre 340 2bb."Wildcat 350" ACD\$11.25 | D314 | 1974-1976 "455-2V"\$5.00 |
| D354 | 1966 340-4 Air Cleaner Filter Instruc. 6424150.....\$3.75 | D317 | 1975-1976 "231-2V"\$5.00 |
| D293 | 1966 "Wildcat 375" 7" Air Cleaner Decal.....\$11.25 | D319 | 1977-1979 "Buick V-6".....\$6.00 |
| D97 | 1966 401 Eng. Air cleaner instruct. #6422189.....\$4.25 | D320 | 1977-1979 "3.8 Litre".....\$6.00 |
| D90 | 1966 Wildcat GS. Air Filter Instr. A85C\$5.50 | D329 | 1978-1981 "Turbo 3.8 Litre".....\$6.00 |
| D98 | 1967 "Buick Wildcat Power". Red decal.\$8.25 | | |
| D181 | 1967 "Front" White lettered decal on snorkel.\$4.00 | | |



D56



D54



D51

Please Note!
 Numbers preceded by an asterisks (*) are very special. Those ending in "A" are "Authentic". For example D99A is a high quality silk screened emblem on an aluminum plate, as the original. We guarantee no point deductions at Judged Shows for these reproductions. Numbers ending in "N" are NOS! If you have a serious eye for detail, you will surely appreciate the clarity and construction of these originals. Some feature raised print and correct embossing.
Quantities are limited.

Decals • Tags • Stickers (Group 0)


Valve Cover Identification

D88	1966-1967 "340-2". Black and silver.....	\$5.00
* D88N	1966-1967 "340-2". Black and silver.....	\$6.75
D89	1966-1967 "340-4". Black and silver.....	\$5.00
* D87N	1967 "300-2" Black and silver.....	\$6.75
D87	1966-1967 "300-2" Black and silver.....	\$5.00
D183	1966-1967 "300-4V" Black and silver.....	\$5.00
D70	1967-1969 "Buick 400-4" Black and silver.....	\$5.00
D65	1967-1969 "Buick 430-4" Black and silver.....	\$5.00
D66	1968-1974 "Buick 350-2" Black and silver.....	\$5.00
D67	1968-1974 "Buick 350-4" Black and silver.....	\$5.00

Interior Decals and Stickers

D165	1961-1962 Glove box "Lacquer Paint" (round).....	\$5.00
D379	1961-1963 "Air Conditioned" Window Decal.....	\$5.00
D71	1961-1963 Casco Automatic Lighter tag.....	\$4.00
D386	1961-1964 Delco Battery Certificate.....	\$4.00
D375	1961-1965 Electric Antenna Tag.....	\$4.75
D281	1963 Tire Pressure Instruction.....	\$5.00
D384	1965-1968 Litter Box Decal.....	\$4.75
D279	1965-1968 Delco Battery Certificate.....	\$4.00
D362	1966 Glove Box Tire Pressure(exc. Wildcat GS).....	\$5.00
D363	1966 Wildcat GS. Glove Box Tire Pressure.....	\$5.00
D95E	1966-1967 "GM Mark of Excell" Embossed.....	\$5.50
D369	1966-1969 New Car Factory Build Sheet.....	\$5.50
D91	1967 Glove Box Tire Pressure.....	\$5.50
D376	1967 Climate Control Tag.....	\$5.00
D337	1968 Glove Box Tire Pressure.....	\$5.00
D55	1968-1975 "GM mark of excellence" door sticker.....	\$3.75
D55E	1968-1975 "GM mark of excell" Embossed.....	\$6.50
D381	1968-1970 Luggage Instruction Tag.....	\$5.50
D377	1968-1970 Climate Control Tag.....	\$5.00
D388	1969-1972 Ignition Lock/Start Sleeve 6".....	\$5.00
D389	1969-1972 Ignition Lock/Start Sleeve 7".....	\$4.75
D77	1969-1975 Windshield washer Bottle Decal.....	\$5.50
D341	1970 All Glove Box Tire Pressure Decal.....	\$5.50
D105	1971 Glove Box Tire Pressure and Maint.....	\$5.00
D380	1971-1973 Starting Instruction Tag.....	\$4.75
D137	1972 Glove Box Tire Pressure and Maint.....	\$5.50
D378	1972-1973 A.C. Instruction Tag.....	\$5.75
D390	1973 Unleaded Fuel Sun Visor Sleeve.....	\$5.50
D138	1973 Glove Box Tire Pressure #1246051.....	\$5.00
D391	1973-1974 Ignition Lock Instruction Sleeve.....	\$5.00
D139	1973-1974 Glove Box Tire Pressure #1247186.....	\$5.00
D342	1973-1974 Glove Box Fuel Recommend.....	\$4.75
D393	1974-1976 Instruction Sun Visor Start Sleeve.....	\$4.75
D212	1975-1976 Push Start Warning Decal.....	\$4.25
D392	1975-1977 Instruction Sun Visor Start Sleeve.....	\$4.75
D366	1976-1977 Headlight Dimmer Instr. Tag.....	\$4.75
D158	1980-1981 Aluminum Wheel Instruction Decal.....	\$4.50

Emission Stickers



D264	1968 400 and 430 Manual transmission.....	\$4.75
D262	1968 All 350 Manual transmission.....	\$4.75
D265	1968 350 & 430 Automatic transmission.....	\$5.00
D261	1968 350 2BBL Automatic transmission.....	\$4.75
D266	1969 350 2BBL Automatic transmission.....	\$4.75
D292	1969 350-4 + 430-4 Automatic transmission.....	\$4.75
D185	1969 400-4 Automatic transmission.....	\$4.75
D263	1969 400 Manual transmission.....	\$4.75
D128	1969 430-4 Auto transmission.....	\$5.00
D167	1970 (Before 1/70). 350 2 BBL. Auto trans.....	\$4.75
D168	1970 350 4 BBL. Auto transmission.....	\$4.75
D62	1970 All with 455 stage 1 engine.....	\$5.00
D294	1970 All V-8 "Evaporative control" decal.....	\$5.00
D309	1970 455 Automatic transmission.....	\$5.00
D291	1970 350 4BBL Automatic transmission High comp.....	\$5.00
D186	1971 350-2BBL.....	\$4.75
D268	1971 Buick 350-4 Automatic transmission.....	\$6.00
D270	1971 Buick GS 455 Automatic transmission.....	\$6.00
D278	1972 Buick 350 4BBL Automatic transmission.....	\$5.75
D307	1972 All 445 Automatic transmission.....	\$5.00
D312	1973 1973 All 455.....	\$6.00
D313	1973 All 445 Stage 1.....	\$6.25
D315	1974 455 4BBL Automatic transmission.....	\$6.25
D316	1974 455 Stage 1 Automatic transmission.....	\$6.25
D318	1976 231-2V.....	\$6.00
D321	1977 305-2V.....	\$6.00
D322	1977 350-4V-AY 460125.....	\$6.00
D323	1977 350-4V A.T. HI-ALT.....	\$6.00
D324	1977 350-4V A.T. OD 556514.....	\$6.00
D325	1977 403-4V A.T. Calif. OT 556519.....	\$6.00
D326	1977 403-4V A.T. SH 558429.....	\$6.00
D327	1977 403-4V A.T. SM 558643.....	\$6.00
D328	1977 403-4V A.T. OM 5573006.....	\$6.00
D330	1978 301 A.T. RM 10002736.....	\$6.00
D331	1978 305-2V CW 472882.....	\$6.00
D332	1978 350 Automatic transmission LM-476338.....	\$6.00
D333	1979 403-4V 6.6 Litre Auto. Trans.SX 22500543.....	\$6.00

Please Note!

Numbers preceded by an asterisks (*) are Very Special. Those ending in "A" are "Authentic". For example D99A is a high quality silk screened emblem on an aluminum plate, as the original. We guarantee no point deductions at judged shows for these reproductions Numbers ending in "N" are NOS! If you have a serious eye for detail, you will surely appreciate the clarity and construction of these originals. Some feature raised print and correct embossing.

Quantities are limited.



D128



D390



D71

Engine Compartment Decals



D46

D46	1960-1968 "Optikleen" Washer Bottle Label.....	\$3.75
D107	1960-1968 "Optikleen" Bottle Cap Decal.....	\$4.00
D178	1961 Cooling Caution Decal	\$4.75
D1	1961-1962 Generator Warning Tag	\$2.00
D184	1961-1962 Oil Filler Cap Decal. (orange).....	\$3.00
D386	1961-1964 Delco Battery Owners Certificate.....	\$3.75
D205	1961-1966 "GM" Antifreeze Tag	\$4.75
D80	1962-1964 Cooling System Sticker. (On fan shroud).....	\$4.75
D130	1963-1967 "Positive to Positive" Battery Warning...	\$4.50
D100	1963-1978 "GM antifreeze" Sticker.....	\$4.00
D246	1965-1966 Cross Flow Radiator Decal	\$5.50
D122	1965-1966 Downflow Radiator Decal.....	\$5.00
D125	1965-1966 Battery Warning Decal.....	\$4.50
D357	1966-1967 "Canada" Oil Change Decal.....	\$5.50
D358	1968-1969 "Canada" Oil Change Decal.....	\$5.50
D63	1968-1974 "Positive to Positive" Battery warning...	\$4.25
D359	1970-1971 "Canada" Oil Change Decal.....	\$5.00
D210	1970-1972 Cooling System Decal.....	\$4.25
D228	1980-1983 Glow Plug Caution 563050.....	\$5.50



D359

Exterior Decals

D398	Buick Tri-Shield 1 1/2" Wheel Center Decal.....	\$4.75
D399	Buick Tri-Shield 2 7/8" Wheel Center Decal.....	\$4.75
D400	1970 Gas Cap Caution Decal (California Cars)	\$5.50
D405	"Unleaded Fuel Only" 5" Straight - White.....	\$5.00
D406	"Unleaded Fuel Only" 5" Straight - Black	\$5.00
D407	"Unleaded Fuel Only" 4" Straight - Blk. & White	\$5.00
D408	"Unleaded Fuel Only" 4" Straight - Blk. & Silver.....	\$5.00
D410	"Unleaded Fuel Only" 3" Curved - White.....	\$5.00
D411	"Unleaded Fuel Only" 3" Curved - Black.....	\$5.00

D310 All Years. Buick Red, White and Blue Tri-Shield Logo.
12" Diameter.....\$9.75

Air Conditioning Tags

D72	1961 Harrison A.C. evap. box tag.....	\$6.00
D172	1961-1963 Compressor warning decal.....	\$5.00
D379	1963 "Air Conditioned" Window decal.....	\$5.50
D297	1964 Frigidaire compressor decal.....	\$5.75
D187	1965 Frigidaire air conditioner compressor decal.....	\$5.75
D190	1965 Harrison air conditioner box decal. EBA-70-65B	\$5.00
D251	1966 Frigidaire compressor decal.....	\$5.00
D191	1966 Harrison air conditioner box decal. EBA-70-66B	\$5.00
D192	1967 Harrison air conditioner box decal. EBA-70-67B	\$5.50
D298	1967-1968 Frigidaire compressor decal.....	\$5.50
D193	1968 Harrison air conditioner box decal. EBA-70-68B	\$5.00
D252	1969 Frigidaire compressor decal.....	\$5.75
D194	1969 Harrison air conditioner box decal. EBA-70-69A	\$5.00
D253	1970 Frigidaire Compressor decal.....	\$5.00
D195	1970 Harrison air conditioner box decal. EBA-70-70B	\$5.75
D299	1971 Frigidaire Compressor decal.....	\$5.75
D196	1971 Harrison air conditioner box decal. EBA-70-71B	\$5.00
D189	1972 Frigidaire air conditioner compressor decal...	\$5.75
D197	1972 Harrison air conditioner box decal. EBA-70-72B	\$5.00
D198	1973 Harrison air conditioner box decal. EBA-070-73B	\$5.00
D199	1974 Harrison air conditioner box decal. EBA-070-74B	\$4.25
D200	1975 Harrison air conditioner box decal. EBA-070-75B	\$5.00
D201	1976 Harrison air conditioner box decal. EBA-070-76B	\$4.25
D415	1977 Harrison air conditioner box decal. ACM-050-77B	\$6.25
D260	1978 Harrison air conditioner box decal. ACM-050-78B	\$6.25
D256	1979 Delco A.C. compressor 1131198	\$6.25
D233	197-1980 Harrison air conditioner box decal. ACM-056C-798	\$5.75
D250	1980 Harrison air conditioner box decal. EBA-112-80B	\$6.25
D258	1981 Delco A.C. compressor 1131198	\$6.25
D255	1981 Harrison air conditioner box decal. 3042218	\$6.25

Please Note!

Numbers preceded by an asterisks (*) are Very Special. Those ending in "A" are "Authentic" . For example D99A is a high quality silk screened emblem on an aluminum plate, as the original. We guarantee no point deductions at judged shows for these reproductions. Numbers ending in "N" are NOS! If you have a serious eye for detail, you will surely appreciate the clarity and construction of these originals.

Some feature raised print and correct embossing.
Quantities are limited.

Decals • Tags • Stickers (Group 0)



D 108



D 112



D 117



D 111



D310



D 118

Garage Wall, Tool Box Decals

- D108 Old Style Buick Logo (blue and white).....\$8.50
- D111 "Genuine Buick Parts" 2" x 2 1/2" Water Transfer..\$1.50
- D112 "Buick 8" 2" x 2 1/2" Water Transfer.....\$1.50
- D117 "Authorized Service" (10" diameter red, white and blue decal).....\$8.50
- D118 "Authorized Service" (5" diameter red, white and blue decal).....\$6.50
- D310 Tri-Shield 12" (red, white and blue).....\$9.75

- D153 1973 LeSabre, Centurion, Electra tire stowage....\$4.50
- D225 1973-1977 Space saver spare decal.....\$5.00
- D227 1973-1977 Tire inflator decal.....\$5.00
- D221 1974 Apollo hatchback jack instructions.....\$5.50
- D222 1974 Apollo sedan jack instructions.....\$4.50
- D220 1974 Century, regal jack instructions.....\$4.50
- D152 1974 Electra and LeSabre tire stowage.....\$5.00
- D151 1974 Electra and LeSabre jack instructions.....\$6.50
- D223 1975 Century and regal jack instructions.....\$4.50
- D335 1976 Century and Regal jack instructions.....\$4.50
- D306 1975-76 LeSabre, Centurion and Electra tire stowage - Regular wheel.....\$4.75
- D280 1975-1976 LeSabre, Electra jack instructions.....\$4.75
- D224 1975-1978 Apollo Sedan jack instructions.....\$4.25
- D226 1973-1974 Apollo hatchback lid decal #1704575.\$5.00
- D281 1963 Electra, Wildcat, LeSabre jack instructions. \$5.00
- D282 1967 Electra, Wildcat, LeSabre jack instructions. \$4.75
- D283 1968 Electra, Wildcat, LeSabre jack instructions. \$4.25
- D284 1969 Electra, Wildcat, LeSabre jack instructions. \$4.50
- D285 1970 Electra, Wildcat, LeSabre jack instructions. \$4.25
- D286 1971 Electra and LeSabre jack instructions. \$5.00
- D287 1972 Electra, LeSabre and Centurion jack instructions. \$4.50
- D288 1972 Electra, LeSabre and Centurion convertible jack instructions. \$4.50

Jacking Instructions & Trunk Stickers



D42

NEW Car Window Sticker & Booklet



D129

- D170 1961 Jack base sticker.....\$4.50
- D119 1961 All. Jack Instructions Trunk Sticker.....\$4.25
- D361 1962 All. Jack Instruction Trunk Sticker.....\$5.00
- D348 1962-1964 All. Jack base decal.....\$4.75
- D281 1963 All. Jack Instructions Trunk Sticker.....\$5.00
- D336 1964 All Jack instructions. Tire pressure.....\$5.50
- D42 1965 Electra, Wildcat, LeSabre jack instructions....\$4.25
- D43 1966 Electra, Wildcat, LeSabre jack instructions....\$4.25
- D395 1970-1972 Space Saver Tire Inflator decal.....\$5.50
- D396 1971-1973 Canada Limited Slip decal.....\$5.50
- D218 1973 LeSabre, Electra, Centurion, jack instrut.\$4.25
- D216 1973 LeSabre, Electra tire stowage with regular wheel. \$4.75

- D127 1963-1964 NEW Car Window Sticker.....\$5.00
- D371 1964 NEW Car Price Booklet.....\$4.75
- D372 1965 NEW Car Price Booklet.....\$4.75
- D129 1965-1966 NEW Car Window Sticker.....\$5.00
- D373 1966 NEW Car Price Booklet.....\$4.75
- D131 1967 NEW Car Window Sticker.....\$5.50
- D344 1968 NEW Car Window Sticker.....\$5.50
- D374 1971 NEW Car Price Booklet.....\$4.75
- D140 1971-1974 NEW Car Window Sticker.....\$5.50