


# Carburetor Rebuilding and Restoration Service (3.725)



Each carburetor is totally disassembled and cleaned in a hot tank solution. Then, each component is correctly plated, painted and colored to duplicate it's original factory finish. The carburetor is reassembled using all proper gaskets, pumps, needles and seats, etc. and new correct screws. Finally, all bench adjustments are made to factory specs. This includes correct shimming of the start switch. The result, the best rebuilt and restored carburetor available in the Hobby. **NOTE:** *This is not an area to skimp on your restoration. Demand the best!*

- 1961-1980** All 2bbl Carburetors w/ Bakelite switch.  
CRS390.....\$329.00 ea.
- 1961-1980** 4bbl. Carburetor rebuilding service.  
CRS520.....\$389.00 ea.
- 1964-1966** All Carter 2 X 4 sets..  
CRS636D.....\$692.00 ea.

## Carburetor Kits Carter Carburetors

- 1961-1967** 4BBL. Numbers: 3088, 89, 3297, 3578, 79,3633, 35, 65, 3826, 27, 3921, 22, 23, 4053, 54, 55, 56, 59, 60, 61, 4179, 80, 81, 4331, 32, 44, 4453. (Carter AFB 4BBL). 2 kits needed for 2 x 4 carbs.  
CKC617.....\$49.50 ea.
- 1961-1967** All with Carter AFB 4bbl. Stainless steel plate between carb. and intake manifold.  
BP576.....\$15.50 ea.

## Rochester Carburetors

- 1961-1962** All GC 4BBL. Numbers: 7013044, 7015040, 7019040, 7020040, 7020041.  
CKR592.....\$41.50 ea.
- 1961-1965** With 300 and 364 engines. 2GC 2BBL. Numbers: 7019042, 090, 093, 7020146, 147, 7023046, 047, 142, 7024046, 047, 7025046, 047.  
CKR615.....\$39.50 ea.
- 1962-1963** With 401 engines. 2GC 2BBL. Numbers: 7020046, 047, 048, 049, 7023041, 042, 043, 145, 146.  
CKR623.....\$39.50 ea.
- 1963-1966** With 401 engines. 4GC 4BBL. Numbers: 7023040, 7023143, 7024040, 7025040, 7025140, 7026040.  
CKR636.....\$39.50 ea.

- 1964** 300 engines. 4GC 4BBL. Numbers: 7024044, 7024045.  
CKR64.....\$35.00 ea.
- 1964-1965** All Rochester 1bbl.  
CKR645.....\$44.75 ea.
- 1966-1967**
  - 1966:** All 400, 401, 425;
  - 1967:** Early with 400 and 430 engines. 4MV 4BBL. Numbers: 7025240, 242, 7027146, 147, 148, 149, 7027240, 241, 7036240, 242.  
CKR667.....\$39.50 ea.
  - 1966-1969** With 300, 340 and 350 engines. 2GC, GV 2BBL. Numbers: 7026046, 047, 146, 147, 7027044, 045, 046, 049, 7028140, 7028141, 7029140, 141, 7036046, 048, 146, 248, 7037034, 7037044, 17054649.  
CKR669.....\$33.50 ea.
  - 1967** Late; With 400, 430 and 455 engines.MVBBL. Numbers: 7027244, 246, 248, 7041304, 305, 306, 307, 308, 309.
  - 1968-1970** Numbers: 7028240, 242, 243, 246, 247, 248, 7029240, 241, 242, 243, 7029246, 7040240, 7040243.  
CKR670.....\$35.00 ea.
  - 1968-1974** With 350 and 455 engines. 4MV 4BBL. Numbers: 7028244, 245, 7029244, 245, 7040244, 245, 7041245, 7041544, 7042244, 245, 944, 7043244, 245, 246, 7044244, 246, 544, 7044546, 17054900, 901, 902.  
CKR684.....\$29.00 ea.
  - 1970-1973** With 455 high performance engine. 4MV 4BBL. Numbers: 7040246, 247, 7041242, 243, 540, 7042240, 242, 243, 940, 7042942, 7043240, 242, 243, 7044240, 241, 252, 540.  
CKR702.....\$27.50 ea.
  - 1970-1974** 350, 455 engines with 2bbl. Numbers: 7040142, 143, 148, 444, 446, 7041142, 143, 442, 7042142, 7042143, 842, 7043142, 143, 144, 7044141, 142, 144, 442, 7044444, 17054651, 17055003, 17057350, 351.  
CKR704.....\$26.50 ea.
  - 1975** With 400 engine. 4MC 4BBL. Number: 7045254.  
CKR75.....\$26.50 ea.
  - 1975-1976** 455 engine. 4MC, MV 4BBL. Numbers: 7045240, 541, 548, 17056240, 540.  
CKR756.....\$26.50 ea.

## Stromberg Carburetors

- 1959-1961** LeSabre with Dynaflo transmission. WW type, 2BBL. Numbers: 7-112A, 7-113A and 7-114A.  
CKS591.....\$59.50 ea.
- 1961** LeSabre with WW 2BBL. Number: 7-114.  
CKS61.....\$49.50 ea.



## Remember!

Check to see that the carburetor number matches that of the part you are ordering.

# Fuel • Exhaust (Group 3)

## Air Filter Elements

1961-1962 All with 4 BBL carburetor.  
AF582.....\$15.50 ea.

1961-1967

1961-1962: 2 BBL;  
1963-1964: All;  
1965-1967: 300-340.

AF607 .....\$15.00 ea.

1964-1966 All V-8 with 2 X 4BBL carburetors.

AF646 .....\$28.75 ea.

1965-1967

1965-1966: 401-425 engines;  
1967: 430 except dual inlet. For 4bbl carbs.

AF657 .....\$15.25 ea.

1968-1975

1968: All 4 BBL;  
1970-1975: 455 engines.

AF680 .....\$12.25 ea.

1968 All with 350 engine 2 BBL carburetors.


AF625 .....\$11.25 ea.

1969-1975 350, 400 and 430 engines with 4 BBL except GS.

AF698 .....\$11.75 ea.



## Air Cleaner to Rocker Cover Hoses (formed as original) (1.745)



1968-1969 All 350, 400 and 430 engines except 1968 2bbl.  
VT689 .....\$18.50 ea.

1970-1974 All.

VT704 .....\$17.50 ea.

## Intake Manifold Plugs

This plug is often rusted out and sometimes missing. Leakage around this plug causes poor carburetion.



1961-1966: All 364, 400, 401, 425 engines with 4-bbl. carburetor.

MP596 .....\$12.75 ea.

## Choke Stove Pipe Replacement Kit

1961-1967

All as required.

CSK530.....\$18.25 kit



## Air Cleaner Wing Nuts

1961-1970 Air cleaner wing nut (1/4"-20 thread).

WN530.....\$1.75 ea.

1971-1980 Air cleaner wing nut (3/8"-16 thread).

WN710.....\$.75 ea.




## Exhaust Manifold Heat Pipe

(Air Cleaner to Exhaust Manifold)

1970-1974 All.

HP704.....Silver.....\$14.50 ea.

HP704B.....Black.....\$17.25 ea.



## Crankcase Ventilation Filter

On Side Of Air Cleaner

1968-1972 All.

CVF682.....\$4.75 ea.



## Carburetor Stud

Made of stainless steel.

1968-1975 All. 350, 400, 430, 455, 4BBL.

CS685.....\$6.00 ea.



## Carburetor Bowl Floats

1960-1967 Carter AFB 4BBL. Brass.(2 needed per car)

CF577C.....\$34.50 ea.

1961-1965 Rochester 2 GC. Brass.

1961-1965 300, 364 engines;

1962-1963 401 engine.

CF615R.....\$24.50 ea.

1966-1967 Rochester 4BBL

1966 All.

1967 Early.

CF667R.....\$19.50 ea.

1967-1974 Rochester 4BBL

1967 Late.

1968-1974 All.

CF674R.....\$19.50 ea.

## Choke Stove Pipe Insulator



This modern aramid fiber sleeve greatly resembles the original. It is heat resistant up to 1100°F. White in color. Also, excellent for wrapping vapor locked fuel lines. Sold by the foot. All years.

PI300.....\$5.25 ft.

## Carburetor Mounting Gaskets

1961 All Stromberg 2BBL Carbs.

CMG551 .....\$4.75 ea.

1961-1964 All Carter and Rochester 2BBL Carbs.

CMG554 .....\$4.50 ea.

1961-1965 All 4BBL;

1966 4BBL w/square bore;

1967 300, 340 4bbl.

CMG576 .....\$4.75 ea.

1966 425 Engine;

1967 All 400, 430, 455 with Rochester.

CMG667 .....\$6.50 ea.

1969-1975 All 400, 430, 455 with Rochester 4BBL.

CMG695 .....\$4.75 ea.



## Carburetor to Air Cleaner Gaskets

1966-1975 All 400, 430, 455 with Rochester 4BBL.

BG5152 .....\$3.75 ea.

### Choke Pull Offs



**1968-1974** 350, 400, 430 and 455 engines with 4BBL Rochester. Front.  
CPO684.....\$16.00 ea.

#### 1968-1971

**1968-1970:** 350, 400, 430 and 455 engines.  
**1971:** 350 engines.  
For Rochester 4BBL. Rear.  
CPO681.....TOS  
**1971** 455 engines. Rochester 4BBL. Rear.  
CPO71 .....\$24.75 ea.

### Gas Filters

**1960-1962** Gas filter element.  
Cars without air conditioning.  
GF572.....\$7.50 ea.



**1960-1962** Gas filter assembly.  
Cars without air conditioning.  
GF572A.....\$29.50 ea.

**1960-1962** Gas filter element.  
Cars with air conditioning.  
GF602.....\$9.50 ea.



**1963-1966** Gas filter.  
All cars without air conditioning.  
GF636 .....\$10.75 ea.



**1963-1966** All V-8 gas filter for cars with air conditioning.  
GF636A.....\$12.50 ea.

**1967** All;  
**1968-1974** All 350 2bbl;  
**1975** All 350 and 400 engines.  
GF675.....\$3.50 ea.



**1968-1974** All except 350 2bbl engines;  
**1975** All 455 engines.  
GF682.....\$3.50 ea.



**All years** replacement. Clear in-line gas filter. Great for near gas tank or frame installation. Important for insuring clean fuel to fuel pump.  
GF100.....\$4.50 ea.

### In Line Gas Filters



GF140.....For 1/4" ID Hose.....\$9.25 ea.

GF516.....For 5/16" IDHose.....\$9.25 ea.



GF516C..For 5/16" ID Hose(clear).\$6.50 ea.

GF380.....For 3/8" ID Hose.....\$9.25 ea.



### PCV Valves

**1963-1967** V6.  
PCV637.....\$6.75 ea.  
**1963-1972** All. V8.  
PCV635.....\$4.75 ea.



### PVC Valve Clamp

**All Years** For PCV hose.  
HC100W.....\$1.10 ea.

### PVC Valve Grommet



**All Years**  
VG634.....\$7.75 ea.

### Dash Pots

**1961-1971** All. Dash pot.  
DP611.....\$18.25 ea.



### Rod Clips

**1961-1966** Carburetor throttle rod clip. 1/4" rod diameter.  
RC460.....\$0.75 ea.



### Ported Vacuum Switches (2.410)

**1968-1976** 350, 400, 430 and 455 engines. (except PVS72 listed below). Located on front of intake manifold: 3 port.  
PVS684.....\$49.50 ea.



### Intake Manifold Gasket Sets

**1960-1966** All 364, 400, 401, 425 engines.  
IMG576 .....\$11.75 ea.  
**1964** All 300 engines.  
IMG64 .....\$19.50 ea.  
**1964-1967** All 225 V-6 engines.  
IMG647 .....\$14.25 ea.  
**1965-1967** All 300 engines.  
IMG657 .....\$16.50 ea.  
**1966-1967** All 340 engines.  
IMG667 .....\$16.50 ea.  
**1967-1971** All 400, 430, 455 engines.  
IMG671 .....\$47.50 ea.  
**1968-1980** All 350 engines.  
IMG685 .....\$39.50 ea.  
**1972-1976** All 455 engines.  
IMG726 .....\$39.50 ea.

### Carter Baffle Plate

**1961-1967** All with Carter AFB 4bbl. Stainless steel plate between carb. and intake manifold. This plate is essential for protection against disintegration of aluminum base of carb. It is also necessary for proper idle and smooth running. Recommended is gasket, baffle plate, gasket.  
BP576.....\$16.25 ea.



# Fuel and Exhaust (Group 3)

## Fuel Pumps (3.900)



**1961-1965** All. 364, 401, 425 engines. Rebuilding service or sold on an exchange with \$50.00 core charge.  
 FP595RS .....\$89.25 ea.

**1961-1965** All 364, 401 and 425 engines. Replacement fuel pump. No exchange necessary, sold outright.  
 FP575 .....\$39.75 ea.

**1964-1965** All 300 engines.  
 FP635 .....\$44.00 ea.

**1966** All 340 engines w/o a.c  
 FP66S .....\$39.50 ea.

**1966** 401 and 425 engines without air conditioning.  
 FP66.....Replacement.....\$44.50 ea.  
 FP66R.....Rebuild service.....\$59.50 ea.

**1966** All. 401 and 425 engines with air conditioning.  
 FP66A.....Replacement.....\$69.50 ea.  
 FP66AR.....Rebuild service.....\$59.50 ea.

**1967** 300 and 340 without air conditioning.  
 FP67 .....\$49.50 ea.

**1967** 300 and 340 with air conditioning.  
 FP67A.....\$39.00 ea.

**1968-1971** All 350 engines with air conditioning  
 FP682A.....\$38.50 ea.

**1967-1975** All 400, 430, 455 engines.  
 FP674 .....\$44.25 ea.

**1968-1975** All 350 without A.C.  
 FP685 .....\$38.50 ea.

**1975-1976** All 455 engines.  
 FP756 .....\$51.00 ea.

## Fuel Pump Rebuilding Kits

**1961-1965** All 364, 401, 425 engines. Rebuilding kit.  
 FPK575 .....\$59.50 ea.

## Fuel Pump Cam Eccentric



**1964-1975** 225, 300, 340 and 350 engines.  
 FPC615.....\$87.50 ea.

## Electric Fuel Pump

**1961-1972** All. 12V Universal replacement pump.  
 FP12 .....\$68.50 ea.

## Fuel Lines Fuel Pump to Carburetor

CARS#	YEARS	APPLICATION	PRICE
FL350	1968-1972:	All 350-4 ~~~~~	\$26.50
FL455	1968-1972:	400, All 455-4 ~~~~~	\$26.50
FL455S	1968-1972:	STAGE 1 455 ~~~~~	\$26.50
FL70	1970:	All 4 Bbl. carburetors~~~	\$26.50

## Fuel Pump Block-off Plates

**1961-1972** All as required.  
 CP300.....\$10.75  
 ea.



## Fuel Pump Hardware Kits

**1961-1966** all 364, 400, 401, 425 engines. Correct bolts/washers.  
 FPH406.....\$2.25 ea.



## Pinch Clamps

*For fuel lines, vacuum lines and PCV hoses*

CARS#	YEARS	PRICE
PC380	All	3/8" OD hose .....\$ 1.00
PC716	All	7/16" OD hose.....\$ 1.00
PC150	All	1/2" OD hose.....\$ 1.00
PC916	All	9/16" OD hose.....\$ 1.00
PC580	All	5/8" OD hose.....\$ 1.00
PC1116	All	1 1/16" OD hose.....\$ 1.25
PC100	All	1" OD hose.....\$ 1.25

## Fuel Line Clip Kits



**1967-1969** Electra, Wildcat, Invicta. 3/8" with return line. 12 piece kit.  
 FLC679R .....\$15.00 ea.  
**1967-1969** Electra, Wildcat, Invicta. 3/8" without return line. 4 piece kit.  
 FLC679 .....\$6.00 ea.  
**1970** Electra, Wildcat, Invicta. 3/8" with return line. 9 piece kit.  
 FLC70BR .....\$15.00 ea.  
**1970** Electra, Wildcat, Invicta. 3/8" without return line. 8 piece kit.  
 FLC70B.....\$10.00 ea.  
**1971-1976** Electra, Wildcat, Invicta. 3/8" with return line. 16 piece kit.  
 FLC716R .....\$28.00 ea.  
**1971-1976** Electra, Wildcat, Invicta. 3/8" without return line. 16 piece kit.  
 FLC716 .....\$18.00 ea.  
**1971-1976** Electra, Wildcat, Invicta. 3/8" with return line. 27 piece kit.  
 FLC776R .....\$32.00 ea.  
**1971-1976** Electra, Wildcat, Invicta. 3/8" without return line. 20 piece kit.  
 FLC776 .....\$25.00 ea.

**Exhaust Manifold Gaskets**



**1957-1966** All. 364, 400, 401, 425 engines.  
 EMG576 .....\$11.75 pr.  
 FG576.....( Flange gasket ) .....\$8.75 pr.



**1964-1967** All 300 and 340 engines.  
 EMG647 .....\$13.00 pr.



**1967-1976** All 400, 430 and 455 engines.  
 EMG676 .....\$15.00 pr.

**1968-1981** All 350 engines.  
 EMG681 .....\$16.50 pr

**Exhaust Manifold French Locks**



**1961-1966** All 364, 400, 401, 425 engines. Stainless steel. As required.  
 FL576 .....\$3.50 ea.



**1962-1966** All 400, 401, 425 engines;  
**1966 All** 300, 340 Engines. Stainless steel. As required.  
 FL626 .....\$1.75 ea.

**Brass Nuts.** Tall. All years as required. 3/8-16. Used on manifolds, pipes, exhaust, trim etc. Solid brass.  
 N6P.....\$3.75 pr.



**Gas Tank Parts**



**1961-1964** Gas tank fuel gauge gasket.  
 GG355 .....\$3.75 ea.



**1961-1975** All. Gas tank strap cushions.  
 SC350.....\$12.75 pr.


**1965-1966** All. Gas tank fuel gauge gasket.  
 GG642 .....\$5.00 ea.

**1967-1981** All. Gas tank fuel gauge gasket  
 GG671 .....\$6.75 ea.

**Gas Tank Bolt Kit**



**1961-1967** All as needed. Two 3/8-16 x 3" Bolts and two (2) lock nuts. Brightly zinc plated.  
 GB610 .....\$5.50 kit



**1967-1975** Gas door. (License plate) bumper.  
 GDB635.....\$5.00 pr.

**Gas Caps**



**1961-1964** Gas cap. (vented).  
 GC575 .....\$9.00 ea.



**1965-1970** All except wagons. Gas tank cap. (non-vented).  
 GC640 .....\$7.50 ea.



**1971-1974** All .  
 GC714 .....\$9.75 ea.



**1982-1984** All Electra.  
**1982-1985** All LeSabre and Wagon;  
 GC827 .....\$12.75 ea.  
**1982-1984** All Electra.  
**1982-1985** All LeSabre and Wagon. GM locking type with key.  
 GC827L .....\$33.50 ea

**Gas Tank Sealer/Liner**

Alcohol resistant. Quart can.  
 TS1.....\$30.00 ea.



**Gas Tank Etch**

Removes light rust and will prep for sealer/liner. 16oz.  
 TE1 .....\$16.00 ea.



**Lead Additive**

All Buick engines needing leaded gas.  
 LA1.....\$13.50 ea.

