

Transmission (Group 4)

Automatic Transmission Kits

Model	Year	Master Overhaul Kit	Banner Kit	Paper, Rubber, Rings & Seals	External Seal-up Kit
Dynaflow.....	1961-1963	TOK613..... \$239.50 ea.	TKB613..... 189.50 ea.	TRK613..... \$167.50 ea.	TSK613..... \$69.50 ea.
ST300.....	1964-1969	TOK300..... \$105.00 ea.	TKB300..... \$83.00 ea.	TRK300..... \$46.00 ea.	
TH350.....	1969-1979	TOK350..... \$95.50 ea.	TKB350..... \$84.50 ea.	TRK350..... \$35.00 ea.	TSK350..... \$29.50 ea.
TH350C.....	1980-1986	TOK350C..... \$114.50 ea.	TKB350C..... \$85.00 ea.	TRK350..... \$35.00 ea.	
TH400.....	1964	TOK400F..... \$114.50 ea.	TKB400F..... \$89.00 ea.	TRK400F..... \$47.50 ea.	
ST400 & TH400...	1965-1998	TOK400..... \$107.50 ea.	TKB400..... \$81.50 ea.	TRK400..... \$44.50 ea.	

Master Overhaul Kit: Gaskets, Friction (lined) Clutches, Lip Seals, Steel Clutches, "O" Rings, Front Pump Seal Sealing Rings and Extension Housing Seal.

Paper, Rubber, Rings and Seals: All gaskets, Lipseals, O-Rings, Sealing Rings (Popular Set), Front Pump Seal and Ext. Hsg. Seal.

External Seal-up Kit: Stops any external Leaks. Contains Front Pump Seal, Extension Housing Seal, Selector Lever Seal and External Gaskets (including Pan Gasket and Converter Gasket or O-Ring).

Banner Kit: Same as Master Kit, but without Steel Clutches.



Auto Transmission Oil Pan Gaskets



1961-1963 All Dynaflow.	
TPG483.....	\$10.00 ea.
1964-1969 Super Turbo 300, 14 bolt.	
TPG649.....	\$11.50 ea.
1964-1972 Turbo-Hydromatic 400, 13 bolt.	
TPG645.....	\$9.50 ea.


Transmission Filter Change Kits



1964-1969 With S.T. 300 (except early 1964).	
TFK300.....	\$36.75 ea.
1964-1966 all TH400;	
1967 early type TH400 with tube.	
TFK400T.....	\$36.75 ea.

1967 Late TH400 with flat filter;	
1968-1998 all TH400.	
TFK400.....	\$15.00 ea.

1969-1986 With TH-350 transmission.	
TFK350.....	\$11.50 ea.



Transmission Seals

1961-1963 Transmission front pump oil seal.	
TS483F.....	\$14.00 ea.
1961-1963 Converter pump seal. O-Ring.	
PS513.....	\$10.75 ea.
1961-1963 All;	
1964 thru 1976 all exc. TH400. Rear trans seal.	
TS616.....	\$10.75 ea.
1964-1976 All. Transmission front pump oil seal.	
TS646.....	\$11.50 ea.
1964-1968 All TH400, rear.	
TS640.....	\$12.25 ea.
1969-1976 All TH400, rear.	
TS696.....	\$11.50 ea.

Vacuum Modulator



1964-1998 All TH350 and TH400.	
VM642.....	\$29.50 ea.

Shifter Cables




1969-1972 All TH350 with long console. Shifter cable.	
SC682.....	\$65.75 ea.

Transmission Mounts



1964-1972
1964-1972: All with standard transmission;
1964-1970: All TH300 and TH350.
TM642.....\$19.00 ea.



1964-1970
1964-1966: Wildcat and Electra with TH400;
1967-1970: LeSabre, Wildcat and Electra with TH400.
TM640\$38.75 ea.



1965-1970
1965-1966: LaSabre with TH400;
1970: Estate Wagon with TH400.
TM650\$12.50 ea.



1971-1974 with TH400 (except 1973 wagon).
TM714\$14.50 ea.

Neutral Safety and Back- Up Switch




1962-1964 All with column shift.
Neutral safety switch.
NSS624\$34.50 ea.

1969-1972 All. Neutral safety switch.
NSS692\$24.50 ea.


Transmission Mount Rebuilding Service

We now offer you complete revulcanization of your motor mounts. Fresh, new rubber will insure safe and smooth running. The mounts listed below are sold on an exchange basis only. If we have your needed mount ready to ship we will charge you an additional core deposit of \$50.00 per item. This charge is fully refundable upon receiving your rebuildable cores. We prefer you send your mounts for rebuilding. Please allow at least 2 weeks for this process.

1961-1962 Transmission mounts.
Exchange.
TM612\$111.25 ea.



1963 All Dynaflow. Transmission mount.
Exchange.
TM63RS\$101.75 ea.



Speedometer Cables

1961-1975 All. State all information.
SC612.....\$22.75 ea.




1961-1975 All. Speedometer cable repair kit.
SRK360.....\$16.00 ea.

Speedometer Cable Lubricant

All years
SCL300.....\$5.00 ea.




**Call Cars Inc.
Today!
908-369-3666**



Brakes (Group 4)

Master Cylinder Resleeve



Master Cylinder Parts for Moraine Power Disc Brake

1971-1980 All.

MCC700.....Cover.....\$9.50 ea.
MCD700.....Diaphragm.....\$7.50 ea.

Brake Overhaul Kits


Our complete kits include the following:

- 4 Wheel cylinder kits and/ or caliper kits
- 1 Master cylinder kit (except 1963)
- 4 Brake shoes with linings or disc pads
- 3 Hydraulic Brake Hoses
- Brake spring hardware kits as required

BOK63....1963 (does not contain master cyl kit).....\$157.50 kit
BOK646M.....1964-1966 All.....\$225.00 kit
BOK678RMP.....1967 w/ 13/16" front wheel cylinders;
1968 All. For Moraine Drum Brakes....\$167.75 kit
BOK670.....1967-1970 Bendix Power Drum.....\$179.50 kit
BOK690RMP...1969-1970 Moraine Power Drum.....\$179.50 kit
BOK713RD.....1971-1973 Moraine Disc.\$179.50 kit

Power Brake Rebuilding Service

Master Cylinder and Booster with Exchange



1961-1962
1960-1961 all;
1962 all with metal vacuum inlet.
Power brake units rebuilt.
PBR610.....\$249.50 ea.
1963 Brake Booster only.
BBR63.....\$215.00 ea.

Brake Booster Hose Pinch Clamp

1961-1975 All.
PC1116.....\$1.25 ea.



Brake Booster Vacuum Check Valve

(4.955)



1967 LeSabre, Wildcat, Electra with Bendix power drum brakes;
1968 thru 1972 All.
CV682\$12.75 ea.

Master Cylinders



1967-1970 All with Bendix power drum brakes.
MC670B\$97.75 ea.
1971-1975 All Moraine power disc brakes.
MC685.....\$59.50 ea.

Master Cylinder Rebuilding Kits

1961-1962 All with Power Brake.
MK602\$22.25 ea.
1961-1966 Regular brakes. Master cylinder kit.
MK596\$26.25 ea.
1964-1966
1964: All;
1965-1966: With Moraine. Power brakes. Master cylinder rebuild kit.
MK646\$20.75 ea.
1967-1970 All with Bendix. Power brake master cylinder rebuilding kit.
MK670\$39.50 ea.
1967-1972 LeSabre, Wildcat, Centurion, Electra. Moraine regular and power brake master cylinder kit. For drum cars.
MK672\$45.75 ea.
1967-1975 All Moraine power disc brakes.
MK675\$30.50 ea.

Wheel Cylinders



Front

- 1961** All with horizontal mounting holes.
 FWC61L.....(left hand)\$42.50 ea.
 FWC61R.....(right hand)\$42.50 ea.

1961-1966

1961: All with diagonal mounting holes;
1962-1966: All.

- FWC617L.....(left hand)\$39.50 ea.
 FWC617R.....(right hand)\$39.50 ea.

1967-1968 All.

- FWC678L.....(left hand)\$49.50 ea.
 FWC678R.....(right hand)\$49.50 ea.

1969-1970 All.

- FWC690L.....(left hand)\$47.00 ea.
 FWC690R.....(right hand)\$47.00 ea.



www.oldbuickparts.com
908-369-3666

Rear

1961-1970 All.

- RWC500L.....(left hand)\$35.00 ea.
 RWC500R.....(right hand)\$35.00 ea.

1971-1975 All. Fits left and right hand.

- RWC718\$19.75 ea.



Wheel Cylinder Repair Kits

- 1961-1966** All 1 1/8" diameter, front
 FK426.....(right hand and left hand).....\$10.25 ea.

- 1967-1970** All with 1 3/16" diameter. Front
 FK670.....(right hand and left hand).....\$9.50 ea.

- 1961-1970** All. Rear. 1" Diameter.
 RK370.....\$9.50 ea.

- 1971-1974** Les., Centurion and Electra w/ 11 x 2" drums.
 Rear
 RK644.....\$7.50 ea.

- 1973-1974** Century and Regal rear. 7/8" diameter.
 RK672.....\$7.50 ea.



Disc Brake Caliper Repair Kits

- 1967-1969** All front disc brakes. (Bendix). For 1 wheel.
 CRK679\$29.50 ea.

- 1970-1996** Front disc brakes. For 1 wheel
1970-1985 LeSabre, Wildcat, Centurion, Electra;
1973-1977 Apollo, Century, Regal;
1970-1992 Estate Wagon;
1991-1996 Roadmaster.
 CRK696\$11.50 ea.

- 1978-1997** Front disc brakes. For 1 wheel.
1978-81 Century;
1983-1984 Century Heavy Duty;
1985-1989 Century Medium Duty;
1990-1996 Century;
1985-1991 Electra;
1986-1994 LeSabre;
1992-1997 Park Avenue;
1988-1991 Reatta.
 CRK767\$11.50 ea.

Brakes (Group 4)

Brake Shoes and Disc Pad Sets (5.017)



Front

1961-1970 All. Drum brakes.

BS197.....	\$49.50 set
1967-1969 All. Disc brakes. (4 pad set).	
DP16.....	\$29.50 set
1970-1980 All. Disc brakes.	
DP52.....	\$34.50 set

Rear

1961-1968 All. (Some models require hole drilling for spring)

BS194.....	\$59.50 set
1969-1970 All.	
BS340.....	\$59.50 set
1971-1974 All. 12" drum.	
BS714.....	\$29.25 set
1971-1976 All. 11" drum. 11' X 2".	
BS363.....	\$49.50 set

Brake Hoses

1961 all. Front brake hose. Left hand or right hand.

FH575.....	\$18.50 ea.
1962-1964 Front brake hose. Left hand or right hand.	
FH624.....	\$19.75 ea.
1965-1968 All. Front drum brake cars.	
FH650.....	\$18.50 ea.
1962-1966 Rear brake hose.	
RH626.....	\$18.50 ea.
1967-1968 Front brake hose. For cars with disc brakes.	
FH678.....	\$32.50 ea.
1967 LeSabre, rear.	
RH67.....	\$22.50 ea.
1967 Wildcat and Electra, rear.	
RH670.....	\$22.50 ea.
1968-1970 All, rear.	
RH680.....	\$31.25 ea.
1969-1970. 1969 all drum or disc; 1970 all drums, Front.	
FH682.....	\$16.50 ea.
1970-1973 1970-1973 all with disc brakes. Front.	
FH703.....	\$19.50 ea.
1973-1975 All. Century and Regal. Front brake hose.	
FH735.....	\$23.25 ea.
1971-1974 All exc. Apollo. Rear brake hose.	
RH714.....	\$38.50 ea.

Brake Adjusting Screws (5.023)

1960 thru 1962 all front or rear, left or right.

BAS362.....	\$10.75 ea.
1963-1991; Fits all front and rear drums.	
1963-1970 all;	
1977-1978 Electra w/ 11" drums;	
1979-1984 Electra;	
1977-1985 LeSabre with 11" drums;	
1977 Century and Regal;	
1977-1991 Estate Wagon.	
BAS636L.....(fits left hand side)	\$12.50 ea.
BAS636R.....(fits right hand side)	\$12.50 ea.
1973-1987:	
1975-1984 Skylark;	
1973-1981 Apollo and Century w/ 9 1/2" x 2" drums;	
1976-1984 Skyhawk;	
1977-1978 Electra w/ 9 1/2" x 2" drums;	
1977-1984 LeSabre w/ 9 1/2" x 2" drums;	
BAS674L.....(fits left hand side)	\$10.75 ea.
BAS674R.....(fits right hand side)	\$10.75 ea.

Brake Spring Kits

1963-1970 All front.

BSK630.....	\$19.50 kit
1963-1970 All rear.	
BSK630R.....	\$11.75 kit



Brake Hose Clip



1961-1990 All.

BC360.....	\$1.25 ea.
------------	------------



1961-1980 All as required. Brake backing plate hole cover.
BC340.....\$1.00 ea.

Pedal Pads (4.630)



1965-1970 LeSabre, Wildcat, Electra with auto trans. (Includes 2 Stainless Steel Strips)
1971-1974 (will fit but pattern is different)
PC650.....\$25.25 ea.



1973-1974 Apollo and Skylark w/ 350 auto trans. and drum brakes. Brake pedal pad.
PC642.....\$8.50 ea.



1973 thru 1978 Parking brake pedal pad.
PC642E.....\$8.75 ea.

Brake Drums (5.809)

Cast Iron replacements.
(When replacing aluminum front drums - purchase in pairs.)

~~~~~**Front**~~~~~

**1961-1964** LeSabre, Wildcat, Invicta, Electra, Riviera;  
**1965** Wildcat, Electra, Riviera.  
BD614F.....\$119.00 ea.  
**1966-1967** Wildcat, Electra, Riviera.  
BD667.....\$119.00 ea.  
**1965-1970** LeSabre.  
BD650.....\$119.00 ea.  
**1968-1970** Wildcat, Electra, Riviera, Estate Wagon.  
BD680.....\$119.00 ea.

~~~~~**Rear**~~~~~

1961-1964 LeSabre, Wildcat, Invicta, Electra, Riviera.
BD614.....\$119.00 ea.
1965-1970 LeSabre, Wildcat, Electra, Riviera.
BD650R.....\$119.00 ea.

Brake Pedal Pads

1961-1964 LeSabre, Invicta, Wildcat, Electra pedal covers. (includes Stainless Steel "POWER BRAKE" metal strip). Black, fawn, blue, brown, olive saddle, red and saddle.



| | | |
|--------------|-----------------------------|-------------|
| PC614..... | Black..... | \$24.50 ea. |
| PC614F..... | Fawn..... | \$24.50 ea. |
| PC614U..... | Blue..... | \$24.50 ea. |
| PC614B..... | Brown..... | \$24.50 ea. |
| PC614OS..... | Olive Saddle..... | \$24.50 ea. |
| PC614R..... | Red..... | \$24.50 ea. |
| PC614S..... | Saddle..... | \$24.50 ea. |
| PP614..... | (Stainless strip only)..... | \$4.75 ea. |

1961-1964 LeSabre, Invicta, Wildcat, Electra pedal covers. (includes Stainless Steel "PARK" metal strip). Black, tan, red, blue, brown, saddle, olive saddle.



| | | |
|---------------|-----------------------------|-------------|
| PC614E..... | Black..... | \$17.00 ea. |
| PC614EF..... | Fawn..... | \$17.00 ea. |
| PC614EU..... | Blue..... | \$17.00 ea. |
| PC614EB..... | Brown..... | \$17.00 ea. |
| PC614EOS..... | Olive Saddle..... | \$17.00 ea. |
| PC614ER..... | Red..... | \$17.00 ea. |
| PC614ES..... | Saddle..... | \$17.00 ea. |
| PP614E..... | (Stainless strip only)..... | \$4.00 ea. |

Stop Light Switches (2.447)




1961-1963 All. Stop light switch.
SLS563.....\$9.75 ea.
1964-1975
1964-1970: All;
1971-1975: Except cruise. Stop lamp switch.
SLS645.....\$12.75 ea.
1971-1975 All with cruise control.
SLS715.....\$7.75 ea.

Silicon Brake Fluid



1961-1980 Silicon brake fluid. (one gallon).
SF360.....\$63.00 ea.

Brake Cables (Group 4)



1961-1975

We can now reproduce any cable listed from **1961 through 1975** Cables are made using correct conduit, cable and hardware. Please note, some cables (*) require that we have your old unit for parts as some hardware items are not available. Some are available with a core charge.

| Year & Model | Front | Center | Rear |
|---|------------------------------|------------------------------|--------------------------------------|
| 1961 LeSabre, Invicta and Wildcat | R1199638.....\$79.50 ea..... | | R1365177 (2).....\$79.50 ea. |
| 1961 Electra | R1199638.....\$79.50 ea..... | | R1365178 (2).....\$79.50 ea. |
| 1962-1964 LeSabre, Invicta & Wildcat | R1365180.....\$79.50 ea..... | | R1365177 (2).....\$79.50 ea. |
| 1962-1964 Electra | R1365180.....\$79.50 ea..... | | R1365178 (2).....\$79.50 ea. |
| 1965-1968 All | R1394222.....\$79.50 ea..... | R1370084.....\$79.50 ea..... | R1369341 (2) (*).....\$79.50 ea. |
| 1969-1970 LeSabre & Wildcat | R1230211.....\$79.50 ea..... | R1386560.....\$51.00 ea..... | R1231508 (2).....\$79.50 ea. |
| 1969-1970 Electra | R1230211.....\$79.50 ea..... | R1386561.....\$51.00 ea..... | R1231508 (2).....\$79.50 ea. |
| 1971-1972 LeSabre and Centurion | R1240335.....\$79.50 ea..... | R1237721.....\$51.00 ea..... | R1236712 (2).....\$79.50 ea. |
| 1971-1973 Electra with 11" Diameter Rear Drums | R1240335.....\$79.50 ea..... | R1235466.....\$79.50 ea..... | R1236712 (2).....\$79.50 ea. |
| 1971-1973 Electra with 12" Diameter Rear Drums | R1240335.....\$79.50 ea..... | R1235466.....\$79.50 ea..... | R1235886 (2).....\$79.50 ea. |
| 1982-1988 Les. ex. wag.BC820F.....\$17.75 ea..... | | BC828RL..... | 1982-1988 Left rear.....\$35.50 ea. |
| | | BC824RR..... | 1982-1984 Right rear.....\$44.75 ea. |
| | | BC858RR..... | 1985-1988 Right rear.....\$43.75 ea. |
| 1988-1990 Les. ex. wag.BC820F.....\$17.75 ea. | | | |

ITEMS NOT PRICED MUST BE QUOTED. PLEASE INQUIRE!