



# Cooling (Group 1)

## Radiator Insulator

**1963-1965** Radiator mounting rubber insulator. Lower.  
RI614.....\$8.75 ea.



**1966** All. Radiator support bracket insulator. Fully molded.  
RI656.....\$32.00 pr.



## Radiator Hoses (1.159)



**1963-1965** Riviera. Lower radiator hose. Formed.  
LH429 .....\$18.50 ea.  
**1963-1965** All. Formed upper hose.  
UH625.....\$21.75 ea.  
**1969-1971** All. Upper.  
RH980.....\$22.25 ea.  
**1971-1974** All. Lower.  
RH648.....\$21.25 ea.  
**1972-1974** All. Upper.  
RH869.....\$22.50 ea.  
**1982-1985** all with 307Y or 350N engine. Upper.  
UH825R .....\$24.50 ea.  
**1982-1985** all with 307Y or 350N engine. Lower.  
LH825R.....\$17.00 ea

## Radiator Hose Clamps

These are authentic "Tower Top" hose clamps made by Wittek Company for GM. They are correct for all **1963-1990** models.



**2 1/16" diameter** - fits most upper hose.  
RC216.....\$2.75 ea.  
**2 1/4" diameter** - fits most lower hose.  
RC214.....\$2.75 ea.  
**2" diameter** - Where smaller clamp is desired..  
RC200.....\$2.75 ea.

## Thermostats

**1963-1966** Riviera thermostat with gasket.  
T536.....\$9.50 ea.  
**1967-1980** Riviera thermostat with gasket.  
T330.....\$9.75 ea.



## Water Outlets

**1963-1966** Water outlet with gasket.  
WO626.....\$22.25 ea.  
WOG536.....(Gasket only).....\$2.25 ea.  
**1967-1974** All. Engine block water outlet with gasket.  
WO615.....\$24.50 ea.  
WOG615.....(Gasket only).....\$2.25 ea.



## Radiator Caps

Take a good look at these Caps. They are identical to the originals. Correct in every detail, they feature the cap number, instructions and of course genuine "AC" identification stamped right into the cadmium plated surface. Show quality, approved and licensed by Buick.

**1963-1964** All. 15 lb.  
RC15D.....\$32.50 ea.  
**1965-1968** All. 15 lb.  
RC15F.....\$32.50 ea.



**1969-1970** All w/o coolant recovery system. 15 lb.  
RC15H .....\$32.50 ea.


## Radiator Cap Replacements

**1963-1969** All. 15 lb.  
RC579.....\$16.50 ea.  
**1970-1976** All.  
RC706.....\$9.75 ea.

## Breather Tubes

(Air Cleaner to Rocker Cover) (1.745)

Breather Tube



**1968-1969** All 350 and 400 4BBL.  
VT689.....\$19.50 ea.



**1970-1971** all V-8; **1972** all 455 engines  
VT704 .....\$16.50 ea.



## Heater Hose Clamps

Buick used "Tower Top" hose clamps on all cars from **1963-1975**. We supply the identical clamps made by the Wittek Company. They are authentic and correct.

1 1/16" for 5/8" heater hose.  
HC580.....\$2.75 ea.  
1" for use on thin walled 5/8" hose.  
HC580S.....\$2.75 ea.  
1 1/4" for 3/4" heater hose.  
HC340.....\$2.75 ea.  
1 3/16" for use on thin walled 3/4" hose.  
HC340S.....\$2.75 ea.



## Core Support Mounting Kit

**1979-1985** All. 4 piece kit. 2 upper and 2 lower cushions.  
CSK795.....\$51.00 ea.

## Coolant Reservoir Cap

**1980-1985** Riviera.  
JC805.....\$8.00 ea.



**Wire Hose Clamps****For 9/16" diameter hose.**

HC916W .....\$1.00 ea.  
 HC916WP.....(5 Pack) ...\$3.25 ea.

**For 3/4" diameter hose.**

HC340W .....\$0.75 ea.  
 HC340WP.....(5 Pack) .....\$3.25 ea.

**For 13/16" diameter hose.**

HC1316W .....\$1.00 ea.  
 HC1316WP.....(5 Pack) .....\$4.25 ea.

**For 15/16" diameter hose.**

HC1516W .....\$0.75 ea.  
 HC1516WP.....(5 Pack) .....\$4.25 ea.

**For 1" diameter hose.**

HC100W.....TOS  
 HC100WP.....(5 Pack) .....\$4.25 ea.

**For 1-1/4" diameter hose.**

HC114W .....\$1.00 ea.  
 HC114WP.....(5 Pack) .....\$5.00 ea.

**For 2" diameter hose.**

HC200W .....\$2.75 ea.  
 HC200WP.....(5 Pack) .....\$2.25 ea.

**Oil Pump Covers****1967-1976** All 430, 455 engines.

OPC646.....\$69.50 ea.

**1974-2009** All 3.8 (231), 4.1 (252) metric engines.

OPC749.....\$69.50 ea.

**Fan Belts****1963-1976** Fan belts.  
(state all information).


FB400 .....\$17.50 ea.

**1963** All w/o AC.

FB1188358.....Exact Reproduction.....\$34.50 ea.

**Fan Shrouds** (1.277)

Fiberglass repro.

FS635....**1963-1965 Riviera** .....\$149.50 ea.FS670..**1967-1970 Riviera w/ a.c** .....\$169.50 ea.**Fan Clutches****1963-1976** Riviera thermal fan clutch.

FC626.....\$64.50 ea.

**Water Pumps****1963-1966** Riviera without air conditioning. Exchange.

WP626RS.....\$79.00 ea.

**1963-1966** Riviera with air conditioning. This pump will also fit non- AC cars.

WP626A .....\$79.50 ea.

**1967-1970** Riviera with air conditioning.

WP670.....\$80.25 ea.

**1967-1972** Riviera without air conditioning.

WP672.....\$57.50 ea.

**1971-1976****1971-1972** All with AC;**1973-1976** All.

WP716.....\$56.25 ea.

**1977-1981** Riviera with 350 engine.

WP731.....\$58.75 ea.

**Water Pump Mounting Gaskets****1963-1966** All.

WPG626.....\$3.75 ea.

**1967-1975** All.

WPG675.....\$3.25 ea.

**1976-1985** All 350, 350B, 350X engines.

WPG615.....\$3.50 ea.

**Water Manifold Gasket Kit****1961-1966** All. Includes 2 gaskets and "O" ring.

WMK536.....\$9.00 ea.

**By-Pass Hoses****1967-1975** Thermostat by-pass hose.

BP676 .....\$9.75 ea.

**Temperature Sending Units** (1.150)**1963-1967** All. (two terminals).

TSU608....(Dash light type) ....\$19.75 ea.

**1966-1968** Electric thermostat gauge.

TSU665 .....\$19.50 ea.

**1969-1972** One terminal in intake manifold.

TSU662....(Dash light type) ....\$12.50 ea.

**1969-1974** All with switch in cylinder head.

TSU694....(Dash light type) ....\$16.50 ea.



# Oiling (Group 1)

## Oil Filters




**1963-1966** All. (Also fits thru 1980 where there is room for taller filter). PF-7 type.  
OF596 .....\$9.75 ea.

**1967-1980** All exc. V-6 and 260 engines. PF-24 type.  
OF670 .....\$9.75 ea.



## PF-24 Oil Filters

A brand new quality reproduction on the original 1967-1975 red, white, and blue, "AC TYPE PF-24" oil filter with logo and proper coloring. A must for the concours restorer.  
OF590AC .....\$22.25 ea.



## Oil Pumps

**1963-1966** Oil pump.  
OP626 .....\$112.00 ea.

**1967-1975** 430-455 engine, oil pump.  
OP675 .....\$59.25 ea.

## Oil Pump Kits

**1963-1966** Oil pump kit.  
OPK626 .....\$47.50 ea.

**1967-1976** Oil pump kit.  
OPK676 .....\$32.25 ea.

OPK676H.....High Volume Kit.....\$59.25 ea.

## Oil Pan

**1967-1970** All. Center sump.  
OP670 .....\$165.00 ea.

**1971-1976** 455 All without factory crossover.  
OP676 .....\$165.00 ea.



## Oil Pan Drain Plug and Gasket

**1963-1975** 1/2"-20 thread.  
OP595 .....\$5.50 ea.

## Oil Pick-up Tube and Screen



Increased oil pick-up over stock 1/2" tube. Gives 5-10 psi oil pressure increase. **1967-1970** engines require that pick-up passage drilled to 5/8". Acts as replacement for **1970** and later engines.

**1962-1966** GS 400, 401, 425 engine. Stock size.  
OPU626 .....\$155.00 ea.

**1967-1975** All 400, 430 and 455 engines.  
OPU675 .....\$82.75 ea.

**1967-1975** 350 engines.  
OPU695 .....\$20.00 ea.

## Oil Pressure Switches (1800)



**1963-1966** Oil pressure switch.  
OPS606 .....\$11.75 ea.



**1968** Oil pressure switch.  
OPS620 .....\$13.75 ea.



**1969-1970** Oil pressure switch.  
OPS690 .....\$12.50 ea.



OC397A



OC397 & OC647



OC684

## Oil Filler/Breather Caps

**1963-1967** All except Chrome jobs. Genuine "AC OIL" Exact Reproduction. Show quality.

OC397 .....\$26.50 ea.

**1963-1967** All except chrome jobs. Twist type. Replacement.

OC397A .....\$9.75 ea.

**1964-1967** "AC OIL" chrome twist on cap.

**1964-1966:** GS with 2-4 carbs;

**1967:** with engine dress up kit.

OC647 .....\$31.00 ea.

**1968-1974** All (Twist on type).

OC684 .....\$4.75 ea.


## Distributor Gear Oiler



**1967-1976** all 400, 430 and 455. This modification increases the life of the distributor gear and cam gear - a must since the cam gear is not replaceable. Provides constant supply of oil spray to both gears. Modification requires small hole to be drilled and tapped on the inside of timing chain cover. Oil pressure is not affected. Requires 1/8" pipe tap and 2-1/64 drill bit not supplied in kit. Instructions included.  
GO676 .....\$16.50 ea.

### Rocker Cover Plug

1964-1967 Solid rocker cover plug.  
CP647.....\$11.75 ea.




### Oil Gaskets

1963-1966 All. Oil pan gasket.  
OPG576.....\$14.50 ea.  
1967-1976 All. 430 and 455 oil pan gasket.  
OPG676.....\$19.00 ea.  
1963-1966 All. Oil pan drain plug gasket.  
ODG615 .....\$2.25 ea.  
1967-1975 All. Oil pan drain plug gasket.  
ODG675 .....\$2.25 ea.  
1963-1966 All. Rear main bearing seal set. Rubber lip.  
RMS576.....\$24.75 ea.  
1963-1966 All. Rear main bearing seal set. Rope type.  
RMS346.....\$14.00 ea.  
1967-1975 All. Rear main bearing seal set.  
RMS615.....\$12.75 ea.  
1977-1980 All. 350 Engines.  
OPG645.....\$10.75 ea.

### PCV Valves

1963-1975 All. PCV valve.  
PCV635.....\$6.75 ea.



### Oil Pump Thrust Plate Repair Kit



This kit provides a NEW WEARING surface for badly scored or worn cover housing. Kit contains all necessary screws, gaskets and instructions.

1967-1976 All.  
OPK685.....\$ 21.00 ea.



### GM Engine Lubricant (E.O.S.)

Genuine GM EOS provides excellent lubrication. Highly recommended. 16 oz.  
EOS300.....\$20.00 ea.

### Crankcase Vent Hose (to Carb)

1972-1975 All. (Formed hose).  
VH725.....\$20.25 ea.



### Air Cleaner to Rocker Cover

#### Vent Tubes <sup>(1.745)</sup>

1968-1969 All.  
VT689.....\$19.50 ea.  
1970-1971 All.  
VT704.....\$16.50 ea.



### Oil Pick-up Tube and Screen

1967-1976 400,455 w/ rear sump. (Increased oil pick-up over stock 1/2" tube. Gives 5-10 psi oil pressure increase. 1967-1970 engines require that pick-up passage drilled to 5/8". Acts as replacement for 1970 Stage 1 and all 1971-1976 455 engines).



OPU676R.....\$69.75 ea.



1967-1976 400,430,455 w. center sump. 5/8" Tube. Requires passage drilled to 5/8"  
OPU676C.....\$74.50 ea.

### Adjustable Oil Pressure Regulator



1961-1972 All. Regulate your oil pressure by adjusting tension on relief spring. Allows for safe and easy adjustment externally.

OPR600.....\$38.00 ea.

### Oil Gaskets

	1961-1966 364, 400, 401 and 425 Engines	1964-1981 300, 340 and 350 Engines	1967-1976 400, 430 and 455 Engines
<b>Oil Pan Gasket</b>	OPG576.....\$14.50	OPG645.....\$10.75	OPG676.....\$19.00
<b>Oil Pan Drain Plug Gasket</b>	ODG615.....\$2.25	ODG615.....\$2.25	ODG675.....\$2.25
<b>Rear Main Bearing Seal Set</b>	RMS576..Rubber Lip type.....\$19.50 RMS346.....Rope type.....\$15.50	RMS615.....\$18.75	RMS615.....\$18.75