



Electrical (Group 2)


Battery Parts



1963-1975 Battery terminal cable cover.
2 per car.
CC315\$6.75 ea.



1963-1975 (+) Terminal and junction block cable cover.
CC325.....\$6.75 ea.



Battery Cables



Our replacement **battery cables** listed below for **TOP POST** batteries are made with heavy duty two (2) gauge copper wire.



Years	Replacement Cables	
	(+) Positive Price	(-) Negative Price
1963-1966	BC30.....\$25.25 ea.	BC24.....\$19.50 ea.
1967-1970	BC72.....\$51.00 ea.	BC24.....\$19.50 ea.
1971-1975	BC48.....\$34.50 ea.	BC31.....\$27.50 ea.

Genuine "Spring Ring" Sets

Our reproduction "**Spring Ring**" cables are made from GM blueprints to be identical to the originals in fit and functions. They are sold in pairs. "Spring Ring" cables are also sold individually. **Inquire!**



Wire Loom

Asphalt coated fabric. Wire loom for battery cables, headlamps, wire etc.



WL180	1/8" ID	\$1.85 ft.
WL316	3/16" ID	\$1.85 ft.
WL140	1/4" ID	\$2.10 ft.
WL516	5/16" ID	\$2.10 ft.
WL380	3/8" ID	\$2.10 ft.
WL716	7/16" ID	\$2.10 ft.
WL120	1/2" ID	\$2.10 ft.
WL916	9/16" ID	\$2.40 ft.
WL580	5/8" ID	\$2.40 ft.
WL340	3/4" ID	\$2.40 ft.

Nylon Wire Loom



NWL140	1/4" ID	\$1.50 ft.
NWL380	3/8" ID	\$6.50 5 ft.
NWL120	1/2" ID	\$6.00 4 ft.
NWL340	3/4" ID	\$1.75 ft.

Wiring Harness Tape



Non-adhesive vinyl harness wrap is same as used by GM. 1" wide, 100 foot roll.

WT100	1" wide.....	\$11.25 roll
-------------	--------------	--------------

Battery Clamps

1963-1970 Clamps feature rubber coating as original.

Battery Bolts



1963-1965 All Rivieras.
BC635.....\$29.50 ea.

1963-1965 All Rivieras. Includes washers and nuts.
BB635.....\$6.50 ea.



1966-1967 All Rivieras.
BC667.....\$29.50 ea.



1966-1970 All Rivieras. Includes washer and nuts.
BB610K.....\$7.00 ea.



1968-1970 All Rivieras.
BC670.....\$29.50 ea.




1971-1976 All.
BC682.....\$4.00 ea.




Bolt for above.
BB682.....\$2.50 ea.

Your Buick is mighty "Choosey" about the company it keeps.....
Treat it to the Best.
Use only Cars
Quality Original and
Reproduction Parts



Starter Rebuilding Service

Check NOS Section
Group 2.041 for outright sales



- 1963**
Riviera.
S623\$189.50 ea.
- 1964-1966** Riviera. (\$25.00 core charge).
S646RS\$189.50 ea.
- 1967-1974** Riviera. (\$25.00 core charge)
S674\$129.50 ea.

Heat Shield Starter Motor



- 1968-1976** All V-8 engines.
SS686\$39.00 ea.

Starter Drives



- 1963** All.
SD623\$39.50 ea.
- 1964-1975** All engines.
SD615\$24.50 ea.

Starter Solenoids



- 1963-1975** All engines.
SS575\$53.00 ea.

Starter Brush Sets



- 1963-1974** All.
SBS539\$6.50 set

Starter Solenoid Repair Kits



- 1963-1975** All.
SRK570\$24.50 kit

Starter ID Tag



- 1963** Delco, starter and distributor ID tag.
ET12\$7.00 ea.

Voltage Regulators



- 1963-1972** All except heavy duty. 62, 80 amp alternators.
VR622\$29.50 ea.
VR622E.....Electronic Replacement\$23.75 ea.
- 1963-1972** All except 1966 and 1967. Heavy duty 62-80 amp alternators. Genuine Delco.
VR622D\$79.50 ea.
- 1965-1975** All with heavy duty 62-80 amp alternators.
VR655\$19.50 ea.

Wire and Cable Retainers



- 1963-1972** Engine compartment wiring strap.
WS5.....7" long.....\$1.50 ea.
- 1963-1972** Engine compartment wiring strap.
WS6 2 3/4" Black.....\$0.85 ea.
WS7 4" Black.....\$0.85 ea.
WS8 4 1/2" Black.....\$0.85 ea.
WS9 8 3/4" Black.....\$0.85 ea.

Wire and Cable Retainers



- 1963-1966** Side frame rail wire retainers.
WR616.....\$5.00 ea.



- 1967-1972** All. Retains positive battery cable to side frame rail.
WR672\$3.25 ea.

Complete Tune-up Kit

1963-1966 All.	
TK617	\$94.50 kit
TK576	\$94.50 kit
1967-1970 All.	
TK671	\$94.50 kit
1971-1974 All.	
TK684	\$94.50 kit

Tune-up Parts



1963-1974 Ignition points.	
D106	\$16.50 ea.



1963-1974 Combination Ignition points and condenser.	
IPC573	\$14.50 ea.



1963-1973 Condenser.	
D204	\$6.00 ea.



1963-1974 Distributor cap.	
D308	\$13.50 ea.
D308R..."Delco Remy" Repro...	\$51.75 ea.



1963-1974 Ignition rotor.	
D409	\$7.50 ea.



1963-1966 Ignition wire set.	
IW576	\$29.50 set



1967-1973 All; 1974 All except HEI.	
IW674	\$23.75 set

Ignition Coils



1963-1973 All. Ignition coil.	
IC539	\$26.50 ea.

1963-1973 Delco ignition coil.	
IC539D	\$58.00 ea.

Universal Coil Bracket



CB350	\$6.50 ea.
CB350C.....(Chrome).....	\$11.50 ea.



Coil Resistor

1963-1974 All.	
CB533	\$11.50 ea.



Wiring Harness Tape

Non-adhesive vinyl harness wrap is same as used by GM. 1" wide, 100 foot roll.
WT100.....1" wide.\$11.25 roll



Signal Flasher

1961-1975 All.	
SF615	\$4.25 ea.

Spark Plugs



1963-1966 All.	
SPR43S	\$2.95 ea.
1967-1971 All.	
SP44TS	\$2.95 ea.
1972-1974 All.	
SP44TS	\$2.95 ea.

Genuine Delco Ignition Wire Sets



1967-1972	
1967: 430 engines;	
1968-1973: All.	
IW672D	\$42.50 set

See next page for date coded wire sets

Spark Plug Wire Parts



1963-1967 Spark plug boots (8 per car). For use with original type copper core ignition wires.	
SB577	\$3.00 ea.



1963-1966 Ignition wire retainer (on rocker covers). Two per car.	
WR596	\$4.75 ea.



1968-1973 All. Ignition wire retainer.	
Two per car.	
WR683	\$4.00 ea.



1967-1973 All. Ignition "3" wire retainers.	
Two per car.	
WT373	\$4.50 ea.



Distributor Knock Sensor

1983-1987	
1983-1984 with 4.1-4;	
1983-1985 with 231-8, 231-9;	
1986-1987 All	
KS838	\$36.00 ea.

Turn Signal Lever



1984-1985 All with pulse wipers and cruise.	
TSL849C	\$129.50 ea.

Electrical (Group 2)



<u>Year</u>	<u>Cars No.</u>	<u>Price</u>
1964	IS64.....	\$32.50 ea.
1969-1975 All tilt wheel	IS699T.....	\$29.50 ea.
1969-1975 All without tilt wheel	IS699.....	\$34.50 ea.

Ignition Lock Cylinder with Keys



<u>Year</u>	<u>Cars No.</u>	<u>Price</u>
1963-1964	IL414	\$22.50 kit
1965	IL65	\$22.50 kit
1966-1967	IL667	\$22.50 kit
1968	IL68	\$22.50 kit
1969-1978	IL695	\$22.50 kit
1979-1991	IL791	\$22.50 kit



Key Blanks (Genuine GM)



1963-1966 Door and Ignition - octagon. KB10.....	\$4.50 ea.
1963-1966 Glove and trunk - rounded. KB11.....	\$4.50 ea.
1967 & 1971 Door and ignition - rectangular. KB48.....	\$3.50 ea.
1967 & 1971 Glove and trunk - oval. KB49.....	\$3.95 ea.
1968 & 1972 Door and ignition - rectangular. KB50.....	\$3.50 ea.
1968 & 1972 Glove and trunk - oval. KB51.....	\$3.50 ea.
1969 & 1973 Door and ignition - rectangular. KB44.....	\$3.50 ea.
1969 & 1973 Glove and trunk - oval. KB45.....	\$3.50 ea.
1970 Door and Ignition - rectangular. KB46.....	\$3.50 ea.
1970 Glove and trunk - oval. KB47.....	\$3.50 ea.
1974 Ignition - rectangular. KB46.....	\$3.50 ea.
1974 Glove, door and trunk - oval. KB47.....	\$3.50 ea.

1975, 1979, 1983, 1985 Ignition - rectangular. KB48.....	\$3.50 ea.
1975, 1979, 1983, 1985 Glove, door and trunk - oval. KB49.....	\$3.50 ea.
1976 & 1980 Ignition - rectangular. KB50.....	\$3.50 ea.
1976 & 1980 Glove, door and trunk - oval. KB51.....	\$3.50 ea.
1977 & 1981 Ignition - rectangular. KB44.....	\$3.50 ea.
1977 & 1981 Glove, door and trunk - oval. KB45.....	\$3.50 ea.
1978 & 1982 Ignition - rectangular. KB46.....	\$3.50 ea.
1978 & 1982 Glove, door and trunk - oval. KB47.....	\$3.50 ea.

Key Caps



1967-1985 All oval keys. KC6700.....	\$1.50 ea.
--	------------



www.oldbuickparts.com

Never Change Points Again!

Upgrade to an electronic ignition. Fits entirely inside the distributor.
 Installs as quickly as changing a set of points. No black boxes,
 complicated wiring or special brackets. Only two wires to connect.

IGNITOR ELECTRONIC IGNITION KITS	NO.	PRICE
---	------------	--------------

8 CYLINDER

1937-1953 All Straight 8, 6 volt, negative ground	PI1183N6	\$125.00
1937-1953 All Straight 8, 12 volt, negative ground (original distributor)	PI1183	\$192.00
1953-1956 All V-8 Mechanical advance under baseplate	PI1185LS	\$99.50
1957-1974 All V-8 Except 215, 300, 340 Engines	PI1181LS	\$95.00
1957-1974 All V-8	PI1181	\$95.00
1957-1974 All V-8 (Ignitor II)	PI91181	\$122.00

6 CYLINDER

1968-1974 All	PI1162A	\$99.00
1962-1967 V-6 Engine	PI1164	\$99.00
1962-1967 V-6 Engine (Odd Fire)	PI1165	\$99.00

HIGH PERFORMANCE COIL

1937-1953 All Straight 8, 6 volt, negative ground (Black)	PC45011	\$39.50
1937-1953 All Straight 8, 6 volt, negative ground (Chrome)	PC45001	\$49.50
1953-1974 All (Black)	PC40011	\$39.50
1953-1974 All (Chrome) 12 v	PC40001	\$46.50
1953-1974 All (For Ignitor II applications only - Chrome) 12 v	PC45001	\$49.50
1953-1974 All (For Ignitor II applications only - Black) 12 v	PC45011	\$39.50
Coil Bracket	CB350	\$6.50
Coil Bracket (Chrome)	CB350C	\$11.50

HIGH PERFORMANCE SPARK PLUG WIRES

Low 500 ohm/ft. resistance with spiral wound alloy to suppress electromagnetic radiation plus redundant current paths.

V-8 7.0mm Stock-Look Custom Set

1953-1960 All	PW708103	\$46.50
1960-1967 Special, Skylark, GS (Ex 1967 GS 400)	PW708103	\$46.50
1967-1966 LeSabre, Wildcat, Invicta, Electra, Riviera All 364, 401, 425 Engines	PW708105	\$44.50
1967 GS-400	PW708102	\$44.50
1968-1974 All 350, 400, 430, 455 w/o HEI	PW708102	\$44.50

6 CYLINDER 7.0mm STOCK-LOOK Custom Set

1968-1974 ALL	PW706101	\$44.50
---------------------	----------	---------

1963-1974 Buick Riviera - Date Coded Spark Plug Wires

For those requiring the best for their show ready car, these reproduction wire sets are unsurpassed. They are manufactured to original GM blueprint specifications. They include the proper boots, terminals, script and correct factory length. All wires are carbon core for radio suppression. They come correctly identified with "**Packard Radio TVRS**" or "**Radio GM**" along with the proper date code to match your car.

Date codes will read as such: 3 Q 67. The first number, "3" corresponds to the third quarter of the year. "Q" means quarter. The last number, "67", is the year, 1967. Thus, a cable marked 3 Q 67 was produced in the third quarter of 1967. You should order your spark plug wire sets with dates that are 6 to 12 months prior to the manufacturing date of your car. *Note:* wires were not dated on vehicles prior to January 1961. Reproduction Spark Plug Wire Sets - 8 Cylinder

PART NO.	DATE	YEAR	DESCRIPTION	PRICE
W3330623	3-Q-62	1963	Spark Plug Wires, V8 All	\$79.50 set
W3330631	1-Q-63	1963	Spark Plug Wires, V8 All	\$79.50 set
W3330633	3-Q-63	1964	Spark Plug Wires, V8 All	\$79.50 set
W3330641	1-Q-64	1964	Spark Plug Wires, V8 All	\$79.50 set
W3330643	3-Q-64	1965	Spark Plug Wires, V8 All	\$79.50 set
W3330651	1-Q-65	1965	Spark Plug Wires, V8 All	\$79.50 set
W3332653	3-Q-65	1966	Spark Plug Wires, V8 All	\$79.50 set
W3332661	1-Q-66	1966	Spark Plug Wires, V8 All	\$79.50 set
W3342663	3-Q-66	1967	Spark Plug Wires, V8 All	\$79.50 set
W3342671	1-Q-67	1967	Spark Plug Wires, V8 All	\$79.50 set
W3342673	3-Q-67	1968	Spark Plug Wires, V8 All	\$79.50 set
W3342681	1-Q-68	1968	Spark Plug Wires, V8 All	\$79.50 set
W3342683	3-Q-68	1969	Spark Plug Wires, V8 All	\$79.50 set
W3342691	1-Q-69	1969	Spark Plug Wires, V8 All	\$79.50 set
W3342693	3-Q-69	1970	Spark Plug Wires, V8 All	\$79.50 set
W3342701	1-Q-70	1970	Spark Plug Wires, V8 All	\$79.50 set
W3342703	3-Q-70	1971	Spark Plug Wires, V8 All	\$79.50 set
W3342711	1-Q-71	1971	Spark Plug Wires, V8 All	\$79.50 set
W3344713	3-Q-71	1972	Spark Plug Wires, V8 All	\$79.50 set
W3344721	1-Q-72	1972	Spark Plug Wires, V8 All	\$79.50 set
W3344723	3-Q-72	1973	Spark Plug Wires, V8 All	\$79.50 set
W3344731	1-Q-73	1973	Spark Plug Wires, V8 All	\$79.50 set
W3344733	3-Q-73	1974	Spark Plug Wires, V8 All Exc Hei	\$79.50 set
W3344741	1-Q-74	1974	Spark Plug Wires, V8 All Exc Hei	\$79.50 set

Distributor Rebuilding Service

See NOS Group 2.361
Section for outright Sale

- 1963-1966 All.
- D596\$167.50 ea.
- 1967-1974 All.
- D674\$167.50 ea.



(2.410)


Vacuum Advances

- 1963-1974 All. Distributor vacuum advance. Oem type.
- VC600\$17.50 ea.

Horns

- 1961-1999 All. (replacement type) May not look the same as original. Bracket and wire as necessary.
- H610L.....(Low Note).....\$59.50 ea.
- H610H.....(High Note).....\$59.50 ea.

Horn Blowing Contact Spring



- 1969-1974: All.
- HS666\$7.75 ea.

Horn Relays (2.815)



- 1963-1967 All with junction block.
- HR617\$87.50 ea.



- 1965-1968 All with relay only.
- HR658\$17.50 ea.



- 1968 All little fuse.
- HR658L\$39.50 ea.

Turn Signal Switches

- 1967-1968 All w/o tilt wheel. Delco color code white or green. Includes wiring.
- DSS678.....\$45.00 ea.
- 1969-1972 All w/o cornering lamps. Includes wiring.
- DSS696.....\$46.75 ea.
- 1976-1990 Headlamp dimmer actuator. All with tilt or tele.
- HDA760\$4.75 ea

Alternators

- 1963-1971 All 61 amp. Exchange.
- A631.....\$72.25 ea.



Alternator Brush Sets



- 1963-1967 all except 62 amp. alternators;
- 1968 thru 1971 all
- ABS621\$12.75 set
- 1964-1967 all 62 amp. alternators.
- ABS647\$7.75 set

- 1963-1971 Alternator rear end bearing (62 amp. jobs).
- GEB581\$15.75 ea.

- 1963-1971 Alternator front bearing.
- GEB581\$15.75 ea.


- 1963-1975 Alternator rear bearing (ex. 62 amp).
- GEB633\$17.50 ea.

- 1972-1980 Alternator front bearing.
- GEB713\$11.25 ea.

Alternator Contact Rubber Boot



- 1963-1972 All.
- AB632\$4.50 ea.



Genuine Guide T-3 Headlight Bulbs

- SB607S.....1963-1967 All.....\$149.00 set of four (4)
- SB681S.....1968-1971 All.....\$149.00 set of four (4)

Headlight Bulb Retainer




- 1967-1973 All as required. 3 tabs. For 4 headlight systems.
- HR683\$9.50 ea.


Electrical (Group 2)

1965, 66, 67 Headlamp Motor Repair

Complete reconditioning of your headlamp motor. Does not include switches. Lifetime warranty. Exceeds OEM performance.



HM667.....(1966-1967).....\$346.50 ea.



1968-1969 Front marker lamp.
MLF689\$16.50 ea.



1968-1969 Front marker lamp gasket.
Small rectangular.
MLG689.....\$4.00 ea.



1971-1973 Rear marker lamp gaskets.
MLG713R.....\$9.75 pr.

Headlamp Visor Relay

1965 All.

HVR65.....\$17.50 ea.



Turn Signal Levers

1969-1970 Buick Special, Skylark, Sportwagon, GS.
Correct Fluted ChromeLever With Black Knob.
All Without Cruise Control.

TSL690.....\$29.00 ea.

1969-1970 All With Cruise Control.

TSL670C.....\$109.00 ea.



1971-1976 All w/ Cruise Control.
Correct Chrome Lever w/ Black Knob.
TSL716.....\$109.00 ea.

1963 -1964 Parking Lamps



1963-1964 Park Lamp Lenses.
Outer lenses, clear w/ no markings. Either side.
PL634R.....\$119.00 ea.



1963-1964 Front Parking Lamp Lenses Grill.
Diecast chrome as original, fits either side.
LG634.....\$249.50 ea.
Set of 6 count screws for above.
LGS634.....\$2.25 set

Parking Lamp Gaskets



1963-1964 Riviera front parking lamp lens gaskets.
PLG634R.....\$9.00 ea.
1965 Riviera front parking lamp lens gaskets.
PLG65R.....\$12.75 pr.

Headlamp Switches



HS593.....**1963** All.....\$49.50 ea.
HS647.....**1964** thru **1967** All.....\$28.50 ea.
HS685.....**1968** thru **1977** All exc.....\$25.50 ea.
HC645....(connector plug for 1964-1977 above)..\$9.75 ea.
HS805R.....**1980** thru **1985** exc. twilight sent.....\$30.25 ea.

Headlight Dimmer Switch



1963-1975 All except guidematic.
HDS615.....\$9.00 ea.

1961-1967 All. Sealed beam retainer screw.
6 per car.
HS400.....\$1.25 ea.

Headlight Support Pads




1970-1975 Headlamp assembly to core support pads. White nylon. 12 per car.
HP705.....\$2.25 ea.
HP705S.....(Set of 12).....\$20.50 set

Headlight Bezel Nuts



1964-1968 All. Headlamp bezel retaining nut.
HBN649.....\$2.25 ea.



1969-1972 Headlamp bezel retaining nut.
HBN692.....\$2.75 ea.
HBN692S.....(Set of 8).....\$19.50 set



1969-1974 Headlamp adjustment nut.
HBN649.....\$4.00 ea.

Sealed Beam Headlamps



1975-1990 All as required.

Rectangular - for 4 lamp systems.

SB4561.....2 prong high beam.....\$13.75 ea.
SB4652.....3 prong low beam.....\$13.75 ea.

Halogen Bulbs

SB4561H.....2 prong high beam.....\$15.75 ea.
SB4652H.....3 prong low beam.....\$15.75 ea.

1963-1964 Tail Lamp Bezels

These difficult to find and nearly impossible to rechrome Bezels have been finally reproduced to the same quality as original.



- 1963-1964** Riviera tail lamp chrome bezel.
TB634\$149.50 ea.
- 1963-1964** Riviera tail lamp bezel gasket. Economical extrusion.
TBE634\$17.50 pr.



- 1963-1964** Riviera tail lamp bezel gasket. 1 piece molded rubber.
TBG634.....\$17.50 ea.
- 1963-1964** Riviera tail lamp bezel gasket. Economical extrusion.
TBG634S\$17.50 pr.

1965 Tail Lamp Bezels



- 1965** Die cast chrome. Show quality.
TB65\$197.50 ea.

Tail Lamp Gaskets



- 1963-1964** Tail Lamp Gasket (2.684) Riviera tail lamp lens gaskets.
TLG634R\$12.75 pr.
- 1965** Riviera tail lamp lens gaskets.
TLG65R.....\$17.00 pr.
- 1965** Riviera tail lamp to body gaskets.
TLP65R\$17.00 pr.
- 1966-1967** Riviera tail lamp lens gaskets.
TLG667R\$19.50 pr.
- 1966-1967** Riviera tail lamp to body gaskets. 8 per car.
TLS667R\$3.75 ea.
- 1968** Riviera tail lamp lens gaskets.
TLG68R\$30.79 pr.

1963-1964 Tail Lamp Lens and Medallions

These are totally new Reproductions at very reasonable prices. In fact these Lenses are far superior to any seen yet. They are 100% correct and feature all markings, such as "GUIDE", along with the proper Buick part number imprinted right into the lens. They also incorporate the additional and necessary reflective lenses needed for safety and Authenticity.

Medallions are also new, made of die cast metal and beautifully chrome plated to be identical to originals.

1963 Rivera Tail Lamp Lenses

(Lens & Medallion) Fits either side.



TL63R



TL63RP

- TL63R.....Complete Assembly\$68.50
- TL63RP.....Lens Only.....\$59.50
- TLE63R.....Medallion Only\$24.50

1964 Rivera Tail Lamp Lenses

(Lens & Medallion). Fits either side.



TL64R



TL64RP

- TL64R.....Complete Assembly\$68.50
- TL64RP.....Lens Only.....\$59.50
- TLE64R.....Medallion Only\$24.50

Back-up Lamp Parts



- 1966-1967** Back-up lamp rubber bumpers.
GDB635.....\$5.00 pr.

License Lamp Gaskets (2.707)



- 1964** License lamp lens gasket.
LLG624.....\$4.25 ea.



- 1965;**
1968-1972 All. License lens gasket.
LLG643.....\$6.75 ea.

- 1969-1972** All. License lamp lens.
LL682.....\$10.25 ea.



Electrical (Group 2)



Bulbs



Year & Model	Head-light	Parking	Direction Signal		Tail	Stop	License Plate	Instrument	Indicator	Dome	Back-up	Marker lamp	
			Front	Rear								Left	Right
1963	SB1, SB2	B1034	B1034	B1034	B1034	B1034	B67	B57161	B194	B901004	B1073	----	----
1964	SB1, SB2	B1157A	B1157	B1157	B1157	B1157	B97	B161194	B194	B901004	B1156	----	----
1965	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B161194	B194	B901004	B1156	----	----
1966	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194	B194	B901004	B1156	----	----
1967	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194	B161	B211	B1156	----	----
1968	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B1941893	B194	B901004	B1156-1157	B194A	B194
1969	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B1811893	B194	B901004	B1157	B194A	B194
1970	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B181194	B194	B211	B1157	B194A	B194
1971	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B161194	B194	B211	B1157	B194	B194
1972	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B161194	B194	B211	B1157	B194	B194
1973	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97194	B194	B194	B211	B1157	B194	B194
1974	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B194	B168	B194	B211	B1157	B194	B194
1975	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B194	B168	B161	B211	B1157	B194	B194
1976	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B194	B168	B161	B211	B1157	B1157A	B1157
1977	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B168	B161	B161	B56189	B1156	B194A	B168
1978	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B168	B161	B161	B56189	B1156	B194A	B168

Prices: 53-\$1.50, 57-\$1.25, 67-\$1.50, 90-\$2.00, B97-\$2.25, 161-\$2.00, 168-\$1.50, 194-\$2.25, 194A-\$3.00, 210-\$5.50, 211-\$2.25, 1004-\$2.75, 1034-\$2.75, 1073-\$2.75, 1156-\$2.50, 1157A-\$2.00, 1157-\$2.00, 1893-\$2.25, SB1-\$11.25, SB2-\$11.25

NOTICE


CAR SHOW ATTENDEES

CARS, Inc. will NOT bring the usual "yellow trailer" to the shows.

We will be happy to bring any parts you need.

Please call in advance of the show to place your order.

Look For Us!



If your thinking of attending any of the shows listed below, be sure to stop by and say "Hello". We will be glad to discuss some of our newest items or simply talk about your **BUICK**.

Plan ahead by calling-in your order weeks ahead of time. We will be able to bring your entire order and save you shipping too.

GS Nationals
Buick Nationals
**Hershey* *GDB 31*
near Lamp Post 86

Headlamp Sockets



For 3 prong beam numbers SB6, 6006, SB12, 6012, SB2, 4000 and 4002.
PT6\$4.75 ea.



For 2 prong beam numbers SB1, 4001.
PT7\$4.25 ea.

Lamp Sockets and Pigtails



Single contact with lead. Fits bulb numbers 51, 53, 55 and 57.
PT1\$2.25 ea.



Single contact with lead. Fits bulb numbers 63, 67, 81, 87, 89, 1073, 1129, 1133, 1141 and 1156.
PT2\$2.25 ea.




Double contact with lead. For ears reversed. Bulbs numbers 82, 88, 90, 210, 1004, 1034, 1154 and 1157.
PT3\$2.75 ea.




Double contact with lead. For ears aligned bulbs.
PT4\$2.50 ea.


Parking and Tail Lamp Sockets



Single contact with lead. For 3/4" to 1 1/8" hole.
LS1\$5.75 ea.



Double contact with lead. For bulb numbers 1034 and 1154. Fits 1 1/8" hole.
LS5\$5.75 ea.



Double contact with leads. Fits 3/4" hole. For bulb numbers 1034, 1154 and 1157.
LS9\$5.75 ea.



Double contact with leads. Fits 3/4" to 1 1/8" hole. For bulb numbers 1034, 1154 and 1157.
LS2\$5.75 ea.



Double contact with leads. Fits 3/4" to 1 1/8" hole. For bulb numbers 82, 88, 90, 210 and 1004.
LS3\$7.75 ea.



Double contact with leads. Fits 1 1/8" hole. For bulb numbers 1034, 1154 and 1157.
LS4\$5.75 ea.

Interior/Dash Sockets



Single contact with lead for dome etc. For bulb numbers 63, 67, 81, 89, 1073, 1129 and 1133.
PT8\$6.75 ea.




Double contact with lead. For dome and map lamps. Reversed ears. Bulb numbers 82, 88, 90, 210 and 1004.
PT9\$6.75 ea.



Double contact with lead for ears aligned bulbs.
PT10\$4.75 ea.

Back-Up and License Lamp Sockets



Single contact with lead. Fits 3/4" hole. Bulb numbers 63, 67, 81, 89, 1129 and 1133.
LS6\$6.00 ea.



Single contact with lead. Fits 1 1/8" hole. For bulb numbers 63, 67, 81, 89, 1129 and 1133.
LS8\$6.00 ea.

Wire Loom



Asphalt coated fabric. Wire loom for battery cables, head lamps, wire etc.

WL180	1/8" ID	\$1.85 ft.
WL316	3/16" ID.	\$1.85 ft.
WL140	1/4" ID	\$2.10 ft.
WL516	5/16" ID	\$2.10 ft.
WL380	3/8" ID.	\$2.10 ft.
WL716	7/16" ID	\$2.10 ft.
WL120	1/2" ID.	\$2.10 ft.
WL916	9/16" ID	\$2.40 ft.
WL580	5/8" ID	\$2.40 ft.
WL340	3/4" ID.	\$2.40 ft.