



# Electrical (Group 2)


## Battery Parts



**1963-1975** Battery terminal cable cover.  
2 per car.  
CC315 .....\$6.25 ea.



**1963-1975 (+)** Terminal and junction block cable cover.  
CC325 .....\$6.25 ea.



## Battery Cables



Our replacement **battery cables** listed below for **TOP POST** batteries are made with heavy duty two (2) gauge copper wire.



Years	Replacement Cables	
	(+) Positive Price	(-) Negative Price
<b>1963-1966</b>	BC30.....\$25.25 ea.	BC24.....\$19.50 ea.
<b>1967-1970</b>	BC72.....\$51.00 ea.	BC24.....\$19.50 ea.
<b>1971-1975</b>	BC48.....\$34.50 ea.	BC31.....\$25.25 ea.

## Genuine "Spring Ring" Sets

Our reproduction **"Spring Ring"** cables are made from GM blueprints to be identical to the originals in fit and functions. They are sold in pairs. "Spring Ring" cables are also sold individually. **Inquire!**



## Wire Loom



Asphalt coated fabric. Wire loom for battery cables, headlamps, wire etc.

WL180 .....	1/8" ID .....	\$1.85 ft.
WL316 .....	3/16" ID .....	\$1.85 ft.
WL140 .....	1/4" ID .....	\$2.10 ft.
WL516 .....	5/16" ID .....	\$2.10 ft.
WL380 .....	3/8" ID .....	\$2.10 ft.
WL716 .....	7/16" ID .....	\$2.10 ft.
WL120 .....	1/2" ID .....	\$2.10 ft.
WL916 .....	9/16" ID .....	\$2.40 ft.
WL580 .....	5/8" ID .....	\$2.40 ft.
WL340 .....	3/4" ID .....	\$2.40 ft.

## Nylon Wire Loom



NWL140 .....	1/4" ID .....	\$1.50 ft.
NWL380 .....	3/8" ID .....	\$6.50 5 ft.
NWL120 .....	1/2" ID .....	\$6.00 4 ft.
NWL340 .....	3/4" ID .....	\$1.75 ft.

## Wiring Harness Tape



Non-adhesive vinyl harness wrap is same as used by GM. 1" wide, 100 foot roll.  
WT100 .....1" wide.....\$11.25 roll

### Battery Clamps

1963-1970 Clamps feature rubber coating as original.



1963-1965 All Rivieras.  
BC635 .....\$27.50 ea.



1966-1967 All Rivieras.  
BC667 .....\$29.50 ea.



1968-1970 All Rivieras.  
BC670.....\$26.50 ea.



1971-1976 All.  
BC682 .....\$4.00 ea.



Bolt for above.  
BB682 .....\$2.25 ea.

### Battery Bolts




1963-1965 All Rivieras. Includes washers and nuts.  
BB635 .....\$6.00 ea.




1966-1970 All Rivieras. Includes washer and nuts.  
BB610 .....\$6.75 ea.

Your Buick is mighty "Choosey" about the company it keeps.....  
Treat it to the Best.  
Use only Cars Quality Original and Reproduction Parts



## Starter Rebuilding Service

Check NOS Section  
Group 2.041 for outright sales



- 1963 Riviera.**  
S623 .....\$189.50 ea.
- 1964-1966 Riviera. (\$25.00 core charge).**  
S646RS .....\$189.50 ea.
- 1967-1974 Riviera. (\$25.00 core charge)**  
S674 .....\$129.50 ea.

## Starter Drives



- 1963 All.**  
SD623 .....\$39.50 ea.
- 1964-1975 All engines.**  
SD615.....\$24.50 ea.

## Starter Solenoids



- 1963-1975 All engines.**  
SS575 .....\$53.00 ea.

## Starter Brush Sets



- 1963-1974 All.**  
SBS539 .....\$6.50 set

## Starter Solenoid Repair Kits



- 1963-1975 All.**  
SRK570 .....\$24.50 kit

## Starter ID Tag



- 1963 Delco, starter and distributor ID tag.**  
ET12.....\$7.00 ea.

## Voltage Regulators



- 1963-1972 All except heavy duty. 62, 80 amp alternators.**  
VR622 .....\$19.75 ea.  
VR622E.....Electronic Replacement .....\$23.75 ea.
- 1963-1972 All except 1966 and 1967. Heavy duty 62-80 amp alternators. Genuine Delco.**  
VR622D .....\$79.50 ea.
- 1965-1975 All with heavy duty 62-80 amp alternators.**  
VR655 .....\$19.50 ea.

## Wire and Cable Retainers



- 1963-1972 Engine compartment wiring strap.**  
WS5.....7" long.....\$1.50 ea.
- 1963-1972 Engine compartment wiring strap.**  
WS6 2 3/4" Black.....\$0.75 ea.  
WS7 4" Black.....\$0.75 ea.  
WS8 4 1/2" Black.....\$0.75 ea.  
WS9 8 3/4" Black.....\$0.75 ea.

## Wire and Cable Retainers



- 1963-1966 All. Two per car. Located on rocker covers.**  
WR596 .....\$4.25 ea.



- 1967-1972 All. Front. Wire retainer. Two per car.**  
WR683.....\$4.00 ea



- 1963-1966 Side frame rail wire retainers.**  
WR616.....\$5.00 ea.



- 1967-1972 All. Retains positive battery cable to side frame rail.**  
WR672 .....\$3.25 ea.

### Complete Tune-up Kit

**1963-1979** Complete Riviera tune-up kit. Includes: spark plugs, ignition wires, points rotor, condenser and cap.  
TK579.....\$79.50 kit

### Tune-up Parts



**1963-1974** Ignition points.  
D106.....\$16.50 ea.



**1963-1974** Combination Ignition points and condenser.  
IPC573 .....\$14.50 ea.



**1963-1973** Condenser.  
D204.....\$6.00 ea.



**1963-1974** Distributor cap.  
D308.....\$13.50 ea.  
D308R... "Delco Remy" Repro...\$51.75 ea.



**1963-1974** Ignition rotor.  
D409.....\$7.50 ea.



**1963-1966** Ignition wire set.  
IW576 .....\$29.50 set



**1967-1973** All; **1974** All except HEI.  
IW674 .....\$23.75 set

### Ignition Coils



**1963-1973** All. Ignition coil.  
IC539 .....\$26.50 ea.  
**1963-1973** Delco ignition coil.  
IC539D .....\$58.00 ea.

### Universal Coil Bracket



CB350.....\$6.50 ea.  
CB350C.....(Chrome).....\$11.50 ea.



### Coil Resistor

**1963-1974** All.  
CR533.....\$11.50 ea.



### Wiring Harness Tape

Non-adhesive vinyl harness wrap is same as used by GM. 1" wide, 100 foot roll.  
WT100.....1" wide. ....\$11.25 roll



### Signal Flasher

**1961-1975** All.  
SF615.....\$4.25 ea.

### Spark Plugs



**1963-1966** All.  
SPR43S.....\$2.95 ea.  
**1967-1971** All.  
SP44TS.....\$2.95 ea.  
**1972-1974** All.  
SP44TS.....\$2.95 ea.

### Genuine Delco Ignition Wire Sets



**1967-1972**  
1967: 430 engines; 1968-1973: All.  
IW672D.....\$42.50 set

*See next page for date coded wire sets*

### Spark Plug Wire Parts



**1963-1967** Spark plug boots (8 per car). For use with original type copper core ignition wires.  
SB577 .....\$3.00 ea.



**1963-1966** Ignition wire retainer (on rocker covers). Two per car.  
WR596 .....\$4.25 ea.



**1968-1973** All. Ignition wire retainer. Two per car.  
WR683 .....\$4.00 ea.

### Distributor Knock Sensor



**1983-1987**  
**1983-1984** with 4.1-4;  
**1983-1985** with 231-8, 231-9;  
**1986-1987** All  
KS838 .....\$36.00 ea.

### Turn Signal Lever



**1984-1985** All with pulse wipers and cruise.  
TSL849C .....\$129.50 ea.

# Electrical (Group 2)



Year	Cars No.	Price
1964	IS64.....	\$27.25 ea.
1969-1975 All tilt wheel	IS699T.....	\$29.50 ea.
1969-1975 All without tilt wheel	IS699.....	\$29.50 ea.

## Ignition Lock Cylinder with Keys



Year	Cars No.	Price
1963-1964	IL614 .....	\$19.50 kit
1965	IL65 .....	\$19.50 kit
1966-1967	IL667 .....	\$19.50 kit
1968	IL68 .....	\$19.50 kit
1969-1978	IL695 .....	\$19.50 kit
1979-1991	IL791 .....	\$19.50 kit



## Key Blanks (Genuine GM)

1963-1966 Door and Ignition - octagon. KB10.....	\$3.50 ea.
1963-1966 Glove and trunk - rounded. KB11.....	\$3.50 ea.
1967 & 1971 Door and ignition - rectangular. KB48.....	\$3.50 ea.
1967 & 1971 Glove and trunk - oval. KB49.....	\$3.50 ea.
1968 & 1972 Door and ignition - rectangular. KB50.....	\$3.50 ea.
1968 & 1972 Glove and trunk - oval. KB51.....	\$3.50 ea.
1969 & 1973 Door and ignition - rectangular. KB44.....	\$3.50 ea.
1969 & 1973 Glove and trunk - oval. KB45.....	\$3.50 ea.
1970 Door and Ignition - rectangular. KB46.....	\$3.50 ea.
1970 Glove and trunk - oval. KB47.....	\$3.50 ea.
1974 Ignition - rectangular. KB46.....	\$3.50 ea.
1974 Glove, door and trunk - oval. KB47.....	\$3.50 ea.



1975, 1979, 1983, 1985 Ignition - rectangular. KB48.....	\$3.50 ea.
1975, 1979, 1983, 1985 Glove, door and trunk - oval. KB49.....	\$3.50 ea.
1976 & 1980 Ignition - rectangular. KB50.....	\$3.50 ea.
1976 & 1980 Glove, door and trunk - oval. KB51.....	\$3.50 ea.
1977 & 1981 Ignition - rectangular. KB44.....	\$3.50 ea.
1977 & 1981 Glove, door and trunk - oval. KB45.....	\$3.50 ea.
1978 & 1982 Ignition - rectangular. KB46.....	\$3.50 ea.
1978 & 1982 Glove, door and trunk - oval. KB47.....	\$3.50 ea.



## Key Caps



1967-1985 All rectangular keys. KC670R.....	\$1.50 ea.
1967-1985 All oval keys. KC670O.....	\$1.50 ea.



## 1963-1974 Buick Riviera - Date Coded Spark Plug Wires

For those requiring the best for their show ready car, these reproduction wire sets are unsurpassed. They are manufactured to original GM blueprint specifications. They include the proper boots, terminals, script and correct factory length. All wires are carbon core for radio suppression. They come correctly identified with "**Packard Radio TVRS**" or "**Radio GM**" along with the proper date code to match your car.

Date codes will read as such: 3 Q 67. The first number, "3" corresponds to the third quarter of the year. "Q" means quarter. The last number, "67", is the year, 1967. Thus, a cable marked 3 Q 67 was produced in the third quarter of 1967. You should order your spark plug wire sets with dates that are 6 to 12 months prior to the manufacturing date of your car. *Note:* wires were not dated on vehicles prior to January 1961. Reproduction Spark Plug Wire Sets - 8 Cylinder

PART NO.	DATE	YEAR	DESCRIPTION	PRICE
W3330623	3-Q-62	1963	Spark Plug Wires, V8 All	\$79.50 set
W3330631	1-Q-63	1963	Spark Plug Wires, V8 All	\$79.50 set
W3330633	3-Q-63	1964	Spark Plug Wires, V8 All	\$79.50 set
W3330641	1-Q-64	1964	Spark Plug Wires, V8 All	\$79.50 set
W3330643	3-Q-64	1965	Spark Plug Wires, V8 All	\$79.50 set
W3330651	1-Q-65	1965	Spark Plug Wires, V8 All	\$79.50 set
W3332653	3-Q-65	1966	Spark Plug Wires, V8 All	\$79.50 set
W3332661	1-Q-66	1966	Spark Plug Wires, V8 All	\$79.50 set
W3342663	3-Q-66	1967	Spark Plug Wires, V8 All	\$79.50 set
W3342671	1-Q-67	1967	Spark Plug Wires, V8 All	\$79.50 set
W3342673	3-Q-67	1968	Spark Plug Wires, V8 All	\$79.50 set
W3342681	1-Q-68	1968	Spark Plug Wires, V8 All	\$79.50 set
W3342683	3-Q-68	1969	Spark Plug Wires, V8 All	\$79.50 set
W3342691	1-Q-69	1969	Spark Plug Wires, V8 All	\$79.50 set
W3342693	3-Q-69	1970	Spark Plug Wires, V8 All	\$79.50 set
W3342701	1-Q-70	1970	Spark Plug Wires, V8 All	\$79.50 set
W3342703	3-Q-70	1971	Spark Plug Wires, V8 All	\$79.50 set
W3342711	1-Q-71	1971	Spark Plug Wires, V8 All	\$79.50 set
W3344713	3-Q-71	1972	Spark Plug Wires, V8 All	\$79.50 set
W3344721	1-Q-72	1972	Spark Plug Wires, V8 All	\$79.50 set
W3344723	3-Q-72	1973	Spark Plug Wires, V8 All	\$79.50 set
W3344731	1-Q-73	1973	Spark Plug Wires, V8 All	\$79.50 set
W3344733	3-Q-73	1974	Spark Plug Wires, V8 All Exc Hei	\$79.50 set
W3344741	1-Q-74	1974	Spark Plug Wires, V8 All Exc Hei	\$79.50 set

### Distributor Rebuilding Service

See NOS Group 2.361  
Section for outright Sale

- 1963-1966 All.
- D596 .....\$167.50 ea.
- 1967-1974 All.
- D674 .....\$167.50 ea.



(2.410)


### Vacuum Advances

- 1963-1974 All. Distributor vacuum advance. Oem type.
- VC600 .....\$16.25 ea.

### Horns

- 1961-1999 All. (replacement type) May not look the same as original. Bracket and wire as necessary.
- H610L.....(Low Note).....\$59.50 ea.
- H610H.....(High Note).....\$59.50 ea.

### Horn Blowing Contact Spring



- 1969-1974: All.
- HS666 .....\$7.75 ea.

### Horn Relays (2.815)



- 1963-1967 All with junction block.
- HR617 .....\$79.75 ea.



- 1965-1968 All with relay only.
- HR658 .....\$16.50 ea.



- 1968 All littlefuse".
- HR658L.....\$39.50 ea.

### Turn Signal Switches

- 1967-1968 All w/o tilt wheel. Delco color code white or green. Includes wiring.
- DSS678.....\$45.00 ea.
- 1969-1972 All w/o cornering lamps. Includes wiring.
- DSS696.....\$46.75 ea.
- 1976-1990 Headlamp dimmer actuator. All with tilt or tele.
- HDA760 .....\$4.75 ea

### Alternators

- 1963-1971 All 61 amp. Exchange.
- A631.....\$72.25 ea.



### Alternator Brush Sets



- 1963-1967 all except 62 amp. alternators;
- 1968 thru 1971 all
- ABS621 .....\$12.75 set
- 1964-1967 all 62 amp. alternators.
- ABS647.. .....\$7.75 set

- 1963-1971 Alternator rear end bearing (62 amp. jobs).
- GEB581.....\$15.75 ea.

- 1963-1971 Alternator front bearing.
- GEB581.....\$15.75 ea.

- 1963-1975 Alternator rear bearing (ex. 62 amp).
- GEB633.....\$11.25 ea.

- 1972-1980 Alternator front bearing.
- GEB713.....\$11.25 ea.

### Alternator Fan (2.274)




- 1963-1975 Correctly cadmium plated.
- 1963-1965: All except 62 amp;
- 1967-1975: All except 80 amp.
- AF585.....\$16.50 ea.

### Alternator Contact Rubber Boot



- 1963-1972 All.
- AB632 .....\$4.50 ea.



### Genuine Guide T-3 Headlight Bulbs


- SB607S.....1963-1967 All.....\$149.00 set of four (4)
- SB681S.....1968-1971 All.....\$149.00 set of four (4)




# Electrical (Group 2)

## 1965, 66, 67 Headlamp Motor Repair

Complete reconditioning of your headlamp motor. Does not include switches. Lifetime warranty. Exceeds OEM performance.



HM667.....(1966-1967).....\$346.50 ea.



**1968-1969** Front marker lamp.  
MLF689.....\$16.50 ea.



**1968-1969** Front marker lamp gasket.  
Small rectangular.  
MLG689.....\$4.00 ea.



**1971-1973** Rear marker lamp gaskets.  
MLG713R .....\$9.75 pr.



**Headlamp Visor Relay**  
**1965** All.  
HVR65.....\$17.50 ea.

## Headlamp Switches



HS593.....**1963** All.....\$49.50 ea.  
HS647.....**1964** thru **1967** All.....\$28.50 ea.  
HS685.....**1968** thru **1977** All exc.....\$25.50 ea.  
HC645....(connector plug for 1964-1977 above)...\$9.75 ea.  
HS805R.....**1980** thru **1985** exc. twilight sent.....\$30.25 ea.

## Headlight Dimmer Switch



**1963-1975** All except guidematic.  
HDS615.....\$9.00 ea.

**1961-1967** All. Sealed beam retainer screw.  
6 per car.  
HS400.....\$1.25 ea.

## Headlight Support Pads



**1970-1975** Headlamp assembly to core support pads. White nylon. 12 per car.  
HP705 .....\$2.25 ea.  
HP705S.....(Set of 12)...\$20.50 set

## Headlight Bezel Nuts



**1964-1968** All. Headlamp bezel retaining nut.  
HBN649.....\$2.25 ea.

**1969-1972** Headlamp bezel retaining nut.  
HBN692.....\$2.50 ea.  
HBN692S.....(Set of 8).....\$18.50 set

## 1963 -1964 Parking Lamp Lens

Die cast chrome as original. Beautifully chrome plated.  
Fit either side.



LG634.....\$249.50ea.

Set of 6 count screws for above.  
LGS634.....\$2.25 set



**1963-1964** Park Lamp Lenses.  
Outer lenses, clear w/ no markings. Either side.  
PL634R.....\$139.50 ea.



## Parking Lamp Gaskets

**1963-1964** Riviera front parking lamp lens gaskets.  
PLG634R .....\$9.00 ea.

**1965** Riviera front parking lamp lens gaskets.  
PLG65R .....\$12.75 pr.

### 1963-1964 Tail Lamp Bezels

These difficult to find and nearly impossible to rechrome Bezels have been finally reproduced to the same quality as original.



- 1963-1964 Riviera tail lamp chrome bezel.**  
TB634 .....\$125.00 ea.
- 1963-1964 Riviera tail lamp bezel gasket.**  
TBG634 .....\$16.50 pr.

### Tail Lamp Gaskets (2.684)

- 1963-1964 Riviera tail lamp lens gaskets.**  
TLG634R .....\$12.75 pr.



- 1965 Riviera tail lamp chrome bezels. Show quality.**  
TB65 .....\$197.50 ea.

- 1965 Riviera tail lamp lens gaskets.**  
TLG65R .....\$17.00 pr.
- 1965 Riviera tail lamp to body gaskets.**  
TLP65R.....\$17.00 pr.
- 1966-1967 Riviera tail lamp lens gaskets.**  
TLG667R .....\$19.50 pr.
- 1966-1967 Riviera tail lamp to body gaskets. 8 per car.**  
TLS667R.....\$3.75 ea.
- 1968 Riviera tail lamp lens gaskets.**  
TLG68R .....\$34.00 pr.

### 1963-1964 Tail Lamp Lens and Medallions

These are totally new Reproductions at very reasonable prices. In fact these Lenses are far superior to any seen yet. They are 100% correct and feature all markings, such as "GUIDE", along with the proper Buick part number imprinted right into the lens. They also incorporate the additional and necessary reflective lenses needed for safety and Authenticity.

Medallions are also new, made of die cast metal and beautifully chrome plated to be identical to originals.

#### 1963 Riviera Tail Lamp Lenses (Lens & Medallion) Fits either side.



- TL63R.....Complete Assembly .....\$68.50
- TL63RP.....Lens Only.....\$59.50
- TLE63R.....Medallion Only .....\$24.50

#### 1964 Riviera Tail Lamp Lenses (Lens & Medallion). Fits either side.



- TL64R.....Complete Assembly .....\$68.50
- TL64RP.....Lens Only.....\$59.50
- TLE64R.....Medallion Only .....\$24.50

### Back-up Lamp Parts



- 1966-1967 Back-up lamp rubber bumpers.**  
GDB635 .....\$5.00 pr.

### License Lamp Gaskets (2.707)



- 1964 License lamp lens gasket.**  
LLG624 .....\$4.25 ea.
- 1965; 1968-1972 License lens gasket.**  
LLG643.....\$6.75 ea.



www.oldbuickparts.com  
**908-369-3666**



## Bulbs



Year & Model	Head-light	Parking	Direction Signal		Tail	Stop	License Plate	Instru-ment	Indi-cator	Dome	Back-up	Marker lamp	
			Front	Rear								Left	Right
1963	SB1, SB2	B1034	B1034	B1034	B1034	B1034	B67	B57161	B194	B901004	B1073	----	----
1964	SB1, SB2	B1157A	B1157	B1157	B1157	B1157	B97	B161194	B194	B901004	B1156	----	----
1965	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B161194	B194	B901004	B1156	----	----
1966	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194	B194	B901004	B1156	----	----
1967	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194	B161	B211	B1156	----	----
1968	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B1941893	B194	B901004	B1156-1157	B194A	B194
1969	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B1811893	B194	B901004	B1157	B194A	B194
1970	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B181194	B194	B211	B1157	B194A	B194
1971	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B161194	B194	B211	B1157	B194	B194
1972	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B161194	B194	B211	B1157	B194	B194
1973	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97194	B194	B194	B211	B1157	B194	B194
1974	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B194	B168	B194	B211	B1157	B194	B194
1975	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B194	B168	B161	B211	B1157	B194	B194
1976	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B194	B168	B161	B211	B1157	B1157A	B1157
1977	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B168	B161	B161	B56189	B1156	B194A	B168
1978	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B168	B161	B161	B56189	B1156	B194A	B168

**Prices:** 53-\$1.50, 57-\$1.25, 67-\$1.50, 90-\$2.00, B97-\$2.25, 161-\$2.00, 168-\$1.50, 194-\$2.25, 194A-\$3.00, 210-\$5.50, 211-\$2.25, 1004-\$2.75, 1034-\$2.75, 1073-\$2.75, 1156-\$2.50, 1157A-\$2.00, 1157-\$2.00, 1893-\$2.25, SB1-\$11.25, SB2-\$11.25

### NOTICE


### CAR SHOW ATTENDEES

CARS, Inc. will NOT bring the usual "yellow trailer" to the shows.

We will be happy to bring any parts you need.

**Please call in advance of the show to place your order.**

## Look For Us!



If your thinking of attending any of the shows listed below, be sure to stop by and say "Hello". We will be glad to discuss some of our newest items or simply talk about your **BUICK**.

Plan ahead by calling-in your order weeks ahead of time. We will be able to bring your entire order and save you shipping too.

*GS Nationals  
Buick Nationals*

*\*Hershey GDB 31  
near Lamp Post 86*

**Headlamp Sockets**



For 3 prong beam numbers SB6, 6006, SB12, 6012, SB2, 4000 and 4002.  
PT6 .....\$4.75 ea.



For 2 prong beam numbers SB1, 4001.  
PT7 .....\$4.25 ea.

**Lamp Sockets and Pigtails**



Single contact with lead. Fits bulb numbers 51, 53, 55 and 57.  
PT1 .....\$2.25 ea.



Single contact with lead. Fits bulb numbers 63, 67, 81, 87, 89, 1073, 1129, 1133, 1141 and 1156.  
PT2 .....\$2.25 ea.




Double contact with lead. For ears reversed. Bulbs numbers 82, 88, 90, 210, 1004, 1034, 1154 and 1157.  
PT3 .....\$2.75 ea.




Double contact with lead. For ears aligned bulbs.  
PT4 .....\$2.50 ea.


**Parking and Tail Lamp Sockets**



Single contact with lead. For 3/4" to 1 1/8" hole.  
LS1 .....\$5.75 ea.



Double contact with lead. For bulb numbers 1034 and 1154. Fits 1 1/8" hole.  
LS5 .....\$5.75 ea.



Double contact with leads. Fits 3/4" hole. For bulb numbers 1034, 1154 and 1157.  
LS9 .....\$5.75 ea.



Double contact with leads. Fits 3/4" to 1 1/8" hole. For bulb numbers 1034, 1154 and 1157.  
LS2 .....\$5.75 ea.



Double contact with leads. Fits 3/4" to 1 1/8" hole. For bulb numbers 82, 88, 90, 210 and 1004.  
LS3 .....\$7.75 ea.



Double contact with leads. Fits 1 1/8" hole. For bulb numbers 1034, 1154 and 1157.  
LS4 .....\$5.75 ea.

**Interior/Dash Sockets**



Single contact with lead for dome etc. For bulb numbers 63, 67, 81 89, 1073, 1129 and 1133.  
PT8 .....\$6.75 ea.




Double contact with lead. For dome and map lamps. Reversed ears. Bulb numbers 82, 88, 90, 210 and 1004.  
PT9 .....\$6.75 ea.



Double contact with lead for ears aligned bulbs.  
PT10 .....\$4.75 ea.

**Back-Up and License Lamp Sockets**



Single contact with lead. Fits 3/4" hole. Bulb numbers 63, 67, 81, 89 1129 and 1133.  
LS6 .....\$6.00 ea.



Single contact with lead. Fits 1 1/8" hole. For bulb numbers 63, 67, 81, 89, 1129 and 1133.  
LS8 .....\$6.00 ea.

**Wire Loom**



Asphalt coated fabric. Wire loom for battery cables, headl-amps, wire etc.

WL180 .....	1/8" ID .....	\$1.85 ft.
WL316 .....	3/16" ID. ....	\$1.85 ft.
WL140 .....	1/4" ID .....	\$2.10 ft.
WL516 .....	5/16" ID .....	\$2.10 ft.
WL380 .....	3/8" ID. ....	\$2.10 ft.
WL716 .....	7/16" ID .....	\$2.10 ft.
WL120 .....	1/2" ID. ....	\$2.10 ft.
WL916 .....	9/16" ID .....	\$2.40 ft.
WL580 .....	5/8" ID .....	\$2.40 ft.
WL340 .....	3/4" ID. ....	\$2.40 ft.