


# Carburetion (Group 3)

## Carburetor Rebuilding and Restoration Service (3.725)

Each carburetor is totally disassembled and cleaned in a hot tank solution. Then, each component is correctly plated, painted and colored to duplicate it's original factory finish. The carburetor is reassembled using all proper gaskets, pumps, needles and seats, etc. and new correct screws. Finally, all bench adjustments are made to factory specs. This includes correct shimming of the start switch. The result, the best rebuilt and restored carburetor available in the Hobby.



**NOTE:** This is not an area to skimp on your restoration. Demand the best!

- 1963-1980** All 2bbl Carburetors w/ Bakelite switch.  
CRS390.....\$329.75 ea.
- 1963-1980** 4bbl. Carburetor rebuilding service.  
CRS520.....\$389.00 ea.
- 1964-1966** All Carter 2 x 4 sets.  
CRS636D.....\$692.00 ea.

## Carburetor Kits

### Carter Carburetors

- 1961-1967** All 2-4BBL and 4BBL.  
Numbers: 3088, 89, 3297, 3578, 79,3633, 35, 65, 3826, 27, 3921, 22, 23, 4053, 54, 55, 56, 59, 60, 61, 4179, 80, 81, 4331, 32, 44, 4453, 3645SB, 3646S, 3925SA (Carter AFB 4BBL). 2 kits needed for 2 x 4 carbs.  
CKC617.....\$51.00 ea.

### Rochester Carburetors

- 1963** With 401 engines. 2GC 2BBL.  
Numbers: 7020046, 047, 048, 049, 7023041, 042, 043, 145, 146.  
CKR623.....\$26.00 ea.
- 1963-1966** With 401 engines. 4GC 4BBL.  
Numbers: 7023040, 7023143, 7024040, 7025040, 7025140, 7026040.  
CKR636.....\$39.50 ea.

### 1966-1967

- 1966** All:  
**1967:**Early; 430 engines. 4MV 4BBL.  
Numbers: 7025240, 242, 7027146, 147, 148, 149, 7027240, 241, 7036240, 242.  
CKR667.....\$39.50 ea.

- 1967** Late; With 400, 430 and 455 engines. 4MV BBL.  
Numbers: 7027244, 246, 248, 7041304, 305, 306, 307, 308, 309.  
**1968-1970** Numbers: 7028240, 242, 243, 246, 247, 248, 7029240, 241, 242, 243, 7029246, 7040240, 7040243.  
CKR670.....\$35.00 ea.

- 1968-1974** With 350 and 455 engines. 4MV 4BBL.  
Numbers: 7028244, 245, 7029244, 245, 7040244, 245, 7041245, 7041544, 7042244, 245, 944, 7043244, 245, 246, 7044244, 246, 544, 7044546, 17054900, 901, 902.  
CKR684.....\$29.00 ea.

- 1970-1974** 350, 455.  
Numbers: 7040142, 143, 148, 444, 446, 7041142, 143, 442, 7042142, 7042143, 842, 7043142, 143, 144, 7044141, 142, 144, 442, 7044444, 17054651, 17055003, 17057350, 351.  
CKR704.....\$26.50 ea.

- 1970-1973** With 455 high performance engine. 4MV 4BBL.  
Numbers: 7040246, 247, 7041242, 243, 540, 7042240, 242, 243, 940, 7042942, 7043240, 242, 243, 7044240, 241, 252, 540.  
CKR702.....\$27.50 ea.

- 1975** With 400 engine. 4MC 4BBL. Number: 7045254.  
CKR75.....\$26.50 ea.

- 1975-1976** 455 engine. 4MC, MV 4BBL.  
Numbers: 7045240, 541, 548, 17056240, 540.  
CKR756.....\$26.50 ea.



BP667

### Carter Baffle Plates



BS576

- 1963-1966** All with Carter AFB 4bbl. Stainless steel plate between carb. and intake manifold. This plate is essential for protection against disintegration of aluminum base of carb. It is also necessary for proper idle and smooth running. Recommended is gasket, baffle plate, gasket.  
BP576.....\$16.25 ea.
- 1966** All 400, 425 Hi Compression;  
**1967** All (For Spread bore Carburetors)  
BP667.....\$17.50 ea.

## Choke Stove Pipe Replacement Kit

- 1963-1967**  
All as required.  
CSK530.....\$18.25 kit



## Choke Stove Pipe Insulator



This modern Aramid Fiber sleeve greatly resembles the original. It is heat resistant up to 650 degrees F. White in color. Also excellent for wrapping vapor locked fuel valves. Sold by the foot. **All years.**  
PI300 .....\$5.25 ft.

## Carburetor Stud

- Made of stainless steel.  
**1968-1975** All. 350, 400, 430, 455, 4BBL and 4-1/8" long.  
CS685.....\$6.00 ea.



### Carburetor Bowl Floats



**1963-1967** Carter AFB 4BBL. Brass. (2 needed per car)  
CF577C .....\$34.50 ea.

**1966-1967** Rochester 4BBL  
**1966** All; **1967** Early.  
CF667R.....\$19.50 ea.

**1967-1974** Rochester 4BBL  
**1967** Late;  
**1968-1974** All.  
CF674R.....\$19.50 ea.

### Carb. Mounting Gaskets



**1963-1965** All;  
**1966** All early models (square bore).  
CMG576 .....\$4.75 ea.  
**1966-1967** All with Rochester.  
CMG667 .....\$6.50 ea.  
**1969-1975** All 400, 430, 455 with Rochester 4BBL.  
CMG695 .....\$4.75 ea.

### Gas Filters



**1963-1966** Gas filter. For cars without air conditioning.  
GF636.....\$10.75 ea.



**1963-1966** For cars with air conditioning.  
GF636A .....\$12.50 ea.



**1967** All; **1975** All.  
GF675.....\$3.50 ea.



**1968-1975** 1968-1974 All;  
1975 All 455 engines.  
GF682.....\$3.50 ea.





**All years** replacement. Clear in-line gas filter. Great for near gas tank or frame installation. Important for insuring clean fuel to fuel pump.  
GF100.....\$4.50 ea.


### In Line Gas Filters



GF140.....For 1/4" ID Hose.....\$9.25 ea.

GF516.....For 5/16" IDHose.....\$9.25 ea. 

GF516C..For 5/16" ID Hose(clear).\$6.50 ea. 

GF380.....For 3/8" ID Hose.....\$9.25 ea. 

### Dash Pots



**1963-1971** Riviera carburetor dash pot.  
DP611.....\$18.25 ea.

### Choke Pull Offs

**1968-1974** 430 and 455 engines with 4BBL Rochester. Front.  
CPO684.....\$16.00 ea.  
**1971** 455 engines. Rochester 4BBL. Rear.  
CPO71.....\$24.75 ea.



### Carburetor to Air Cleaner Gaskets



**1966-1975** All 400, 430, 455 with Rochester 4BBL.  
BG5152 .....\$3.75 ea.

### Ported Vacuum Switches

**1968-1974** All except 1972 with three port, two terminals.  
PVS684.....\$49.50 ea.  
**1972** All three ported with two terminals. (in manifold).  
PVS72.....\$49.50 ea.



### Rod Clips

**1963-1966** Carburetor throttle rod clip. 1/4" rod diameter.  
RC460 .....\$075 ea.



### Pinch Clamps (Corbin Clamps)

*For fuel lines, vacuum lines and PCV hoses*

CARS #	YEARS	PRICE
PC380	All .....3/8" OD hose	\$ 1.00 ea.
PC716	All .....7/16" OD hose	\$ 1.00 ea.
PC150	All .....1/2" OD hose	\$ 1.00 ea.
PC916	All .....9/16" OD hose	\$ 1.00 ea.
PC580	All .....5/8" OD hose	\$ 1.00 ea.
PC1116	All .....11/16" OD hose	\$ 1.25 ea.
PC100	All .....1" OD hose	\$ 1.25 ea.

### Intake Manifold Plugs


This plug is often rusted out and sometimes missing. Leakage around this plug causes poor carburetion.

**1963-1966:** All engines with 4-bbl. carburetor.  
MP596 .....\$12.75 ea.



### Mass Air Flow Sensor

1985 Riviera.  
MAS85.....\$87.50 ea.



### Prom Calibrator (3.670)

1985 Riviera with turbo motor.  
EP85TR.....\$70.25 ea.

# Fuel • Exhaust (Group 3)

## Air Filter Elements (3.410)



**1963-1964** 401 and 425 engines with single carburetors.  
AF636 .....\$22.75 ea.

**1964-1966** 425 engines with 2 4BBL carburetors.  
AF646 .....\$28.75 ea.



**1965-1966**  
1965-1966: 401-425 engines;  
1967: 430 except dual inlet.  
AF657 .....\$15.25 ea.

**1967** Riviera G.S. with dual snorkel air cleaner.  
AF607 .....\$15.00 ea.

**1968; 1970-1975** All.  
AF680 .....\$12.25 ea.

**1969** All.  
AF698 .....\$11.75 ea.

## Air Cleaner Parts


**1963-1970** Air cleaner wing nut (1/4"-20 thread).  
WN530 .....\$1.75 ea.

**1971-1980** Air cleaner wing nut (5/16"-18 thread).  
WN710 .....\$0.75 ea.



**1964-1966** Dual Quad Air Cleaner Nut / Stud  
AN646 .....\$22.00 ea.

## Air Cleaner Heat Pipe



**1970-1974** Air cleaner-exhaust manifold. Heat pipe.


 HP704 (silver finish) .....\$14.50 ea.

 HP704B (black finish) .....\$17.25 ea.

## Breather Tubes

(Air Cleaner to Rocker Cover) (1.745)

Breather Tube



**1968-1969** All 350 and 400 4BBL.  
VT689 .....\$18.50 ea.

**1970-1971** all.  
VT704 .....\$17.50 ea.

## Crankcase Ventilation Filter

*On Side Of Air Cleaner*



**1968-1972** All.  
CVF682 .....\$ 4.75 ea.

## Intake Manifold Gaskets



**1963-1966** All.  
IMG576 .....\$11.75 set

**1967-1971** All.  
IMG671 .....\$47.50 ea.

**1972-1976** All.  
IMG726 .....\$39.50 ea.

## Exhaust Parts

**Brass Nuts.** Tall. All years as required.  
3/8-16. Used on manifolds, pipes,  
exhaust, trim etc. Solid brass.



N6P .....\$3.75 pr.

## Exhaust Manifold Gaskets



EMG576



EMG676

**1963-1966** All.  
EMG576 .....\$11.75 pr.

**1967-1976** All.  
EMG676 .....\$15.00 pr.

## Exhaust Manifold French Locks



**1963-1966** All as required. Stainless steel!  
FL576 .....\$3.50 ea.



**1963-1966** All as required. Stainless steel!  
FL626 .....\$1.75 ea.

### Fuel Pumps (3.900)



- 1963-1965** All. Rebuilding service or sold on an exchange with \$50.00 core charge.  
 FP595RS.....\$89.25 ea.  
**1963-1965** Replacement fuel pump.  
 Sold outright no exchange necessary.  
 FP575.....\$39.75 ea.  
**1966** All without air conditioning.  
 FP66.....\$44.50 ea.  
**1966** All with air conditioning.  
 FP66A.....\$69.50 ea.  
**1967-1974** Fuel pump.  
**1967-1968:** All, except those with fuel pump in tank;  
**1971-1974:** All except GS.  
 FP674.....\$44.25 ea.  
**1970-1973**  
**1970:** GS stage 1;  
**1971-1973:** GS.  
 FP683.....\$55.00 ea.  
**1975-1976** All 455 engines.  
 FP756.....\$51.00 ea.

### Fuel Pump Rebuilding Kit



- 1963-1965** All.  
 FPK575.....\$59.50 ea.

### Fuel Pump Block-Off Plates



- 1963-1976** All as required.  
 CP300.....\$10.75 ea.

### Fuel Pump Hardware Kits

- 1963-1966** all 401, 425 engines. Correct bolts/washers.  
 FPH406.....\$2.25 ea.

### Fuel Injector Seals

- 1984-1985** Used on all injectors and fuel pressure regulator. 13 needed per car.  
 IS847.....\$1.25 ea.  
 IS847S.....(Set of 15).....\$12.75 set

### 1979-1985 Gas Tank

- 1979-1980** All exc. 350 engine;  
**1981-1983** All;  
**1984-1985** All with 307Y.  
 Includes filler neck. Shipping about \$95.  
 GT795.....\$197.50 ea.  
 GS795.....(Strap cushions for above).....\$25.25 pr.

### Fuel Line Clip Kits



- 1971-1976** Riviera. 3/8" with return line. 16 piece kit.  
 FLC716R.....\$28.00 ea.  
**1971-1976** Riviera. 3/8" without return line. 16 piece kit.  
 FLC716.....\$18.00 ea.  
**1977-1986** Riviera. 3/8" with return line. 27 piece kit.  
 FLC776R.....\$32.00 ea.  
**1977-1986** Riviera. 3/8" without return line. 20 piece kit.  
 FLC776.....\$25.00 ea.

### Gas Tank Parts

- 1963-1965** Riviera gas tank sending unit gasket.  
 GG355.....\$3.75 ea.  
**1963-1965** Gas door bumper.  
 GDB635.....\$5.00 pr.  
**1963-1970** All. Gas tank bolt kit. Two 3/8-16 x 3" bolts and two lock nuts. Brightly zinc plated.  
 GB610.....\$5.50 kit  
**1963-1985** All. Gas tank strap cushions.  
 SC350.....\$12.75 pr.  
**1966-1970** Riviera gas tank fuel gauge gasket. (3.112)  
 GG642.....\$5.00 ea.  
**1973-1985** Riviera gas tank fuel gauge gasket.  
 GG671.....\$6.75 ea.

### Gas Tank Caps



- 1963-1965** Riviera gas tank cap. (vented).  
 GC575.....\$9.00 ea.  
**1966-1970** Gas tank cap. (non-vented).  
 GC640.....\$7.50 ea.  
**1971-1974** All.  
 GC714.....\$9.75 ea.  
**1982-1985** Riviera.  
 GC827.....\$12.75 ea.  
**1982-1985** Riviera (Locking type with key).  
 GC827L.....\$33.50 ea.



GC827

GC827L