


Carburetion (Group 3)

Carburetor Rebuilding and Restoration Service (3.725)

Each carburetor is totally disassembled and cleaned in a hot tank solution. Then, each component is correctly plated, painted and colored to duplicate it's original factory finish. The carburetor is reassembled using all proper gaskets, pumps, needles and seats, etc. and new correct screws. Finally, all bench adjustments are made to factory specs. This includes correct shimming of the start switch. The result, the best rebuilt and restored carburetor available in the Hobby.



NOTE: This is not an area to skimp on your restoration. Demand the best!

- 1963-1980** All 2bbl Carburetors w/ Bakelite switch.
CRS390.....\$379.50 ea.
- 1963-1980** 4bbl. Carburetor rebuilding service.
CRS520.....\$389.00 ea.
- 1964-1966** All Carter 2 x 4 sets.
CRS636D.....\$692.00 ea.

Carburetor Kits

Carter Carburetors

- 1961-1967** All 2-4BBL and 4BBL.
Numbers: 3088, 89, 3297, 3578, 79,3633, 35, 65, 3826, 27, 3921, 22, 23, 4053, 54, 55, 56, 59, 60, 61, 4179, 80, 81, 4331, 32, 44, 4453, 3645SB, 3646S, 3925SA (Carter AFB 4BBL). 2 kits needed for 2 x 4 carbs.
CKC617.....\$51.00 ea.

Rochester Carburetors

- 1963** With 401 engines. 2GC 2BBL.
Numbers: 7020046, 047, 048, 049, 7023041, 042, 043, 145, 146.
CKR623.....\$26.00 ea.
- 1963-1966** With 401 engines. 4GC 4BBL.
Numbers: 7023040, 7023143, 7024040, 7025040, 7025140, 7026040.
CKR636.....\$39.50 ea.

1966-1967

- 1966** All:
- 1967:** Early; 430 engines. 4MV 4BBL.
Numbers: 7025240, 242, 7027146, 147, 148, 149, 7027240, 241, 7036240, 242.
CKR667.....\$39.50 ea.

- 1967** Late; With 400, 430 and 455 engines. 4MV BBL.
Numbers: 7027244, 246, 248, 7041304, 305, 306, 307, 308, 309.

- 1968-1970** Numbers: 7028240, 242, 243, 246, 247, 248, 7029240, 241, 242, 243, 7029246, 7040240, 7040243.
CKR670.....\$35.00 ea.

- 1968-1974** With 350 and 455 engines. 4MV 4BBL.
Numbers: 7028244, 245, 7029244, 245, 7040244, 245, 7041245, 7041544, 7042244, 245, 944, 7043244, 245, 246, 7044244, 246, 544, 7044546, 17054900, 901, 902.
CKR684.....\$29.00 ea.

- 1970-1974** 350, 455.
Numbers: 7040142, 143, 148, 444, 446, 7041142, 143, 442, 7042142, 7042143, 842, 7043142, 143, 144, 7044141, 142, 144, 442, 7044444, 17054651, 17055003, 17057350, 351.
CKR704.....\$26.50 ea.

- 1970-1973** With 455 high performance engine. 4MV 4BBL.
Numbers: 7040246, 247, 7041242, 243, 540, 7042240, 242, 243, 940, 7042942, 7043240, 242, 243, 7044240, 241, 252, 540.
CKR702.....\$27.50 ea.

- 1975** With 400 engine. 4MC 4BBL. Number: 7045254.
CKR75.....\$26.50 ea.

- 1975-1976** 455 engine. 4MC, MV 4BBL.
Numbers: 7045240, 541, 548, 17056240, 540.
CKR756.....\$26.50 ea.



BP667

Carter Baffle Plates



BP576

- 1963-1966** All with Carter AFB 4bbl. Stainless steel plate between carb. and intake manifold. This plate is essential for protection against disintegration of aluminum base of carb. It is also necessary for proper idle and smooth running. Recommended is gasket, baffle plate, gasket.
BP576.....\$17.50 ea.

- 1966** All 400, 425 Hi Compression;
- 1967** All (For Spread bore Carburetors)
BP667.....\$17.50 ea.

Choke Stove Pipe Replacement Kit

- 1963-1967**
All as required.
CSK530.....\$18.25 kit



Choke Stove Pipe Insulator



This modern Aramid Fiber sleeve greatly resembles the original. It is heat resistant up to 650 degrees F. White in color. Also excellent for wrapping vapor locked fuel valves. Sold by the foot. **All years.**
PI300.....\$5.25 ft.

Carburetor Stud

- Made of stainless steel.
- 1968-1975** All. 350, 400, 430, 455, 4BBL and 4-1/8" long.
CS685.....\$6.00 ea.



Carburetor Bowl Floats



- 1963-1967** Carter AFB 4BBL. Brass. (2 needed per car)
CF577C.....\$34.50 ea.
- 1966-1967** Rochester 4BBL
1966 All: **1967** Early.
CF667R.....\$19.50 ea.
- 1967-1974** Rochester 4BBL
1967 Late;
1968-1974 All.
CF674R.....\$19.50 ea.

Carb. Mounting Gaskets



- 1963-1965** All;
1966 All early models (square bore).
CMG576.....\$4.75 ea.
- 1966-1967** All with Rochester.
CMG667.....\$6.50 ea.
- 1969-1975** All 400, 430, 455 with Rochester 4BBL.
CMG695.....\$4.75 ea.

Gas Filters



- 1963-1966** Gas filter. For cars without air conditioning.
GF636.....\$12.50 ea.
- 1963-1966** For cars with air conditioning.
GF636A.....\$12.50 ea.
- 1967** All; **1975** All.
GF675.....\$3.50 ea.
- 1968-1975** 1968-1974 All;
1975 All 455 engines.
GF682.....\$3.50 ea.
- All years** replacement. Clear in-line gas filter. Great for near gas tank or frame installation. Important for insuring clean fuel to fuel pump.
GF100.....\$4.50 ea.

In Line Gas Filters



GF140.....For 1/4" ID Hose.....\$9.25 ea.

GF516.....For 5/16" IDHose.....\$9.25 ea.



GF516C..For 5/16" ID Hose(clear).\$6.50 ea.

GF380.....For 3/8" ID Hose.....\$9.25 ea.



Dash Pots



- 1963-1971** Riviera carburetor dash pot.
DP611.....\$29.50 ea.

Choke Pull Offs

- 1968-1974** 430 and 455 engines with 4BBL Rochester. Front.
CPO684.....\$19.50 ea.
- 1971** 455 engines. Rochester 4BBL. Rear.
CPO71.....\$24.75 ea.



Carburetor to Air Cleaner Gaskets



- 1966-1975** All 400, 430, 455 with Rochester 4BBL.
BG5152.....\$3.75 ea.

Ported Vacuum Switches

- 1968-1974** All except 1972 with three port, two terminals.
PVS684.....\$49.50 ea.
- 1972** All three ported with two terminals. (in manifold).
PVS72.....\$49.50 ea.



Rod Clips

- 1963-1966** Carburetor throttle rod clip. 1/4" rod diameter.
RC460.....\$0.75 ea.



Pinch Clamps (Corbin Clamps)

For fuel lines, vacuum lines and PCV hoses



CARS #	YEARS	PRICE
PC380	All3/8" OD hose	\$ 1.00 ea.
PC716	All7/16" OD hose	\$ 1.00 ea.
PC150	All1/2" OD hose	\$ 1.00 ea.
PC916	All9/16" OD hose	\$ 1.00 ea.
PC580	All5/8" OD hose	\$ 1.00 ea.
PC1116	All11/16" OD hose	\$ 1.25 ea.
PC100	All1" OD hose	\$ 1.25 ea.

Intake Manifold Plugs


This plug is often rusted out and sometimes missing. Leakage around this plug causes poor carburetion.

- 1963-1966:** All engines with 4-bbl. carburetor.
MP596.....\$12.75 ea.



Mass Air Flow Sensor

- 1985** Riviera.
MAS85.....\$87.50 ea.



Prom Calibrator (3.670)

- 1985** Riviera with turbo motor.
EP85TR.....\$70.25 ea.

Fuel • Exhaust (Group 3)

Air Filter Elements (3.410)



1963-1964 401 and 425 engines with single carburetors.
AF636\$22.75 ea.

1964-1966 425 engines with 2 4BBL carburetors.
AF646\$32.50 ea.



1965-1966
1965-1966: 401-425 engines;
1967: 430 except dual inlet.
AF657\$15.25 ea.

1967 Riviera G.S. with dual snorkel air cleaner.
AF607\$15.00 ea.

1968; 1970-1975 All.
AF680\$12.25 ea.

1969 All.
AF698\$11.75 ea.

Air Cleaner Parts

1963-1970 Air cleaner wing nut (1/4"-20 thread).
WN530\$1.75 ea.


1971-1980 Air cleaner wing nut (5/16"-18 thread).
WN710\$0.75 ea.



1964-1966 Dual Quad Air Cleaner Nut / Stud
AN646\$22.00 ea.

Air Cleaner Heat Pipe

1970-1974
Air cleaner-exhaust manifold.
Heat pipe.




HP704 (silver finish)\$14.50 ea.

HP704B (black finish)\$17.25 ea.

Breather Tubes

(Air Cleaner to Rocker Cover) (1.745)

Breather Tube



1968-1969
All 350 and 400 4BBL.
VT689\$19.50 ea.



1970-1971 all.
VT704\$19.50 ea.

Crankcase Ventilation Filter

On Side Of Air Cleaner



1968-1972 All.
CVF682\$4.75 ea.

Intake Manifold Gaskets



1963-1966 All.
IMG576\$18.50 set

1967-1971 All.
IMG671\$47.50 ea.

1972-1976 All.
IMG726\$39.50 ea.

Exhaust Parts

Brass Nuts. Tall. All years as required.
3/8-16. Used on manifolds, pipes,
exhaust, trim etc. Solid brass.



N6P\$3.75 pr.



EMG576



EMG676

Exhaust Manifold Gaskets

1963-1966 All.
EMG576\$13.50 pr.

1967-1976 All.
EMG676\$15.00 pr.

Exhaust Manifold French Locks

1963-1966 All as required. Stainless steel!
FL576\$3.50 ea.

1963-1966 All as required. Stainless steel!
FL626\$1.75 ea.



Manifold Anti-Rattle Spring

1963-1969 All.
MS629\$7.75 ea.



1963-1985 Exhaust pipe to manifold
bolt kit. Stainless steel with brass nuts.
FBK340\$9.95 ea.

Fuel Pumps (3.900)

1963-1965 All. Rebuilding service or sold on an exchange with \$50.00 core charge.
FP595RS.....\$89.25 ea.

1963-1965 Replacement fuel pump. Sold outright no exchange necessary.
FP575.....\$39.75 ea.

1966 All without air conditioning.
FP66.....\$44.50 ea.

1966 All with air conditioning.
FP66A.....\$69.50 ea.

1967-1974 Fuel pump.
1967-1968: All, except those with fuel pump in tank;
1971-1974: All except GS.
FP674.....\$44.25 ea.

1970-1973
1970: GS stage 1;
1971-1973: GS.
FP683.....\$75.00 ea.

1975-1976 All 455 engines.
FP756.....\$39.50 ea.

1977-1984 All 307 engines with 2 fuel lines at pump.
FP774.....\$39.50 ea.



Fuel Pump Rebuilding Kit

1963-1965 All.
FPK575.....\$69.50 ea.



Fuel Pump Block-Off Plates

1963-1976 All as required.
CP300.....\$12.50 ea.



Fuel Pump Hardware Kits

1963-1966 all 401, 425 engines. Correct bolts/washers.
FPH406.....\$2.25 ea.

Fuel Line Clip Kits

1971-1976 Riviera. 3/8" with return line. 16 piece kit.
FLC716R.....\$28.00 ea.

1971-1976 Riviera. 3/8" without return line. 16 piece kit.
FLC716.....\$18.00 ea.

1977-1986 Riviera. 3/8" with return line. 27 piece kit.
FLC776R.....\$32.00 ea.

1977-1986 Riviera. 3/8" without return line. 20 piece kit.
FLC776.....\$25.00 ea.



Gas Tank Sealer/Liner

Alcohol resistant. Quart can.
TS1.....\$34.50 ea.



Gas Tank Straps

1963-1965
TS635R.....\$40.00 ea.

1966-1970
TS660R.....\$40.00 ea.

Gas Tank Strap Cushions

1963-1985 All.
SC350.....\$12.75 pr.

Gas Tanks (shipped oversize)

1963-1965
GT635R.....\$290.00 ea.

1966-1970
GT660R.....\$350.00 ea.

1979-1980 All exc. 350 engine;
1981-1983 All;
1984-1985 All with 307Y.
Includes filler neck. Shipping about \$95.
GT795.....\$197.50 ea.
GS795.....(Strap cushions for above).....\$25.25 pr.



Gas Tank Sending Units

1963-1964 With AC - 2 fuel lines.
SU634RA.....\$79.00 ea.

1963-1964 Without AC - 1 fuel line.
SU634R1.....\$79.00 ea.

1965 With AC - 2 fuel lines.
SU65RA.....\$79.00 ea.

1965 Without AC - 1 fuel line.
SU65R1.....\$79.00 ea.



Gas Tank Parts

1963-1965 Riviera gas tank sending unit gasket.
GG355.....\$3.75 ea.

1963-1965 Riviera fuel gauge screws & washers kit. (5)
GGS355.....\$4.50 kit.

1963-1965 Gas door bumper.
GDB635.....\$5.00 pr.

1963-1970 All. Gas tank bolt kit. Two 3/8-16 x 3" bolts and two lock nuts. Brightly zinc plated.
GB610.....\$5.50 kit

1963-1985 All. Gas tank strap cushions.
SC350.....\$12.75 pr.

1966-1970 Riviera gas tank fuel gauge gasket. (3.112)
GG642.....\$5.00 ea.

1973-1985 Riviera gas tank fuel gauge gasket.
GG671.....\$6.75 ea.

Gas Tank Caps

1963-1965 Riviera gas tank cap. (vented).
GC575.....\$9.50 ea.

1966-1970 Gas tank cap. (non-vented).
GC640.....\$7.50 ea.

1971-1974 All.
GC714.....\$9.75 ea.

1982-1985 Riviera.
GC827.....\$12.75 ea.

1982-1985 Riviera (Locking type w/ key).
GC827L.....\$33.50 ea.

