

Windshield • Front Vent (Group 10)

Windshield Washer Parts



- 1963-1972** Windshield washer jar cap (90 degree).
WC632.....\$4.50 ea.
- 1971-1975** Windshield washer jar.
1971-1972: All;
1975: All.
WJ715.....TOS



**See Hardware
Section Group 17 for
Windshield Clips**

Windshield Washer Pump Repair Kits

- 1963-1968** All with 90 degree hose fittings.
WRK594.....\$12.25 kit
- 1963-1968** All with straight hose fittings;
1969-1974 All with depressed wipers.
WRK614.....\$12.25 kit

Windshield Wiper Hose

- 1961-1975** Windshield wiper hose. (7/64").
VH764.....\$1.50 per foot
- 1961-1975** Windshield wiper hose. (5/32").
VH532.....\$1.50 per foot
- 1961-1975** Windshield wiper hose. (7/32").
VH732.....\$1.50 per foot
- 1961-1975** Windshield wiper hose. (1/4").
VH14.....\$1.50 per foot

*****We have a limited supply of **NOS 1/4"** vacuum hose. It features correct outside diameter and "draw" lines for that authentic look.*****

- VH14OEM.....\$3.50 ft.



- 1963-1970** Windshield washer plastic reservoir. "Buick" emblem as original.
WJ630.....\$38.50 ea.
WC632.....(Cap for above)\$4.50 ea.

Optikleen Bottles and Caps

- 1963-1968** all. Bottle assembly. Includes stainless steel bracket and cap.
OB598.....\$36.50 ea.
- 1963-1968** All. Includes stenciled writing.
OC598.....(Cap Only).....\$6.75 ea.
- 1963-1968** Optikleen bottle label.
D46\$3.75 ea.
- 1963-1968** Optikleen bottle cap label.
D107\$4.00 ea.



Windshield and Rear Glass Seal

- Glass setting tape. Provides instant and tight seal.
GS600.....3/8" round x 15' long.....\$12.75 ea.
- Butyl dam tape. For use with complete cut-out jobs.
GS601.....3/8" x 1/4" x 15' long.....\$12.75 ea.



Vent Window Weatherstrip

- 1963-1965** Vent window weatherstrip.
VW635.....\$133.50 pr.
- 1963-1965** Vent window vertical seal.
VS635R\$45.75 pr.
- 1963-1965** Door glass to vent seal with upper tip.
VS635.....\$77.00 pr.

Cowl Seals and Clips

- 1963-1965** Riviera. Rubber extrusion.
CS635.....\$26.50 ea.
- 1963-1965** Riviera. Cowl seal clips (12.801)
LR615\$2.25 ea.
- 1968-1970** Cowl seal. 45" extrusion. (9.127)
CS680R\$42.00 ea.
- 1971-1973** Riviera cowl seal.
CS718.....\$38.25 ea.



- 1968-1971** All. Cowl vent screen "H" retainers. 5 per car.
CSR682\$4.00 ea.
CSR682S.....(set of 5).....\$17.00 set.

(Group 10) Door and Roof Rail Weatherstripping



Door Weatherstrip Sets

We are the first company to reproduce the early Riviera door weatherstrips. After years of satisfied customers and show winning cars, our door seals are proven to be #1. They come in pairs, ready to install with correct pins already inserted. They also feature the correct molded ends for proper look and function.

- 1963-1965** Door weatherstrip with molded ends.
DWS635\$69.00 pr.
- 1966-1970** Door weatherstripping with molded ends.
DWS660\$84.50 pr.
- 1971-1973** Riviera door weatherstrip with molded ends.
DWS713\$75.25 pr.
- 1974-1976** Riviera door weatherstrip with molded ends.
DWS746\$71.50 pr.
- 1979-1985** Riviera door weatherstrip with molded ends.
DWS795\$95.00 pr.

Weatherstrip Kits

- 1963-1965 Riviera** Basic Weatherstrip Kit.
Kit Includes: Door weatherstrip with molded ends, roof rail weatherstrip set and trunk weatherstrip.
BRK635.....\$159.00 set
- 1966-1970 Riviera** Basic Weatherstrip Kit.
Kit Includes: Door weatherstrip with molded ends, roof rail weatherstrip set and trunk weatherstrip.
BRK660.....\$163.75 set
- 1971-1973 Riviera** Basic Weatherstrip Kit.
Kit Includes: Door weatherstrip with molded ends, roof rail weatherstrip set and trunk weatherstrip.
BRK713.....\$163.75 set




- 3M Super Weatherstrip Adhesive.** The best we've found
WA360\$12.00 ea.

Roof Rail Weatherstrip Sets

We are the first company to reproduce the early Riviera roof rail weatherstrips. After years of satisfied customers and show winning cars, our seals are proven to be #1. They come in pairs, ready to install with correct hardware included. They also feature the correct molded ends for proper look and function.

- 1963-1965** Side roof rail weatherstrip with molded ends.
RR635\$69.00 pr.
- 1966-1970** Side roof rail weatherstrip with molded ends.
Stops at quarter window
RR660\$81.25 pr.
- 1971-1973** Side roof rail weatherstrip with molded ends.
RR713R.....\$92.75 pr.
- 1974-1976** Side roof rail weatherstrip with molded ends.
RR746R.....\$78.50 pr.
- 1979-1985** Side roof rail weatherstrip with molded ends.
RR795R.....\$89.25 pr.

Window Channel Kits (Sweepers)



- 1963-1965** Inner and outer window channel sweeper kit.
Made as original. 8 piece kit complete with screws.
WK635\$95.25 kit
- 1966-1967** Inner and outer window channel sweeper kit.
Made as original. 8 piece kit complete with screws.
WK667\$95.75 kit
- 1968-1970** Inner and outer window channel sweeper kit.
Made as original. 8 piece kit complete with screws.
WK680\$85.25 kit
- 1971-1973** Inner and outer window channel sweeper kit.
Made as original. 8 piece kit complete with screws.
WK713\$119.00 kit
- 1979-1985** Hardtops. Inner and outer window channel sweeper kit. 8 piece kit as original, complete with screws.
WK795\$96.00 kit

Exterior Door Parts (Group 10)



1963-1967 Outside Rear View Mirror

Reproduction non-remote mirror fits either side. Identical to the original. Licensed by GM. Includes bracket, gasket and hardware.

- MK617F\$109.00 kit
- Bracket and hardware kit. Will also fit original mirrors.
- MB617\$9.75 ea.
- Gasket only. Will also fit original non-remote mirrors.
- MG617F\$9.75 ea.

Gasket for original remote mirror.

- MG617RC\$9.75 ea.

Outer Door Skin Retainers 1963-1965 Riviera

We have produced the very hard-to-find and authentically correct nuts and bolts to correctly mount your outer panels.



Special Hex head nut with dome. 8 needed per car.

- N1 (1)\$3.75 ea.
- N1S (pack of 8)\$25.75 ea.



Special Hex head flange nut. 14 needed per car.

- N2\$1.25 ea.

Special T-bolt. 28 needed per car.

- S9\$3.75 ea.



Complete 58 piece kit.

- DPK635\$129.50 ea.

Door Bumpers and Parts



- 1963-1965** Riviera door bumper.
- DB595\$2.75 ea.



- 1966-1970** Riviera door bumper.
- DB660R\$3.25 ea.



- 1971-1976** All.
- DB500C\$2.75 ea.

Door Lock Pairs With Two (2) Keys

1963-1965 Riviera. With original style keys.

- DLS596\$36.00 set



1966-1967 Riviera. With original style keys.

- DLS608\$36.00 set

1968-1973 Riviera. With original style keys.

- DLS683\$17.00 set

Door Handles and Gaskets (10.527)

Includes buttons and springs.

1963-1965 Chrome outside door handles. Includes buttons, springs and gaskets. Show quality!



- DH605S\$86.00 set



1966-1970 All. Less buttons.

- DH660S\$90.25 set



1963-1970 Gasket set, outside door handle. Die cut rubber construction. 4 piece set for 2 handles. (10.537)

- HG590\$10.00 set

Door Handle Pushbutton Kit

Includes 2 each: Pushbuttons, Rubber "O"-Rings, Springs, Retainers and Instructions.

1963-1972 All.




- HB642\$18.50 pr.

Door Handle Gasket (10.537)

1971-1973 All. Fits either side.



- HG713\$5.50 ea.



1974-1976 Door handle gasket set. (10.537)

- HG716\$7.50 set



1963-1975 Door lock cylinder gasket. (10.537)

- KLG540\$1.25 ea.

Door Strikers (10.569)

1971-1976 All.



- DS716\$14.00 ea.

1966-1970 All;

1979-1985 All.



- DS645\$12.00 ea.



1971-1976 Riviera door striker silencer.

- LS716\$1.25 ea.

Lock Buttons and Ferrules



- 1963-1965** All. Chrome door lock buttons.
LB616.....\$4.25 ea.
- 1968-1970** Chrome door lock buttons.
LB680.....\$4.25 ea.
- 1971-1986** Chrome door lock buttons.
LB710.....\$4.25 ea.
- 1968-1985** Lock button ferrule. All as required
BF685.....\$2.75 ea.

Power Window Motors

State left hand or right hand. Plug may differ. Hard wire if necessary.



- 1963-1981** Power window motor.
- WM600LF.....Left Hand Front.....\$127.25 ea.
- WM600RF.....Right Hand Front.....\$127.25 ea.
- WM600LR.....Left Hand Rear.....\$127.25 ea.
- WM600RR.....Right Hand Rear.....\$127.25 ea.
- 1982-1985** Convertibles. Power window motor. (outright).
- WM827.....(Fits Either Side)\$37.50 ea.
- WM827D.....(Genuine Delco).....\$59.50 ea.
- 1982-1985** Convertibles. Rear 1/4 Power window motor.
- WM825L.....(Left Hand).....\$167.75 ea.
- WM825R.....(Right Hand).....\$167.75 ea.

Power Window Switches and Bezels



- 1964-1970** All "4 in a row" type with bezel.
PWS640.....\$67.50 ea.



- 1964-1970** All single switch with bezel.
PWS640S.....\$36.50 ea.



- 1961-1977** All "4 in a row" type with bezel.
PWS717.....\$75.75 ea.



- 1971-1977** All single switch with bezel.
PWS717S.....\$29.50 ea.



- 1982-1985** Rear quarter window switch.
PWS825R.....\$18.75 ea.



- 1982-1985** Power window switch in front armrest.
PWS825 (2 Button).....\$51.00 ea.



- 1982-1985** All. Window switch bezel. Chrome. (1-button).
WSB825S.....\$39.75 ea.

Window Crank Handles



- 1963-1964** All as required.
WH594\$16.50 ea.

Vent Crank Handles



- 1963-1964** All as required.
VC594\$16.50 ea.



- 1963-1975** As required. Door handle retaining clip. (10 per pack).
HRC540\$2.25 ea.

Handle Removal Tool

Remove Window and Door Handle Retaining Clips Without Damaging Door Panels



- 1963-1977** All.
HT360\$7.75 ea.



- 1963-1965** Door handle tension spring.
HS395\$1.50 ea.



- 1963-1973** Door handle washers.
HW552\$3.00 ea.



- 1968-1974** All with black knob.
WH680B.....\$8.75 ea.



- 1968-1974** All a clear knob.
WH680C\$8.75 ea.

Inside Door Handles (Paddle Type)

- 1963-1967** All as arranged, 2 pr. needed for deluxe interiors.
DH607\$51.00 pr.

Power Vent Window Gears



- 1963-1965** Power vent window gears. Bronze.
VG595.....(L&R Hand).....\$89.50 pr.

Power Door Locks and Bezels



- 1968-1970** All square switch. "LOCK".
DLS680\$69.75 ea.



- 1971-1977** All square switch. "LOCK".
DLS717\$59.50 ea.



- 1982-1985** All with switch in armrest.
DLS825R.....\$49.00 ea.

Door Panel Retainers



- 1963-1975** All as required.
DPR598.....\$1.00 ea.

Arm Rest Base (14.686)



- 1963-1964** Riviera. All w/o custom interior.
ARB634.....\$57.50 pr.



- 1965-1966** Riviera. All w/o custom interior.
ARB656.....\$48.50 pr.

Interior Door Parts (Group 10)

Door Sill Plates



(11.175)

1963-1965 Door sill plates with logo.

DS614\$59.50 pr.

1966-1970 All.

DS660\$109.00 pr.

1971-1975 Riviera.

DS715\$89.50 pr.



1963-1985 Glass setting tape.

Sold by the foot.

ST330.....\$0.85 ft.

Air Duct Hose

Sturdy, wire reinforced defroster and air duct made like the original with rubber impregnated cloth covering. Specify inner diameter and length. Sold in foot increments only.



AD150.....	1 1/2"\$8.00 ft.
AD200.....	2"\$9.50 ft.
AD250.....	2 1/2"\$11.25 ft.
AD300.....	3"\$12.00 ft.
AD350.....	3 1/2"\$12.25 ft.
AD375.....	3 3/4"\$12.25 ft.
AD400.....	4"\$12.50 ft.
AD500.....	5"\$13.25 ft.
AD538.....	5 3/8"\$14.00 ft.

Door Hinge Pins and Bushings



1963-1970 Door hinge pin. 11/32" OD x 4".

HP310.....(cut if too long)\$3.00 ea.



1963-1970 Door hinge pin bushing. Two per pin.

HB310\$1.00 ea.



1973-1990 Door hinge pin. All as required.


HP670\$3.00 ea.



1973-1990 Door hinge pin bushings. All as required.

HB820\$1.00 ea.


Window Rollers (10.783)



1963-1966 All as required.

Window regulator roller and rivet.

WR576.....\$3.25 ea.



1963-1967 Riviera and as required.

7/8" wide.


WR637.....\$3.75 ea.



1968-1990 all as required. 1 1/16" OD,

1 1/64" ID. nylon.


WR727.....\$2.25 ea.



1979-1985 all as required. 5/16 wide.


WR785.....\$6.50 ea.

Drain Hole Seals




1964-1972 All except 1965. Seal, door bottom drain hole.

HS645.....\$4.00 ea.



1965 Seal, door bottom drain hole.

HS625.....\$4.00 ea.



1969-1970 All. Conduit for power window wiring from front door to body. Approx. 17" length extruded rubber tube.

DC650\$68.25 pr.



Sunshade Rest Grommets

1963-1972 All as required.
SG632\$5.75 pr.



Sunshade Sleeves

1965-1977 All.
SS642.....\$5.75 pr.



1984-1985 All.
SS829.....TOS



Visor Supports

1966-1970 all. Fits either side.
VS642\$19.75 ea.



1963-1965 Riviera odometer reset knob.
RK425.....\$3.75 ea.



1963-1965 Interior coat hook.
CH396\$11.25 pr.

Interior Rear View Mirror



1967-1970 All.
10" Polished stainless steel backing, day/night lever.
IM692.....\$46.00 ea.



Glove Boxes (10.260)

1963 All w/o a.c.
GB63R.....\$28.50 ea.

1963 All with a.c.
GB63RA.....\$28.50 ea.



1964 All black flock.
GB64RB.....\$28.50 ea.

1964 All gray flock.
GB64RG\$28.50 ea.

1965 All black flock.
GB65R.....\$28.50 ea.

1968-1970 All with a.c. glove box.
GB680.....\$26.50 ea.



1971-1973 All.
GB713.....\$27.50 ea.



1963-1965 Glove box door bumpers.
DB635.....\$2.50 pr.

Glove Box Lock (10.266)
with Two Original Keys



1966-1967 Riviera.
GBL667.....\$31.25 ea.



1968-1973 Riviera.
GBL683TOS



1971-1972 Glove box lock and trunk lock
with 2 matching original keys.
LS712.....\$59.75 set



Glove Box Light Switch

1968-1974 Includes lightbulb and new terminal.
GBS644\$14.00 ea.



Rear Ash Trays

1966-1967 All with deluxe arm rests.
AT597\$22.25 ea.