

## Floorpans and Rocker Panels (12.000)

### 1963-1965 ALL

Front Toeboard (12.980)

- FP635TL.....(LEFT SIDE) .....\$74.50 ea.
- FP635TR.....(RIGHT SIDE) .....\$74.50 ea.

Floor Pan (12.980)

- FP635FFL.....(FRONT LEFT) .....\$87.50 ea.
- FP635FFR.....(FRONT RIGHT) .....\$87.50 ea.
- FP635RFL.....(REAR LEFT) .....\$87.50 ea.
- FP635RFR.....(REAR RIGHT) .....\$87.50 ea.

Under Seats (12.980)

- FP635FSL.....(FRONT LEFT) .....\$74.50 ea.
- FP635FSR.....(FRONT RIGHT) .....\$74.50 ea.
- FP635RSL.....(REAR LEFT) .....\$111.50 ea.
- FP635RSR.....(REAR RIGHT) .....\$111.50 ea.

Rocker Panels (12.934)

- RP635RL.....(LEFT OUTER PANEL) .....\$34.50 ea.
- RP635RR.....(RIGHT OUTER PANEL) .....\$34.50 ea.
- RP635IL.....(LEFT INNER PANEL) .....\$39.50 ea.
- RP635IR.....(RIGHT INNER PANEL) .....\$39.50 ea.

### 1971-1973 ALL

Front Toeboard (12.980)

- FP713TL.....(LEFT) .....\$97.50 ea.
- FP713TR.....(RIGHT) .....\$97.50 ea.

Floor Pan (12.980)

- FP713FFL.....(FRONT LEFT) .....\$74.50 ea.
- FP713FFR.....(FRONT RIGHT) .....\$74.50 ea.
- FP713RFL.....(REAR LEFT) .....\$74.50 ea.
- FP713RFR.....(REAR RIGHT) .....\$74.50 ea.


Under Seats (12.980)

- FP713FSL.....(FRONT LEFT) .....\$74.50 ea.
- FP713FSR.....(FRONT RIGHT) .....\$74.50 ea.
- FP713RSL.....(REAR LEFT) .....\$137.50 ea.
- FP713RSR.....(REAR RIGHT) .....\$137.50 ea.

## Body Plugs



- BP120 .....1/2" Hole Diameter .....\$1.75 ea.
- BP580 .....5/8" Hole Diameter .....\$1.75 ea.
- BP340 .....3/4" Hole Diameter .....\$2.25 ea.
- BP780 .....7/8" Hole Diameter .....\$2.25 ea.
- BP100 .....1" Hole Diameter .....\$1.75 ea.
- BP114 .....1 1/4" Hole Diameter .....\$1.75 ea.
- BP112 .....1 1/2" Hole Diameter .....\$2.25 ea.



1963-1965 Riviera rocker panel rubber hole plug.  
RP635 .....\$4.75 ea.



## Trunk Floor Pan

1963-1965 All.

Trunk pan (12.980)

TP635 .....\$239.00 ea.

## 1963-1965 Door Panel Retainers

We have reproduced the correct bolts and nuts that retain the unique removable door panels on your Riviera. These visible hardware items are needed for correct installation and show appearance.



Hex nut with dome. 8 needed per door.  
N1 .....\$3.75 ea.  
N1S.....(Set of 8 for 1 door) .....\$25.75 set



Hex nut. 7 needed per door.  
N2 .....\$1.25 ea.

T-screw. 14 needed per door.

S9.....\$3.75 ea.



Complete kit for both doors. 58 pieces. A \$171.50 value.

DPK635 .....\$129.50 ea.



www.oldbuickparts.com

908-369-3666

# Rear 1/4 Panel • Roof (Group 12)

## 1963-1964 Rear 1/4 Ornaments



After years of R&D these ornaments or "Horseshoes" are finally completed. They are quality made to be better than Buick produced. The fit and finish are beautiful, chrome plated to perfection and ready to install. Clips are included in the kit. During production in late 1963 or early 1964 Buick changed the pin location of these ornaments. It is believed that the forward end of the ornament was lifting possibly from car wash brushes. The forward pin was located nearer to the end for better support. Our answer was to make pins in both locations. You merely twist the 2 pins not needed with pliers, then dress with a file or dremel tool to level the remaining stud.

**1963-1964 All.** Set of all 4 pieces for entire car.  
RO634.....\$247.00 set


## Panel Ornament Clips



**1963-1964** Rear 1/4 panel ornament clips for retaining chrome "Horseshoe" ornaments.  
MC2 .....\$2.25 ea.  
MC2S.....(Set of 36).....\$51.00 ea.



## Convertible Tops please inquire!



## Convertible Top Pumps

**1982-1985** Convertible top motor pump.  
TP645 .....\$175.00 ea.

## Plastic Side Moulding Clip

**1963-1972** For 3/8" wide retention. Fits all **1963-1965** Fenders, doors and quarter panel side mouldings.



MC600 .....\$1.00 ea.

**1963-1965 All.** Front fender and rear 1/4 panel moldings. Wire molding clip. Possibly fits other models.

MC5 .....\$0.50 ea.

## Side Molding Clip Kit



**1963-1965** Contains all necessary and correct plastic clips, wire clips, nuts, etc. To attach all side molding to both sides of car. **36 pieces included.**

CK635R.....\$27.75 kit

## Roof Panel Emblems

**1982-1985 All.** Fits either side.  
RE825R.....\$40.75 ea.



## Sunroof Weatherstripping

**1978 thru 1985** all with electric sliding sunroof.  
SW787 .....\$149.50 ea.

## Vinyl Roofs - Landau Tops

We can supply vinyl roofs and Landau tops for any Riviera from 1963 thru 1993. Please state year and color. See our website for colors.


VR633R.....Black or White .....\$199.00 ea.  
VR633RC.....Colors .....\$229.00 ea.



**1963-1975** Trunk weatherstrip.  
TW54217 .....\$28.25 ea.




**1976-1983** Trunk Weatherstrip. Pinchweld type  
TW761 .....\$33.00 ea.



**1963-1976** Trunk bumper. Rubber "cap" type.  
TB415 .....\$1.75 ea.



**1963-1976** Trunk bumper.  
Rubber "plug in" type.  
TB495 .....\$2.75 ea.



**1966-1968** Trunk latch bumper.  
TB598 .....\$3.75 ea.



**1963-1981** Spare tire hold down bolt.  
5/16" - 18 x 9 1/2"  
STB611 .....\$11.75 ea.



**1963-1973** Spare tire hold down wing nut.  
TN615 .....\$18.00 ea.



**1982-1985** All. Tire/jack retaining nut.  
TN820 .....\$12.75 ea.



**1963-1980** As required. Trunk lock gasket.  
KLG540 .....\$1.25 ea.



**1963-1965** Riviera. Trunk lock gasket.  
TLG65 .....\$4.75 ea.



**1963-1968** Trunk floor pan plug. 3/4" hole.  
BP598 .....\$2.25 ea.



**1963-1975** As required. Body plug. 1 1/2" hole.  
BP355 .....\$3.25 ea.

### Trunk Release Button



**1979-1985** All as required.  
TRB829 .....\$21.50 ea.

### Trunk Lock and Keys



**1963-1964** All with lock on body. Not for locks in emblems.  
TL609B .....\$19.75 set



**1966-1968** 1966, 1967, 1968. All with lock on lid.  
TL609 .....\$16.50 set



**1971-1972** Glove box lock and trunk lock sets with 2 matching original keys.  
LS712 .....\$59.75 set

### Trunk Emblems



**1965**  
"Riviera" deck lid monogram. 6 flat spade studs.  
DM65R .....\$36.00 ea.



**1965-1967; 1970** "Riviera" deck lid monogram. 4 Round studs.  
DM657R .....\$33.50 ea.



**1965** "Gran Sport" trunk script. 2nd type. 5 3/4" long.  
Located on rear panel.  
DM65GS2 .....\$39.50 ea.



**1966-1967** "By Buick" trunk emblem.  
DM667R .....\$33.50 ea.



**1971-1972** "Riviera by Buick" deck lid monogram.  
DM712R .....\$35.50 ea.



**1971-1972** Trunk lock bezel.  
DB72R .....\$39.50 ea.



**1973** "Riviera Buick" deck lid monogram.  
DM73R .....\$35.00 ea.

### Trunk Supports



(gas charged)  
**1979 thru 1983** All. Fits either side.  
TS793R .....\$22.25 ea.

### Hog Rings



For attaching seat covers to frame  
HR360 ..... Bag of 100 .....\$8.75 ea.

### Hog Ring Pliers



For attaching hog rings to seat covers.  
HRP360 .....\$30.25 ea.