


Electrical (Group 2)

Starters and Rebuilding Service



1961-1963 All 215 V-8. Sold outright.
S613.....\$149.50 ea.

Rebuilding Service

1961-1963 All Rebuilding Service.
S613RS.....\$129.50 ea.

1964-1967 225, 300, 340 engines. Rebuilding Service.
S647RS.....\$189.50 ea.

1965-1966 GS 400 engines. Rebuilding Service.
S646RS.....\$189.50 ea.

1967-1972 400 and 455 engines. Exchange or rebuilding service.
S674.....\$129.50 ea.

1968-1972 350 engines.
S684.....\$119.50 ea.

Starter ID Tag



1961-1967 Delco, starter, generator and distributor ID tag. (Red).
ET12\$7.00 ea.




Ignition Coils

1961-1972
IC539.....\$26.50 ea.

1961-1972
IC539D.....(Genuine Delco).....\$58.00 ea.



1961-1972 Resistor.
CR533\$11.50 ea.



Universal Coil Bracket

CB350\$6.50 ea.
CB350C.....(Chrome).....\$11.50 ea.

Starter Solenoids



1961-1972 All.
SS575\$53.00 ea.

Starter Solenoid Repair Kit



1961-1972 All.
SRK570.....\$24.50 ea.

Starter Brush Sets

1961-1972 Brush set.
SBS539\$6.50 set



Starter Drives

1961-1972 All.
SD615\$24.50 ea.


Wire and Cable Retainers



1964-1972 Engine compartment wiring strap.
WS5.....7" long.....\$1.50 ea.
WS6 2 3/4" Black.....\$0.75 ea.
WS7 4" Black.....\$0.75 ea.
WS8 4 1/2" Black.....\$0.75 ea.
WS9 8 3/4" Black.....\$0.75 ea.




1961-1966 Side frame rail wire retainers.
WR616\$5.00 ea.







1967-1972 All. Retains positive battery cable to side frame rail.
WR672.....\$3.25 ea.

Battery Hold Down Clamps



As original, 1961 thru 1967 clamps are rubber coated steel.

-  **1961-1963 All. (Clamp only).**
BC613.....\$28.50 ea.
-  **1964-1965 All. Except GS.**
BC645..... \$27.50 ea.
-  **1965 GS.**
BC65GS.....\$27.50 ea.
-  **1966-1967 All.**
BC657.....\$26.50 ea.

Battery Hold Down Bolts



1961-1962 All inside. Cut to length if necessary. Includes washer and nut.

BB612.....\$5.75 ea.



1961-1967

1961-1962 All outside;

1963-1967 All. Includes washer and nut.

BB610.....\$6.75 ea.

Battery Trays



1968-1972 All. Tray only.

BT682\$29.50 ea.



Clamp only.

BC682.....\$3.00 ea.



Bolt only.

BB682\$2.25 ea.

NOTICE


CAR SHOW ATTENDEES

CARS, Inc. will NOT bring the usual "yellow trailer" to the shows.

We will be happy to bring any parts you need.

Please call in advance of the show to place your order.

Look For Us!



If your thinking of attending any of the shows listed below, be sure to stop by and say "Hello". We will be glad to discuss some of our newest items or simply talk about your

Plan ahead by calling in your order weeks ahead of time. We will be able to bring your entire order and save you shipping too.

GS Nationals
Buick Nationals
*Hershey GDB 31>34
near Lamp Post 93

Electrical (Group 2)

Battery Cables

Our **battery cables** listed below for **TOP POST** batteries are made with heavy duty two (2) gauge copper wire, covered with black insulation.



Our reproduction "**Spring Ring**" cables are made from GM blueprints to be identical to the originals in fit and functions. They are sold in pairs. "Spring Ring" cables are also sold individually. **Inquire!**

Years

Replacement Cables

Genuine "Spring Ring" Sets



	(+) Positive	Price	(-) Negative	Price
1961-1962 All.....	BC24	\$19.50 ea.....	BC17	\$16.50 ea.
1963 All V-6	BC24	\$19.50 ea.....	BC19	\$17.50 ea.
1963 All V-8	BC31	\$25.25 ea.....	BC17	\$16.50 ea.
1964-65 300 engines.....	BC38	\$27.25 ea.....	BC31	\$25.25 ea.
1965-66 400 eng. GS.....	BC31	\$25.25 ea.....	BC24	\$19.50 ea.
1966-67 300, 340.....	BC38	\$27.25 ea.....	BC31	\$25.25 ea.
1967-68 350, 400.....	BC48	\$34.50 ea.....	BC31	\$25.25 ea.
1969 350	BC42	\$30.25 ea.....	BC24	\$19.50 ea.
1969 400	BC48	\$34.50 ea.....	BC31	\$25.25 ea.
1970-72 350.....	BC42	\$30.25 ea.....	BC31	\$25.25 ea.
1970-72 455.....	BC48	\$34.50 ea.....	BC31	\$25.25 ea.




BC248.....	\$91.00 pr.
BC258.....	\$91.00 pr.
BC255.....	\$91.00 pr.
BC264.....	\$91.00 pr.
BC285.....	\$91.00 pr.
BC287.....	\$91.00 pr.
BC294.....	\$91.00 pr.
BC300.....	\$91.00 pr.

Side Terminal Cables - Delco Replacements

1972 350 engines.....	BC35S	\$19.75 ea.	BC30S	\$19.25 ea.
1972 455 engines.....	BC45S	\$20.25 ea.	BC30S	\$19.75 ea.




1961-1972 Battery cable cover.
CC315\$6.25 ea.



1961-1972 All. Battery cable cover.
Located on switch side and junction
block.
(Two per car).
CC325.....\$6.25 ea.

Battery Terminal Protectors



Stops corrosion indefinitely. Two protectors in each kit.
BW300.....\$3.75 kit

Wire Loom

Asphalt coated fabric. Wire loom for battery cables, headlamps, wire etc.



WL180	1/8" ID	\$1.55 ft.
WL316	3/16" ID	\$1.55 ft.
WL140	1/4" ID	\$1.80 ft.
WL516	5/16" ID	\$1.80 ft.
WL380	3/8" ID	\$1.80 ft.
WL716	7/16" ID	\$1.80 ft.
WL120	1/2" ID	\$1.80 ft.
WL916	9/16" ID	\$2.15 ft.
WL580	5/8" ID	\$2.15 ft.
WL340	3/4" ID	\$2.15 ft.


Nylon Wire Loom

NWL140	1/4" ID	\$1.50 ft.
NWL380	3/8" ID	\$1.50 ft.
NWL120	1/2" ID	\$1.50 ft.
NWL340	3/4" ID	\$1.75 ft.

Wiring Harness Tape

Non-adhesive vinyl Harness wrap is same as used by GM.
1" wide, 100 foot roll.

WT100	1" wide.....	\$11.25 roll
-------------	--------------	--------------



Ignition Switches

(See NOS section-Group 2.188 for models not listed)

Years	Cars #	Price
1964 All.....	IS64S.....	\$27.25 ea.
1965 All.....	IS65S.....	TOS
1966-1967 All.....	IS667.....	\$39.50 ea.
1969-1972(All tilt wheel)	IS699T.....	\$29.50 ea.
1969-1972 (All without tilt).....	IS699.....	\$29.50 ea.



Ignition Lock Cylinder with Keys

Years	Cars #	Price
1961,1962 All	IL614.....	\$19.50 kit
1963 All	IL63S	\$19.50 kit
1964 All	IL614.....	\$19.50 kit
1965 All	IL65.....	\$19.50 kit
1966-1967 All	IL667.....	\$19.50 kit
1968 All	IL68.....	\$19.50 kit
1969 and 1972 All	IL695.....	\$19.50 kit



Key Blanks (Genuine GM)

We can also make keys from your code. Please inquire.

- 1961-1966 Door and Ignition - Octagon.
KB10.....\$3.50 ea.
- 1961-1966 Glove and Trunk - Rounded.
KB11.....\$3.50 ea.
- 1967 and 1971 Door and Ignition - Rectangular.
KB48.....\$3.50 ea.
- 1967 and 1971 Glove and Trunk - Oval.
KB49.....\$3.50 ea.
- 1968 and 1972 Door and Ignition - Rectangular.
KB50.....\$3.50 ea.
- 1968 and 1972 Glove and Trunk - Oval.
KB51.....\$3.50 ea.
- 1969 and 1973 Door and Ignition - Rectangular.
KB44.....\$3.50 ea.
- 1969 and 1973 Glove and Trunk - Oval.
KB45.....\$3.50 ea.
- 1970 Door and Ignition - Rectangular.
KB46.....\$3.50 ea.
- 1970 Glove and Trunk - Oval.
KB47.....\$3.50 ea.

- 1974 Ignition - Rectangular.
KB46.....\$3.50 ea.
- 1974 Glove, Door and Trunk - Oval.
KB47.....\$3.50 ea.
- 1975-1979 and 1983-1985 Ignition - Rectangular.
KB48.....\$3.50 ea.
- 1975-1979 and 1983-1985
Glove, Door and Trunk - Oval.
KB49.....\$3.50 ea.
- 1976 and 1980 Ignition - Rectangular.
KB50.....\$3.50 ea.
- 1976 and 1980 Glove, Door and Trunk - Oval.
KB51.....\$3.50 ea.



Key Caps



- 1967-1985 All Rectangular Keys.
KC670R.....\$1.50 ea.
- 1967-1985 All Oval Keys.
KC670O.....\$1.50 ea.

Electrical (Group 2)



Tune-ups Kits

Tune-up Parts

Quality Replacement parts for all **1961-1972** Models.

Complete Tune-up kit includes: Points, Plugs, Wires, Cap, Rotor and Condenser.



1961-1963 * V-8

CARS#	YEARS	APPLICATION	PRICE
D106	1961-1963	Point Set	\$16.50 ea.
D203	1961-1963	Condenser	\$6.00 ea.
D308	1961-1963	Distributor Cap	\$13.50 ea.
D409	1961-1963	Rotor	\$7.50 ea.

1966-1967 * V-6

CARS#	YEARS	APPLICATION	PRICE
D106	1966-1967	Point Set	\$16.50 ea.
D204	1966-1967	Condenser	\$6.00 ea.
DC67	1966-1967	Distributor Cap	\$10.75 ea.
D413	1966-1967	Rotor	\$6.50 ea.

*1966 cars with adjusting window in front of distributor

Complete Tune-up Kit

TK613\$89.50 ea.

Complete Tune-up Kit

TK67\$87.50 ea.

1962-1966 * V-6

CARS#	YEARS	APPLICATION	PRICE
D106	1962-1966	Point Set	\$16.50 ea.
D203	1962-1966	Condenser	\$6.00 ea.
DC626	1962-1966	Distributor Cap	\$9.75 ea.
D413	1962-1966	Rotor	\$6.50 ea.

* 1966 cars with adjusting window on side of distributor

1964-1972 V-8

CARS#	YEARS	APPLICATION	PRICE
D106	1964-1972	Point Set	\$16.50 ea.
D203	1964-1965	Condenser	\$6.00 ea.
	1965	With side adjusting window condenser....	\$6.00 ea.
D204	1966	With window front:	
	1967-1972	All. Condenser.....	\$6.00 ea.
D308	1964-1972	Distributor Cap	\$13.50 ea.
D409	1964-1972	Rotor	\$7.50 ea.

Complete Tune-up Kit

TK626\$89.50 ea.

1964-65 SP, SK, GS, All V-8 models with side adjusting window in cap.

TK645\$59.00 ea.

1964-66 SP, SK, GS, All V-8 models.

TK66\$59.00 ea.

1967-72 SP, SK, GS, All V-8 models.

TK672\$57.00 ea.

Complete Tune-up Kit

TK642\$83.50 ea.

Spark Plugs

1961-1963 215 V-8 with 2BBL carb.
SP45FFS.....\$2.95 ea.

1961-1964

1961-1963: 215 V-8 with 4BBL carb.;
1964: All 300.

SPR43FS.....\$2.95 ea.

1962-1967 All V-6.

SPR43S.....\$2.95 ea.



1965-1967 300 and 340 engines with 2BBL carb.

SP45R.....\$2.95 ea.

1965-1967

1965-1966: 300, 340 and 400 with 4BBL carb.;

1967: 340 engines with 4BBL carb.

SPR43S\$2.95 ea.

1967-1971

1967-1969: 400 engines;

1970-1971: 350 4BBL GS;

1970-1971: All 455 engines.

SP44TS\$2.95 ea.

1968-1972

1968-1971: All 350 engines exc. GS;

1972: All.

SP45TS\$2.95 ea.

Spark Plug Rubber Boots



Correct for all 1961-1967 Models.

SP577\$3.00 ea.



Spark Plug Wire Sets

CARS#	YEARS	APPLICATION	PRICE
IW576	1961-1966	All V-8	\$29.50 ea.
IW629D	1962-1967	All 6 Cyl ...(Delco) ..	\$36.75 ea.
IW674	1967-1972	All V-8.....	\$23.75 set
IW672D	1967-1972	All V-8.....(Delco)...	\$42.50 ea.



1961-1966: All;

1966: 300, 340, 400 engine ign. wire
retainer on rocker covers. Two per car.
WR596.....\$4.25 ea.




1967-1972 All. Front "4", ign. wire
retainer. Two per car.
WR683.....\$4.00 ea.



1967-1972 All. Rear "3" ign. wire
retainer.
WR673.....\$4.00 ea.

Distributor Adjusting Tool



1961-1972 All. If you have ever tried to adjust your points
without this tool you know how **NECESSARY** it is.
DT575.....\$10.00 ea.

"Delco Remy" Distributor Cap



1961-1972 All V-8. Identical
reproduction.
D308R....("Delco Remy").....\$51.75 ea.



www.oldbuickparts.com

908-369-3666

Electrical (Group 2)

Engine Harnesses

WH4505.....	(1964 All V-6).....	\$179.50
WH4510.....	(1964 All V-8).....	\$179.50
WH5940.....	(1965 All 300 V-8).....	\$179.50
WH6100.....	(1965 All GS 400 V-8).....	\$179.50
WH6180.....	(1965 All V-6).....	\$179.50
WH9470.....	(1966 All V-6).....	\$170.00
WH9475.....	(1966 All 300,340 V-8).....	\$165.00
WH9480.....	(1966 All GS 400 V-8).....	\$164.00
WH10695.....	(1967 All V-6).....	\$170.00
WH19130.....	(1967 All 300,340 V-8).....	\$158.00
WH11325.....	(1967 All GS 400 V-8).....	\$149.50
WH12140.....	(1968 All 350 V-8).....	\$189.00
WH12145.....	(1968 All GS 400 V-8).....	\$189.00
WH13470.....	(1969 All 350 V-8 w/ ac).....	\$189.00
WH12740.....	(1969 All 350 V-8 w/o ac).....	\$189.00
WH13475.....	(1969 All GS 400 V-8 w/ ac).....	\$189.00
WH12745.....	(1969 All GS 400 V-8 w/o ac).....	\$189.00
WH15830.....	(1970 All 350 V-8 man. trans w/ ac).....	\$189.00
WH36250.....	(1970 All 350 V-8 man. trans w/o ac).....	\$189.00
WH13730.....	(1970 All 350 V-8 auto trans w/ ac).....	\$189.00
WH34970.....	(1970 All 350 V-8 auto trans w/o ac).....	\$189.00
WH13735.....	(1970 All 455 V-8 man. trans w/ ac).....	\$189.00
WH36256.....	(1970 All 455 V-8 man. trans w/o ac).....	\$189.00
WH13745.....	(1970 All 455 V-8 auto. trans w/ ac).....	\$189.00
WH13740.....	(1970 All 455 V-8 auto. trans w/o ac).....	\$189.00
WH33015.....	(1971 All 350 V-8 w/ ac).....	\$189.00
WH33010.....	(1971 All 350 V-8 w/o ac).....	\$189.00
WH33005.....	(1971 All 455 V-8 w/ ac).....	\$189.00
WH19135.....	(1971 All 455 V-8 w/o ac).....	\$189.00
WH32105.....	(1972 All 350 V-8 w/ ac).....	\$189.00
WH32100.....	(1972 All 350 V-8 w/o ac).....	\$189.00
WH32115.....	(1972 All 455 V-8 w/ ac).....	\$189.00
WH32110.....	(1972 All 455 V-8 w/o ac).....	\$189.00

Idle Stop Solenoid Harnesses

WH38695.....	(1971 All with auto trans.).....	\$20.35
WH31825.....	(1972 All V-8.).....	\$25.03

Front Lamp Harnesses

WH5760.....	(1964 All with manual trans).....	\$202.65
WH4515.....	(1964 All with auto trans).....	\$197.40
WH5950.....	(1965 All with manual trans exc. GS).....	\$190.05
WH6095.....	(1965 GS with manual trans).....	\$190.05
WH5945.....	(1965 All with auto trans).....	\$197.40
WH9960.....	(1966 All with tach.).....	\$202.65
WH35770.....	(1966 All without tach.).....	\$197.40
WH18488.....	(1966 GS.).....	\$197.40
WH11210.....	(1967 All.).....	\$190.05
WH12150.....	(1968 All.).....	\$197.40
WH12750.....	(1969 All.).....	\$179.50
WH13755.....	(1970 All.).....	\$190.05
WH15905.....	(1971-1972 All.).....	\$190.05

Dash Harnesses

1964-1967 owners - You must supply your old fuse box.

WH4500.....	(1964 All).....	\$477.00
WH6090.....	(1965 console shift, man. trans).....	\$489.00
WH6165.....	(1965 col. shift auto trans or man floor shift).....	\$476.00
*WH6225.....	(1965 console shift, auto. trans).....	\$476.00
WH10225.....	(1966 col. shift auto trans or man floor shift).....	\$489.50
WH10270.....	(1966 console shift, auto. trans).....	\$476.50
WH10275.....	(1966 console shift, man. trans).....	\$476.50
WH11140.....	(1967 col. shift auto trans or man floor shift).....	\$476.00
WH11145.....	(1967 console shift, auto. trans).....	\$489.50
WH11150.....	(1967 console shift, man. trans).....	\$476.00
WH12130.....	(1968 column shift).....	\$512.00
WH12135.....	(1968 console shift).....	\$512.00
WH12725.....	(1969 column shift).....	\$512.00
WH12730.....	(1969 console shift).....	\$512.00
WH13715.....	(1970 column shift with warning lights).....	\$512.00
WH15740.....	(1970 console shift with warning lights).....	\$512.00
WH19170.....	(1970 column shift with gauges).....	\$512.00
WH19175.....	(1970 console shift with gauges).....	\$512.00
WH15945.....	(1971 with gauges).....	\$512.00
WH19180.....	(1971 with warning lights).....	\$512.00
WH15945.....	(1972 with gauges, w/o seat belt warning).....	\$512.00
WH18290.....	(1972 with warning lights & seat belt warning).....	\$488.51
WH19180.....	(1972 with warning lights w/o seat belt warning).....	\$533.14

* requires your old fuse block.

Air Conditioning Harnesses

WH35958.....	(1964-1965 All).....	\$132.00
WH35871.....	(1966-1967 All).....	\$126.50
WH35942.....	(1968 All).....	\$126.50
WH35872.....	(1968 ac jumper wire to blower motor).....	\$12.38
WH32310.....	(1969-1972 All).....	\$127.50

**Fax Us
Your Order**

Save Time!

**When sending us a long order
it is easier to just fax it.**

908-369-7595

Power Window Harnesses

WH6665.....	(1963 Skylark 2-dr. r.h. rear 1/4).....	\$79.80
WH6670.....	(1963 Skylark 2-dr. l.h. rear 1/4).....	\$79.80
WH6685.....	(1963 Skylark convt. r.h. rear 1/4).....	\$77.00
WH6690.....	(1963 Skylark convt. l.h. rear 1/4).....	\$77.00
WH6955.....	(1964 All. r.h. door).....	\$83.74
WH6960.....	(1964 All. l.h. door).....	\$161.80
WH6965.....	(1964 crossover from l.h. to r.h. front windows).....	\$58.80
WH6990.....	(1964 All 2-dr. ht rear 1/4. fits either side).....	\$58.80
WH6995.....	(1964 All convt rear 1/4. fits either side).....	\$59.33
WH7170.....	(1964 2-dr. rear 1/4 exten. to motor. fits either side).....	\$19.80
WH7005.....	(1964 convt. rear 1/4 exten. to motor. fits either side).....	\$19.80
WH36048.....	(1964-1972 All. single switch pigtail).....	\$22.50
WH7605.....	(1965 All. r.h. door).....	\$82.95
WH7610.....	(1965 All. l.h. door).....	\$162.75
WH7640.....	(1965-1966 All. 2-dr. ht rear 1/4. fits either side).....	\$58.80
WH7655.....	(1965-67 2-dr. rear 1/4 exten. to motor. either side).....	\$20.35
WH7660.....	(1965-67 convt. rear 1/4 exten. to motor. either side).....	\$19.80
WH7695.....	(1965-1967 All. convt rear 1/4. fits either side).....	\$59.33
WH8200.....	(1965-66 crossover from l.h. to r.h. front windows).....	\$63.00
WH8260.....	(1966-1967 All. l.h. door).....	\$161.18
WH27310.....	(1966-1967 All. r.h. door).....	\$83.74
WH31135.....	(1968 All. l.h. door).....	\$161.18
WH14165.....	(1968 All. r.h. door).....	\$84.79
WH14405.....	(1968-1969 All. rear 1/4 & intermediate body).....	\$118.65
WH39470.....	(1969 All. 2-dr. l.h. door).....	\$193.20
WH37817.....	(1969 All. 2-dr. l.h. door).....	\$103.95
WH31140.....	(1970-1971 All. 2-dr. l.h. door).....	\$195.30
WH14470.....	(1970-1972 All. 2-dr. r.h. door).....	\$102.90
WH14505.....	(1970-1972 All. 2-dr. rear 1/4. windows).....	\$118.65
WH39471.....	(1972 All. 2-dr. l.h. door).....	\$193.30

Tachometer Harnesses

WH28985.....	(1968-1972 All. extension from coil to dash).....	\$25.03
WH28990.....	(1968-1969 All. extension to tachometer).....	\$42.90
WH702T.....	(1970-1972 All. Hood mounted tachometer).....	\$42.50

Dome Lamp Harnesses

WH6885.....	(1964 All. 2-dr. sedans).....	\$19.25
WH6880.....	(1964 All. 4-dr. sedans).....	\$19.25
WH7580.....	(1965 All. 2-dr. ht models).....	\$19.25
WH7575.....	(1965 All. sedan models).....	\$19.25

Courtesy Lamp Harnesses

WH6890.....	(1964 All. Skylark).....	\$34.00
WH7710.....	(1965-1967 All.).....	\$34.00

Power Seat Harnesses

WH6945.....	(1964 All 4-way bench.).....	\$126.00
WH7600.....	(1965 All 4-way bucket, l.h.).....	\$126.00
WH7595.....	(1965-1967 All 4-way power).....	\$126.00

Rear Body/Tail Lamp Harnesses

WH19070.....	(1964 All except convertibles).....	\$135.45
WH19080.....	(1964 Skylark convertible).....	\$168.00
WH19075.....	(1964 Special convertible).....	\$168.00
WH7730.....	(1965 Special 2-dr. ht).....	\$139.65
WH7930.....	(1965 Skylark 2-dr. ht).....	\$134.40
WH7720.....	(1965 Special convertible).....	\$170.36
WH7725.....	(1965 Skylark convertible).....	\$168.00
WH19085.....	(1966 All hardtops).....	\$135.45
WH19090.....	(1966 Special convertible).....	\$172.20
WH19095.....	(1966 Skylark convertible).....	\$168.00
WH13910.....	(1967 All hardtops).....	\$135.45
WH13915.....	(1967 Special convertible).....	\$172.20
WH13920.....	(1967 Skylark convertible).....	\$168.00
WH19100.....	(1968 All).....	\$135.45
WH19105.....	(1968 All 2-dr. ht. Intermediate).....	\$139.65
WH19110.....	(1968 All convertible. Intermediate).....	\$199.50
WH19115.....	(1969 All).....	\$134.40
WH19120.....	(1969 All ht. models. Intermediate).....	\$135.45
WH19125.....	(1969 All convertible. Intermediate).....	\$199.50
WH18470.....	(1970-1971 All).....	\$134.40
WH18860.....	(1970-1972 All ht. models. Intermediate).....	\$134.40
WH18865.....	(1970-1972 All convertible. Intermediate).....	\$165.90
WH32300.....	(1972 All).....	\$134.40

Wiring Harness Tape



Non-adhesive vinyl Harness wrap is same as used by GM. 1" wide, 100 foot roll.
 WT1001" wide.....\$11.25 roll

DATE CODED SPARK PLUG WIRE SETS

For those requiring the best for their show ready car, these reproduction wire sets are unsurpassed. They are manufactured to original GM blueprint specifications. They include the proper boots, terminals, script and correct factory length. All wires are carbon core for radio suppression. They come correctly identified with "**Packard Radio TVRS**" or "**Radio GM**" along with the proper date code to match your car.

Date codes will read as such: 3 Q 67. The first number, "3" corresponds to the third quarter of the year. "Q" means quarter. The last number, "67", is the year, 1967. Thus, a cable marked 3 Q 67 was produced in the third quarter of 1967. You should order your spark plug wire sets with dates that are 6 to 12 months prior to the manufacturing date of your car. *Note:* wires were not dated on vehicles prior to January 1961.



1964-1966 Special, Skylark and GS.
300, 340 and 400 C.I. V-8 All.

1967-1971 300, 340 and 350 C.I. V-8 All.

1972 350 and 455 C.I. V-8 All.

Year	Application	Date	Part Number	Price
1961	V-8 All 2 Barrel		W3324000.....	\$79.50 ea.
1961	V-8 All 2 Barrel	1-Q-61	W3324611.....	\$79.50 ea.
1961	V-8 All 4 Barrel		W3326000.....	\$79.50 ea.
1961	V-8 All 4 Barrel	1-Q-61	W3326611.....	\$79.50 ea.
1962	V-8 All 2 Barrel	3-Q-61	W3324613.....	\$79.50 ea
1962	V-8 All 2 Barrel	1-Q-62	W3324621.....	\$79.50 ea
1962	V-8 All 4 Barrel	3-Q-61	W3326613.....	\$79.50 ea
1962	V-8 All 4 Barrel	1-Q-62	W3326621.....	\$79.50 ea
1963	V-8 All 2 Barrel	3-Q-62	W3324623.....	\$79.50 ea
1963	V-8 All 2 Barrel	1-Q-63	W3324631.....	\$79.50 ea
1963	V-8 All 4 Barrel	3-Q-62	W3326623.....	\$79.50 ea
1963	V-8 All 4 Barrel	1-Q-63	W3326631.....	\$79.50 ea
1964	V-8 All 300 C.I.	3-Q-63	W3334633.....	\$79.50 ea
1964	V-8 All 300 C.I.	1-Q-64	W3334641.....	\$79.50 ea
1965	V-8 All 300 and 340 C.I.	3-Q-64	W3334643.....	\$79.50 ea
1965	V-8 All 300 and 340 C.I.	1-Q-65	W3334651.....	\$79.50 ea
1966	V-8 All 300 and 340 C.I.	3-Q-65	W3334653.....	\$79.50 ea
1966	V-8 All 300 and 340 C.I.	1-Q-66	W3334661.....	\$79.50 ea
1966	V-8 All 300, 340 and 400 C.I.	3-Q-65	W3332653.....	\$79.50 ea
1966	V-8 All 300, 340 and 400 C.I.	1-Q-66	W3332661.....	\$79.50 ea
1967	V-8 All 300, 340 C.I.	3-Q-66	W3338663.....	\$79.50 ea
1967	V-8 All 300, 340 C.I.	1-Q-67	W3338671.....	\$79.50 ea
1967	V-8 All 400, 430 and 455 C.I.	3-Q-66	W3342663.....	\$79.50 ea
1967	V-8 All 400, 430 and 455 C.I.	1-Q-67	W3342671.....	\$79.50 ea

Year	Application	Date	Part Number	Price
1968	V-8 All 350 C.I.	3-Q-67	W3338673.....	\$79.50 ea
1968	V-8 All 350 C.I.	1-Q-68	W3338681.....	\$79.50 ea
1968	V-8 All 400 C.I.	3-Q-67	W3342673.....	\$79.50 ea
1968	V-8 All 400 C.I.	1-Q-68	W3342681.....	\$79.50 ea
1969	V-8 All 350 C.I.	3-Q-68	W3338683.....	\$79.50 ea
1969	V-8 All 350 C.I.	1-Q-69	W3338691.....	\$79.50 ea
1969	V-8 All 400 C.I.	3-Q-68	W3342683.....	\$79.50 ea
1969	V-8 All 400 C.I.	1-Q-69	W3342691.....	\$79.50 ea
1970	V-8 All 350 C.I.	3-Q-69	W3338693.....	\$79.50 ea
1970	V-8 All 350 C.I.	1-Q-70	W3338701.....	\$82.50 ea
1970	V-8 All 455 C.I.	3-Q-69	W3342693.....	\$79.50 ea
1970	V-8 All 455 C.I.	1-Q-70	W3342701.....	\$79.50 ea
1971	V-8 All 350 C.I.	3-Q-70	W3338703.....	\$79.50 ea
1971	V-8 All 350 C.I.	1-Q-71	W3338711.....	\$79.50 ea
1971	V-8 All 455 C.I.	3-Q-70	W3342703.....	\$79.50 ea
1971	V-8 All 455 C.I.	1-Q-71	W3342711.....	\$79.50 ea
1972	V-8 All 350 C.I.	3-Q-71	W3340713.....	\$79.50 ea
1972	V-8 All 350 C.I.	1-Q-72	W3340721.....	\$79.50 ea
1972	V-8 All 455 C.I. Exc HEI	3-Q-71	W3344713.....	\$79.50 ea
1972	V-8 All 455 C.I. Exc HEI	1-Q-72	W3344721.....	\$79.50 ea
6 Cylinder (V-6)				
1962	V-6 All	3-Q-61	W3210613.....	\$79.50 ea.
1962	V-6 All	1-Q-62	W3210621.....	\$79.50 ea.
1963	V-6 All	3-Q-62	W3210623.....	\$79.50 ea.
1963	V-6 All	1-Q-63	W3210631.....	\$79.50 ea.
1964	V-6 All	3-Q-63	W4012633.....	\$79.50 ea.
1964	V-6 All	1-Q-64	W4012641.....	\$79.50 ea.
1965	V-6 All	3-Q-64	W4012643.....	\$79.50 ea.
1965	V-6 All	1-Q-65	W4012651.....	\$79.50 ea.
1966	V-6 All	3-Q-65	W4012653.....	\$79.50 ea.
1966	V-6 All	1-Q-66	W4012661.....	\$79.50 ea.
1967	V-6 All	3-Q-66	W4012663.....	\$79.50 ea.
1967	V-6 All	1-Q-67	W4012671.....	\$79.50 ea.

Stoplight Switch



1961-1963 All.
SLS563.....\$9.00 ea.



1964-1972
1964-1972: All;
1971-1972: All except cruise control.
SLS645.....\$9.50 ea.



1971-1972 All with cruise control.
SLS715.....\$9.50 ea.



www.oldbuickparts.com

908-369-3666

Electrical (Group 2)

Generators (Rebuilding Service)

- 1961-1962 All.**
G612.....\$189.50 ea.
1961-1962 Generator brush set.
ABS621.....\$12.75 set.
1961-1962 Generator front bearing.
GEB412.....\$8.75 ea.




Alternators

- 1963-1971 All 61 AMP.**
A631.....\$69.50 ea.

Alternator Fan (2.274)

Genuine replacement.
Cadmium plated.



- 1963-1972**
1963-1965: All except 62 AMP;
1967-1972: All.
AF585.....\$16.50 ea.

Alternator Brace/Adjuster (2.317)

- 1969-1970 All 400, 455 engines. (oem # 1387139)**
AB690.....\$79.75 ea.
1971-1972 All 455 engines. (oem #)
AB715B.....\$19.00 ea.

Voltage Regulators



- 1961-1962 All with generator, without air conditioning.**
VR572.....\$59.50 ea.
1961-1962 All with generator, with air conditioning.
VR582A.....\$69.50 ea.
1962-1972 Delco alternator regulator. All except heavy duty 62, 80 AMP jobs.
VR622.....\$19.75 ea.
VR622D.....Genuine Delco.....\$79.50 ea.
VR622E.....Electronic Replacement.....\$23.75 ea.
1965-1972 All with Heavy Duty 62-80 AMP alternators.
VR655.....\$19.75 ea.

Alternator Parts

- 1963-1971 All. Alternator front bearing.**
GEB581.....\$15.75 ea.



- 1972-1973 All. Alternator front bearing.**
GEB723.....\$11.25 ea.

Alternator Contact Rubber Boot



- 1963-1972 All.**
AB632.....\$4.57 ea.

Distributors

(Rebuilding Service)

- 1961-1963 All V-8.**
D613.....\$147.50 ea.
1962-1965 All V-6.
D625.....\$147.50 ea.
1964-1967 300 engine.
D647.....\$167.75 ea.
1965-1966 GS 400.
D596.....\$167.75 ea.
1966-1967 All V-6.
D667.....\$167.75 ea.
1966-1967 340 engines.
D667.....\$167.75 ea.
1967-1972
1967 400 engines;
1968-1972 All.
D674.....\$167.75 ea.

Distributor Vacuum Control




- 1961-1974 All. Oem replacement.**
VC600.....\$16.25 ea.

Genuine Guide T-3 Headlight Bulbs



- 1961-1967 All.**
SB607S\$149.00 set of 4
1968-1971 All.
SB681S\$149.00 set of 4

Headlamp Switches

- 1961-1963 All.**
HS593.....\$49.50 ea. 
- 1964-1967 All.**
HS647.....\$28.50 ea.
HC645.....(connector plug for above).....\$9.75 ea.
- 1968-1972 All.**
HS685\$25.50 ea.
HC645.....(connector plug for above).....\$9.75 ea.



Bulbs








Headlamp Dimmer Switches

- 1961-1972 All exc. Guidematic.**
HDS615.....\$9.00 ea. 

Headlamp Door Screw Set

- Set of 8. Correct chrome plated with small head.
HS702\$5.50 set

Headlamp Nuts and Pads

-  **1964-1966 All.** Headlamp bezel retaining nut.
HBN649\$2.25 ea.
-  **1963-1968** Headlamp body and beam adjusting nut.
HN634.....\$1.25 ea.
-  **1969-1972** Headlamp bezel retaining nut.
HBN692\$2.50 ea.
HBN692S.....(Set of 8).....\$18.50 set
-  **1969-1972** Headlamp adjusting nut and screw.
HN694.....\$3.75 ea.
-  **1970-1972** Headlamp assembly to core support pads. White nylon. 12 per car.
HP705.....\$2.25 ea.
HP705S.....(Set of 12).....\$20.50 set

Year & Model	Head-light	Parking	Direction Front	Signal Rear	Tail	Stop	License Plate	Instru-ment	Indi-cator	Dome	Back-up	Marker Left	Lamp Right
1961	SB1, SB2	B1034	B1034	B1034	B1034	B1034	B67	B194-1816	B194	B211	B1073	---	---
1962	SB1, SB2	B1034	B1034	B1034	B1034	B1034	B67	B194-1816	B194	B90-211	B1073	---	---
1963	SB1, SB2	B1034	B1034	B1034	B1034	B1034	B67	B194	B194	B90-1004	B1073	---	---
1964	SB1, SB2	B1157	B1034	B1157	B1157	B1157	B97	B194	B194	B90-211	B1156	---	---
1965	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194	B194	B90-211	B1156	---	---
1966	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194	B161	B90-211	B1156	---	---
1967	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194	B161	B211	B1156	---	---
1968	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194-1893	B194	B90-1004	B1157	B194A	B194
1969	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194-1893	B194	B90-1004	B1157	B194A	B194
1970	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194-1893	B194	B90-211	B1157	B194A	B194
1971	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194-1893	B194	B90-211	B1157	B194	B194
1972	SB1, SB2	B1157A	B1157A	B1157	B1157	B1157	B97	B194-1893	B194	B90-211	B1157	B194	B194

Prices: SB1 & SB2-\$11.25, 53-\$1.50, 57-\$1.25, 67-\$1.50, 90-\$2.00, B97-\$2.25, 161,168-\$2.25, 181-\$1.75, 194-\$2.25, 194A-\$3.00, 210-\$5.50, 211-\$2.25, 1004-\$2.75, 1034-\$2.75, 1073-\$2.75, 1156-\$2.50, 1157A-\$3.50, 1157-\$2.50, 1816-\$2.25, 1893-\$2.25.


Electrical (Group 2)


1965 Skylark & GS Park Lamp Lenses



PL65GS.....\$135.00 pr.
 PLG65GS.....Gaskets for above.....\$20.00 pr.

1968-1969 Front Parking Lamp Gaskets

PLG689.....\$9.75 pr. 



Side Body Marker Lights

1968-1969 left and right front marker lens.

MLF689.....\$16.50 ea.

Marker Lamp Gaskets

1968-1969 Front or rear.

MLG689.....\$4.00 ea. 

1970-1972 Front and Rear Marker Lamps and Gaskets

Marker Lamps:

ML702F.....Front Amber.....\$99.00 pr.
 ML702R.....Rear Red.....\$99.00 pr.
 ML702S.....Front and Rear.....\$189.00 st.



Gaskets:


(Manufactured to be identical to originals).

MG702S.....Set of 4.....\$29.75 st.
 MG702F.....Front Only.....\$15.50 pr.
 MG702R.....Rear Only.....\$16.50 pr.

Same as above but flat rubber replacements

MLG702F.....Front Markers.....\$6.25 pr.
 MLG702R.....Rear Markers.....\$6.25 pr.

1965 Tail Lamp Gasket Set



1965 All Skylark and GS. Eight piece set, inner and outer.

TLG65S.....\$37.50 st.

1967 Tail Lamp Gaskets



TLG67S(lens to housing).....\$15.00 pr.

TLM67S(lamp to body).....\$12.75 pr.

Front Marker Lamp Retainer



1970-1972

MLR702F.....\$12.00 ea.

1968-1969 Tail Lamp Gaskets



TLG689.....\$9.75 pr.

1970-1972 Tail Lamp Lenses & Gaskets



1970 Tail Lamp Lens (Fits either side)

TL70.....\$89.75 ea.

TLG702.....Gaskets for above.....\$10.00 pr.

1971 Tail Lamp Lenses

TL71L.....(Fits L.H. Side).....\$109.00 ea.

TL71R.....(Fits R.H. Side).....\$109.00 ea.

TLG702.....Gaskets for above.....\$10.00 pr.

1972 Tail Lamp Lenses

TL72L.....(Fits L.H. Side).....\$109.00 ea.

TL72R.....(Fits R.H. Side).....\$109.00 ea.

TLG702.....Gaskets for above.....\$10.00 pr.

1972 Rear Tail Lamp Cushions



An excellent reproduction of the Rubber tail lamp cushions used on 1972 Skylark and GS models. (7.831)

TLC72L.....(Left Side).....\$180.00 ea.

TLC72R.....(Right Side).....\$180.00 ea.

TLC72.....(Both Sides).....\$350.00 ea.

1961 Tail Lamp Lenses



1961 Special 4-Door Sedan Models.

TL61SL.....(Fits L.H. Side).....\$24.50 ea.

TL61SR.....(Fits R.H. Side).....\$24.00 ea.

1963 Back-up Lens

1963 All. Genuine Guide. Fits either side.
BL63S.....\$17.00 ea.



1967 Back-up Lamp Gasket



1967 All except wagons.
BLG67S.....\$4.75 ea.

Back-up Lamp Switches



1962-1963 Special with 4 speed manual transmission.
BLS623\$59.50 ea.

1964-1966 Special, Skylark, GS with 4 speed manual transmission.
BLS636\$59.50 ea.

1967-1968 Special, Skylark, GS. All manual transmission with floor shift.
BLS678\$59.50 ea.

Directional Signal Switches (2.895)



1964-1966 All with tilt wheel.
DSS646T.....\$80.25 ea.



1965-1966 All w/o tilt wheel. Stamped "guide". Includes wiring.
DSS656\$80.25 ea.

1965-1966 All w/o tilt wheel. Stamped "BPC". Includes wiring.
DSS656BPC\$80.25 ea.



1967-1968 All w/o tilt wheel. Delco color code white or green. Includes wiring.
DSS678.....\$46.25 ea.

1969-1972 All w/o cornering lamps. Includes wiring.
DSS696.....\$46.25 ea.

Horn Relays (2.815)

1961-1967 All with junction block.
HR617.....\$79.75 ea.



1965-1968:
1965-1967 All except GS with 62 amp. alternator;
1968 All. "Littlefuse"
HR658L.....\$39.50 ea.

1969-1972 All.
HR693TOS

Signal Flasher

1961-1972 All.
SF615.....\$4.25 ea.



License Lamp Parts

1961-1962 License lamp gasket set.
LG462\$7.00 set



1968-1972 License lamp lens assembly.
LLA682\$19.75 ea.



1964-1972 License lamp gasket . (2.707)
LLG643\$6.75 ea.



1968-1972 License lamp lens.
LL682.....\$10.25 ea.



Wire Loom

Asphalt coated fabric. Wire loom for battery cables, headl-amps, wire etc.



WL180	1/8" ID	\$1.85 ft.
WL316	3/16" ID.	\$1.85 ft.
WL140	1/4" ID	\$2.10 ft.
WL516	5/16" ID	\$2.10 ft.
WL380	3/8" ID.	\$2.10 ft.
WL716	7/16" ID	\$2.10 ft.
WL120	1/2" ID.	\$2.10 ft.
WL916	9/16" ID	\$2.40 ft.
WL580	5/8" ID	\$2.40 ft.
WL340	3/4" ID.	\$2.40 ft.

Lamp Sockets • Pigtails (Group 2)

Headlamp Sockets



For 3 prong beam numbers SB6, 6006, SB12, 6012, SB2, 4000 and 4002.
PT6\$4.75 ea.



For 2 prong beam numbers SB1, 4001.
PT7\$4.25 ea.

Lamp Sockets and Pigtails



Single contact with lead. Fits bulb numbers 51, 53, 55 and 57.
PT1\$2.25 ea.



Single contact with lead. Fits bulb numbers 63, 67, 81, 87, 89, 1073, 1129, 1133, 1141 and 1156.
PT2\$2.25 ea.




Double contact with lead. For ears reversed. Bulbs numbers 82, 88, 90, 210, 1004, 1034, 1154 and 1157.
PT3\$2.75 ea.




Double contact with lead. For ears aligned bulbs.
PT4\$2.50 ea.


Parking and Tail Lamp Sockets



Single contact with lead. For 3/4" to 1 1/8" hole.
LS1\$4.25 ea.



Double contact with lead. For bulb numbers 1034 and 1154. Fits 1 1/8" hole.
LS5\$5.75 ea.



Double contact with leads. Fits 3/4" hole. For bulb numbers 1034, 1154 and 1157.
LS9\$5.75 ea.



Double contact with leads. Fits 3/4" to 1 1/8" hole. For bulb numbers 1034, 1154 and 1157.
LS2\$5.75 ea.



Double contact with leads. Fits 3/4" to 1 1/8" hole. For bulb numbers 82, 88, 90, 210 and 1004.
LS3\$6.85 ea.



Double contact with leads. Fits 1 1/8" hole. For bulb numbers 1034, 1154 and 1157.
LS4\$5.75 ea.

Interior/Dash Sockets



Single contact with lead for dome etc. For bulb numbers 63, 67, 81, 89, 1073, 1129 and 1133.
PT8\$8.75 ea.




Double contact with lead. For dome and map lamps. Reversed ears. Bulb numbers 82, 88, 90, 210 and 1004.
PT9\$7.00 ea.



Double contact with lead for ears aligned bulbs.
PT10\$2.50 ea.

Back-Up and License Lamp Sockets



Single contact with lead. Fits 3/4" hole. Bulb numbers 63, 67, 81, 89, 1129 and 1133.
LS6\$5.75 ea.



Single contact with lead. Fits 1 1/8" hole with ground wire. For bulb numbers 63, 67, 81, 89, 1129 and 1133.
LS7TOS



Single contact with lead. Fits 1 1/8" hole. For bulb numbers 63, 67, 81, 89, 1129 and 1133.
LS8\$6.00 ea.