


Hood • Front Fenders (Group 8)



Hood Insulation Kits (Die Cut) 8.021

- 1961-1962 All. Pre-cut, ready to install.
 HI612\$34.00 ea.
 1964-1967 All. 5 piece kit. Pre-cut, ready to install.
 HI647\$32.50 ea.
 1968-1972 All. 5 piece kit. Pre-cut, ready to install.
 HI682\$32.50 ea.

Spray Adhesive for Application of Hood Insulation

- SA360.....(20 oz).....\$18.00 ea.



Hood Bumpers

-  **1961-1972** Adjustable front hood rubber bumper with stud. 8mm x 1 1/2".
 HB585.....\$4.00 ea.
 HS585.....Stud only.....\$2.50 ea.
-  Retaining nut for above.
 BN650.....\$5.50 ea.
-  **1961-1972** Front hood rubber bumper cap.
 HB595.....\$2.50 ea.
-  **1961-1962** All. Hood to fender bumper. 4 per car.
 HFB612S\$3.00 ea.
-  **1963-1968** All. Hood to fender bumper. 5/8" wide.
 HFB610\$2.75 ea.
-  **1969-1972** All. Hood to fender bumper. 1 1/4" wide.
 HFB611\$2.75 ea.
-  **1963** All. Special and Skylark. Hood to fender bumper.
 HFB63\$4.00 ea.
-  **1968-1972** All. Hood to cowl bumper.
 HB682.....\$2.25 ea.

GS Hood Vent Grills



- Die cast chrome as original.
1970 and 1972 All. Will also fit 1971.
 HG702\$179.00 pr.

Hood Insert Bezels





- 1970-1972**
 HB702.....\$139.00 pr.



Hood Emblems, Letters, Parts

- 1970 GS.** Front hood moulding. Die cast chrome.
 HM70GS.....\$296.00 ea.

BUICK


- 1967** All. Hood letters. "BUICK".
 HL67\$51.00 set
- 1969** GS "400" emblem. Fits either side.
 HE400\$33.00 ea.
 HE400P.....(Matched pair)\$64.50 pr.
- 1969** GS "350" emblem. Fits either side.
 HE350\$39.75 ea.
 HE350P.....(Matched pair)\$75.75 pr.
- 1969** GS "Stage 1" hood emblem. Fits either side.
 HE69S1\$29.50 ea.
 HE69S1P.....(Matched pair).....\$55.00 pr.



- 1972** Tri-Shield in chrome circle
 HE72.....\$124.50 ea.

Hood Release Handle

- 1970-1972** All.
 HH702.....\$15.50 ea.





Front Inner Fender

1970-1972 All. Fits R.H. side.
IF702R.....\$199.00 ea.

Front Inner Fender Repair Panel

1970-1972 all. Replaces the usually rusted area on the battery side, inner fender.
BP702.....\$94.50 ea.



Fender Splash Aprons

1961-1962 Front inner fender.
FA612\$16.50 set
1964-1965 Front inner fender.
FA645\$16.00 set
1966-1967 Front inner fender.
FA667\$16.00 set
1968-1972 Inner fender.
Includes staples as original.
FA682\$17.00 set



Fender Apron Clips

1963-66 All as required.
FSC636.....\$2.25 ea.
FSC636S.....(Set of 15).....\$33.50 ea.



Make Your Own Fender Splash Aprons

Correct composition rubber material is excellent for duplication using your old aprons as a pattern.
MR4812.....(48" x 12").....\$40.75 ea.
MR4824.....(48" x 24").....\$81.50 ea.
MR4836.....(48" x 36").....\$112.25 ea.
MR4848.....(48" x 48").....\$163.00 ea.
MR4860.....(48" x 60").....\$203.75 ea.

Rocker Panel Mouldings (8.304)

1970-1972 All models as required. Sold in pairs. Hardware included.
RM702.....Without Stripes.....\$209.00 pr.
RM702R.....Red Stripes.....\$299.00 pr.
PS1.....Red Pin Stripping Kit.....\$10.00 ea.
PS2.....Black Pin Stripping Kit\$10.00 ea.

Rocker Panel Moulding Clips (8.304)

Round discs for retaining mouldings. Use for any hanging moulding.



MC99\$1.50 ea.
MC99S.....(Pack of 25).....\$36.00 ea.

Front Fender Nameplates
1965 Skylark Fender Emblems



FE65B.....\$58.00 set.



1968-1972 "GS" Fender monogram. Please note: Mounting studs may be slightly different from some earlier models.
FM682G.....\$25.00 ea.



1970-1972 "Buick Motor Division" Plate.
FM702BMD.....\$39.75 ea.



1970-1972 "455" Plate.
FM455.....\$25.25 ea.



1970-1972 "Stage 1" monogram. Please note: mounting studs are 5 1/4" apart exactly like originals.
FM702.....\$49.50 ea.
FM704.....(replacement pins are 2" apart).....\$41.50 ea.



1970-1972 "Stage 2" monogram.
FM705.....\$49.50 ea.



1969 Skylark Front Fender Louvers

FO69L.....(L.H. side)\$25.25 ea.
FO69R.....(R.H. side)\$25.25 ea.