


# Hood • Front Fenders (Group 8)



## Hood Insulation Kits (Die Cut) 8.021

- 1961-1962 All. Pre-cut, ready to install.  
 HI612 .....\$34.00 ea.  
 1964-1967 All. 5 piece kit. Pre-cut, ready to install.  
 HI647 .....\$32.50 ea.  
 1968-1972 All. 5 piece kit. Pre-cut, ready to install.  
 HI682 .....\$32.50 ea.

## Spray Adhesive for Application of Hood Insulation

- SA360.....(20 oz).....\$18.00 ea.



## Hood Bumpers

-  **1961-1972** Adjustable front hood rubber bumper with stainless steel stud.  
 HA585.....\$5.75 ea.  
 HS585...Stud only. Stainless Steel...\$4.75 ea.
-  Retaining nut for above.  
 BN650.....\$5.50 ea.
-  **1961-1972** Front hood rubber bumper cap.  
 HB595.....\$2.50 ea.
-  **1961-1962** All. Hood to fender bumper. 4 per car.  
 HFB612S .....\$3.00 ea.
-  **1963-1968** All. Hood to fender bumper. 5/8" wide.  
 HFB610 .....\$2.75 ea.
-  **1969-1972** All. Hood to fender bumper. 1 1/4" wide.  
 HFB611 .....\$2.75 ea.
-  **1963** All. Special and Skylark. Hood to fender bumper.  
 HFB63 .....\$4.00 ea.
-  **1968-1972** All. Hood to cowl bumper.  
 HB682.....\$2.25 ea.

## Hood Emblems, Letters, Parts

### GS Hood Vent Grills



- Die cast chrome as original.  
 1970 and 1972 All. Will also fit 1971.  
 HG702 .....\$179.00 pr.

### Hood Insert Bezels






- 1970-1972  
 HB702.....\$139.00 pr.




- 1970 GS. Front hood moulding. Die cast chrome.  
 HM70GS.....\$296.00 ea.

## BUICK

- 1964-1965** Hood letters. "BUICK".  
 HL645 .....\$69.50 set
- 1967** All. Hood letters. "BUICK".  
 HL67 .....\$69.50 set
- 1969** GS "400" emblem. Fits either side.  
 HE400 .....\$33.00 ea.  
 HE400P.....(Matched pair) .....\$64.50 pr.
-  **1969** GS "350" emblem. Fits either side.  
 HE350 .....\$39.75 ea.  
 HE350P.....(Matched pair) .....\$75.75 pr.
-  **1969** GS "Stage 1" hood emblem. Fits either side.  
 HE69S1 .....\$29.50 ea.  
 HE69S1P.....(Matched pair).....\$55.00 pr.
-  **1972** Tri-Shield in chrome circle  
 HE72.....\$124.50 ea.

## Hood Release Handle

- 1970-1972 All.  
 HH702.....\$15.50 ea.





**Front Inner Fender**

1970-1972 All. Fits R.H. side.  
IF702R.....\$199.00 ea.

**Front Inner Fender Repair Panel**

1970-1972 all. Replaces the usually rusted area on the battery side, inner fender.  
BP702.....\$94.50 ea.



**Fender Splash Aprons**

1961-1962 Front inner fender.  
FA612 .....\$16.50 set  
1964-1965 Front inner fender.  
FA645 .....\$16.00 set  
1966-1967 Front inner fender.  
FA667 .....\$16.00 set  
1968-1972 Inner fender.  
Includes staples as original.  
FA682 .....\$17.00 set



**Fender Apron Clips**



1963-66 All as required.  
FSC636.....\$2.25 ea.  
FSC636S.....(Set of 15).....\$33.50 ea.

**Make Your Own Fender Splash Aprons**

Correct composition rubber material is excellent for duplication using your old aprons as a pattern.

MR4812.....(48" x 12").....\$40.75 ea.  
MR4824.....(48" x 24").....\$81.50 ea.  
MR4836.....(48" x 36").....\$112.25 ea.  
MR4848.....(48" x 48").....\$163.00 ea.  
MR4860.....(48" x 60").....\$203.75 ea.

**Rocker Panel Mouldings** (8.304)

1970-1972 All models as required. Sold in pairs. Hardware included.

RM702.....Without Stripes.....\$209.00 pr.  
RM702R.....Red Stripes.....\$299.00 pr.  
PS1.....Red Pin Stripping Kit.....\$10.00 ea.  
PS2.....Black Pin Stripping Kit.....\$10.00 ea.

**Rocker Panel Moulding Clips** (8.304)

Round discs for retaining mouldings. Use for any hanging moulding.



MC99 .....\$1.50 ea.  
MC99S.....(Pack of 25).....\$36.00 ea.

**Front Fender Nameplates**  
1965 Skylark Fender Emblems



FE65B.....\$58.00 set.

1965 "Special" on Front Fender.  
FM645S .....\$36.50 ea.



1968-1972 "GS" Fender monogram. Please note: Mounting studs may be slightly different from some earlier models.  
FM682G.....\$25.00 ea.



1970-1972 "Buick Motor Division" Plate.  
FM702BMD.....\$39.75 ea.



1970-1972 "455" Plate.  
FM455.....\$25.25 ea.



1970-1972 "Stage 1" monogram. Please note: mounting studs are 5 1/4" apart exactly like originals.  
FM702.....\$49.50 ea.  
FM704.....(replacement pins are 2" apart).....\$41.50 ea.



1970-1972 "Stage 2" monogram.  
FM705.....\$49.50 ea.



**1969 Skylark Front Fender Louvers**

FO69L.....(L.H. side) .....\$25.25 ea.  
FO69R.....(R.H. side) .....\$25.25 ea.