


Windshield (Group 10)

Windshields



1970-1972 Skylark and GS Convertibles.

- WS702CC.....(Clear w/o antenna).....\$189.00 ea.
- WS702CT.....(Tinted w/o antenna).....\$189.00 ea.
- WS702CTA.....(Tinted w/o antenna).....\$189.00 ea.

Windshield Gaskets and Seals

1961-1963

1961-1962: Special and Skylark;
1963: All Special and Skylark convertibles.


- WS613.....\$123.50 ea.

1961-1972 All "Gasketless" windshield and rear glass.
Glass setting tape. Provides instant and tight seal.

- GS600.....\$12.75 ea.

Butyl dam tape. For use with complete cut-out jobs.

- GS601.....\$12.75 ea.



Windshield Reveal Moulding Sets

1964-1965 All Special, Skylark and GS;

1966-1967 Special and Skylark 4-door models. 5 piece kit.

- WRM647S\$167.75 set

1968-1972 Skylark and GS 2 door hardtop models. 3 piece set.

- WRM682S\$129.50 set

1968-1972 Skylark and GS 2 door convertible. 3 piece set.

- WRM682C\$209.00 set

Windshield Clip Kits

1968-1972 all 2-dr. and 4 dr. Hardtop, convertibles and wagons.

22 piece kit.

- WCK682A.....\$11.75 ea

Wiper Blades and Refills



1963-1965 All. 15" Replacement blades with inserts.

- WB15\$16.50 ea.

1968-1972 Genuine Trico refills. 16"

- WBR16\$15.00 pr.

Windshield Wiper Motors



1964-1967 All with 2-speed wipers.

- WM647.....\$119.50 ea.

1968-1972 All with hidden wipers.

(Depressed park)

- WM682D.....Delco rebuilt.....TOS

Wiper Motor Mounting Kit



1961-1972 All. Includes correct "sems" screws.

- WMK590.....\$14.25 kit

Washer Pumps and Repair Kits



Washer Pump

1963-1968 all 2 and 3 speed;

1968-1972 all w/o depressed park.

- WP634\$58.00 ea.

1961-1972 Repair Kit

1961-1968: All with straight hose fittings;

1969-1972: All with depressed wipers.

- WRK614.....\$12.25 ea.

1961-1972 Repair Kit

1961-1967: All with 90 angled hose fittings;

1968-1972: All without depressed wipers.

- WRK594\$12.25 ea.




908-369-3666

www.oldbuickparts.com

Windshield Washer Jars




1964-1966. Includes cap.
1964-1965: Special and Skylark;
1966: All first type.
WJ646.....\$44.75 ea.

1968-1970. Has tabs that screw to fender well.
WJ680\$46.25 ea. 



Cap for Above Jar
WC632.....\$4.50 ea.

WH680.....\$18.50 ea.
(Hose for above with yellow stripe). 



1966 All 2nd type;
1967-1972 All. Type used in bracket.
WJ632\$14.00 ea.




WC632.....(Cap for above jar).....\$4.50 ea.

WJB632.....(Bracket for jar)\$15.00 ea.



Washer Jar Filter
1961-1972 Washer jar filter.
WF598\$4.75 ea.

Windshield Wiper Hose



1961-1975 Windshield wiper hose. (7/64").
VH764.....\$1.50 per foot
1961-1975 Windshield wiper hose. (5/32").
VH532.....\$1.50 per foot
1961-1975 Windshield wiper hose. (7/32").
VH732.....\$1.50 per foot
1961-1975 Windshield wiper hose. (1/4").
VH14.....\$1.50 per foot



****We have a limited supply of
NOS 1/4" vacuum hose. It features correct outside diameter and "draw" lines for that authentic look.***
VH14OEM.....\$3.50 ft.

Windshield Washer Nozzles



1968-1972 All.
WN682.....\$21.50 pr.

Optikleen Bottles and Caps



1961-1968 all. Bottle assembly. Includes Stainless steel bracket and cap.
OB598.....\$36.50 ea.

1961-1968 All. Includes stenciled writing.
OC598.....(Cap Only).....\$6.75 ea.

1961-1968 Optikleen bottle label for above.
D46.....\$3.75 ea.

1961-1968 Optikleen bottle cap label.
D107.....\$4.00 ea.



Backglass Clip Kits

1968-1972 all 2-dr., 4 dr. Hardtops and sedans. 18 piece kit.

BCK682A.....\$13.25 ea.

For other models see hardware section.



Inside Rear View Mirrors (10.185)



1961-1962 10" wide mirror.
IM572\$76.50 ea.



1963-1972 10" wide mirror.
Stainless steel backed, day-nite with gray rubber bumper.
IM692\$46.00 ea.



1963-1977 12" wide mirror.
Stainless steel backed, day-nite with gray rubber bumper.
IM694\$59.00 ea.

Inside Rear View Mirror Support

1964 Buick Special, Skylark.
1965-1966 Special, Skylark, GS.
All Except Convertibles
MS646.....\$38.50 ea.



1967 Buick Special, Skylark, GS.
All Except Convertibles.
MS67.....\$38.50 ea.



Dash • Interior • Sunvisors (Group 10)

Sunvisor Supports (10.219)



1961-1963 All, except convertibles.

VS613\$49.50 pr.



1964-1972 All, except convertibles.

VS642\$19.75 ea.

Convertible Sunvisor Supports (10.219)



1964-1965 All convertibles. Diecast, very strong, nicely plated.

VS645C\$65.75 pr.

1966-1967 All convertibles. Diecast, very strong, nicely plated.

VS667C\$65.75 pr.



1968 thru 1972 All. Diecast, high strength. Identical to oem.

VS682C\$59.50 pr.

Sunshade Rest Grommet



1963-1972 All as required.

SG632\$5.75 pr.

Sunshade Sleeve



1965-1972 All.

SS642\$5.75 pr.

1968 -1972 Interior Pillar Garnish

Part numbers listed below are for black. For colors, add \$10 with trim code.

PG689.....1968-1969 2 dr. HT.....\$70.25 set

PG689S.....1968-1969 Sedans.....\$70.25 set

PG682C..1968-1972 Convertibles....\$89.75 set



Glove Box Inserts



1961-1963 All w/o ac.

GB613\$24.25 ea.

1964-1965 All.

GB645\$18.50 ea.

1966-1967 All.

GB667\$18.50 ea.

1968-1969 All without A.C.

GB689\$18.50 ea.

1968-1969 All with A.C.

GB689A\$18.50 ea.

1970-1972 All without A.C.

GB702\$18.50 ea.

1970-1972 All with A.C.

GB702A\$18.50 ea.

Glove Box Locks with Two Original Keys (10.266)



1961-1963 Original.

GBL546\$27.75 set

1961-1963 Late style.

GBL613\$25.25 set

*1964 Original.

GBL64\$24.75 set

*1964 Late style.

GBL64L\$21.75 set

1965-1967 Original.

GBL415\$29.25 set

1965-1967 Late style.

GBL657L\$17.00 set

1968 Original.

GBL68\$32.75 set

1968-1972 Late style.

GBL684\$28.25 ea.

CASE NOT INCLUDED

1961-1963 Odometer reset knob.

RK425\$3.75 ea.




Glove Box Light Switch

1964-1972 Special, Skylark, GS. Includes light bulb and new terminal.

GBS644\$14.00

Woodgrain Kits (10.252)

Beautiful woodgrain replaces worn cracked or faded inserts. Available for dash inserts and console. Self adhesive backing for easy installation. Precision die cut with lights turned on.




1970-1972 Full Set w/o AC. Dash and console kits
 WGK702\$85.75 ea.
1970-1972 Full Set w/ AC. Dash and console kits.
 WGK702A.....\$85.75 ea.

1970-1972 Dash kit only. For non-AC cars.
 DK702.....\$39.00 ea.
1970-1972 Dash kit only. For AC cars.
 DK702A\$39.00 ea.



1970-1972 Skylark, GS, GSX with or without A/C. New reproduction backlit dashkit in the correct black finish.
 DK702B.....\$69.00 ea.



1970-1972 Skylark, GS, GSX without A/C. New reproduction backlit dashkit in the correct woodgrain finish.
 DK702T.....\$69.00 ea.



1970-1972 Console woodgrain kit only.
 CK702.....\$29.75 ea.

Cigarette Lighter

Show quality with correct black insert.
1970-1972 Skylark, GS, GSX.
 CL702.....\$28.75 ea.



Console Parts Lids

1965-1972 Console lid. For Short console with padded lid that has emblem installed. Black or white or paint to match.
 CL652B.....(Black).....\$149.00 ea.
 CL652W.....(White)\$149.00 ea.



1968-1969 Console lid. Black or paint to match. For cars with long console.
 CL689A.....\$40.25 ea.



Console Lid Emblem

1965-1972 Tri shield emblem for short padded lid.
 CE652\$39.00 ea.



Console Lid Chrome Trim Plate

1970-1972 Console lid chrome trim plate. Located under lid. For cars with long console.
 CLP705.....\$59.50 ea.




Console Locks

1965-1967 All.
 GBL657L.....\$17.00 ea.



Shift Handle Lever Chrome Trim Plate

1970 thru 1972 all with long console.
 SL705.....\$28.25 ea.



Dash Monograms

1966 "Skylark" with bird.
 DM66S.....\$30.25 ea.
1966 "GS" Dash emblem.
 DE66GS\$14.50 ea.



1967 "GS 400".
 DM67400.....\$33.50 ea.

Interior • Weatherstripping (Group 10)



Roof Rail Weatherstrip

RR623	1962-1963:	All 2-Door Hardtops ...\$126.25 pr.
RR645	1964-1965;	All 2-Door Hardtops.....\$58.00 pr.
RR667	1966-1967:	All 2-Door Hardtops.....\$58.00 pr.
RR667H	1966-1967:	All 4-Door Hardtops.....\$79.50 pr.
RR68	1968:	All 2-Door Hardtops.....\$58.00 pr.
RR689H	1968-1969	All 4-Door Hardtops...\$227.50 pr.
RR692	1969-1972:	All 2-Door Hardtops.....\$58.00 pr.
RR702H	1970-1972	All 4-Door Hardtops...\$169.50 pr.



Roof Rail Window Guides

1969-1972 All two and four door Hardtops.
WG692\$15.00 pr.



1964-1972 Package Shelves (15.024)

This is the Cardboard or Mesh covered area behind the rear seats. Exact Reproduction, Die Cut for Perfect Fit / Easy Installation Replaces Sun Faded or Cracked Shelf. Available in All Colors. Finished in Cardboard or Quality Cloth Mesh. Please State Mesh or Cardboard, and Color.

CARS#	YEARS	TYPE	PRICE
PS645M	1964-1965 2 dr. HT.....	MESH.....	\$53.00
PS645C	1964-1965 2 dr. HT.....	Cardboard	\$30.75
PS645MS	1964-1965 2 & 4 dr Sedans...	MESH.....	\$53.00
PS645CS	1964-1965 2 & 4 dr Sedans...	Cardboard ..	\$30.75
PS667M	1966-1967 2 dr. HT.....	MESH.....	\$53.00
PS667C	1966-1967 2 dr. HT.....	Cardboard	\$30.75
PS667CH	1966-1967 4 dr. HT.....	Cardboard	\$30.75
PS667MH	1966-1967 4 dr. HT.....	MESH.....	\$53.00
PS667CS	1966-1967 4 dr. Sedans.....	Cardboard.....	\$29.95
PS667MS	1966-1967 4 dr. Sedans.....	MESH.....	\$53.00
PS682M	1968-1972 Skylark 2 dr. HT	MESH.....	\$53.00
PS692M	1969-1972 GS 2 dr. HT.....	MESH	\$53.00
PS682C	1968-1972 Skylark 2 dr. HT.	Cardboard	\$33.50
PS692C	1969-1972 GS2 dr. HT.....	Cardboard.....	\$33.50

Package Shelf Jute Underpadding

PJ645A	1964-1965 All	\$10.75
PJ667A	1966-1967 All 2-dr. Hardtop	\$10.75
PJ667AH	1966-1967 All 4-dr. Hardtop	\$14.25
PJ667AS	1966-1967 All 4-dr. Sedans	\$14.25
PJ682A	1968-1972 Skylark	\$10.75
PJ692GS	1969-1972 GS	\$10.75


Rear Glass Moulded Seals

1961-1963 Special 2-door. Model 4027.	
BS613	\$144.25 ea.
1961-1963 4-door Sedans. Model 4119.	
BS613A	\$149.25 ea.
1961-1963 Skylark 2-door hardtops.	
BS613B	\$110.50 ea.

Glass Setting Tape

All "Gasketless" windshield and rear glass.
Provides instant and tight seal. 3/8" round x 15'.
GS600.....\$12.75 ea.

Butyl dam tape. For use with complete window replacement.
1/4" x 3/8" square x 15'.
GS601.....\$12.75 ea.



www.oldbuickparts.com
908-369-3666



1961-1967 Outside Rear View Mirrors

Non-Remote reproduction fits either side. Identical to the original. Licensed by GM. Includes bracket and hardware. One of our most beautiful reproductions.

- MK617F.....(1961 thru 1963 Models).....\$109.00 kit
- MK617R.....(1964 thru 1967 Models).....\$109.00 kit

Gasket Only. Will also fit original non-remote mirrors.

- MG617F.....(1961 thru 1963 Models).....\$9.75 ea.
- MG617R.....(1964 thru 1967 Models).....\$9.75 ea.

Bracket Kit. Contains metal bracket and screws.

Fits either side.

- MB617\$9.75 ea.
- Gasket for original Remote Mirror.
- MG617RC\$9.75 ea.

1970-1972 Sport Mirror Gasket



- MG702SL.....(Left Side)\$4.00 ea.
- MG702SR.....(Right Side)\$4.00 ea.

1970-1972 Sport Mirror Bracket

- MB702SL.....(Left Side)\$14.00 ea.
- MB702SR.....(Right Side)\$14.00 ea.

Door Lock Pairs with Two Keys



- 1961** Original style keys.
DLS608\$36.00 set
- 1961** Late style keys.
DLS61\$23.75 set
- 1962-1966** Original style keys.
DLS596\$36.00 set
- 1962-1966** Late style keys.
DLS683\$17.00 set
- 1967-1968** Original style keys.
DLS678\$30.00 set
- 1967-1968** Late style keys.
DLS683\$17.00 set
- 1969-1972** Late style keys.
DLS683\$17.00 set

Exterior Door Parts (Group 10)



(10.470)

1966-1972 Door Hinges

Our Door Hinges are made from factory blueprints for exact fit and function. They come completely assembled, ready to install.

1964-1965 All

H645LL.....(Lower Left Side).....	\$58.00 ea.
H645LR.....	\$58.00 ea.
H645U.....(Either Side Upper).....	\$63.50 ea.
H645K.....(Complete Set of 4 Kit).....	\$229.50 ea.

1966-1967 All

H667LL.....(Lower Left Side).....	\$58.00 ea.
H667LR.....(Lower Right Side).....	\$58.00 ea.
H667U.....(Either Side Upper).....	\$53.00 ea.
H667K.....(Complete Set of 4 Kit).....	\$216.50 ea.

1968-1972 All

H682LL.....(Lower Left Side).....	\$58.00 ea.
H682LR.....(Lower Right Side).....	\$58.00 ea.
H682U.....(Either Side Upper).....	\$53.00 ea.
H682K.....(Complete Set of 4 Kit).....	\$216.50 ea.

Door Hinge Bolt Kits

1964-1965 All upper. For 2 hinges

1964-1967 All lower. For 2 hinges.

6 screws, 6 bolts

HH647\$14.25 set

1968-1972

HBK682.....(Complete 24 piece kit).....\$25.25 ea.



Door Hinge Springs

1965-1967 All.

HS657\$9.25 ea.



Door Hinge Repair Kits

Kit will fix two doors and includes 4 hardened shouldered pivot pins and 8 sintered bronze bushings.

1964-1967 All.

DHK647\$30.75 set

1968-1972 All.

DHK682\$20.50 set



Door Hinge Detent Repair Kits



1965-1967 All.

DRP667\$40.75 set

1968-1972 All.

DRP682\$43.25 set



Handle Gasket Sets

1963-1972 Outside Door Handles

1964-1967 All front and rear. Both sides, includes buttons and springs.

DH640S.....(Both Sides).\$ 58.00 set

Door Handle Gasket Set for above handles

HG640\$3.50 set

1968-1969 All models-front or rear. Includes buttons with springs, hardware and gaskets. Left and right hand kit.

DH689S\$58.00 set



1963 All;

1970-1972 All models-front or rear.

Includes buttons with springs, hardware and gaskets. Left and right hand kit.

DH635S\$58.00 set

Door handle gasket set for above handles

HG590.....\$6.00 set

Door Handle Pushbutton Kit

Includes 2 each: Pushbuttons, Rubber "O"-Rings, Springs, and Retainers.

Note: The Shafts Must Be Trimmed to Length.


1963-1972 All.

HB642\$18.50 pr.

Door Handle Gasket Set

1961-1962 All.

HG612S.....\$10.50 pr.



Door Lock Gasket

1961-1972 All.

KLK540\$1.25 ea.



Door Lock Striker

1964-1972 All.

DS645.....\$12.00 ea.




Door Handle Bolts

1964-1972 All

DHB642.....\$8.25 set



Door Weatherstrip Sets




Our Door Weather-strip-ping is of the Highest Quality, Manufactured to be Identical to the Original. Each Strip Comes With Pre-Inserted Pins and Correctly Fastened Moulded Ends for Authentic Look and Long Lasting Function. SOLD in PAIRS

DWS613F	1961-1963 Special and Deluxe 4 door Models, Front.....	\$134.25 pr.
DWS613R	1961-1963 Special and Deluxe 4 door Models, Rear.....	\$184.00 pr.
DWS613S	1961-1963 All 2 door Sedans.....	\$133.25 pr.
DWS623	1962-1963 All 2-dr. HT & Convertible. .	\$158.75 pr.
DWS645	1964-1965 All 2 Dr. HT & Convertible....	\$58.00 pr.
DWS645P	1964-1965 2-Dr. Sedans.....	\$58.00 pr.
DWS647	1964-1967 4 Door Sedans and Wagons. Front Doors.....	\$58.00 pr.
DWS647B	1964-1967 4 Door Sedans .Rear Doors.	\$58.00 pr.
DWS647C	1964-1965 All Wagons .Rear Doors; 1966-1967 Special Wagon Rear doors.	\$58.00 pr.
DWS667S	1966-1967 Skylark Wagon. Rear doors.	\$58.00 pr.
DWS667	1966-1967 2-dr Hardtop & Convertible.	\$58.00 pr.
DWS667H	1966-1967 4 Door Hardtop. Front.....	\$77.25 pr.
DWS667R	1966-1967 4 Door Hardtop. Rear.....	\$77.25 pr.
DWS667P	1966-1967 2 Door Sedan.....	\$58.00 pr.
DWS68	1968 2 Dr. H.T. & Convert.....	\$58.00 pr.
DWS692	1969-1972 2-dr Hardtop & Convertible. .	\$58.00 pr.
DWS682P	1968-1972 2 Door Sedans.....	\$58.00 pr.
DWS682H	1968-1972 4-door hardtop. Front.....	\$58.00 pr.
DWS689R	1968-1969 4-door hardtop. Rear.....	\$167.75 pr.
DWS702R	1970-1972 4-door hardtop. Rear.....	\$137.75 pr.
DWS682A	1968-1972 4-dr Sedans & Wagons, front. .	\$58.00 pr.
DWS682B	1968-1972 4-dr Sedans & Wagons, rear.	\$58.00 pr.



Weatherstripping by the Foot

1961-1963 Hardtop and convert. Smooth-skinned extrusion with pre-inserted pins
DW577.....\$2.75 ft.



Front Vent Window Weatherstrip

Our Weatherstrips are Pre-Moulded for Correct Fit

VW613S	1961-1963 All Exc. Convert.....	\$117.00 pr.
VW623S	1962-1963 Convertibles.....	\$117.00 pr.
VW645	1964-1965 All 2-Door HT & Conv....	\$130.75 pr.
VW647	1964-1967 All 2 and 4 door Sedans; 1966-1967 all 4 dr. Sedans	\$97.50 pr.
VW667	1966-67 All 2- Door HT & Convert. ...	\$68.00 pr.
VW68	1968 All 2-door Hardtop & Convert. .	\$68.00 pr.
VW682	1968-1972 Sedan.....	\$68.00 pr.

Front Window Glass Channel

(at Window Frame) Includes Moulded End

VS645	1964-65 2-Dr. Hardtops & Convert.....	\$ 23.50 pr.
VS667	1966-67 2-Dr. Hardtops & Convert.....	\$ 23.50 pr.
VS68	1968 2-Dr. Hardtops & Convert.....	\$ 23.50 pr.

1961-1967 Vent Window Handles



1961-1965 All models;	
1966-1967 all 4-door hardtop models.	
VH615L.....	(L.H. Side)\$22.25 ea.
VH615R.....	(R.H. Side)\$22.25 ea.
1966 thru 1967 all 2-door models.	
VH667L.....	(L.H. Side)\$27.75 ea.
VH667R.....	(L.H. Side)\$27.75 ea.

Hardened Roll Pins for above handles
VHP617\$2.75 ea.

Division Post Cushions (10.701)

	1962-1963 All Skylark hardtops models. Includes metal core. WTC623.....\$35.00 pr.
	1962-1963 All convertibles. WTC623C.....\$38.25 pr.

Weatherstrip Kits (Group 10)

Weatherstrip Kits for All 1964-1972 Models

Basic Rubber Kit Includes: Door Weatherstrips with Moulded Ends, Roof Rail Seals, Trunk Seal.

Complete Rubber Kit Includes: Roof Rail Seals with Header Seal, Pillar Post Seals, Door Seals, Trunk Seal, OEM Window Sweeper Kit, Quarter Window Seals, Lock Pillar Seals, Cowl Seals (1968-1972), Door Lock Gaskets.

1964-1965 All 2-dr. Hardtops. Basic Rubber Kit.	
BRK645H	\$115.00 ea.
1964 All 2-dr. Hardtops. Complete Rubber Kit.	
CRK64H	\$262.25 ea.
1965 All 2-dr. Hardtops. Complete Rubber Kit.	
CRK65H	\$262.25 ea.
1964-1965 All Convertibles. Basic Rubber Kit.	
BRK645C	\$279.50 ea.
1964 All Convertibles. Complete Rubber Kit.	
CRK64C.....(For 1964 Models).....	\$438.00 ea.
1965 All Convertibles. Complete Rubber Kit.	
CRK65C.....(For 1965 Models).....	\$438.00 ea.
1964-1965 All 2-dr. Sedans. Basic Rubber Kit.	
BRK645S.....	\$86.50 ea.



1966-1967 All 2-dr. Hardtops. Basic Rubber Kit. For cars w/o wide belt mouldings.	
BRK667H	\$158.50 ea.
1966-1967 All 2-dr. Hardtops. Complete Rubber Kit.	
CRK667H	\$262.25 ea.
1966-1967 All Convertibles. Basic Rubber Kit.	
BRK667C	\$296.50 ea.
1966-1967 All Convertibles. Complete Rubber Kit.	
CRK667C	\$524.25 ea.



3M Super weatherstrip adhesive. The best we've found.
WA360.....\$11.75 ea.

1968 All 2-dr. Hardtop. Basic Rubber Kit.	
BRK68H	\$156.25 ea.
1968 All 2-dr. Hardtop. Complete Rubber Kit.	
CRK68H	\$277.50 ea.
1968 All Convertibles. Basic Rubber Kit.	
BRK68C	\$277.25 ea.
1968 All Convertibles. Complete Rubber Kit.	
CRK68C	\$438.00 ea.
1969 Special, Skylark 2-dr. Hardtop. Complete Rubber Kit.	
CRK69H	\$278.00 ea.
1969 GS 2-dr. Hardtop. Complete Rubber Kit.	
CRK69GSH.....	\$278.00 ea.
1969 Skylark Convertibles. Complete Rubber Kit.	
CRK69C	\$438.00 ea.
1969 GS Convertibles. Complete Rubber Kit.	
CRK69GC	\$438.00 ea.

1969-1972 All 2-dr. Hardtops. Basic Rubber Kit.	
BRK692H	\$97.50 ea.
1969-1972 All Convertibles. Basic Rubber Kit.	
BRK692C	\$263.75 ea.


1970-1972 All Skylark 2-dr. Hardtops. Complete Kit.	
CRK702H	\$277.50 ea.
1970-1972 All GS 2-dr. Hardtops. Complete Kit.	
CRK702GH	\$277.50 ea.
1970-1972 All Convertibles. Complete Rubber Kit.	
CRK702C	\$438.00 ea.

1964-1972 Door Panel Moisture Shields


Die cut mylar shields installed between the door interior panel and the door body preventing moisture from getting into the interior.

1964-1967 All 2-door hardtop models.	
DPS647H.....	\$22.50 set
1964-1967 All Convertibles.	
DPS647C.....	\$22.50 set
1968-1972 All 2-door hardtop models.	
DPS682H.....	\$22.50 set
1968-1972 All Convertibles.	
DPS682C.....	\$22.50 set

(Group 10) Window Sweeper Kits



(10.710)



All of the below listed Sweeper kits contain 8 horizontal weatherstrips that seal the bottom of the side doorglass and rear quarter glass. Both inside and outside seals are included in the kits. All pieces come with the correct chrome beads (where necessary) and pre-bent metal backing. All kits come with clips and hardware for easy installation.

Our kits are OEM **"original type"** as they look and function as originals. We understand that there are aftermarket kits available through other vendors that have **"flat"** beads instead of the original **"round"** beads. We have found these kits to be inferior both in function and appearance, therefore, we refuse to sell them. Instead you will find that we sell the best "original" style kits at a fraction of the cost of those found elsewhere. Don't be fooled or settle for less.

1964 All 2-dr. Hardtops.	
WK64H	\$117.50 ea.
1964 All Convertibles.	
WK64C	\$117.50 ea.
1965 All 2-dr. Hardtops.	
WK65H	\$117.50 ea.
1965 All Convertibles.	
WK65C	\$117.50 ea.
1965 All 2-dr. Sedans.	
WK65D	\$117.50 ea.
1966-1967 Skylark 2-dr. H.T., w/o wide aluminum moldings.	
WK667H	\$117.50 ea.
1966-1967 GS 2-dr. H.T.	
WK667GSH.....	\$117.50 ea.
1966-1967 All Converts, w/o wide aluminum moldings.	
WK667C	\$117.50 ea.
1966-1967 All Converts, w/ wide aluminum moldings.	
WK667D	\$117.50 ea.
1966-1967 All 2-dr. Sedans. Clip position may differ.	
WK667S	\$117.50 ea.
1966-1967 All 4-dr. Hardtops.	
WK667A	\$117.50 ea.
1966-1967 All 2-dr. Hardtops, with wide aluminum moldings.	
WK667HW.....	\$117.50 ea.

1968 All 2-dr. Hardtops.	
WK68H	\$117.50 ea.
1968 All Convertibles without belt moldings.	
WK68C	\$117.50 ea.
1968 All Convertibles with belt moldings.	
WK68CB	\$117.50 ea.
1968 2-dr. Sedan.	
WK68S	\$117.50 ea.
1969 All Skylark 2-dr. Hardtops.	
WK69SH	\$117.50 ea.
1969 All GS 2-dr. Hardtops.	
WK69H	\$117.50 ea.
1969 All Skylark Convertibles.	
WK69C	\$117.50 ea.
1969 All GS Convertibles.	
WK69GC	\$117.50 ea.
1970-1972 All Skylark 2-dr. Hardtops.	
WK702H	\$117.50 ea.
1970-1972 All GS 2-dr. Hardtops.	
WK702GH	\$117.50 ea.
1970-1972 All Convertibles.	
WK702C	\$117.50 ea.
1970-1972 All 2-dr. Sedans.	
WK702S.....	\$117.50 ea.



www.oldbuickparts.com
908-369-3666




3M Super weatherstrip Adhesive. The best we've found.
 WA360.....\$12.00 ea.

Door • Windows • Weatherstripping (Group 10)

Flexible Window Channel

Used around perimeter of front and rear windows. Flexible rubber with flocking. Trimming to exact length is required. Sold in 6' lengths only.




1961-1963 All Closed Models.

WC613\$22.25 ea.

1964-1972 All Closed Models.

WC642\$22.25 ea.



Side Window Sash Channels

1961-1964 Channel, front window lower sash. Formed steel channel. Ready for attaching to your old brackets. Cut and use as required. 32 3/8" in length.

WC614.....\$78.25 pr.

1961-1963 Special 4-dr. models front door lower sash channels.

WC613A\$93.75 pr.

1961-1963 Special 4-dr. models rear door lower sash channels.

WC613B\$71.50 pr.


1962-1963 Special Convertible door lower sash channels.

WC623A.....\$87.25 pr.

1962-1963 Special and Skylark hardtop lower sash channels.

WC623B.....\$101.25 pr.

Inner Window Sweepers



1961-1962 Special 4-dr. models. Includes correct installed clips.

WS612E.....(Front)\$44.50 pr.

WS612F.....(Rear)\$44.50 pr.

1961-1963 All 2-dr. models. Includes correct installed clips.

WS613D.....(Front)\$46.25 pr.


1962-1963 Skylark hardtop. Includes correct installed clips.

WS623F.....(Rear)\$58.50 pr.

1962-1963 All Convertibles. Includes correct installed clips.

WS623G.....(Rear)\$55.25 pr.

Outer Window Sweepers



1961-1968 Outer window sweeper with round chrome bead. For use on front, rear and quarter windows without chrome reveal mouldings. Stainless steel bead with rubber lip.

WS618.....64" length\$26.00 ea.

WS618A.....(2) 32" lengths.....\$25.00 pr.

WS618B.....(2) 48" lengths.....\$27.25 pr.

1961-1962 Special 4-dr. models w/ chrome reveal molding.

WS612A.....(Front)\$41.75 pr.

WS612B.....(Rear)\$51.25 pr.

1961-1963 Special 4-dr. sedans and wagons. Made with chrome bead and proper attaching clips as original.

1961 2nd type;

1962 All 4-dr. sedans and wagons;

1963 1st. type

WS613B.....(Front)\$46.25 pr.

WS613C.....(Rear).....\$46.25 pr.

1962-1963 Special convertibles and All Skylark models.

For models with chrome reveal molding. Does not have chrome bead. See WG623A for plastic guide.


WS623C.....(Front)\$50.00 pr.

1962-1963 All Skylark hardtop models. Does not have chrome bead. See WG623B for plastic guide.

WS623D.....(Rear).....\$50.50 pr.


1962-1963 All Convertibles. Rubber lipped seal as original.

WS623E.....(Rear).....\$50.25 pr.



1962-1963 Plastic guide plate. Attaches to various outer window sweepers.

WG623A.....\$8.50 ea.




1962-1963 Plastic guide plate. Attaches to various outer window sweepers.

WG623B.\$11.00 ea.



1961-1972 All as required. Glass setting tape. Sold by the foot.

ST330.....\$0.85 ft.



1965 Lower door sash channel filler weatherstrip. All as required for windows with bolt on channels.

SF65.....\$4.25 ft.

Door Handles

For handles not listed NOS Section Group 10.512.

1961 Special 4 dr. Sedan door handles.

DH591.....\$16.00 ea.



1961-1962 All. "Drumstick" type door handles.

DH542.....\$27.25 ea.




1965-1967 All without "Paddle Type" door handles.

DH657.....\$10.00 ea.

1961-1967 All two door Hardtop and Convertibles with "Paddle Type" handles.

DH607.....\$51.00 pr.



1968-1972 All. Beautifully chrome plated.

DH682L.....(Left Hand).....\$16.50 ea.

DH682R.....(Right Hand).....\$16.50 ea.

Vent Window Cranks



1961-1964 All as required. Chrome handle with elongated open slot.

VC594.....\$16.50 ea.

1961-1972 All tension spring.

HS395.....\$1.50 ea.



1961-1972 All. Window crank spring washer.

HW552.....\$3.00 ea.

Window Rollers (see more in group 17)

1963-1966 All as required. Window regulator roller and Rivet.

WR576.....\$3.25 ea.

1968-1990 All as required. .68 OD, .017 ID. nylon WR727\$2.25 ea.

1974-1987 All as required. .94 OD nylon with brass threaded stud.

WR747.....TOS



Window Cranks



1964 All as required. Chrome handle with chrome knob. Elongated open slot.

WH594.....\$16.50 ea.



1965-1966 All as required. Chrome handle with chrome knob.

WH656.....\$12.50 ea.

1967 With correct black knob.

WH67.....\$12.50 ea.



1968-1972 All with black knob.

WH680B.....\$6.00 ea.



1968-1972 All a clear knob.

WH680C.....\$6.00 ea.

Knob Replacement Kit

Will fit from 1961.

1968-1972 Black.

KK680B\$3.00 ea.

1968-1972 Clear.

KK680C.....\$3.00 ea.



Handle Removal Tool

Remove window and door handle retaining clips without damaging door panels.

1961-1972 All.

HT360\$7.75 ea.



Handle Retaining Clip

1961-1972 All as required. Door handle retaining clip (10 pack).

HRC318\$2.25 set



Doors Floor Panels (Group 10)



Door Sill Step Plates

1964-1967 All two door models.

DS647.....\$54.50 pr.

1968-1972 All two door models.

DS682.....\$49.00 pr.

1961-1972 Door sill screws.

TS634\$0.25 ea.

Door Bumpers (10.587)



1961-1963

DB570\$2.75 ea.



1964-1965 As required.

DB646\$2.75 ea.



1964-1967 All (4 per car).

1964 all Special 2-dr. models and All Skylark models;

1965-1967 All Special, Skylark and GS 2-dr. models.

DB667\$2.75 ea.



1968-1972 All.

DB500C\$2.75 ea.



Power Window Motors

1961-1972 Power window motor. State left hand or right hand. Plug may differ. Hard wire if necessary.

WM600L.....Left Hand\$127.25 ea.

WM600R.....Right Hand\$127.25 ea.

Conduit for Front Door Power Lines



DC647..... 1964-1967 All.....\$46.50 pr.

DC68..... 1968 All.....\$51.00 pr.

DC692..... 1969-1972 All.....\$40.75 pr.



Power Window Switches and Bezels

1964-1970 All "4 in a row" type assembly and bezel.

PWS640\$67.50 ea.



1964-1970 All single switch with bezel.

PWS640S\$36.50 ea.

1971-1977 All "4 in a row" type with bezel.


PWS717\$75.75 ea.

1971-1972 All single switch with bezel.

PWS717S.....\$29.50 ea.



Power Door Locks and Bezels



1968-1970 All square switch. "LOCK" .

DLS680\$69.75 ea.



1971-1972 All square switch. "LOCK" .

DLS717\$59.50 ea.

Coat Hooks

1961-1972 All.

CH396.....\$11.25 ea.

