



### Dome Lamp Lenses



**1971-1972** All closed models.  
DL827 .....\$7.75 ea.



**1971-1972** All closed models.  
DLH717 .....\$9.75 ea.

### Courtesy Lamp Lenses



**1961-1972** All convertibles.  
CL544 .....\$5.25 ea.



**1961-1972** All convertibles. Courtesy lamp housing. Chrome plated.  
CLH542 .....\$27.75 ea.



**1961-1965** All with three circular rings.  
CL615 .....\$7.75 ea.



**1966-1968** All with smooth surface.  
CL618.....\$6.25 ea.



CB618...(Chrome bezel for above)...\$28.50 ea.

**1968-1969.** Correct rectangular lens with tri-shield

**1968-1969:** Wagons;

**1969:** All with long rectangular lens.

CL69 .....\$12.00 ea.



**1969** Wildcat and Electra. Round courtesy lens with tri shield. Compare to CL695.  
CL69R.....\$12.75 ea.



**1969-1972** All with seven (7) circular rings. Correct coloring as original.  
CL695 .....\$9.00 ea.



**1969-1972** All courtesy lamp housing.  
CLH692 .....\$17.00 ea.

### Air Duct Hose

Sturdy, wire reinforced defroster and air duct made like the original with rubber impregnated cloth covering. Specify inner diameter and length. Sold in one foot increments only.



AD150..... 1 1/2".....\$8.00 ft.  
AD200.....2".....\$9.50 ft.  
AD250..... 2 1/2".....\$11.25 ft.  
AD300.....3".....\$12.00 ft.  
AD350.....3 1/2".....\$12.25 ft.  
AD375..... 3 3/4".....\$12.25 ft.  
AD400..... 4".....\$12.50 ft.  
AD500..... 5".....\$13.25 ft.  
AD538..... 5 3/8".....\$14.00 ft.

### Door Sill Plates (11.175)



**1961-1963** All 2-door models. Pair.

Custom made 10 mo. delivery.

DS613S.....\$242.50 pr.

**1964-1967** All 2-door models. Pair. In stock. Includes "Fisher" emblem sticker.

DS647.....\$48.50 pr.

**1964-1967** All 2-door models. Pair. In stock. Also, includes "Fisher" emblem already riveted to sill as original.

Show Ready.

DS647R.....\$68.50 pr.

**1968-1972** All 2-door models. Pair. In stock.

DS682.....\$59.50 pr.

### Door Jamb Switches



**1961-1963** Special, Skylark (front).

DJS613.....\$18.50 ea.

**1964-1972**

**1964-1967:** Special (front);

**1968-1970:** All, right front;

**1969:** Skylark, Sportwagon (rear);

**1971-1972:** Custom, GS and Sportwagon.

DJS642.....\$ 6.75 ea.



**1968-1972**


**1968-1970:** Left front;

**1971-1972:** Skylark, except custom, GS and Sportwagon.

DJS665.....\$ 8.75 ea.



# Rear 1/4 Window • Rocker Panel (Group 11)



## Quarter Window Seals

This is the Vertical Rubber Sealing Strip Between the Front and Rear Side Window on All Hardtops and Convertibles;

**SOLD IN PAIRS**

- 1961-1963 All.  
QS550 .....\$17.00 pr.
- 1964-1965 Convertibles.  
QS645C .....\$18.50 pr.
- 1964-1965 Hardtops.  
QS645H .....\$18.50 pr.
- 1966-1967 All.  
QS667 .....\$18.50 pr.
- 1968-1972 All.  
QS682 .....\$18.50 pr.

## Quarter Window Chrome

1964-1972 All two door hardtop and convertible models. Our formed chrome channels come complete with correct seal to adhere to glass.

### 1964-1965 Models

- QC645L.....Left Side.....\$42.00 ea.
- QC645R.....Right Side .....\$42.00 ea.

### 1966-1967 Models

- QC667L.....Left Side.....\$42.00 ea.
- QC667R.....Right Side .....\$42.00 ea.

### 1968 Models

- QC68L.....Left Side.....\$42.00 ea.
- QC68R.....Right Side .....\$42.00 ea.

### 1969-1972 Models

- QC692L.....Left Side.....\$42.00 ea.
- QC692R.....Right Side .....\$42.00 ea.


## Quarter Window Lock Pillar Seals

- 1962-1963 All two door hardtops.  
LPS623.....\$55.75 pr.

- 1962-1963 All convertibles.  
LPS623C .....\$49.25 pr.



- 1964-1965 All two door hardtops and convertibles.  
LPS645 .....\$18.50 pr.



- 1964-1965 All convertibles. Filler at rear on inner panel. Found at bottom rear side of window when window is rolled up.  
LPS645C.....\$64.75 pr.

- 1966-1967 All two door hardtops and convertibles.  
LPS667 .....\$14.50 pr.




- 1966-1967 All 4-door hardtops. For rear doors.  
LPS667H.....\$39.50 pr.



- 1968-1972 All two door hardtops, convertibles and Sport Wagons.  
LPS682 .....\$18.50 pr.

## Quarter Window Auxillary Seals (11.015)

- 1968-1972 all 2-door hardtop and convertible. Located at rear base of quarter window at bottom.  
QS682A.....\$



- 1961-1963 Special 4-door sedans. Weatherstrip, rear quarter fixed window.  
RQS613 .....\$97.00 pr.



- 1968-1972 All 2-door models. Lower window guide roller. Use as required.  
WR682.....\$4.75 ea.

## Lock Pillar Vents



PV69 PV702

- 1969 All 2-dr. Models.  
PV69 .....\$13.00 ea.
- 1970-1972 All 2-dr. Models.  
PV702 .....\$16.00 ea.