



Dome Lamp Lenses



1971-1972 All closed models.
DL827\$7.75 ea.



1971-1972 All closed models.
DLH717\$9.75 ea.

Courtesy Lamp Lenses



1961-1972 All convertibles.
CL544\$5.25 ea.



1961-1972 All convertibles. Courtesy lamp housing. Chrome plated.
CLH542\$27.75 ea.



1961-1965 All with three circular rings.
CL615\$7.75 ea.



1966-1968 All with smooth surface.
CL618.....\$6.25 ea.



CB618...(Chrome bezel for above)...\$40.75 ea.

1968-1969. Correct rectangular lens with tri-shield

1968-1969: Wagons;

1969: All with long rectangular lens.

CL69\$12.00 ea.



1969 Wildcat and Electra. Round courtesy lens with tri shield. Compare to CL695.
CL69R.....\$12.75 ea.



1968-1969. Replacement lens with ribs.

1968-1969: Wagons;

1969: All with long rectangular lens.

CL689\$6.50 ea.



1969-1972 All with seven (7) circular rings. Correct coloring as original.
CL695\$9.00 ea.



1969-1972 All courtesy lamp housing.
CLH692\$17.00 ea.

Air Duct Hose

Sturdy, wire reinforced defroster and air duct made like the original with rubber impregnated cloth covering. Specify inner diameter and length. Sold in one foot increments only.



AD150..... 1 1/2".....\$8.00 ft.
AD200.....2".....\$9.50 ft.
AD250..... 2 1/2".....\$11.25 ft.
AD300.....3".....\$12.00 ft.
AD350.....3 1/2".....\$12.25 ft.
AD375..... 3 3/4".....\$12.25 ft.
AD400..... 4".....\$12.50 ft.
AD500..... 5".....\$13.25 ft.
AD538..... 5 3/8".....\$14.00 ft.

Door Sill Plates (11.175)



1961-1963 All 2-door models. Pair.

Custom made 10 mo. delivery.

DS613S.....\$242.50 pr.

1964-1967 All 2-door models. Pair. In stock. Includes "Fisher" emblem sticker.

DS647.....\$48.50 pr.

1964-1967 All 2-door models. Pair. In stock. Also, includes "Fisher" emblem already riveted to sill as original. Show Ready.

DS647R.....\$68.50 pr.

1968-1972 All 2-door models. Pair. In stock.

DS682.....\$59.50 pr.

Door Jamb Switches



1961-1963 Special, Skylark (front).

DJS613.....\$18.50 ea.

1964-1972

1964-1967: Special (front);

1968-1970: All, right front;

1969: Skylark, Sportwagon (rear);

1971-1972: Custom, GS and Sportwagon.

DJS642.....\$ 6.75 ea.



1968-1972

1968-1970: Left front;

1971-1972: Skylark, except custom, GS and Sportwagon.

DJS665.....\$ 8.75 ea.



Rear 1/4 Window • Rocker Panel (Group 11)

Quarter Window Seals

This is the Vertical Rubber Sealing Strip
Between the Front and Rear Side Windows
on All Hardtops and Convertibles;
SOLD IN PAIRS



1961-1963 All. QS550.....	\$17.00 pr.
1964-1965 Convertibles. QS645C.....	\$18.50 pr.
1964-1965 Hardtops. QS645H.....	\$18.50 pr.
1966-1967 All. QS667.....	\$18.50 pr.
1968-1972 All. QS682.....	\$18.50 pr.

Quarter Window Chrome

1964-1972 All two door hardtop and convertible models.
Our formed chrome channels come complete with correct
seal to adhere to glass.

1964-1965 Models

QC645L.....Left Side.....	\$38.50 ea.
QC645R.....Right Side.....	\$38.50 ea.

1966-1967 Models

QC667L.....Left Side.....	\$38.50 ea.
QC667R.....Right Side.....	\$38.50 ea.

1968 Models

QC68L.....Left Side.....	\$38.50 ea.
QC68R.....Right Side.....	\$38.50 ea.

1969-1972 Models

QC692L.....Left Side.....	\$38.50 ea.
QC692R.....Right Side.....	\$38.50 ea.


Quarter Window Lock Pillar Seals

1962-1963 All two door hardtops.
LPS623.....\$55.75 pr.

1962-1963 All convertibles.
LPS623C.....\$49.25 pr.



1964-1965 All two door hardtops and convertibles.
LPS645.....\$18.50 pr.



1964-1965 All convertibles. Filler at rear on inner panel. Found at bottom rear side of window when window is rolled up.
LPS645C.....\$64.75 pr.

1966-1967 All two door hardtops and convertibles.
LPS667.....\$14.50 pr.




1966-1967 All 4-door hardtops. For rear doors.
LPS667H.....\$39.50 pr.



1968-1972 All two door hardtops, convertibles and Sport Wagons.
LPS682.....\$18.50 pr.

Quarter Window Auxillary Seals (11.015)

1968-1972 all 2-door hardtop and convertible. Located at rear base of quarter window at bottom.
QS682A.....\$



1961-1963 Special 4-door sedans. Weatherstrip, rear quarter fixed window.
RQS613.....\$97.00 pr.



1968-1972 All 2-door models. Lower window guide roller. Use as required.
WR682.....\$4.75 ea.

Lock Pillar Vents



PV69 PV702

1969 All 2-dr. Models.
PV69.....\$13.00 ea.

1970-1972 All 2-dr. Models.
PV702.....\$16.00 ea.